

Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Lilli Pilli Public School (4084)
Region:	Sydney AMU
State Electorate:	Cronulla
Local Government Area:	Sutherland

Last Reviewed By:	WSP 28-AUG-2015
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	Yes
Please refer to the latest site specific Asbestos Management Plans available from the Department's website (Refer to Note 2).	



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>

<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00B - Library/Pupil Facilities - 1950 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting						
Gable Verge Lining	Flat AC Sheeting						
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00B - R0001 - Reading Area - 85.83 m2							
No Asbestos							
B00B - R0002 - Library Office/Workroom - 21.66 m2							
No Asbestos							
B00B - R0003 - K.L.A. Store - 6.73 m2							
No Asbestos							
B00B - R0004 - External Movement - 4.65 m2							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00B - R0005 - Home Base - 56.49 m2							
No Asbestos							
B00B - R0006 - Home Base Store - 5.34 m2							
Floor Coverings Res/Textile	Vinyl Tiles	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0007 - Cleaning Distributed Store - .63 m2							
Floor Coverings Res/Textile	Vinyl Tiles	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0008 - Personal Effects Storage - 7.42 m2							
No Asbestos							
B00B - R0009 - Movement - 4.59 m2							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00B - R0010 - Movement - 1.47 m2							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00B - R0011 - General Storeroom - .63 m2							
Floor Coverings Res/Textile	Vinyl Tiles	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0012 - Home Base - 56.57 m2							
No Asbestos							
B00B - R0013 - Home Base Store - 5.34 m2							
Floor Coverings Res/Textile	Vinyl Tiles	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0015 - General Storeroom - 13.72 m2							
No Asbestos							
B00B - R0016 - Movement - 4.69 m2							
No Asbestos							
B00B - R0017 - Special Programs Room - 55.79 m2							
No Asbestos							

B00B - R0018 - Covered Outdoor Learning Area - 260.69 m2							
No Asbestos							
B00B - R9001 - General Storeroom - 83.69 m2							
No Asbestos							
B00B - R9002 - Movement - 25.53 m2							
Ceiling Structures/Linings	Flat AC Sheeting	26m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00B - R9003 - Canteen - 20.22 m2							
No Asbestos							
B00B - R9004 - Canteen Office/Store - 2.97 m2							
No Asbestos							
B00B - R9005 - Canteen Office/Store - 3.41 m2							
No Asbestos							
B00C - General Learning - 1956 - Timber							
Exterior							
Gable Verge Lining	Flat AC Sheeting						
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Eaves Linings	Flat AC Sheeting						
Interior							
B00C - R0001 - Personal Effects Storage - 21.71 m2							
Ceiling Structures/Linings	Flat AC Sheeting	22m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00C - R0002 - General Storeroom - 10.82 m2							
No Asbestos							
B00C - R0003 - General Storeroom - 11.06 m2							
No Asbestos							
B00C - R0004 - Home Base - 53.73 m2							
No Asbestos							
B00C - R0005 - Home Base - 53.51 m2							
No Asbestos							
B00C - R0006 - Personal Effects Storage - 15 m2							
No Asbestos							
B00D - General Learning/Communal Facilities - 1957 - Timber							
Exterior							
Eaves Linings	Flat AC Sheeting	20m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Gable Verge Lining	Flat AC Sheeting						
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00D - R0001 - Sports Store - 7.49 m2							
Ceiling Structures/Linings	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00D - R0002 - Cleaning Distributed Store - 9.06 m2							
No Asbestos							

B00D - R0003 - Home Base Store - 12.77 m2							
No Asbestos							
B00D - R0004 - Practical Activities - 1hb - 6.37 m2							
Floor Coverings Res/Textile	Vinyl Tiles	4m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00D - R0005 - Home Base - 46.84 m2							
Wall Linings Internal	Flat AC Sheeting	3m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00D - R0006 - Home Base - 53.58 m2							
Wall Linings Internal	Flat AC Sheeting	3m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00D - R0007 - Staff Room Annexe - 9.24 m2							
No Asbestos							
B00D - R0008 - Craft Store - 12.6 m2							
No Asbestos							
B00D - R0009 - Special Programs Room - 53.51 m2							
Floor Coverings Res/Textile	Vinyl Tiles	9m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	3m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00D - R0010 - Raised Platform - 26.24 m2							
No Asbestos							
B00D - R0011 - Communal Space - 94 m2							
Wall Linings Internal	Flat AC Sheeting	6m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00D - R0012 - Staff Toilet - 5.56 m2							
Wall Linings Internal	Flat AC Sheeting	4m2	Partition	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00D - R0013 - Staff Toilet - 3.97 m2							
Wall Linings Internal	Flat AC Sheeting	4m2	Partition	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00D - R0014 - General Storeroom - 11.68 m2							
No Asbestos							
B00D - R0015 - Main Switch Board - 4.11 m2							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00D - R0016 - Movement - 94.83 m2							
Ceiling Structures/Linings	Flat AC Sheeting	95m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00D - R9001 - General Assistant/Bulk Store - 12.32 m2							
No Asbestos							
B00E - General Learning - 1950 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting						
Gable Verge Lining	Flat AC Sheeting						
Ceiling Voids	No Asbestos Found						

Underfloor Voids	No Asbestos Found							
Interior								
B00E - R0001 - Home Base Store - 6.92 m2								
No Asbestos								
B00E - R0002 - Practical Activities - 1hb - 1.09 m2								
No Asbestos								
B00E - R0003 - Withdrawal Space - 1hb - 6.88 m2								
No Asbestos								
B00E - R0004 - Movement - 4.06 m2								
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)	
B00E - R0005 - Home Base - 55.69 m2								
Wall Linings Internal	Flat AC Sheeting	1m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)	
B00E - R0006 - Movement - 4.06 m2								
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)	
B00E - R0007 - Withdrawal Space - 1hb - 6.86 m2								
No Asbestos								
B00E - R0008 - Home Base Store - 6.87 m2								
No Asbestos								
B00E - R0009 - Home Base - 55.89 m2								
Wall Linings Internal	Flat AC Sheeting	2m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)	
B00E - R0010 - Practical Activities - 1hb - 1.16 m2								
No Asbestos								
B00F - Pupil Facilities - 1957 - Timber								
Exterior								
Eaves Linings	Flat AC Sheeting	6m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Ceiling Voids	No Asbestos Found							
Underfloor Voids - Slab on Ground	No Asbestos Found							
Interior								
B00F - R0001 - Toilets - Girls - 21.19 m2								
Ceiling Structures/Linings	Flat AC Sheeting	22m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)	
B00F - R0002 - Cleaning Distributed Store - 1.82 m2								
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)	
B00G - Pupil Facilities - 1957 - Timber								
Exterior								
Ceiling Voids	No Asbestos Found							
Underfloor Voids - Slab on Ground	No Asbestos Found							
Interior								
B00G - R0001 - Drinking Facilities - 9.86 m2								

No Asbestos							
B00G - R0002 - Drinking Facilities - 9.41 m2							
No Asbestos							
B00H - Pupil Facilities - 1957 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	6m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Interior							
B00H - R0001 - Toilets - Boys - 25.51 m2							
Ceiling Structures/Linings	Flat AC Sheeting	26m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00H - R0002 - Cleaning Distributed Store - 1.82 m2							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00I - General Learning - 1961 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	40m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting						
Wall Linings Internal - Infill	Flat AC Sheeting	5	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00I - R0002 - General Storeroom - 3.24 m2							
Floor Coverings Res/Textile	Vinyl Tiles	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00I - R0008 - Personal Effects Storage - 10.27 m2							
No Asbestos							
B00I - R0009 - Movement - 11.86 m2							
Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00I - R0010 - Movement - 8.16 m2							
Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00I - R0011 - General Storeroom - 2.85 m2							
No Asbestos							
B00I - R0012 - Staff Room Annexe - 15.62 m2							
No Asbestos							
B00I - R0013 - Practical Activities - 1hb - 9.18 m2							
No Asbestos							
B00I - R0014 - Home Base - 46.99 m2							

Wall Linings Internal	Flat AC Sheeting	2m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Floor Coverings Res/Textile	Vinyl Tiles	10m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B001 - R0015 - Personal Effects Storage - 10.48 m2							
No Asbestos							
B001 - R0017 - Movement - 8.21 m2							
Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B001 - R0025 - Movement - 4.69 m2							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B001 - R0026 - Entry Vestibule - 11.44 m2							
No Asbestos							
B001 - R0027 - Principal - 16.65 m2							
No Asbestos							
B001 - R0028 - General Storeroom - 7.95 m2							
No Asbestos							
B001 - R0029 - Sick Bay - 6.82 m2							
No Asbestos							
B001 - R0030 - Staff Room - 36.73 m2							
No Asbestos							
B001 - R0031 - Clerical Office - 22.45 m2							
No Asbestos							
B001 - R0032 - Staff Toilet - 1.85 m2							
Wall Linings Internal	Flat AC Sheeting						
B001 - R0033 - Movement - 2.35 m2							
Wall Linings Internal	Flat AC Sheeting						
B001 - R0034 - Movement - 4.84 m2							
No Asbestos							
B001 - R0035 - Movement - 3.34 m2							
No Asbestos							
B001 - R0036 - Home Base - 65.21 m2							
Wall Linings Internal - Infill	Compressed AC Sheet	1m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B001 - R0037 - Home Base Store - 5.6 m2							
No Asbestos							
B001 - R0038 - Home Base Store - 3.57 m2							
No Asbestos							
B001 - R0039 - Home Base - 60.21 m2							
Wall Linings Internal - Infill	Compressed AC Sheet	1m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B001 - R0040 - Movement - 10.7 m2							
No Asbestos							
B001 - R0041 - Movement - 3.32 m2							
Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B001 - R0042 - General Storeroom - 10.89 m2							
No Asbestos							

B00I - R0043 - Communal Space - 61.8 m2							
No Asbestos							
B00J - General Learning/Library - 1965 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	40m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting						
Wall Linings Internal - Infill	Flat AC Sheeting	4	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00J - R0001 - Staff Room - 21.78 m2							
No Asbestos							
B00J - R0002 - Staff Toilet - 3.26 m2							
Partition Walls (Cubicles)	Compressed AC Sheet						
B00J - R0003 - Movement - 6.96 m2							
Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00J - R0004 - Movement - 8.1 m2							
Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00J - R0005 - Personal Effects Storage - 3.13 m2							
Floor Coverings Res/Textile	Vinyl Tiles	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00J - R0006 - Home Base Store - 6.98 m2							
Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00J - R0007 - Home Base - 46.78 m2							
No Asbestos							
B00J - R0008 - Practical Activities - 1hb - 9.83 m2							
No Asbestos							
B00J - R0009 - Home Base - 56.98 m2							
No Asbestos							
B00J - R0010 - Home Base Store - 10.38 m2							
Floor Coverings Res/Textile	Vinyl Tiles	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00J - R0011 - Movement - 6.96 m2							
Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00J - R0012 - Movement - 9.22 m2							
Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00J - R0013 - Personal Effects Storage - 3.17 m2							

Floor Coverings Res/Textile	Vinyl Tiles	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00J - R0014 - Practical Activities - 1hb - 9.8 m2							
Floor Coverings Res/Textile	Vinyl Tiles	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00J - R0015 - Home Base - 47.04 m2							
No Asbestos							
B00J - R0016 - Home Base Store - 6.97 m2							
Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00K - Other-After School Care/General Learning - 1957 - Brick/Veneer							
Exterior							
Eaves Linings	Flat AC Sheeting	40m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting						
Wall Linings Internal - Infill	Flat AC Sheeting	1	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00K - R0001 - Out Of School Hours Care Centre - 56.78 m2							
No Asbestos							
B00K - R0002 - Personal Effects Storage - 10.3 m2							
Wall Linings Internal	Flat AC Sheeting	2m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Floor Coverings Res/Textile	Vinyl Tiles	11m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00K - R0003 - Movement - 6.32 m2							
Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00K - R0004 - Movement - 4.83 m2							
No Asbestos							
B00K - R0005 - Uniform Shop - 10.3 m2							
No Asbestos							
B00K - R0006 - Home Base - 56.7 m2							
No Asbestos							
B00K - R9001 - Sports Store - 54.57 m2							
Ceiling Structures/Linings	Flat AC Sheeting	55m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00L - Pupil Facilities - 1957 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	4m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						

Underfloor Voids	No Asbestos Found	
New XYZ	AC Fragments/Debris	
Interior		
B00L - R0001 - Drinking Facilities - 8.17 m2		
No Asbestos		
B00L - R0002 - Toilets - Girls - 39.01 m2		
No Asbestos		
B00L - R0003 - Cleaning Distributed Store - 1.16 m2		
No Asbestos		
B00L - R0004 - Toilets - Boys - 40.5 m2		
No Asbestos		
B00L - R0005 - Drinking Facilities - 8.04 m2		
No Asbestos		
B00M - Pupil Facilities/Communal Facilities - 2011 - Brick/Veneer		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Interior		
B00M - R0001 - Communal Space - 137.02 m2		
No Asbestos		
B00M - R0002 - Raised Platform - 66.74 m2		
No Asbestos		
B00M - R0003 - Communal/Performance Store - 10.68 m2		
No Asbestos		
B00M - R0004 - Hall Chair Store - 11.59 m2		
No Asbestos		
B00M - R0005 - P.E. Store - 17.21 m2		
No Asbestos		
B00M - R0006 - Toilets - Boys - 11 m2		
No Asbestos		
B00M - R0007 - Toilet - Lobby - 2 m2		
No Asbestos		
B00M - R0008 - Sound Cupboard - 2.63 m2		
No Asbestos		
B00M - R0009 - Disabled Shower/Toilet - 7.5 m2		
No Asbestos		
B00M - R0010 - Toilet - Lobby - 3.29 m2		
No Asbestos		
B00M - R0011 - Toilets - Girls - 10.88 m2		
No Asbestos		
B00M - R0012 - Distribution Board - 2.9 m2		
No Asbestos		Note: No inspection of live electrical installation
B00M - R0013 - Cleaning Distributed Store - 5.01 m2		
No Asbestos		
B00M - R0014 - Covered Outdoor Learning Area - 168.85 m2		
No Asbestos		
B00M - R0015 - Plant - .3 m2		
No Asbestos		

B00M - R0016 - Movement - 8.11 m2	
No Asbestos	
B00M - R0017 - Movement - 11.12 m2	
No Asbestos	
B00M - R0018 - Movement - 14.64 m2	
No Asbestos	
B00M - R0019 - Movement - 5.76 m2	
No Asbestos	

Demountables

OS 502 15488 - Admin Staff/Principal/Clerk/Dup/Clinic - Placement Date : 18-JAN-2003

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found