

Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Lismore Heights Public School (4085)
Region:	North Coast AMU
State Electorate:	Lismore
Local Government Area:	Lismore

Last Reviewed By:	Greencap 14-APR-2016
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	No
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>

<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - Administration/Staff Facilities - 1969 - Brick/Block							
Exterior							
Ceiling Voids	Non Accessible Area						
Underfloor Voids	No Asbestos Found						
Interior							
B00A - R0001 - Principal - 17.21 m2							
No Asbestos							
B00A - R0004 - Clerical Office - 12.8 m2							
No Asbestos							
B00A - R0006 - Sick Bay - 8.28 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0007 - Duplicating Workroom - 22.36 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0008 - Interview - 11.29 m2							
No Asbestos							
B00A - R0010 - Deputy Principal - 11.39 m2							
No Asbestos							
B00A - R0011 - Deputy Principal - 11.33 m2							
No Asbestos							
B00A - R0012 - Cleaning Distributed Store - 1.29 m2							
No Asbestos							
B00A - R0014 - Distribution Board - 1.2 m2							
No Asbestos							Note: No inspection of live electrical installation
B00A - R0016 - General Storeroom - 22.82 m2							
No Asbestos							
B00A - R0017 - External Movement - 63.27 m2							
Ceiling Structures/Linings	Flat AC Sheeting	57m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Compressed AC Sheet	12m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0018 - External Movement - 42.07 m2							
Ceiling Structures/Linings	Flat AC Sheeting	42m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0021 - Movement - 10.22 m2							
No Asbestos							
B00A - R0022 - Movement - 21.36 m2							
No Asbestos							
B00A - R0023 - Toilet - Lobby - 2.29 m2							
No Asbestos							
B00A - R0024 - Toilet - Lobby - 3.18 m2							
No Asbestos							
B00A - R0025 - Staff Toilet - 1.38 m2							
No Asbestos							
B00A - R0026 - Staff Toilet - 1.92 m2							
No Asbestos							
B00A - R0027 - Staff Kitchen - 10.28 m2							
No Asbestos							

B00A - R0028 - Staff Room - 42.04 m2							
No Asbestos							
B00A - R0029 - Entry Vestibule - 10.67 m2							
Require Inspection							
B00A - R0030 - External Movement - 5.11 m2							
Require Inspection							
B00B - General Learning - 1956 - Brick/Veneer							
Exterior							
Underfloor Voids - Slab on Ground	Non Accessible Area						
Ceiling Voids	No Asbestos Found						
Interior							
B00B - R0003 - Home Base Store - 4.11 m2							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0005 - Home Base - 56.71 m2							
No Asbestos							
B00B - R0006 - Home Base Store - 4.09 m2							
No Asbestos							
B00B - R0007 - Practical Activities - 1hb - 9.73 m2							
No Asbestos							
B00B - R0008 - Home Base Store - 4.07 m2							
No Asbestos							
B00B - R0009 - Practical Activities - 1hb - 10 m2							
No Asbestos							
B00B - R0010 - Home Base - 56.56 m2							
No Asbestos							
B00B - R0011 - External Movement - 53.34 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
Wall Linings Internal - Infill	Compressed AC Sheet	12m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0012 - External Movement - 59.87 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00B - R0013 - Toilets-Unisex - 7.05 m2							
Require Inspection							
B00B - R0014 - Movement - 9.63 m2							
Require Inspection							
B00B - R0015 - Home Base - 83.74 m2							
Require Inspection							
B00C - General Learning/Pupil Facilities - 1969 - Brick/Block							
Exterior							
Underfloor Voids - Slab on Ground	Non Accessible Area						
Ceiling Voids	No Asbestos Found						
Gable Verge Lining	Flat AC Sheeting	30m2	North & South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Interior							
B00C - R0001 - External Movement - 96.23 m2							
No Asbestos							

B00C - R0002 - General Storeroom - 5.91 m2							
No Asbestos							
B00C - R0003 - General Storeroom - 9.43 m2							
No Asbestos							
B00C - R0004 - Toilets - Girls - 22.63 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	16m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00C - R0005 - Toilets - Boys - 31.94 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Partition Walls (Cubicles)	Compressed AC Sheet	12m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0006 - Distribution Board - .89 m2						Note: No inspection of live electrical installation	
No Asbestos							
B00C - R0007 - Cleaning Distributed Store - 5.73 m2							
No Asbestos							
B00C - R0008 - External Movement - 5.58 m2							
No Asbestos							
B00C - R0009 - External Stairs - 12.31 m2							
No Asbestos							
B00C - R1001 - External Movement - 40.73 m2							
Ceiling Structures/Linings	Flat AC Sheeting	41m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Compressed AC Sheet	16m2	East & West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R1002 - Home Base - 56.79 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	57m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R1003 - Home Base Store - 3.9 m2							
Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R1004 - Practical Activities - 1hb - 10.14 m2							
No Asbestos							
B00C - R1005 - Practical Activities - 1hb - 10.14 m2							
No Asbestos							
B00C - R1006 - Home Base Store - 3.9 m2							
Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R1007 - Home Base - 56.87 m2							
Floor Coverings Res/Textile	Vinyl Tiles	57m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R1008 - External Stairs - 12.31 m2							
Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00D - General Learning/Library - 1969 - Timber							
Exterior							

Eaves Linings	Flat AC Sheeting	50m2	North, South, Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	Non Accessible Area						
Underfloor Voids	No Asbestos Found						
Interior							
B00D - R0001 - K.L.A. Store - 13.28 m2							
No Asbestos							
B00D - R0002 - Library Office/Workroom - 22.18 m2							
No Asbestos							
B00D - R0003 - Reading Area - 155.43 m2							
No Asbestos							
B00D - R0004 - Movement - 8.84 m2							
No Asbestos							
B00D - R0005 - Seminar/Study - 12.42 m2							
No Asbestos							
B00D - R0006 - Seminar/Study - 12.71 m2							
No Asbestos							
B00D - R0007 - Home Base - 60.62 m2							
No Asbestos							
B00D - R0008 - Distribution Board - .38 m2							
						Note: No inspection of live electrical installation	
No Asbestos							
B00D - R0009 - Practical Activities - 1hb - 32.47 m2							
No Asbestos							
B00D - R0010 - Home Base - 59.45 m2							
No Asbestos							
B00D - R0011 - External Movement - 18.04 m2							
No Asbestos							
B00D - R0012 - External Movement - 15.43 m2							
No Asbestos							
B00D - R0013 - Covered Vehicle Area/Porte Cochere - 21.22 m2							
Require Inspection							
B00E - General Learning - 1969 - Timber							
Exterior							
Eaves Linings	Flat AC Sheeting	160m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	Non Accessible Area						
Underfloor Voids	No Asbestos Found						
Interior							
B00E - R0001 - Home Base - 53.29 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
B00E - R0002 - Staff Toilet - 2.1 m2							
Wall Linings Internal	Compressed AC Sheet	10m2	Throughout, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R0003 - Practical Activities - 1hb - 31.2 m2							

No Asbestos							
B00E - R0004 - Home Base - 52.84 m2							
No Asbestos							
B00E - R0005 - Movement - 37.18 m2							
No Asbestos							
B00E - R0006 - Withdrawal Space - 1hb - 39.45 m2							
No Asbestos							
B00E - R0008 - Staff Room Annexe - 9.57 m2							
Wall Linings Internal	Flat AC Sheeting	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0009 - Staff Toilet - 4.24 m2							
Wall Linings Internal	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0010 - Practical Activities - 1hb - 37.42 m2							
Ceiling Structures/Linings	Flat AC Sheeting	37m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0011 - Home Base - 52.45 m2							
No Asbestos							
B00E - R0012 - Home Base - 53.58 m2							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0013 - Home Base - 53.58 m2							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0014 - Practical Activities - 1hb - 33.76 m2							
Ceiling Structures/Linings	Flat AC Sheeting	34m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0015 - Home Base - 53.51 m2							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0016 - General Storeroom - 8.35 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00E - R0017 - Cleaning Distributed Store - 3.1 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00E - R0018 - Withdrawal Space - 1hb - 14.52 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00E - R0019 - Distribution Board - .75 m2							
Note: No inspection of live electrical installation							
Wall Linings Internal	Compressed AC Sheet	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0022 - Disabled Toilet - 7.44 m2							
No Asbestos							

B00E - R0023 - Movement - 1.14 m2							
No Asbestos							
B00E - R0024 - External Movement - 58.7 m2							
No Asbestos							
B00E - R0025 - Movement - 2.22 m2							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0026 - Stairs - 11.63 m2							
Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R9001 - General Storeroom - 10.55 m2							
No Asbestos							
B00E - R9002 - Plant - 41.48 m2							
No Asbestos							
B00E - R9003 - General Assistant/Bulk Store - 12.44 m2							
No Asbestos							
B00E - R9004 - External Movement - 76.45 m2							
No Asbestos							
B00E - R9005 - Staff Toilet - 2.54 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00E - R9006 - General Storeroom - 24.79 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00E - R9007 - Out Of School Hours Care Centre - 7.76 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00E - R9008 - Movement - 9.67 m2							
No Asbestos							
B00E - R9009 - Movement - 13.64 m2							
Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Linings Internal	Flat AC Sheeting	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R9011 - Toilets - Girls - 12.07 m2							
Wall Linings Internal	Flat AC Sheeting	34m2	North, South, East, Throughout, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R9012 - Toilets - Boys - 13.85 m2							
Wall Linings Internal	Flat AC Sheeting	34m2	North, South, West, Throughout, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R9013 - No Access - 1.32 m2							
No Asbestos							
B00E - R9014 - Kiln Room - 7.07 m2							
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Linings Internal	Flat AC Sheeting	8m2	Throughout, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)

B00E - R9015 - Movement - 54.41 m2							
Wall Linings Internal	Flat AC Sheeting	40m2	Throughout, Lower portion, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R9016 - Drinking Facilities - 5.74 m2							
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	8m2	Throughout, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R9017 - External Stairs - 14.08 m2							
No Asbestos							
B00E - R9018 - Drinking Facilities - 2.26 m2							
No Asbestos							
B00F - Communal Facilities - 1982 - Brick/Block							
Exterior							
Underfloor Voids - Slab on Ground	Non Accessible Area						
Ceiling Voids	Non Accessible Area						
Interior							
B00F - R0001 - External Movement - 167.39 m2							
Ceiling Structures/Linings	Flat AC Sheeting	167m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00F - R0002 - Cleaning Distributed Store - 6.12 m2							
No Asbestos							
B00F - R0003 - Staff Toilet - 3.63 m2							
No Asbestos							
B00F - R0004 - Canteen Office/Store - 5.37 m2							
No Asbestos							
B00F - R0005 - Canteen Office/Store - 2.78 m2							
No Asbestos							
B00F - R0006 - Canteen - 27.47 m2							
No Asbestos							
B00F - R0007 - General Assistant/Bulk Store - 13.75 m2							
No Asbestos							
B00F - R0008 - General Storeroom - 5.42 m2							
No Asbestos							
B00F - R0009 - Toilets - Boys - 8.3 m2							
No Asbestos							
B00F - R0010 - Music Store - 4.2 m2							
No Asbestos							
B00F - R0011 - Communal Space - 164.6 m2							
No Asbestos							
B00F - R0012 - Hall Chair Store - 4.2 m2							
No Asbestos							
B00F - R0013 - Raised Platform - 35.83 m2							
No Asbestos							
B00F - R0014 - Movement - 28.47 m2							
No Asbestos							
B00F - R0015 - Toilets - Girls - 8.28 m2							

No Asbestos							
B00F - R0016 - Sports Store - 12.55 m2							
No Asbestos							
B00F - R0017 - Distribution Board - .39 m2							Note: No inspection of live electrical installation
Electrical - Backing Board	Resinous Board	1	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Door - Lining	Flat AC Sheeting	1	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G - General Learning - 2010 - Brick/Veneer							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00G - R0001 - External Movement - 78.78 m2							
No Asbestos							
B00G - R0002 - Access Shower/Toilet/Change - 7.97 m2							
No Asbestos							
B00G - R0003 - Toilets - Boys - 17.49 m2							
No Asbestos							
B00G - R0004 - Toilets - Girls - 29.63 m2							
No Asbestos							
B00G - R0005 - Cleaning Distributed Store - 4.18 m2							
No Asbestos							
B00G - R0006 - Special Programs Store - 5.41 m2							
No Asbestos							
B00G - R0007 - Special Programs Room - 38.59 m2							
No Asbestos							
B00G - R0008 - Practical Activities - 1hb - 19.14 m2							
No Asbestos							
B00G - R0009 - Home Base Store - 6.37 m2							
No Asbestos							
B00G - R0010 - Home Base - 60.96 m2							
No Asbestos							
B00G - R0011 - Withdrawal Space - 1hb - 11.73 m2							
No Asbestos							
B00G - R0012 - Home Base - 60.9 m2							
No Asbestos							
B00G - R0013 - Home Base Store - 6.34 m2							
No Asbestos							
B00G - R0014 - Practical Activities - 1hb - 19.11 m2							
No Asbestos							

Demountables

There are no Demountable(s) Located at this school as per the AMS records as of 09-Sep-2020