

Asbestos Register


(Hazardous Materials and Risk Assessment)

School:	Liverpool Public School (7424)
Region:	South Western Sydney AMU
State Electorate:	Liverpool
Local Government Area:	Liverpool

Last Reviewed By:	WSP 03-JAN-2017
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	No
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	

7424 - Liverpool Public School
Site Plan (11543)



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>

<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - General Learning/Administration - 1989 - Brick/Block							
Exterior							
Underfloor Voids - Slab on Ground	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
Interior							
B00A - R0001 - Personal Effects Storage - 14.88 m2							
No Asbestos							
B00A - R0002 - Home Base - 61 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0003 - Home Base Store - 4.12 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0004 - Security Store - 4.1 m2							
No Asbestos							
B00A - R0005 - Practical Activities - 1hb - 36.33 m2							
No Asbestos							
B00A - R0006 - Cleaning Distributed Store - 2.2 m2							
No Asbestos							
B00A - R0007 - Home Base Store - 3.6 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0008 - Home Base - 60.99 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0009 - Withdrawal Space - 1hb - 11.55 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0010 - Personal Effects Storage - 14.88 m2							
No Asbestos							
B00A - R0011 - Staff Room - 59.75 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0012 - Staff Room Annexe - 24.67 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0013 - Clerical Office - 12.63 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0014 - Deputy Principal - 12.55 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0015 - Movement - 4.36 m2							
No Asbestos							
B00A - R0016 - Principal - 16.9 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0017 - Cleaning Distributed Store - 3.66 m2							
No Asbestos							
B00A - R0018 - Sick Bay - Shower/Toilet - 4.88 m2							
No Asbestos							
B00A - R0019 - Sick Bay - 9.07 m2							

No Asbestos		
B00A - R0020 - Interview - 12.12 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R0021 - Movement - 7.74 m2		
No Asbestos		
B00A - R0022 - Entry Vestibule - 17.05 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R0023 - Movement - 38.17 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R0024 - Clerical Office - 13.1 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R0025 - Security Store - 12.75 m2		
No Asbestos		
B00A - R0026 - Distribution Board - .76 m2		Note: No inspection of live electrical installation
No Asbestos		
B00A - R0027 - Security Store - 9.67 m2		
No Asbestos		
B00A - R0028 - Staff Toilet - 4.08 m2		
No Asbestos		
B00A - R0029 - Staff Toilet - 3.99 m2		
No Asbestos		
B00A - R0030 - Duplicating Workroom - 31.84 m2		
No Asbestos		
B00A - R0031 - Movement - 272.95 m2		
No Asbestos		
B00A - R0032 - Movement - 54.5 m2		
No Asbestos		
B00A - R0033 - Entry Vestibule - 8.01 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R0034 - Staff Toilet - 2.03 m2		
No Asbestos		
B00A - R0035 - Community Clinic - 21.21 m2		
No Asbestos		
B00A - R0036 - Entry Vestibule - 14.18 m2		
No Asbestos		
B00A - R0037 - Cleaning Distributed Store - 1.92 m2		
No Asbestos		
B00A - R0038 - Cleaning Supplies - 14.72 m2		
No Asbestos		
B00A - R0039 - Plant - 1.26 m2		
No Asbestos		
B00A - R0040 - Distribution Board - 1.49 m2		Note: No inspection of live electrical installation
No Asbestos		
B00A - R0041 - Hall Chair Store - 11.46 m2		
No Asbestos		
B00A - R0042 - Communal Space - 203.43 m2		
No Asbestos		
B00A - R0043 - Sports Store - 16.81 m2		

No Asbestos		
B00A - R0044 - Raised Platform - 40.2 m2		
No Asbestos		
B00A - R0045 - Movement - 2.31 m2		
No Asbestos		
B00A - R0046 - Movement - 1.92 m2		
No Asbestos		
B00A - R0047 - Plant - .62 m2		
No Asbestos		
B00A - R0048 - General Assistant/Bulk Store - 16.21 m2		
No Asbestos		
B00A - R0049 - Cleaning Supplies - 12.81 m2		
No Asbestos		
B00A - R0050 - Disabled Toilet - 4.32 m2		
No Asbestos		
B00A - R0051 - Toilets - Girls - 19.47 m2		
No Asbestos		
B00A - R0054 - Toilets - Boys - 16.71 m2		
No Asbestos		
B00A - R0055 - Canteen - 44.26 m2		
No Asbestos		
B00A - R0056 - Canteen Office/Store - 5.48 m2		
No Asbestos		
B00A - R0057 - Canteen Office/Store - 6.79 m2		
No Asbestos		
B00A - R0058 - Garden Store - 12.9 m2		
No Asbestos		
B00A - R0059 - Main Switch Board - 6.47 m2		
No Asbestos		
B00A - R1001 - Personal Effects Storage - 9 m2		
No Asbestos		
B00A - R1002 - Home Base - 60.66 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R1003 - Home Base Store - 5.14 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R1004 - Distribution Board - .65 m2		
		Note: No inspection of live electrical installation
No Asbestos		
B00A - R1005 - Practical Activities - 1hb - 40.87 m2		
No Asbestos		
B00A - R1006 - Security Store - 4.06 m2		
No Asbestos		
B00A - R1007 - Home Base Store - 3.86 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R1008 - Home Base - 60.85 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R1009 - Withdrawal Space - 1hb - 12.25 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R1010 - Personal Effects Storage - 9 m2		

No Asbestos		
B00A - R1011 - Personal Effects Storage - 9 m2		
No Asbestos		
B00A - R1012 - Home Base - 60.74 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R1013 - Home Base Store - 3.6 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R1014 - Cleaning Distributed Store - 2.21 m2		
No Asbestos		
B00A - R1015 - Practical Activities - 1hb - 40.99 m2		
No Asbestos		
B00A - R1016 - Security Store - 4.1 m2		
No Asbestos		
B00A - R1017 - Home Base Store - 3.91 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R1018 - Home Base - 60.91 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R1019 - Withdrawal Space - 1hb - 12.13 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R1020 - Personal Effects Storage - 11.26 m2		
No Asbestos		
B00A - R1021 - Drinking Facilities - 17.96 m2		
No Asbestos		
B00A - R1022 - Toilets - Girls - 21.22 m2		
No Asbestos		
B00A - R1023 - Distribution Board - 1.97 m2		
		Note: No inspection of live electrical installation
No Asbestos		
B00A - R1024 - Toilets - Boys - 23.49 m2		
No Asbestos		
B00A - R1025 - General Storeroom - 32.76 m2		
No Asbestos		
B00A - R1026 - Personal Effects Storage - 12.15 m2		
No Asbestos		
B00A - R1027 - Home Base - 60.82 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R1028 - Home Base Store - 3.65 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R1029 - Cleaning Distributed Store - 2.2 m2		
No Asbestos		
B00A - R1030 - Practical Activities - 1hb - 40.99 m2		
No Asbestos		
B00A - R1031 - Security Store - 4.1 m2		
No Asbestos		
B00A - R1032 - Home Base Store - 4.1 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R1033 - Home Base - 60.82 m2		

Floor Coverings Res/Textile	No Asbestos Found							
B00A - R1034 - Withdrawal Space - 1hb - 12.25 m2								
Floor Coverings Res/Textile	No Asbestos Found							
B00A - R1035 - Personal Effects Storage - 12.16 m2								
No Asbestos								
B00A - R1036 - Movement - 160.29 m2								
No Asbestos								
B00B - General Learning - 1928 - Brick/Block								
Exterior								
Eaves Linings	Flat AC Sheeting	120m2	North facing, South facing, East facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Ceiling Voids	AC Fragments/Debris	10	East	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)	Chrysotile (white asbestos)	
Underfloor Voids	No Asbestos Found							
Interior								
B00B - R0001 - Staff Room Annexe - 17.98 m2								
No Asbestos								
B00B - R0002 - Home Base - 47.77 m2								
No Asbestos								
B00B - R0003 - Home Base - 47.77 m2								
No Asbestos								
B00B - R0004 - Home Base - 47.25 m2								
No Asbestos								
B00B - R0005 - Home Base - 35.38 m2								
No Asbestos								
B00B - R0006 - Withdrawal Space - 1hb - 32.12 m2								
No Asbestos								
B00B - R0007 - Practical Activities - 1hb - 40.56 m2								
No Asbestos								
B00B - R0008 - Security Store - 12.78 m2								
No Asbestos								
B00B - R0009 - Movement - 13.69 m2								
No Asbestos								
B00B - R0010 - Movement - 4.35 m2								
No Asbestos								
B00B - R0011 - General Storeroom - 5.04 m2								
No Asbestos								
B00B - R0012 - Movement - 3.46 m2								
No Asbestos								
B00B - R0013 - Movement - 50.23 m2								
No Asbestos								
B00B - R0014 - Movement - 60.46 m2								
No Asbestos								
B00B - R1001 - Cleaning Distributed Store - 6.09 m2								
No Asbestos								
B00B - R1002 - General Storeroom - 19.23 m2								
No Asbestos								
B00B - R1003 - Home Base - 49.77 m2								
No Asbestos								

B00B - R1004 - Home Base - 49.71 m2		
No Asbestos		
B00B - R1005 - Home Base - 50.72 m2		
No Asbestos		
B00B - R1006 - Home Base - 67.24 m2		
No Asbestos		
B00B - R1007 - Practical Activities - 1hb - 42.07 m2		
No Asbestos		
B00B - R1008 - Movement - 49.06 m2		
No Asbestos		
B00B - R1009 - Movement - 8.92 m2		
No Asbestos		
B00B - R1010 - Craft Store - 15.63 m2		
No Asbestos		
B00C - General Learning - 1882 - Brick/Block		
Exterior		
Underfloor Voids	Flat AC Sheeting	
Ceiling Voids	Non Accessible Area	
Interior		
B00C - R0001 - Home Base - 65.14 m2		
No Asbestos		
B00C - R0002 - Withdrawal Space - 1hb - 12.95 m2		
No Asbestos		
B00C - R0003 - Home Base Store - 6.3 m2		
No Asbestos		
B00C - R0004 - Home Base Store - 6.21 m2		
No Asbestos		
B00C - R0005 - Home Base - 66.51 m2		
No Asbestos		
B00C - R0006 - Practical Activities - 1hb - 54.3 m2		
No Asbestos		
B00C - R0007 - Distribution Board - .81 m2		Note: No inspection of live electrical installation
Floor Coverings Res/Textile	Flat AC Sheeting	
B00C - R0008 - Movement - 132.2 m2		
No Asbestos		
B00C - R0009 - Toilets - Boys - 13.54 m2		
No Asbestos		
B00C - R0010 - Toilets - Girls - 13.68 m2		
No Asbestos		
B00D - Library/Tiered Learning - 1889 - Brick/Block		
Exterior		
Ceiling Voids	Non Accessible Area	
Underfloor Voids	No Asbestos Found	
Interior		
B00D - R0001 - Library Office/Workroom - 24.14 m2		
No Asbestos		
B00D - R0002 - General Storeroom - 14.23 m2		
No Asbestos		

B00D - R0003 - Reading Area - 131.04 m2							
No Asbestos							
B00D - R0004 - Reading Area - 112.27 m2							
No Asbestos							
B00D - R0005 - P.E. Store - 17.5 m2							
No Asbestos							
B00D - R0006 - Movement - 47.97 m2							
No Asbestos							
B00D - R0007 - Distribution Board - 1.21 m2						Note: No inspection of live electrical installation	
No Asbestos							
B00D - R0008 - Disabled Toilet - 5.58 m2							
No Asbestos							
B00D - R0009 - Cleaning Distributed Store - 3.01 m2							
No Asbestos							
B00D - R0010 - Plant - 8.16 m2							
No Asbestos							
B00D - R0011 - Special Programs Room - 45.71 m2							
No Asbestos							
B00D - R0012 - Special Programs Store - 2.17 m2							
No Asbestos							
B00D - R0013 - Movement - 2.53 m2							
No Asbestos							
B00D - R0014 - Distribution Board - .92 m2						Note: No inspection of live electrical installation	
No Asbestos							
B00E - General Learning/Support Unit - 1871 - Brick/Block							
Exterior							
Ceiling Voids	Non Accessible Area						
Underfloor Voids	No Asbestos Found						
Interior							
B00E - R0001 - Practical Activities - 1hb - 13.16 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
Wall Linings Internal	Flat AC Sheeting						
B00E - R0002 - Home Base - 27.96 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
Wall Linings Internal	Flat AC Sheeting						
B00E - R0003 - Withdrawal Space - 1hb - 26.97 m2							
No Asbestos							
B00E - R0004 - Staff Room Annexe - 13.44 m2							
Ceiling Structures/Linings	Flat AC Sheeting	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0005 - Movement - 18.96 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
Wall Linings Internal	Flat AC Sheeting						
B00E - R0006 - Practical Activities - 1hb - 33.65 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
Wall Linings Internal	Flat AC Sheeting						
B00E - R0007 - Outdoor Learning Area - 30.61 m2							

No Asbestos		
B00E - R0008 - Withdrawal Space - 1hb - 30.14 m2		
No Asbestos		
B00E - R0009 - Home Base - 31.23 m2		
No Asbestos		
B00E - R0010 - Special Programs Room - 30.32 m2		
No Asbestos		
B00E - R0011 - Personal Effects Storage - 8.96 m2		
Floor Coverings Res/Textile	Vinyl Sheet	
Wall Linings Internal	Flat AC Sheeting	
B00E - R0012 - Cleaning Distributed Store - 2.96 m2		
Floor Coverings Res/Textile	Vinyl Sheet	
Wall Linings Internal	Flat AC Sheeting	
B00E - R0013 - Home Base Store - 5.98 m2		
Floor Coverings Res/Textile	Vinyl Sheet	
Wall Linings Internal	Flat AC Sheeting	
B00E - R0014 - General Storeroom - 6.72 m2		
Floor Coverings Res/Textile	Vinyl Sheet	
Wall Linings Internal	Flat AC Sheeting	
B00E - R0015 - Distribution Board - .84 m2		
		Note: No inspection of live electrical installation
Floor Coverings Res/Textile	Flat AC Sheeting	
B00F - General Learning - 1992 - Brick/Veneer		
Exterior		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00F - R0001 - Movement - 29.71 m2		
No Asbestos		
B00F - R0002 - Cleaning Distributed Store - .34 m2		
No Asbestos		
B00F - R0003 - Distribution Board - .34 m2		
		Note: No inspection of live electrical installation
No Asbestos		
B00F - R0004 - Home Base - 61.44 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0005 - Withdrawal Space - 1hb - 12.06 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0006 - Home Base - 61.52 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0007 - Practical Activities - 1hb - 32.8 m2		
No Asbestos		
B00F - R0008 - Home Base Store - 11.56 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00G - Pupil Facilities - 1989 - Brick/Block		

Exterior							
Underfloor Voids - Slab on Ground	No Asbestos Found						
Eaves Linings	Flat AC Sheeting	6m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						
Interior							
B00G- R0001 - Toilets - Girls - 16.72 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	12m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G- R0002 - Toilets - Boys - 16.18 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	6m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G- R0003 - Staff Toilet - 2.11 m2							
No Asbestos							
B00G- R0004 - Movement - 1.73 m2							
No Asbestos							
B00G- R0005 - Staff Toilet - 2.11 m2							
No Asbestos							
B00H - General Learning - 2010 - Brick/Veneer							
Exterior							
Underfloor Voids - Slab on Ground	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
Interior							
B00H - R0001 - Practical Activities - 1hb - 19 m2							
No Asbestos							
B00H - R0002 - Home Base - 59.85 m2							
No Asbestos							
B00H - R0003 - Home Base Store - 6.07 m2							
No Asbestos							
B00H - R0004 - Withdrawal Space - 1hb - 7.66 m2							
No Asbestos							
B00H - R0005 - Practical Activities - 1hb - 18.57 m2							
No Asbestos							
B00H - R0006 - Home Base - 61.25 m2							
No Asbestos							
B00H - R0007 - Home Base Store - 6.28 m2							
No Asbestos							
B00H - R0008 - Withdrawal Space - 2hb - 11.71 m2							
No Asbestos							
B00H - R0009 - Practical Activities - 1hb - 19.12 m2							
No Asbestos							
B00H - R0010 - Home Base - 61.2 m2							
No Asbestos							
B00H - R0011 - Home Base Store - 6.28 m2							
No Asbestos							
B00H - R0012 - Distribution Board - .39 m2							
No Asbestos							Note: No inspection of live electrical installation
B00H - R0013 - External Movement - 93.49 m2							
No Asbestos							

B00H - R0014 - External Stairs - 10.63 m2	
No Asbestos	
B00H - R1001 - Practical Activities - 1hb - 19.47 m2	
No Asbestos	
B00H - R1002 - Home Base - 59.33 m2	
No Asbestos	
B00H - R1003 - Home Base Store - 6.11 m2	
No Asbestos	
B00H - R1004 - Withdrawal Space - 1hb - 7.68 m2	
No Asbestos	
B00H - R1005 - Practical Activities - 1hb - 19.19 m2	
No Asbestos	
B00H - R1006 - Home Base - 61.39 m2	
No Asbestos	
B00H - R1007 - Home Base Store - 6.09 m2	
No Asbestos	
B00H - R1008 - Withdrawal Space - 2hb - 11.82 m2	
No Asbestos	
B00H - R1009 - Practical Activities - 1hb - 19.19 m2	
No Asbestos	
B00H - R1010 - Home Base - 61.18 m2	
No Asbestos	
B00H - R1011 - Home Base Store - 6.11 m2	
No Asbestos	
B00H - R1012 - External Movement - 88.11 m2	
No Asbestos	
B00H - R1013 - External Stairs - 16.35 m2	
No Asbestos	

Demountables

OS 602 10167 - Learning Unit - Standard With P.A.A. - Placement Date : 20-SEP-2017

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 601 11247 - Learning Unit - Standard/Withdrawal - Placement Date : 12-JAN-2001

Exterior

Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

Interior

R1- Entry

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Assumed Asbestos

R2- General Learning Space

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	55m2	Assumed Asbestos

R3- Store

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Assumed Asbestos
----------------------------	------------------	------	------------------

OS 604 11320 - Learning Unit - Single Kindergarten - Placement Date : 30-JUN-1995

Exterior

Eaves Linings	Flat AC Sheeting	14.4m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

Interior

R1- Entry

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Assumed Asbestos

R2- Home Base/Kindergarten

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	73m2	Assumed Asbestos

R3- Practical Activity Area

Ceiling Structures/Linings	Flat AC Sheeting	8m2	Assumed Asbestos
----------------------------	------------------	-----	------------------

R4- Trainer toilet

Toilet Partitions	Compressed AC Sheet	4m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Assumed Asbestos

R5- Cupboard

Ceiling Structures/Linings	Flat AC Sheeting	1m2	Assumed Asbestos
----------------------------	------------------	-----	------------------

OS 601 11643 - Learning Unit - Standard/Withdrawal - Placement Date : 23-JUL-1998

Exterior

Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

Interior

R1- Entry

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Assumed Asbestos

R2- General Learning Space

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	55m2	Assumed Asbestos

R3- Store

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Assumed Asbestos
OS 602 13651 - Learning Unit - Standard With P.A.A. - Placement Date : 01-FEB-2006			
No Asbestos Found			
OS 602 15364 - Learning Unit - Standard With P.A.A. - Placement Date : 18-AUG-2016			
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.			
No Asbestos Found			
OS 603 18182 - Learning Unit - Standard With P.A.A. A/C - Placement Date : 02-JAN-2006			
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.			
No Asbestos Found			