

Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Liverpool Boys High School (8186)
Region:	South Western Sydney AMU
State Electorate:	Liverpool
Local Government Area:	Liverpool

Last Reviewed By:	Greencap 13-DEC-2017
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	Yes
Please refer to the latest site specific Asbestos Management Plans available from the Department's website (Refer to Note 2).	



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - Administration/General Learning/Science Learning - 1955 - Brick/Block							
Exterior							
Ceiling Voids	Non Accessible Area						
External Wall Structure - Awnings	Flat AC Sheeting						
Gable Verge Lining	Flat AC Sheeting	50m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	Non Accessible Area						
Underfloor Voids	Non Accessible Area						
Interior							
B00A - R0001 - Staff Study - 26.54 m2							
No Asbestos							
B00A - R0002 - Cleaning Store - Distributed - 3.56 m2							
No Asbestos							
B00A - R0003 - Staff - Toilet - 5.73 m2							
No Asbestos							
B00A - R0004 - General Storeroom - 8.33 m2							
No Asbestos							
B00A - R0005 - General Learning Space - 49.85 m2							
No Asbestos							
B00A - R0006 - General Learning Space - 49.88 m2							
No Asbestos							
B00A - R0007 - General Learning Space - 49.85 m2							
No Asbestos							
B00A - R0008 - General Learning Space - 49.92 m2							
No Asbestos							
B00A - R0009 - General Learning Space - 49.79 m2							
No Asbestos							
B00A - R0010 - General Learning Space - 49.71 m2							
No Asbestos							
B00A - R0011 - Office/Store - 17.17 m2							
No Asbestos							
B00A - R0012 - Movement - 157.25 m2							
No Asbestos							
B00A - R0013 - Cleaning Store - Distributed - 6.22 m2							
No Asbestos							
B00A - R0017 - Leading Teacher - 13.28 m2							
No Asbestos							
B00A - R0018 - Staff - Toilet - 6.03 m2							
No Asbestos							
B00A - R0022 - Isolation Space - 12.17 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
B00A - R0025 - Movement - 18.31 m2							
No Asbestos							
B00A - R0027 - Movement - 6.57 m2							
No Asbestos							
B00A - R0029 - Printing/Photocopying - 33.54 m2							

No Asbestos							
B00A - R0030 - Movement - 49.25 m2							
No Asbestos							
B00A - R0031 - External Movement - 65.98 m2							
Floor Coverings Res/Textile	Resinous Membrane						
B00A - R0032 - External Movement - 11.15 m2							
No Asbestos							
B00A - R0034 - Stairs - 11.07 m2							
No Asbestos							
B00A - R0035 - Stairs - 2.54 m2							
No Asbestos							
B00A - R0036 - Stairs - 2.24 m2							
No Asbestos							
B00A - R0037 - Distribution Board Cupboard - .64 m2							
							Note: No inspection of live electrical installation
No Asbestos							
B00A - R0039 - Student Waiting - 19.28 m2							
No Asbestos							
B00A - R0040 - Deputy Principal Office - 15.46 m2							
No Asbestos							
B00A - R0041 - Deputy Principal Office - 15.94 m2							
No Asbestos							
B00A - R0042 - General Storeroom - 7.65 m2							
No Asbestos							
B00A - R0043 - Movement - 7.14 m2							
No Asbestos							
B00A - R0044 - General Storeroom - 5.25 m2							
Floor Coverings Res/Textile	Vinyl Tiles	5.25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
B00A - R0045 - Archive Store - 5.36 m2							
No Asbestos							
B00A - R0046 - Staff Kitchen - 9.87 m2							
No Asbestos							
B00A - R0047 - Commonroom - 84.75 m2							
No Asbestos							
B00A - R0048 - Distribution Board Cupboard - .41 m2							
							Note: No inspection of live electrical installation
Electrical - Backing Board	Resinous Board	1	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
B00A - R0049 - External Movement - 1.7 m2							
No Asbestos							
B00A - R0050 - External Movement - 4.03 m2							
No Asbestos							
B00A - R0051 - Movement - 7.91 m2							
Require Inspection							
B00A - R0052 - Interview/Meeting - 9.94 m2							
Require Inspection							
B00A - R0053 - Public Reception - 21.6 m2							
Require Inspection							
B00A - R0054 - Toilets-Disabled - 6.62 m2							
Require Inspection							

B00A - R0055 - Administration - Clerical - 47.34 m2		
Require Inspection		
B00A - R0056 - Student Waiting - 46.65 m2		
Require Inspection		
B00A - R0057 - Principal Office - 19.34 m2		
Require Inspection		
B00A - R1001 - Cleaning Store - Distributed - 3.61 m2		
No Asbestos		
B00A - R1002 - Leading Teacher - 26.56 m2		
No Asbestos		
B00A - R1003 - Staff - Toilet - 5.5 m2		
No Asbestos		
B00A - R1004 - Resources Store - 16.68 m2		
Floor Coverings Res/Textile	Vinyl Tiles	
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	
B00A - R1005 - Staff Study - 52.27 m2		
No Asbestos		
B00A - R1006 - General Learning Space - 52.19 m2		
No Asbestos		
B00A - R1007 - General Learning Space - 52.18 m2		
No Asbestos		
B00A - R1008 - General Learning Space - 52.13 m2		
No Asbestos		
B00A - R1009 - General Learning Space - 52.27 m2		
No Asbestos		
B00A - R1010 - General Learning Space - 52.26 m2		
No Asbestos		
B00A - R1011 - Resources Store - 17.46 m2		
No Asbestos		
B00A - R1012 - Interview/Office - Type 1 - 13.86 m2		
No Asbestos		
B00A - R1013 - Laboratory L.S. - 103.16 m2		
No Asbestos		
B00A - R1014 - Preparation - Science - 33.16 m2		
No Asbestos		
B00A - R1015 - Laboratory L.S. - 101.87 m2		
No Asbestos		
B00A - R1018 - General Storeroom - 23.14 m2		
No Asbestos		
B00A - R1019 - Computer Learning Space - 66.77 m2		
No Asbestos		
B00A - R1020 - Stairs - 12.72 m2		
No Asbestos		
B00A - R1021 - Stairs - 11.32 m2		
No Asbestos		
B00A - R1022 - Stairs - 11.05 m2		
No Asbestos		
B00A - R1023 - Handwashing Facilities - .79 m2		
No Asbestos		
B00A - R1024 - Movement - 163.97 m2		

No Asbestos							
B00A - R1025 - Movement - 26.42 m2							
No Asbestos							
B00A - R1026 - Movement - 79.78 m2							
No Asbestos							
B00A - R1027 - Staff Study - 32.09 m2							
No Asbestos							
B00A - R1028 - Tea Room - 2.25 m2							
No Asbestos							
B00A - R1029 - Movement - 16.68 m2							
No Asbestos							
B00A - R1030 - Handwashing Facilities - 1.13 m2							
No Asbestos							
B00A - R9001 - General Storeroom - 3.23 m2							
No Asbestos							
B00A - R9003 - Art Learning Space - 106.42 m2							
Floor Coverings Res/Textile	Vinyl Tiles	108m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R9004 - Art Learning Space - 107.36 m2							
Floor Coverings Res/Textile	Vinyl Tiles	108m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R9005 - Resources Store - 10.34 m2							
No Asbestos							
B00A - R9006 - Resources Store - 11.07 m2							
Floor Coverings Res/Textile	Vinyl Tiles	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R9007 - External Movement - 52.22 m2							
No Asbestos							
B00A - R9008 - Kiln Space - 25.69 m2							
Floor Coverings Res/Textile	Vinyl Tiles	27m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R9009 - Stairs - 7.1 m2							
No Asbestos							
B00A - R9010 - Interview/Office - Type 1 - 21.46 m2							
No Asbestos							
B00A - R9011 - Tea Room - 3.69 m2							
No Asbestos							
B00A - R9012 - External Movement - 2.62 m2							
Ceiling Structures/Linings	Compressed AC Sheet						
B00A - R9013 - External Movement - 2.62 m2							
Ceiling Structures/Linings	Compressed AC Sheet						
B00B - General Learning/Science Learning - 1955 - Brick/Block							
Exterior							
Underfloor Voids - Slab on Ground	Non Accessible Area						
Ceiling Voids	Non Accessible Area						
Interior							
B00B - R0001 - Cleaning Store - Distributed - 5.63 m2							
No Asbestos							

B00B - R0002 - Distribution Board Cupboard - .68 m2							Note: No inspection of live electrical installation
No Asbestos							
B00B - R0003 - Laboratory L.S. - 92.87 m2							
Floor Coverings Res/Textile	Vinyl Tiles	94m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (70 - 120 m2) - (X8)						
B00B - R0004 - Preparation - Science - 28.63 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Floor Coverings Res/Textile	Vinyl Tiles	29m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0005 - Chemical Store - 10.17 m2							
Floor Coverings Res/Textile	Vinyl Tiles	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00B - R0006 - Apparatus Store - 26 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Floor Coverings Res/Textile	Vinyl Tiles	23m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0007 - Staff Shower - 7.21 m2							
No Asbestos							
B00B - R0008 - General Storeroom - .98 m2							
No Asbestos							
B00B - R0009 - Movement - 7.96 m2							
No Asbestos							
B00B - R0010 - Change - 31.8 m2							
No Asbestos							
B00B - R0011 - Toilets-Boys - 37.82 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	30m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0012 - Change - 31.72 m2							
No Asbestos							
B00B - R0013 - Staff - Toilet - 5.69 m2							
No Asbestos							
B00B - R0014 - Distribution Board Cupboard - .62 m2							Note: No inspection of live electrical installation
No Asbestos							
B00B - R0015 - Resources Store - 11.95 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00B - R0017 - Laboratory L.S. - 92.85 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (70 - 120 m2) - (X8)						
Floor Coverings Res/Textile	Vinyl Tiles	93m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Plant / Equipment - Fume Cupboard	Flat AC Sheeting	1	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0020 - Laboratory L.S. - 92.98 m2							

Ceiling Structures/Linings	Vermiculite - Composite Sample - (70 - 120 m2) - (X8)						
Floor Coverings Res/Textile	Vinyl Tiles	94m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0021 - Distribution Board Cupboard - .68 m2							Note: No inspection of live electrical installation
No Asbestos							
B00B - R0022 - Cleaning Store - Distributed - 5.6 m2							
No Asbestos							
B00B - R0025 - General Storeroom - 7.51 m2							
No Asbestos							
B00B - R0026 - External Movement - 18.2 m2							
No Asbestos							
B00B - R0027 - Movement - 11.89 m2							
No Asbestos							
B00B - R0028 - Movement - 11.65 m2							
No Asbestos							
B00B - R0029 - Movement - 11.57 m2							
No Asbestos							
B00B - R0030 - Stairs - 9.71 m2							
No Asbestos							
B00B - R0031 - Stairs - 10.01 m2							
No Asbestos							
B00B - R0032 - Stairs - 9.94 m2							
No Asbestos							
B00B - R0033 - Preparation - Science - 39.36 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
Floor Coverings Res/Textile	Vinyl Tiles	39.35m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0034 - Staff Study - 12.96 m2							
Floor Coverings Res/Textile	Vinyl Tiles	12.96m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00B - R0035 - Tea Room - 13.55 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Floor Coverings Res/Textile	Vinyl Tiles	13.54m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0036 - Movement - 22.45 m2							
Wall Linings Internal - Infill	Flat AC Sheeting						
B00B - R0037 - External Movement - 189.22 m2							
No Asbestos							
B00B - R1001 - Distribution Board Cupboard - .67 m2							Note: No inspection of live electrical installation
No Asbestos							
B00B - R1002 - General Learning Space - 52.65 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
B00B - R1003 - General Learning Space - 52.72 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						

B00B - R1004 - Resources Store - 6.19 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00B - R1005 - Resources Store - 6.25 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00B - R1006 - General Learning Space - 52.72 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
B00B - R1007 - General Learning Space - 52.21 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
B00B - R1008 - General Learning Space - 52.25 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
B00B - R1009 - General Storeroom - 6.28 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00B - R1010 - Cleaning Store - Distributed - 6.23 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00B - R1012 - Resources Store - 20.14 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00B - R1013 - Distribution Board Cupboard - .69 m2							
							Note: No inspection of live electrical installation
No Asbestos							
B00B - R1014 - Resources Store - 12.3 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Floor Coverings Res/Textile	Vinyl Sheet						
B00B - R1015 - Computer Learning Space - 52.8 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
B00B - R1016 - Staff Study - 26.18 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Floor Coverings Res/Textile	Vinyl Tiles	26.17m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R1018 - Staff Study - 26.07 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Floor Coverings Res/Textile	Vinyl Tiles	26.06m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R1019 - Careers Advisers Office - 12.14 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00B - R1020 - Interview/Office - Type 1 - 12.78 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00B - R1021 - Staff - Toilet - 5.12 m2							
No Asbestos							
B00B - R1022 - Clinic - Boys - 5.88 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00B - R1023 - Administration - Clerical - 16.82 m2							

Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)							
B00B - R1024 - Leading Teacher - 8.56 m2								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)							
B00B - R1025 - Distribution Board Cupboard - .72 m2						Note: No inspection of live electrical installation		
No Asbestos								
B00B - R1027 - Stairs - 17.71 m2								
No Asbestos								
B00B - R1028 - Stairs - 17.74 m2								
No Asbestos								
B00B - R1029 - Stairs - 17.91 m2								
No Asbestos								
B00B - R1030 - Staff Study - 62.54 m2								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)							
Floor Coverings Res/Textile	Vinyl Tiles	52.51m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00B - R1031 - Tea Room - 2.96 m2								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)							
Floor Coverings Res/Textile	Vinyl Tiles	2.96m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00B - R1032 - Handwashing Facilities - .49 m2								
No Asbestos								
B00B - R1033 - Student Waiting - 14.17 m2								
Plant / Equipment - Thermocon Heater	Insulation Material	1	Northeast	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos	
B00B - R1034 - External Movement - 252.78 m2								
No Asbestos								
B00C - Technological & Applied Studies/Pupil Facilities - 1955 - Brick/Block								
Exterior								
Ceiling Voids	No Asbestos Found							
Underfloor Voids - Slab on Ground	Non Accessible Area							
External Roof Structure	Non Accessible Area							
Interior								
B00C - R0002 - Archive Store - 24.37 m2								
No Asbestos								
B00C - R0005 - Main Switchroom - 24.17 m2								
No Asbestos								
B00C - R0006 - General Storeroom - 70.58 m2								
No Asbestos								
B00C - R0007 - General Storeroom - 59.83 m2								
No Asbestos								
B00C - R0008 - General Storeroom - 6.65 m2								
No Asbestos								
B00C - R0009 - General Storeroom - 6.23 m2								
No Asbestos								
B00C - R0010 - General Storeroom - 13.67 m2								
No Asbestos								
B00C - R0012 - Garden Store Room - 25.16 m2								

No Asbestos							
B00C - R0014 - Staff Study - 38.61 m2							
No Asbestos							
B00C - R0019 - Sport Equipment Store - 13.98 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00C - R0021 - General Storeroom - 6.44 m2							
No Asbestos							
B00C - R0022 - Staff - Toilet - 3.52 m2							
No Asbestos							
B00C - R0023 - Cleaning Store - Distributed - 1.54 m2							
No Asbestos							
B00C - R0024 - Pantry - 12.35 m2							
No Asbestos							
B00C - R0025 - General Assistants - 64.97 m2							
No Asbestos							
B00C - R0026 - General Storeroom - 11.79 m2							
No Asbestos							
B00C - R0027 - Staff Study - 19.27 m2							
No Asbestos							
B00C - R0028 - Movement - 4.34 m2							
No Asbestos							
B00C - R0030 - Staff Study - 35.16 m2							
No Asbestos							
B00C - R0031 - Sport Equipment Store - 20.87 m2							
Floor Coverings Res/Textile	Vinyl Tiles	22m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0032 - Sport Equipment Store - 5.44 m2							
No Asbestos							
B00C - R0033 - Staff - Toilet - 1.61 m2							
No Asbestos							
B00C - R0034 - Fitness Laboratory - 83.87 m2							
No Asbestos							
B00C - R0035 - Dark Room - 7.82 m2							
No Asbestos							
B00C - R0037 - External Movement - 259.82 m2							
No Asbestos							
B00C - R0038 - Movement - 199.01 m2							
No Asbestos							
B00C - R0039 - General Storeroom - 3.58 m2							
No Asbestos							
B00C - R0040 - Food Technology L.S. - 105.54 m2							
No Asbestos							
B00C - R0041 - Pantry - 6.84 m2							
No Asbestos							
B00C - R0044 - Art Learning Space - 48.83 m2							
No Asbestos							
B00C - R0045 - Darkroom Space - .82 m2							
No Asbestos							
B00C - R0046 - Dark Room - 8.84 m2							
No Asbestos							
B00C - R0047 - Resources Store - 7.82 m2							

No Asbestos							
B00C - R0048 - General Storeroom - 12.81 m2							
No Asbestos							
B00C - R0049 - Computer Store - 13.38 m2							
No Asbestos							
B00C - R0050 - Student Canteen - 96.71 m2							
No Asbestos							
B00C - R0051 - General Storeroom - 26.09 m2							
No Asbestos							
B00C - R0052 - Bulk Store - 11.53 m2							
No Asbestos							
B00C - R0053 - External Movement - 28.74 m2							
No Asbestos							
B00C - R0054 - External Movement - 35.5 m2							
No Asbestos							
B00C - R1001 - Staff - Toilet - 7.04 m2							
No Asbestos							
B00C - R1003 - Cleaning Store - Distributed - 3.61 m2							
No Asbestos							
B00C - R1004 - Computer Room - 10.38 m2							
No Asbestos							
B00C - R1005 - Resources Store - 16.97 m2							
Wall Linings Internal	Flat AC Sheeting	7m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
B00C - R1006 - Design L.S. - 82 m2							
Wall Linings Internal	Flat AC Sheeting	15m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
B00C - R1007 - Resources Store - 16.8 m2							
Wall Linings Internal	Flat AC Sheeting	15m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
B00C - R1008 - Class Tools Storage - 10.36 m2							
Wall Linings Internal	Flat AC Sheeting	15m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
B00C - R1009 - Wood Technology L.S. - 110.66 m2							
No Asbestos							
B00C - R1010 - Resources Store - 16.83 m2							
Wall Linings Internal	Flat AC Sheeting	8m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
B00C - R1011 - Resources Store - 10.36 m2							
Wall Linings Internal	Flat AC Sheeting	7m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
B00C - R1012 - Design L.S. - 53.58 m2							
Wall Linings Internal	Flat AC Sheeting	53.56m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
B00C - R1013 - Computer Learning Space - 57.18 m2							
No Asbestos							
B00C - R1014 - Project Store - Type 1 - 27.62 m2							
No Asbestos							
B00C - R1016 - Materials Store - 15.81 m2							

No Asbestos							
B00C - R1017 - Resources Store - 10.23 m2							
No Asbestos							
B00C - R1022 - Bulk Store - 21.65 m2							
Wall Linings Internal	Flat AC Sheeting	15m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
B00C - R1023 - Tiered Learning Area - 60.64 m2							
No Asbestos							
B00C - R1024 - Resources Store - 10.39 m2							
Wall Linings Internal	Flat AC Sheeting	7m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
B00C - R1026 - Handwashing Facilities - .96 m2							
No Asbestos							
B00C - R1027 - Handwashing Facilities - .95 m2							
No Asbestos							
B00C - R1029 - Wood Technology L.S. - 104.8 m2							
Wall Linings Internal	Flat AC Sheeting	15m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
B00C - R1030 - Dust Extraction Space - 3.81 m2							
No Asbestos							
B00C - R1031 - Staff Study - 11.59 m2							
No Asbestos							
B00C - R1032 - Staff Study - 29.06 m2							
No Asbestos							
B00C - R1033 - Tea Room - 3.63 m2							
No Asbestos							
B00C - R1034 - Movement - 71.12 m2							
No Asbestos							
B00C - R1035 - Metal Technology L.S. - 119.94 m2							
No Asbestos							
B00C - R1036 - Welding Area - 19.16 m2							
No Asbestos							
B00C - R1037 - External Movement - 31.98 m2							
No Asbestos							
B00C - R1038 - Movement - 82.89 m2							
No Asbestos							
B00C - R1039 - External Movement - 31.34 m2							
No Asbestos							
B00C - R1040 - Wood Technology L.S. - 110 m2							
No Asbestos							
B00C - R1041 - Materials Store - 21.21 m2							
No Asbestos							
B00C - R1042 - Dust Extraction Space - 4.93 m2							
No Asbestos							
B00D - Pupil Facilities - 1955 - Brick/Block							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids - Slab on Ground	Non Accessible Area						
Interior							
B00D - R0003 - External Movement - 6.02 m2							

No Asbestos							
B00D - R0004 - Movement - 4.05 m2							
No Asbestos							
B00D - R0005 - External Movement - 14.11 m2							
No Asbestos							
B00D - R0006 - Toilets-Boys - 5.3 m2							
No Asbestos							
B00D - R0007 - Toilets-Disabled - 9.85 m2							
No Asbestos							
B00D - R0008 - Toilets-Boys - 85.32 m2							
No Asbestos							
B00D - R0009 - General Storeroom - 9.77 m2							
No Asbestos							
B00D - R0010 - Plant - 1.33 m2							
No Asbestos							
B00D - R0011 - External Movement - 60.13 m2							
No Asbestos							
B00D - R1001 - Movement - 135.03 m2							
No Asbestos							
B00D - R1002 - Movement - 65.14 m2							
No Asbestos							
B00E - Music - 1993 - Brick/Veneer							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00E - R0001 - External Movement - 35.38 m2							
No Asbestos							
B00E - R0003 - Practice/Seminar - 11.83 m2							
No Asbestos							
B00E - R0004 - Practice/Seminar - 11.96 m2							
No Asbestos							
B00E - R0005 - Music Learning Space - 59.35 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00E - R0006 - Music Store - 16.88 m2							
No Asbestos							
B00E - R0007 - Practice/Seminar - 26.25 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00E - R0008 - Music Learning Space - 77.08 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00F - General Learning - 1955 - Brick/Veneer							
Exterior							
Eaves Linings	Flat AC Sheeting	50m2	North & South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	20m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Underfloor Voids	No Asbestos Found						
Ceiling Voids	Non Accessible Area						

Interior							
B00F - R0001 - Resources Store - 5.59 m2							
Ceiling Structures/Linings	Flat AC Sheeting	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00F - R0002 - External Movement - 64.3 m2							
Ceiling Structures/Linings	Flat AC Sheeting	62m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00F - R0006 - General Learning Space - 52.79 m2							
Ceiling Structures/Linings	Flat AC Sheeting	54m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00F - R0007 - General Learning Space - 159.52 m2							
WIndow	Mastic						
B00G - General Learning - 1955 - Brick/Veneer							
Exterior							
Eaves Linings	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Gable Verge Lining	No Asbestos Found						
Interior							
B00G - R0001 - General Learning Space - 63.54 m2							
No Asbestos							
B00G - R0002 - Resources Store - 5.85 m2							
No Asbestos							
B00G - R0003 - General Learning Space - 52.07 m2							
No Asbestos							
B00G - R0006 - Resources Store - 5.62 m2							
No Asbestos							
B00G - R0007 - External Movement - 44.47 m2							
Ceiling Structures/Linings	Flat AC Sheeting	44m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G - R0008 - General Learning Space - 52.21 m2							
No Asbestos							
B00G - R0009 - General Learning Space - 52.72 m2							
No Asbestos							
B00I - Library/Multi Purpose Facilities - 1955 - Brick/Block							
Exterior							
Gable Verge Lining	Flat AC Sheeting	40m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Underfloor Voids	No Asbestos Found						
Ceiling Voids - Raked Ceiling	Non Accessible Area						
Interior							
B00I - M1001 - General Storeroom - 6.15 m2							
No Asbestos							
B00I - R0001 - Movement - 131.21 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (120 - 250 m2) - (X15)						
B00I - R0002 - Chair Store - 27.75 m2							
Material - Stored / Debris Material	Flat AC Sheeting						
B00I - R0003 - Distribution Board Cupboard - .5 m2							
							Note: No inspection of live electrical installation

No Asbestos	
B001 - R0004 - Toilets-Boys - 5.58 m2	
No Asbestos	
B001 - R0005 - Toilets-Girls - 7.13 m2	
No Asbestos	
B001 - R0009 - Cleaning Store - Distributed - 8.59 m2	
No Asbestos	
B001 - R0012 - Librarian - 13.88 m2	
No Asbestos	
B001 - R0013 - Library Administration - 17.82 m2	
No Asbestos	
B001 - R0014 - Plant - 31.86 m2	
No Asbestos	
B001 - R0015 - Movement - 2 m2	
No Asbestos	
B001 - R0016 - External Movement - 8.71 m2	
No Asbestos	
B001 - R0017 - Study Space - 12.1 m2	
No Asbestos	
B001 - R0018 - Study Space - 13.1 m2	
No Asbestos	
B001 - R0019 - Stairs - 2.36 m2	
No Asbestos	
B001 - R0022 - Study Space - 10.61 m2	
No Asbestos	
B001 - R0023 - Main Area - 465.06 m2	
No Asbestos	
B001 - R0024 - External Movement - 17.8 m2	
No Asbestos	
B001 - R0025 - External Movement - 4.33 m2	
No Asbestos	
B001 - R0026 - Movement - 2.33 m2	
No Asbestos	
B001 - R0027 - Stairs - 6.24 m2	
No Asbestos	
B001 - R0029 - Library Administration - 50.6 m2	
No Asbestos	
B001 - R0030 - Audio Visual Workroom - 37.83 m2	
No Asbestos	
B001 - R0031 - General Storeroom - 19.69 m2	
No Asbestos	
B001 - R0032 - Senior Study - 26.12 m2	
No Asbestos	
B001 - R1001 - Staff Kitchen - 6.57 m2	
No Asbestos	
B001 - R1002 - Movement - 39.65 m2	
No Asbestos	
B001 - R1003 - Multi-Purpose Space - 293.29 m2	
No Asbestos	
B001 - R1004 - Stage - 78.36 m2	
No Asbestos	
B001 - R1005 - Movement - 19.61 m2	

No Asbestos	
B00I - R1006 - Toilets-Girls - 21.53 m2	
No Asbestos	
B00I - R1007 - Toilets-Boys - 19.47 m2	
No Asbestos	
B00I - R1008 - Movement - 3.24 m2	
No Asbestos	
B00I - R1009 - External Movement - 113.57 m2	
No Asbestos	
B00I - R1010 - External Movement - 9.48 m2	
No Asbestos	
B00I - R1011 - Stairs - 3.89 m2	
No Asbestos	
B00I - R1012 - Movement - 1.59 m2	
No Asbestos	
B00I - R1013 - Stairs - 14.67 m2	
No Asbestos	
B00I - R1014 - Stairs - 2.6 m2	
No Asbestos	
B00I - R2001 - Control Room - 43.46 m2	
No Asbestos	
B00I - R2002 - Movement - 1.47 m2	
No Asbestos	
B00I - R2003 - Stairs - 3.84 m2	
No Asbestos	
B00J - Building Services - 1955 - Brick/Block	
Exterior	
Require Inspection	
Interior	
B00J - R0001 - General Storeroom - 5.6 m2	
Require Inspection	
B00J - R0002 - Cleaning Store - Distributed - 3.95 m2	
Require Inspection	
B00K - Language Centre - 2010 - Brick/Veneer	
Exterior	
Underfloor Voids - Slab on Ground	Non Accessible Area
Ceiling Voids - Raked Ceiling	Non Accessible Area
Interior	
B00K - R0001 - Computer Learning Space - 91.81 m2	
No Asbestos	
B00K - R0002 - Seminar - Type 2 - 18.78 m2	
No Asbestos	
B00K - R0003 - Resources Store - 10.05 m2	
No Asbestos	
B00K - R0004 - Computer Store - 9.4 m2	
No Asbestos	
B00K - R0005 - External Movement - 27.12 m2	
No Asbestos	

B00L - Performance Learning - 2008 - Brick/Veneer**Exterior**

Underfloor Voids	No Asbestos Found	
Ceiling Voids - Raked Ceiling	No Asbestos Found	

Interior**B00L - R0001 - Performance Workspace - 122.47 m2**

No Asbestos

B00L - R0002 - Resources Store - 4.87 m2

No Asbestos

B00L - R0003 - External Movement - 21.8 m2

Wall Linings Internal - Infill / Balustrade	Compressed AC Sheet	
Ceiling Structures/Linings	Flat AC Sheeting	

B00M - Technological & Applied Studies/Mechanical Service - 2014 - Steel**Exterior**

Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	

Interior**B00M - R0001 - Workshop - 264.81 m2**

No Asbestos

B00M - R0002 - External Movement - 72.26 m2

No Asbestos

B00Z - Building Services - 1955 - Brick/Block**Exterior**

Ceiling Voids	Non Accessible Area	
Underfloor Voids	Non Accessible Area	

Interior**B00Z - R0001 - Plant - 2.84 m2**

No Asbestos

Demountables

There are no Demountable(s) Located at this school as per the AMS records as of 09-Sep-2020