

Asbestos Register


(Hazardous Materials and Risk Assessment)

School:	Lucas Heights Community School (8271)
Region:	Sydney AMU
State Electorate:	Holsworthy
Local Government Area:	Sutherland

Last Reviewed By:	Greencap 11-DEC-2017
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	Yes
Please refer to the latest site specific Asbestos Management Plans available from the Department's website (Refer to Note 2).	

8271 - Lucas Heights Community School
Site Plan (13494)



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>

<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - General Learning/Pupil Facilities - 1991 - Brick/Veneer							
Exterior							
Underfloor Voids - Slab on Ground	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
Interior							
B00A - R0001 - Cleaning Store - Distributed - 2.02 m2							
No Asbestos							
B00A - R0002 - Home Base Store - 5.93 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0003 - Practical Activities - 1hb - 20.22 m2							
No Asbestos							
B00A - R0004 - Home Base - 57.51 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0005 - Withdrawal Space - 1hb - 11.72 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0006 - Home Base - 57.37 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0007 - Practical Activities - 1hb - 20.21 m2							
No Asbestos							
B00A - R0008 - Distribution Board - .96 m2							
						Note: No inspection of live electrical installation	
No Asbestos							
B00A - R0009 - Home Base Store - 6.48 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0010 - Home Base Store - 6.56 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0011 - Home Base - 57.56 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0012 - Practical Activities - 1hb - 20.22 m2							
No Asbestos							
B00A - R0013 - Withdrawal Space - 1hb - 11.72 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0014 - Home Base - 57.57 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0015 - Practical Activities - 1hb - 20.21 m2							
No Asbestos							
B00A - R0016 - Home Base Store - 7.51 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0017 - Toilets - Girls - 23.64 m2							
No Asbestos							
B00A - R0018 - Toilets - Boys - 17.6 m2							
No Asbestos							
B00A - R0021 - External Movement - 101.01 m2							
No Asbestos							
B00B - General Learning/Pupil Facilities - 1991 - Brick/Veneer							
Exterior							
Underfloor Voids - Slab on Ground	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
Interior							
B00B - R0001 - Home Base Store - 5.91 m2							
Floor Coverings Res/Textile	No Asbestos Found						

B00B - R0002 - Practical Activities - 1hb - 23.94 m2		
No Asbestos		
B00B - R0003 - Home Base - 55.49 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0004 - Withdrawal Space - 1hb - 5.05 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0005 - Home Base Store - 6.76 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0006 - Cleaning Store - Distributed - 3.06 m2		
No Asbestos		
B00B - R0007 - Practical Activities - 1hb - 20.24 m2		
No Asbestos		
B00B - R0008 - Home Base - 57.5 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0009 - Withdrawal Space - 1hb - 11.66 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0010 - Practical Activities - 1hb - 20.27 m2		
No Asbestos		
B00B - R0011 - Home Base - 57.5 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0012 - Home Base Store - 6.51 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0013 - Distribution Board - 1.52 m2		
		Note: No inspection of live electrical installation
No Asbestos		
B00B - R0016 - External Movement - 191.95 m2		
No Asbestos		
B00C - Administration/General Learning - 1991 - Brick/Block		
Exterior		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00C - R0001 - Deputy Principal Office - 17.19 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0002 - Interview/Office - Type 1 - 12.6 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0003 - Deputy Principal Office - 16.2 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0004 - Entry - 61.86 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0005 - External Movement - 7.14 m2		
No Asbestos		
B00C - R0006 - Administration - Clerical - 61.5 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0007 - Interview/Office - Type 1 - 12.37 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0008 - Principal Office - 18.89 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0009 - Deputy Principal Office - 15.75 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0010 - Interview/Office - Type 1 - 12.6 m2		
Floor Coverings Res/Textile	No Asbestos Found	

B00C - R0011 - Ancillary Staff - 21.6 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0012 - Staff - Toilet - 5.4 m2		
No Asbestos		
B00C - R0013 - Security Store - 18.22 m2		
No Asbestos		
B00C - R0014 - Clinic - Girls - 13.95 m2		
No Asbestos		
B00C - R0015 - Clinic-Toilets - 2.39 m2		
No Asbestos		
B00C - R0016 - Clinic-Toilets - 2.39 m2		
No Asbestos		
B00C - R0017 - Clinic - Boys - 14.31 m2		
No Asbestos		
B00C - R0018 - Teachers Aides - 12.24 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0019 - General Storeroom - 1.2 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0020 - Distribution Board - 1.23 m2		
		Note: No inspection of live electrical installation
No Asbestos		
B00C - R0021 - External Movement - 3.39 m2		
No Asbestos		
B00C - R0022 - Duplicating Workroom - 58.5 m2		
No Asbestos		
B00C - R0023 - External Movement - 3.42 m2		
No Asbestos		
B00C - R0024 - Staff - Toilet - 7.42 m2		
No Asbestos		
B00C - R0025 - General Storeroom - 7.9 m2		
No Asbestos		
B00C - R0026 - Security Store - 19.13 m2		
No Asbestos		
B00C - R0027 - Staff - Toilet - 4.09 m2		
No Asbestos		
B00C - R0028 - Distribution Board - 1.08 m2		
		Note: No inspection of live electrical installation
No Asbestos		
B00C - R0029 - Movement - 109.19 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0031 - External Movement - 7.45 m2		
No Asbestos		
B00C - R0032 - Cleaning Store - Distributed - 2.02 m2		
No Asbestos		
B00C - R0033 - Home Base Store - 5.91 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0034 - Practical Activities - 1hb - 20.28 m2		
No Asbestos		
B00C - R0035 - Home Base - 57.44 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0036 - Withdrawal Space - 1hb - 11.61 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0038 - Practical Activities - 1hb - 20.28 m2		
No Asbestos		

B00C - R0039 - Home Base - 57.51 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0040 - Home Base Store - 6.42 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0041 - Distribution Board - 1.52 m2		Note: No inspection of live electrical installation
No Asbestos		
B00C - R0042 - Toilets - Boys - 19.53 m2		
No Asbestos		
B00C - R0043 - Toilets - Girls - 25.7 m2		
No Asbestos		
B00C - R0044 - External Movement - 236.81 m2		
No Asbestos		
B00C - R0045 - Student Canteen - 53.35 m2		
No Asbestos		
B00C - R0046 - Disabled Toilet - 5.8 m2		
No Asbestos		
B00C - R0047 - Canteen Office/Store - 10.08 m2		
No Asbestos		
B00C - R0048 - Distribution Board - .65 m2		Note: No inspection of live electrical installation
No Asbestos		
B00C - R0049 - External Movement - 31.72 m2		
No Asbestos		
B00C - R0051 - External Movement - 113.81 m2		
No Asbestos		
B00C - R0052 - External Movement - 4.25 m2		
No Asbestos		
B00D - Library/Staff Facilities - 1991 - Brick/Block		
Exterior		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00D - R0001 - Reading Area - 276.22 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0002 - Library Office/Workroom - 4.8 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0003 - External Movement - 53.51 m2		
No Asbestos		
B00D - R0004 - Cleaning Store - Distributed - 3 m2		
No Asbestos		
B00D - R0005 - Commonroom - 160.85 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0006 - Staff - Toilet - 4.92 m2		
No Asbestos		
B00D - R0007 - Staff - Toilet - 6.22 m2		
No Asbestos		
B00D - R0008 - Distribution Board - 1.06 m2		Note: No inspection of live electrical installation
No Asbestos		
B00D - R0009 - Communications Room - 50 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0010 - Librarian - 15.28 m2		
Floor Coverings Res/Textile	No Asbestos Found	

B00D - R0011 - Library Office/Workroom - 67.17 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0012 - Library Office/Workroom - 7.17 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0013 - Reading Area - 317.47 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0014 - Movement - 50.72 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0015 - Movement - 27.49 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0016 - External Movement - 99.54 m2		
No Asbestos		
B00D - R0017 - Seminar - 13.21 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0018 - Seminar - 12.47 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0019 - Seminar - 12.69 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0020 - External Movement - 58.72 m2		
No Asbestos		
B00E - General Learning - 1991 - Brick/Block		
Exterior		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00E - R0001 - Kiln Space - 7.02 m2		
No Asbestos		
B00E - R0002 - Sport Equipment Store - 16.07 m2		
No Asbestos		
B00E - R0003 - External Movement - 3.91 m2		
No Asbestos		
B00E - R0004 - Cleaning Supplies Store - 3.4 m2		
No Asbestos		
B00E - R0005 - Home Base Store - 5.58 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0006 - Withdrawal Space - 1hb - 3.84 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0007 - Home Base - 60.29 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0008 - Practical Activities - 1hb - 20.29 m2		
No Asbestos		
B00E - R0009 - Distribution Board - 1.35 m2		
No Asbestos		Note: No inspection of live electrical installation
B00E - R0010 - Disabled Toilet - 4.8 m2		
No Asbestos		
B00E - R0011 - General Storeroom - 11.2 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0012 - External Movement - 17.02 m2		
No Asbestos		
B00E - R0013 - Staff Room Annexe - 12.29 m2		
Floor Coverings Res/Textile	No Asbestos Found	

B00E - R0014 - Staff Room Annexe - 12.32 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0015 - General Learning Space - 46.02 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0017 - General Learning Space - 46.33 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0018 - External Movement - 83.11 m2		
No Asbestos		
B00E - R0019 - Practical Activities - 22.89 m2		
No Asbestos		
B00E - R0020 - Disabled Shower/Toilet - 11.47 m2		
No Asbestos		
B00E - R0021 - Home Base Store - 10.55 m2		
No Asbestos		
B00F - General Learning/Staff Facilities - 1991 - Brick/Block		
Exterior		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00F - R0001 - Cleaning Supplies Store - 40.52 m2		
No Asbestos		
B00F - R0002 - General Assistant/Bulk Store - 25.48 m2		
No Asbestos		
B00F - R0003 - Cleaning Supplies Store - 13.07 m2		
No Asbestos		
B00F - R0004 - Canteen Office/Store - 18.18 m2		
No Asbestos		
B00F - R0005 - Student Canteen - 52.42 m2		
No Asbestos		
B00F - R0006 - Disabled Toilet - 4.8 m2		
No Asbestos		
B00F - R0007 - Cleaning Store - Distributed - 3.38 m2		
No Asbestos		
B00F - R0008 - Distribution Board - 2.57 m2		
No Asbestos		Note: No inspection of live electrical installation
B00F - R0009 - Serviced Learning Space - 51.87 m2		
No Asbestos		
B00F - R0010 - Wheelchair Store - 17.8 m2		
No Asbestos		
B00F - R0011 - Cleaning Store - Distributed - 4.5 m2		
No Asbestos		
B00F - R0012 - Therapy - 21.82 m2		
No Asbestos		
B00F - R0013 - Toilet - P - 9.07 m2		
No Asbestos		
B00F - R0014 - Laundry - P - 11.84 m2		
No Asbestos		
B00F - R0015 - Movement - 6.58 m2		
No Asbestos		
B00F - R0016 - Special Learning Space - 52.08 m2		
Floor Coverings Res/Textile	No Asbestos Found	

B00F - R0017 - Special Learning Space - 55.05 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0018 - Movement - 23.15 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0019 - Interview/Office - Type 1 - 9.27 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0020 - Computer Store - 11.14 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0021 - Computer Learning Space - 63.55 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0022 - Darkroom Space - 28.05 m2		
No Asbestos		
B00F - R0023 - General Storeroom - 16.82 m2		
No Asbestos		
B00F - R0024 - Distribution Board - .78 m2		Note: No inspection of live electrical installation
No Asbestos		
B00F - R0025 - Movement - 10.46 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0026 - Computer Learning Space - 50.02 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0027 - Movement - 14.41 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0028 - Staff Room Annexe - 336.53 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0029 - Movement - 6.53 m2		
No Asbestos		
B00F - R0030 - Interview/Meeting - 13.47 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0031 - Staff - Toilet - 9.58 m2		
No Asbestos		
B00F - R0032 - External Movement - 95.41 m2		
No Asbestos		
B00F - R0033 - External Movement - 287.98 m2		
No Asbestos		
B00F - R0034 - External Movement - 28.41 m2		
No Asbestos		
B00F - R0035 - External Movement - 219.31 m2		
No Asbestos		
B00F - R0036 - External Stairs - 13.59 m2		
No Asbestos		
B00F - R0037 - External Stairs - 12.68 m2		
No Asbestos		
B00F - R0038 - External Stairs - 13.1 m2		
No Asbestos		
B00F - R0039 - External Stairs - 7.1 m2		
No Asbestos		
B00F - R1001 - External Movement - 36.99 m2		
No Asbestos		
B00F - R1002 - General Learning Space - 48.55 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R1003 - General Learning Space - 48.55 m2		

Floor Coverings Res/Textile	No Asbestos Found	
B00F - R1004 - General Learning Space - 49.04 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R1005 - General Learning Space - 48.74 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R1006 - General Learning Space - 48.55 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R1007 - General Storeroom - 17.13 m2		
No Asbestos		
B00F - R1008 - General Storeroom - 17.13 m2		
No Asbestos		
B00F - R1009 - General Learning Space - 47.2 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R1010 - General Learning Space - 47.2 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R1011 - Distribution Board - .65 m2		
		Note: No inspection of live electrical installation
No Asbestos		
B00F - R1012 - Withdrawal Space - 1hb - 15.67 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R1013 - General Learning Space - 47.25 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R1014 - General Learning Space - 47.08 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R1015 - General Storeroom - 17.28 m2		
No Asbestos		
B00F - R1016 - General Learning Space - 46.76 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R1017 - General Learning Space - 46.95 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R1018 - External Movement - 11.01 m2		
No Asbestos		
B00F - R1019 - General Learning Space - 46.95 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R1020 - Withdrawal Space - 1hb - 15.44 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R1021 - General Learning Space - 46.59 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R1022 - External Movement - 21.45 m2		
No Asbestos		
B00F - R1023 - General Learning Space - 46.65 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R1024 - General Learning Space - 46.65 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R1025 - Withdrawal Space - 1hb - 20.04 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R1026 - General Learning Space - 46.53 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R1027 - External Movement - 21.58 m2		
No Asbestos		
B00F - R1028 - Withdrawal Space - 1hb - 14.18 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R1029 - General Storeroom - 17.28 m2		

No Asbestos		
B00F - R1030 - Staff - Toilet - 3.75 m2		
No Asbestos		
B00F - R1031 - Cleaning Store - Distributed - 2.79 m2		
No Asbestos		
B00F - R1032 - Distribution Board - .62 m2		Note: No inspection of live electrical installation
No Asbestos		
B00F - R1033 - General Learning Space - 47.97 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R1034 - Movement - 351.19 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R1035 - External Stairs - 11.21 m2		
No Asbestos		
B00F - R1036 - External Stairs - 17.06 m2		
No Asbestos		
B00F - R1037 - External Stairs - 17.59 m2		
No Asbestos		
B00F - R1038 - External Stairs - 20.73 m2		
No Asbestos		
B00G - Pupil Facilities/Building Services - 1992 - Brick/Block		
Exterior		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00G - R0001 - External Movement - 105.33 m2		
No Asbestos		
B00G - R0002 - Communal Space - 458.37 m2		
No Asbestos		
B00G - R0003 - Interview/Office - Type 1 - 11.76 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00G - R0004 - Staff Shower/Change - 9.18 m2		
No Asbestos		
B00G - R0005 - Cleaning Store - Distributed - 3.05 m2		
No Asbestos		
B00G - R0006 - Sport Equipment Store - 31.26 m2		
No Asbestos		
B00G - R0007 - General Storeroom - 3.54 m2		
No Asbestos		
B00G - R0008 - Sport Equipment Store - 19.72 m2		
No Asbestos		
B00G - R0009 - Shower/Change - 23.17 m2		
No Asbestos		
B00G - R0010 - Shower/Change - 9.12 m2		
No Asbestos		
B00G - R0011 - Shower/Change - 9.12 m2		
No Asbestos		
B00G - R0012 - Shower/Change - 22.98 m2		
No Asbestos		
B00G - R0013 - Distribution Board - 1.03 m2		Note: No inspection of live electrical installation
No Asbestos		
B00H - Performing Arts/Other-After School Care - 1991 - Brick/Block		

Exterior		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00H - R0001 - External Movement - 30.64 m2		
No Asbestos		
B00H - R0002 - Disabled Toilet - 4.8 m2		
No Asbestos		
B00H - R0003 - Distribution Board - 1.96 m2		Note: No inspection of live electrical installation
No Asbestos		
B00H - R0004 - Out Of School Hours Care Centre - 9.98 m2		
No Asbestos		
B00H - R0005 - Out Of School Hours Care Centre - 12.99 m2		
No Asbestos		
B00H - R0006 - Out Of School Hours Care Centre - 2.02 m2		
No Asbestos		
B00H - R0007 - Out Of School Hours Care Centre - 9.91 m2		
No Asbestos		
B00H - R0008 - Out Of School Hours Care Centre - 10.47 m2		
No Asbestos		
B00H - R0009 - Out Of School Hours Care Centre - 42.56 m2		
No Asbestos		
B00H - R0010 - Out Of School Hours Care Centre - 25.48 m2		
No Asbestos		
B00H - R0011 - Out Of School Hours Care Centre - 83.07 m2		
No Asbestos		
B00H - R0012 - Performance Workspace - 194.03 m2		
No Asbestos		
B00H - R0013 - Toilets - Boys - 28.86 m2		
No Asbestos		
B00H - R0014 - Toilets - Girls - 28.82 m2		
No Asbestos		
B00H - R0015 - Performing Arts Chair Store - 30.85 m2		
No Asbestos		
B00H - R0016 - Plant - 4.38 m2		
No Asbestos		
B00H - R0017 - Plant - 8.63 m2		
No Asbestos		
B00H - R0018 - Main Switch Board - 6 m2		
No Asbestos		
B00H - R0019 - General Storeroom - 3.74 m2		
No Asbestos		
B00H - R0020 - External Movement - 54.44 m2		
No Asbestos		
B00I - Tiered Learning/Staff Facilities - 1991 - Brick/Block		
Exterior		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00I - R0001 - Staff Room Annexe - 23.71 m2		
Floor Coverings Res/Textile	No Asbestos Found	

B00I - R0002 - Disabled Toilet - 5.16 m2		
No Asbestos		
B00I - R0003 - External Movement - 7.46 m2		
No Asbestos		
B00I - R0004 - Distribution Board - 1.3 m2		Note: No inspection of live electrical installation
No Asbestos		
B00I - R0005 - Special Programs Store - 2.98 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00I - R0006 - Tiered Learning Area - 45.94 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00I - R0007 - Garden Store Room - 9.95 m2		
No Asbestos		
B00I - R0008 - Plant - 6.25 m2		
No Asbestos		
B00J - Science/Music - 1991 - Brick/Block		
Exterior		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00J - R0001 - Distribution Board - 1.6 m2		Note: No inspection of live electrical installation
No Asbestos		
B00J - R0002 - Cleaning Store - Distributed - 2.02 m2		
No Asbestos		
B00J - R0003 - Music Entry/Display - 29.13 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00J - R0004 - Music Learning Space - 58.8 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00J - R0005 - Music Learning Space - 76.49 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00J - R0006 - Practice/Seminar - 24.39 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00J - R0007 - Resources - 24.88 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00J - R0008 - Music Store - 16.9 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00J - R0009 - Laboratory L.S. - 88.52 m2		
No Asbestos		
B00J - R0010 - Laboratory L.S. - 88.22 m2		
No Asbestos		
B00J - R0011 - Apparatus Store - 40.66 m2		
No Asbestos		
B00J - R0012 - General Storeroom - 11.78 m2		
No Asbestos		
B00J - R0013 - Preparation - 98.94 m2		
No Asbestos		
B00J - R0014 - Growing/Breeding - 19.27 m2		
No Asbestos		
B00J - R0015 - External Movement - 4.57 m2		
No Asbestos		
B00J - R0016 - Distribution Board - 1.65 m2		Note: No inspection of live electrical installation
No Asbestos		

B00J - R0017 - Chemical Store - 13.4 m2		
No Asbestos		
B00J - R0018 - Laboratory L.S. - 88.14 m2		
No Asbestos		
B00J - R0019 - Toilets - Girls - 34.17 m2		
No Asbestos		
B00J - R0020 - Toilets - Boys - 33.91 m2		
No Asbestos		
B00J - R0021 - Laboratory L.S. - 88.14 m2		
No Asbestos		
B00J - R0022 - Laboratory L.S. - 91.2 m2		
No Asbestos		
B00J - R0023 - Movement - 12.51 m2		
No Asbestos		
B00J - R0024 - Laboratory L.S. - 91.28 m2		
No Asbestos		
B00J - R0028 - External Movement - 305.39 m2		
No Asbestos		
B00K - General Learning - 1992 - Brick/Veneer		
Exterior		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00K - R0001 - Home Base Store - 7.02 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00K - R0002 - Cleaning Store - Distributed - 2.04 m2		
No Asbestos		
B00K - R0003 - Practical Activities - 1hb - 21.53 m2		
No Asbestos		
B00K - R0004 - Home Base - 56.18 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00K - R0005 - Withdrawal Space - 1hb - 10.13 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00K - R0007 - Practical Activities - 1hb - 21.51 m2		
No Asbestos		
B00K - R0008 - Home Base - 56.17 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00K - R0009 - Home Base Store - 6.76 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00K - R0010 - Home Base Store - 6.76 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00K - R0011 - Distribution Board - 1.18 m2		
No Asbestos		Note: No inspection of live electrical installation
B00K - R0012 - Practical Activities - 1hb - 21.53 m2		
No Asbestos		
B00K - R0013 - Home Base - 56.12 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00K - R0014 - Withdrawal Space - 1hb - 10.3 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00K - R0016 - Practical Activities - 1hb - 21.51 m2		
No Asbestos		

B00K - R0017 - Home Base - 55.98 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00K - R0018 - Home Base Store - 6.95 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00K - R0019 - External Movement - 91.01 m2		
No Asbestos		
B00L - Communal Facilities/Pupil Facilities - 1992 - Brick/Block		
Exterior		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00L - R0001 - General Storeroom - 12.81 m2		
No Asbestos		
B00L - R0002 - Distribution Board - .93 m2		Note: No inspection of live electrical installation
No Asbestos		
B00L - R0003 - Chair Store - 12 m2		
No Asbestos		
B00L - R0004 - Movement - 4.09 m2		
No Asbestos		
B00L - R0005 - Raised Platform - 53.36 m2		
No Asbestos		
B00L - R0006 - External Movement - 2.79 m2		
No Asbestos		
B00L - R0007 - Cleaning Supplies Store - 11.29 m2		
No Asbestos		
B00L - R0008 - Communal Space - 194.26 m2		
No Asbestos		
B00L - R0009 - External Movement - 54.53 m2		
No Asbestos		
B00L - R0010 - Plant - .53 m2		
No Asbestos		
B00L - R0011 - Toilets - Girls - 7.51 m2		
No Asbestos		
B00L - R0012 - Toilets - Boys - 3.86 m2		
No Asbestos		
B00L - R0013 - Shower/Change - 2.6 m2		
No Asbestos		
B00L - R0014 - Cleaning Store - Distributed - 2.68 m2		
No Asbestos		
B00L - R0015 - Sport Equipment Store - 16.16 m2		
No Asbestos		
B00M - General Learning/Pupil Facilities - 1992 - Brick/Block		
Exterior		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00M - R0001 - External Movement - .66 m2		
No Asbestos		
B00M - R0002 - Careers Advisers Office - 12.12 m2		
Floor Coverings Res/Textile	No Asbestos Found	

B00M - R0003 - Careers Advisers Office - 12.27 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00M - R0004 - No Access - 13.19 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00M - R0005 - General Learning Space - 45.95 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00M - R0006 - Withdrawal Space - 1hb - 16.18 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00M - R0007 - General Learning Space - 46.08 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00M - R0008 - General Learning Space - 46.01 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00M - R0009 - External Movement - 42.92 m2		
No Asbestos		
B00M - R0010 - Toilets - Boys - 24.06 m2		
No Asbestos		
B00M - R0011 - Disabled Toilet - 5.77 m2		
No Asbestos		
B00M - R0012 - Toilets - Girls - 29.66 m2		
No Asbestos		
B00M - R0013 - General Learning Space - 46.08 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00M - R0014 - General Learning Space - 46.01 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00M - R0015 - Withdrawal Space - 1hb - 16.07 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00M - R0016 - General Storeroom - 18.7 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00M - R0017 - Distribution Board - .8 m2		
		Note: No inspection of live electrical installation
No Asbestos		
B00M - R0018 - Cleaning Store - Distributed - 2.87 m2		
No Asbestos		
B00M - R0019 - Seminar - 67.04 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00M - R0020 - Movement - 90.71 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00N - Technological & Applied Studies/Computer Learning - 1992 - Brick/Block		
Exterior		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00N - R0001 - Interview/Office - Type 1 - 12.02 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00N - R0002 - Cleaning Store - Distributed - 1.93 m2		
No Asbestos		
B00N - R0003 - Laundry - 5.31 m2		
No Asbestos		
B00N - R0004 - Staff - Toilet - 4.67 m2		
No Asbestos		
B00N - R0005 - Staff - Toilet - 4.68 m2		
No Asbestos		

B00N - R0006 - Food/Research Space - 37.56 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00N - R0007 - Food Technology L.S. - 74.42 m2		
No Asbestos		
B00N - R0008 - Distribution Board - .63 m2		Note: No inspection of live electrical installation
No Asbestos		
B00N - R0009 - Materials Technology L.S. - 168.66 m2		
No Asbestos		
B00N - R0010 - Design L.S. - 63.29 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00N - R0011 - Wood Technology Bay - 68.58 m2		
No Asbestos		
B00N - R0012 - Materials Technology L.S. - 167.6 m2		
No Asbestos		
B00N - R0013 - Distribution Board - .99 m2		Note: No inspection of live electrical installation
No Asbestos		
B00N - R0014 - Design L.S. - 74.16 m2		
No Asbestos		
B00N - R0015 - Design/Technology L.S. - 74.15 m2		
No Asbestos		
B00N - R0016 - Computer Learning Space - 74.3 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00N - R0017 - Resource/Project Store - 23.33 m2		
No Asbestos		
B00N - R0018 - Computer Learning Space - 74.28 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00N - R0019 - Metal Technology Bay - 62.75 m2		
No Asbestos		
B00N - R0020 - Materials Store - 31.17 m2		
No Asbestos		
B00N - R0021 - Resource/Project Store - 14.17 m2		
No Asbestos		
B00N - R0022 - Personal Effects Storage - 2.82 m2		
No Asbestos		
B00N - R0023 - Welding Area - 8.55 m2		
No Asbestos		
B00N - R0024 - Dust Extraction Space - 6.77 m2		
No Asbestos		
B00N - R0025 - Pantry - 26.99 m2		
No Asbestos		
B00N - R0026 - Food Technology L.S. - 73.42 m2		
No Asbestos		
B00N - R0027 - External Movement - 328.74 m2		
No Asbestos		
B00N - R0028 - External Movement - 7.61 m2		
No Asbestos		
B00N - R0029 - Covered Vehicle Area/Porte Cochere - 69.31 m2		
No Asbestos		
B00P - Art - 1992 - Brick/Block		
Exterior		
Underfloor Voids - Slab on Ground	No Asbestos Found	

Ceiling Voids	No Asbestos Found	
Interior		
B00P - R0001 - External Movement - 113.05 m2		
No Asbestos		
B00P - R0002 - Distribution Board - 1.39 m2		Note: No inspection of live electrical installation
No Asbestos		
B00P - R0003 - Cleaning Store - Distributed - 2.85 m2		
No Asbestos		
B00P - R0004 - Kiln Space - 8.68 m2		
No Asbestos		
B00P - R0005 - Workshop - 49.98 m2		
No Asbestos		
B00P - R0006 - Art Learning Space - 59.64 m2		
No Asbestos		
B00P - R0007 - Resources Store - 14.72 m2		
No Asbestos		
B00P - R0008 - Cleaning Supplies Store - 15.73 m2		
No Asbestos		
B00P - R0009 - Art Learning Space - 60.9 m2		
No Asbestos		
B00P - R0010 - Art Learning Space - 61.06 m2		
No Asbestos		
B00P - R0011 - Resources Store - 14.37 m2		
No Asbestos		
B00P - R0012 - Art Learning Space - 59.51 m2		
No Asbestos		
B00P - R0013 - Resources Space - 11.61 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00P - R0014 - Resources Space - 11.61 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00Q - General Learning/Other - 2010 - Brick/Veneer		
Exterior		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00Q - R0001 - General Assistant/Bulk Store - 12.58 m2		
No Asbestos		
B00Q - R0002 - Home Base Store - 18.45 m2		
No Asbestos		
B00Q - R0003 - Home Base - 59.58 m2		
No Asbestos		
B00Q - R0004 - Withdrawal Space - 2hb - 6.29 m2		
No Asbestos		
B00Q - R0005 - Withdrawal Space - 2hb - 11.28 m2		
No Asbestos		
B00Q - R0006 - Home Base Store - 59.55 m2		
No Asbestos		
B00Q - R0007 - Special Programs Store - 6.29 m2		
No Asbestos		
B00Q - R0008 - Special Programs Room - 18.18 m2		
No Asbestos		

B00Q - R0009 - Special Programs Room - 36.91 m2	
No Asbestos	
B00Q - R0010 - Practical Activities - 1hb - 7.04 m2	
No Asbestos	
B00Q - R0011 - Home Base Store - 18.17 m2	
No Asbestos	
B00Q - R0012 - Home Base - 60.03 m2	
No Asbestos	
B00Q - R0013 - Withdrawal Space - 2hb - 6.18 m2	
No Asbestos	
B00Q - R0014 - Home Base Store - 11.34 m2	
No Asbestos	
B00Q - R0015 - Practical Activities - 1hb - 59.61 m2	
No Asbestos	
B00Q - R0016 - Movement - 18.16 m2	
No Asbestos	
B00Q - R0017 - Practical Activities - 1hb - 6.26 m2	
No Asbestos	
B00Q - R0018 - Practical Activities - 1hb - 118.01 m2	
No Asbestos	
B00Q - R0019 - Sports Store - 12.44 m2	
No Asbestos	
B00Q - R0020 - Secure Storeroom - 15.01 m2	
No Asbestos	

Demountables

There are no Demountable(s) Located at this school as per the AMS records as of 09-Sep-2020