


# Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Lake Munmorah High School (8279)
Region:	Hunter/Central Coast AMU
State Electorate:	Swansea
Local Government Area:	Central Coast

Last Reviewed By:	WSP 29-JUN-2017
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	No
No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.	



# Preface to Asbestos Register

## Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
  - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
  - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
  - o Any wall cavity
  - o Sub floor area, particularly formwork for slabs in/on ground,
  - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.  
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

## Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

## Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

## Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

## Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>  
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

## Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

### 3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
<b>B00A - Administration/Staff Facilities - 2001 - Brick/Veneer</b>							
<b>Exterior</b>							
Underfloor Voids - Slab on Ground	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00A - R0001 - Interview/Office - Type 1 - 12.84 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0002 - Interview/Office - Type 1 - 12.84 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0003 - Clinic - Boys - 12.84 m2</b>							
No Asbestos							
<b>B00A - R0004 - Staff - Toilet - 2.06 m2</b>							
No Asbestos							
<b>B00A - R0005 - Staff - Toilet - 2.04 m2</b>							
No Asbestos							
<b>B00A - R0006 - Clinic - Girls - 12.77 m2</b>							
No Asbestos							
<b>B00A - R0007 - Movement - 22.64 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0008 - Principal Office - 19.04 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0009 - Staff - Toilet - 4.04 m2</b>							
No Asbestos							
<b>B00A - R0010 - Staff - Toilet - 4.04 m2</b>							
No Asbestos							
<b>B00A - R0013 - Interview/Office - Type 1 - 12.77 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0014 - Public Entry - 16.26 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0016 - Staff Kitchen - 4.75 m2</b>							
No Asbestos							
<b>B00A - R0017 - Administration - Clerical - 90.74 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0019 - Pupil Entry - 35.86 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0020 - External Movement - 170.33 m2</b>							
No Asbestos							
<b>B00A - R0021 - Interview/Office - Type 1 - 12.7 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0022 - Deputy Principal Office - 12.66 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0023 - Cleaning Supplies Store - 8.25 m2</b>							
No Asbestos							
<b>B00A - R0024 - Security Store - 14.8 m2</b>							
No Asbestos							
<b>B00A - R0025 - Security Store - 29.49 m2</b>							
No Asbestos							
<b>B00A - R0026 - Security Store - 13.94 m2</b>							
No Asbestos							
<b>B00A - R0027 - Cleaning Store - Distributed - 3.49 m2</b>							

No Asbestos		
<b>B00A - R0028 - Distribution Board Cupboard - .76 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00A - R0029 - Plant - .34 m2</b>		
No Asbestos		
<b>B00A - R0030 - Distribution Board Cupboard - .66 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00A - R0031 - Plant - .41 m2</b>		
No Asbestos		
<b>B00A - R0032 - External Stairs - 12.07 m2</b>		
No Asbestos		
<b>B00A - R0033 - Stairs - 16.56 m2</b>		
No Asbestos		
<b>B00A - R0034 - External Movement - 3.74 m2</b>		
No Asbestos		
<b>B00A - R0035 - Interview/Meeting - 25.97 m2</b>		
No Asbestos		
<b>B00A - R0036 - Movement - 22.81 m2</b>		
No Asbestos		
<b>B00A - R0037 - Administration - Clerical - 2.15 m2</b>		
No Asbestos		
<b>B00A - R1001 - Staff Study - 179.85 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00A - R1002 - Commonroom - 105.2 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00A - R1003 - Staff Study - 185.86 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00A - R1004 - Staff - Toilet - 4.2 m2</b>		
No Asbestos		
<b>B00A - R1005 - Staff - Toilet - 4.2 m2</b>		
No Asbestos		
<b>B00A - R1006 - Staff - Toilet - 4.2 m2</b>		
No Asbestos		
<b>B00A - R1007 - Disabled Toilet - 6.17 m2</b>		
No Asbestos		
<b>B00A - R1008 - Staff - Toilet - 3.86 m2</b>		
No Asbestos		
<b>B00A - R1009 - Staff - Toilet - 3.79 m2</b>		
No Asbestos		
<b>B00A - R1010 - Interview/Office - Type 1 - 13.01 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00A - R1011 - Interview/Office - Type 1 - 12.93 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00A - R1012 - Duplicating Workroom - 35.45 m2</b>		
No Asbestos		
<b>B00A - R1013 - Interview/Office - Type 1 - 12.87 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00A - R1014 - Interview/Office - Type 1 - 13.17 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00A - R1015 - Plant - .33 m2</b>		
No Asbestos		
<b>B00A - R1016 - Distribution Board Cupboard - .7 m2</b>		<b>Note: No inspection of live electrical installation</b>

No Asbestos		
<b>B00A - R1017 - Distribution Board Cupboard - .9 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00A - R1018 - Plant - .42 m2</b>		
No Asbestos		
<b>B00A - R1019 - Movement - 67.11 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00A - R1020 - External Movement - 10.66 m2</b>		
No Asbestos		
<b>B00A - R1021 - External Movement - 15.94 m2</b>		
No Asbestos		
<b>B00A - R1022 - External Stairs - 12.07 m2</b>		
No Asbestos		
<b>B00A - R1023 - Stairs - 21.8 m2</b>		
No Asbestos		
<b>B00B - Technological &amp; Applied Studies/Pupil Facilities - 2001 - Brick/Veneer</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00B - R0001 - General Learning Space - 59.59 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00B - R0002 - General Learning Space - 58.03 m2</b>		
No Asbestos		
<b>B00B - R0003 - General Learning Space - 58.69 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00B - R0004 - General Learning Space - 58.63 m2</b>		
No Asbestos		
<b>B00B - R0005 - General Learning Space - 58.42 m2</b>		
No Asbestos		
<b>B00B - R0006 - General Learning Space - 58.83 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00B - R0007 - Garden Store Room - 16.05 m2</b>		
No Asbestos		
<b>B00B - R0008 - Toilets - Boys - 31.08 m2</b>		
No Asbestos		
<b>B00B - R0010 - Toilets - Girls - 31.3 m2</b>		
No Asbestos		
<b>B00B - R0012 - Darkroom Space - 27.83 m2</b>		
No Asbestos		
<b>B00B - R0013 - Cleaning Store - Distributed - 3.39 m2</b>		
No Asbestos		
<b>B00B - R0015 - Materials Workshop - Type 2 - 106.13 m2</b>		
No Asbestos		
<b>B00B - R0016 - Resource/Project Store - 9.37 m2</b>		
No Asbestos		
<b>B00B - R0017 - Secure Storeroom - 18.97 m2</b>		
No Asbestos		
<b>B00B - R0025 - Distribution Board Cupboard - .53 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00B - R0028 - Materials Workshop - Type 2 - 120.68 m2</b>		

No Asbestos		
<b>B00B - R0029 - Resource/Project Store - 88.28 m2</b>		
No Asbestos		
<b>B00B - R0030 - Dust Extraction Space - 6.11 m2</b>		
No Asbestos		
<b>B00B - R0031 - Toilets-Disabled - 5.07 m2</b>		
No Asbestos		
<b>B00B - R0032 - Dust Extraction Space - 6.13 m2</b>		
No Asbestos		
<b>B00B - R0033 - Staff - Toilet - 4.02 m2</b>		
No Asbestos		
<b>B00B - R0034 - Staff Shower - 3.72 m2</b>		
No Asbestos		
<b>B00B - R0035 - Materials Workshop - Type 2 - 120.59 m2</b>		
No Asbestos		
<b>B00B - R0036 - Distribution Board Cupboard - .66 m2</b>		
		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00B - R0037 - Distribution Board Cupboard - .73 m2</b>		
		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00B - R0038 - Other-Vacant - .72 m2</b>		
No Asbestos		
<b>B00B - R0039 - Main Switchroom - 7.34 m2</b>		
No Asbestos		
<b>B00B - R0040 - External Movement - 251.74 m2</b>		
No Asbestos		
<b>B00B - R0041 - Movement - 5.41 m2</b>		
No Asbestos		
<b>B00B - R0042 - Stairs - 16.58 m2</b>		
No Asbestos		
<b>B00B - R0043 - Craft Store - 16.82 m2</b>		
No Asbestos		
<b>B00B - R0044 - Kiln Space - 6.88 m2</b>		
No Asbestos		
<b>B00B - R0045 - Plant - 4.51 m2</b>		
No Asbestos		
<b>B00B - R0046 - Plant - .91 m2</b>		
No Asbestos		
<b>B00B - R0047 - Materials Store - 16.34 m2</b>		
No Asbestos		
<b>B00B - R0048 - Workshop Area - 103.47 m2</b>		
No Asbestos		
<b>B00B - R0049 - Materials Store - 10 m2</b>		
No Asbestos		
<b>B00B - R0050 - Workshop Area - 124.44 m2</b>		
No Asbestos		
<b>B00B - R0051 - Agriculture Covered Area - 63.67 m2</b>		
No Asbestos		
<b>B00B - R1001 - General Learning Space - 60.57 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00B - R1002 - General Learning Space - 57.87 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00B - R1003 - General Learning Space - 58.77 m2</b>		

Floor Coverings Res/Textile	No Asbestos Found	
<b>B00B - R1004 - General Learning Space - 58.54 m2</b>		
No Asbestos		
<b>B00B - R1005 - General Learning Space - 58.48 m2</b>		
No Asbestos		
<b>B00B - R1006 - Distribution Board Cupboard - .83 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00B - R1008 - Materials Store - 15.04 m2</b>		
No Asbestos		
<b>B00B - R1009 - Kitchen - Type 1 - 111.16 m2</b>		
No Asbestos		
<b>B00B - R1011 - Seminar/Technology Space - 18.08 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00B - R1014 - Distribution Board Cupboard - .87 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00B - R1015 - Preparation - Materials - 16.76 m2</b>		
No Asbestos		
<b>B00B - R1016 - Pantry - 4.85 m2</b>		
No Asbestos		
<b>B00B - R1018 - General Learning Space - 58.26 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00B - R1021 - Movement - 18.94 m2</b>		
No Asbestos		
<b>B00B - R1022 - Music Store - 20.39 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00B - R1023 - Practice/Seminar - 20.88 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00B - R1024 - Performance Workshop - 107.32 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00B - R1025 - Movement - 124.83 m2</b>		
No Asbestos		
<b>B00B - R1026 - Stairs - 20.86 m2</b>		
No Asbestos		
<b>B00B - R1027 - Distribution Board Cupboard - 6.42 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00B - R1028 - Pantry - 13.8 m2</b>		
No Asbestos		
<b>B00B - R1029 - Food/Research Space - 6.58 m2</b>		
No Asbestos		
<b>B00B - R1030 - Food Technology L.S. - 105.17 m2</b>		
No Asbestos		
<b>B00B - R1031 - External Movement - 32.01 m2</b>		
No Asbestos		
<b>B00B - R1032 - Laundry - .81 m2</b>		
No Asbestos		
<b>B00C - Multi Purpose Facilities - 2001 - Brick/Veneer</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00C - R0001 - Sport Equipment Store - 16.46 m2</b>		

No Asbestos		
<b>B00C - R0002 - Student Canteen - 55.54 m2</b>		
No Asbestos		
<b>B00C - R0003 - Office/Store - 15.08 m2</b>		
No Asbestos		
<b>B00C - R0004 - Staff - Toilet - 4.36 m2</b>		
No Asbestos		
<b>B00C - R0005 - Sport Equipment Store - 23.03 m2</b>		
No Asbestos		
<b>B00C - R0006 - Performing Arts Store - 30.19 m2</b>		
No Asbestos		
<b>B00C - R0007 - Performance Workshop - 162.1 m2</b>		
No Asbestos		
<b>B00C - R0008 - Sport Equipment Store - 24.65 m2</b>		
No Asbestos		
<b>B00C - R0009 - Control Room - 9.58 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R0010 - Chair Store - 31.81 m2</b>		
No Asbestos		
<b>B00C - R0011 - Clinic-Waiting - 11.87 m2</b>		
No Asbestos		
<b>B00C - R0012 - Multi-Purpose Space - 624.22 m2</b>		
No Asbestos		
<b>B00C - R0013 - Stage - 97.14 m2</b>		
No Asbestos		
<b>B00C - R0014 - General Storeroom - 1.37 m2</b>		
No Asbestos		
<b>B00C - R0015 - Plant - .91 m2</b>		
No Asbestos		
<b>B00C - R0016 - General Storeroom - 1.14 m2</b>		
No Asbestos		
<b>B00C - R0017 - Distribution Board Cupboard - 1.35 m2</b>		
		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00C - R0018 - Plant - .71 m2</b>		
No Asbestos		
<b>B00C - R0019 - General Storeroom - 12.05 m2</b>		
No Asbestos		
<b>B00C - R0020 - Plant - .77 m2</b>		
No Asbestos		
<b>B00C - R0021 - Distribution Board Cupboard - 1.17 m2</b>		
		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00C - R0022 - Movement - 355.32 m2</b>		
No Asbestos		
<b>B00C - R0023 - Movement - 7.85 m2</b>		
No Asbestos		
<b>B00C - R0024 - Movement - 4.11 m2</b>		
No Asbestos		
<b>B00C - R0025 - Movement - 4.34 m2</b>		
No Asbestos		
<b>B00C - R0026 - Movement - 4.63 m2</b>		
No Asbestos		
<b>B00C - R0027 - Machine Storage - 27.54 m2</b>		



No Asbestos		
<b>B00D - General Learning - 2001 - Brick/Veneer</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00D - R0001 - General Learning Space - 58.42 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R0002 - General Learning Space - 58.56 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R0003 - General Learning Space - 58.1 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R0004 - General Learning Space - 57.58 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R0005 - General Learning Space - 58.21 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R0006 - General Learning Space - 62.74 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R0007 - Study Space - 32.67 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R0009 - Seminar - 24.74 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R0012 - Distribution Board Cupboard - .59 m2</b>		
		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00D - R0013 - Plant - .3 m2</b>		
No Asbestos		
<b>B00D - R0014 - Distribution Board Cupboard - .64 m2</b>		
		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00D - R0015 - Secure Storeroom - 27.69 m2</b>		
No Asbestos		
<b>B00D - R0016 - Movement - 22.01 m2</b>		
No Asbestos		
<b>B00D - R0017 - Stairs - 21.1 m2</b>		
No Asbestos		
<b>B00D - R0018 - Movement - 164.8 m2</b>		
No Asbestos		
<b>B00D - R0019 - Stairs - 26.76 m2</b>		
No Asbestos		
<b>B00D - R0020 - Student Kitchen - 29.41 m2</b>		
No Asbestos		
<b>B00D - R0021 - Practical Activities - 37.33 m2</b>		
No Asbestos		
<b>B00D - R1001 - General Learning Space - 57.92 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R1002 - General Learning Space - 58.62 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R1003 - General Learning Space - 58.01 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R1004 - General Learning Space - 57.27 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R1005 - General Learning Space - 58.37 m2</b>		

Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R1006 - General Learning Space - 62.75 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R1007 - Study Space - 31.73 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R1008 - Study Space - 32.54 m2</b>		
No Asbestos		
<b>B00D - R1009 - Seminar - 23.01 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R1010 - Study Space - 31.71 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R1011 - Secure Storeroom - 27.52 m2</b>		
No Asbestos		
<b>B00D - R1012 - Distribution Board Cupboard - .59 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00D - R1013 - Plant - .31 m2</b>		
No Asbestos		
<b>B00D - R1014 - Distribution Board Cupboard - .62 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00D - R1015 - Movement - 157.09 m2</b>		
No Asbestos		
<b>B00D - R1016 - Movement - 22 m2</b>		
No Asbestos		
<b>B00D - R1017 - Stairs - 21.11 m2</b>		
No Asbestos		
<b>B00D - R1018 - Stairs - 26.76 m2</b>		
No Asbestos		
<b>B00D - R2001 - General Learning Space - 58.01 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R2002 - General Learning Space - 58.7 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R2003 - General Learning Space - 58.08 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R2004 - General Learning Space - 57.27 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R2005 - General Learning Space - 58.37 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R2006 - General Learning Space - 62.74 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R2007 - Study Space - 31.74 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R2008 - Study Space - 32.55 m2</b>		
No Asbestos		
<b>B00D - R2009 - Seminar - 23.01 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R2010 - Study Space - 31.71 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R2011 - Secure Storeroom - 27.49 m2</b>		
No Asbestos		
<b>B00D - R2012 - Distribution Board Cupboard - .59 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00D - R2013 - Plant - .31 m2</b>		

No Asbestos		
<b>B00D - R2014 - Distribution Board Cupboard - .63 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00D - R2015 - Movement - 159.11 m2</b>		
No Asbestos		
<b>B00D - R2016 - Movement - 22 m2</b>		
No Asbestos		
<b>B00D - R2017 - Stairs - 21.11 m2</b>		
No Asbestos		
<b>B00D - R2018 - Stairs - 24.05 m2</b>		
No Asbestos		
<b>B00E - General Learning/Science Learning - 2001 - Brick/Veneer</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00E - R0001 - General Learning Space - 58.62 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R0002 - General Learning Space - 57.43 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R0003 - General Learning Space - 58.06 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R0004 - General Learning Space - 58.7 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R0005 - Movement - 16.97 m2</b>		
No Asbestos		
<b>B00E - R0006 - Growing/Breeding - 13.66 m2</b>		
No Asbestos		
<b>B00E - R0007 - Cleaning Store - Distributed - 3.88 m2</b>		
No Asbestos		
<b>B00E - R0008 - Plant - 4.62 m2</b>		
No Asbestos		
<b>B00E - R0009 - Science Laboratory - 101.1 m2</b>		
No Asbestos		
<b>B00E - R0010 - General Storeroom - 14.29 m2</b>		
No Asbestos		
<b>B00E - R0011 - Preparation - 16.47 m2</b>		
No Asbestos		
<b>B00E - R0012 - Chemical Store - 11.65 m2</b>		
No Asbestos		
<b>B00E - R0013 - Preparation - 78.36 m2</b>		
No Asbestos		
<b>B00E - R0014 - Science Laboratory - 101.11 m2</b>		
No Asbestos		
<b>B00E - R0015 - Distribution Board Cupboard - .71 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00E - R0016 - Plant - .31 m2</b>		
No Asbestos		
<b>B00E - R0017 - Distribution Board Cupboard - .62 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00E - R0018 - Seminar - 20.07 m2</b>		

Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R0019 - Lift - 2.13 m2</b>		
No Asbestos		
<b>B00E - R0020 - Movement - 255.98 m2</b>		
No Asbestos		
<b>B00E - R0021 - Movement - 3.73 m2</b>		
No Asbestos		
<b>B00E - R0022 - Stairs - 24.94 m2</b>		
No Asbestos		
<b>B00E - R0023 - Stairs - 20.96 m2</b>		
No Asbestos		
<b>B00E - R0024 - Movement - 7.18 m2</b>		
No Asbestos		
<b>B00E - R1001 - General Learning Space - 63.06 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R1002 - General Learning Space - 58.38 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R1003 - General Learning Space - 57.1 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R1004 - General Learning Space - 58 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R1005 - General Learning Space - 58.63 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R1006 - General Learning Space - 58.06 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R1007 - Study Space - 31.83 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R1008 - Study Space - 32.25 m2</b>		
No Asbestos		
<b>B00E - R1009 - Seminar - 23.26 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R1010 - Study Space - 32.06 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R1011 - Secure Storeroom - 27.45 m2</b>		
No Asbestos		
<b>B00E - R1012 - Distribution Board Cupboard - .62 m2</b>		
No Asbestos		Note: No inspection of live electrical installation
<b>B00E - R1013 - Plant - .31 m2</b>		
No Asbestos		
<b>B00E - R1014 - Distribution Board Cupboard - .6 m2</b>		
No Asbestos		Note: No inspection of live electrical installation
<b>B00E - R1015 - Stairs - 18.59 m2</b>		
No Asbestos		
<b>B00E - R1016 - Movement - 22.34 m2</b>		
No Asbestos		
<b>B00E - R1017 - Movement - 193.92 m2</b>		
No Asbestos		
<b>B00E - R1018 - Lift - 2.13 m2</b>		
No Asbestos		
<b>B00E - R1019 - Stairs - 24.94 m2</b>		
No Asbestos		
<b>B00E - R2001 - General Learning Space - 62.9 m2</b>		

Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R2002 - General Learning Space - 58.67 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R2003 - General Learning Space - 57.23 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R2004 - General Learning Space - 58.2 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R2005 - General Learning Space - 58.84 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R2006 - General Learning Space - 57.93 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R2007 - Study Space - 32.39 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R2008 - Study Space - 30.61 m2</b>		
No Asbestos		
<b>B00E - R2009 - Seminar - 23.12 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R2010 - Study Space - 32.46 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R2011 - Secure Storeroom - 27.72 m2</b>		
No Asbestos		
<b>B00E - R2012 - Distribution Board Cupboard - .61 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00E - R2013 - Plant - .31 m2</b>		
No Asbestos		
<b>B00E - R2014 - Distribution Board Cupboard - .6 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00E - R2015 - Stairs - 20.67 m2</b>		
No Asbestos		
<b>B00E - R2016 - Movement - 22.19 m2</b>		
No Asbestos		
<b>B00E - R2017 - Movement - 182.55 m2</b>		
No Asbestos		
<b>B00E - R2018 - Lift - 2.13 m2</b>		
No Asbestos		
<b>B00E - R2019 - Stairs - 24.98 m2</b>		
No Asbestos		
<b>B00F - Library/Computer Learning - 2001 - Brick/Veneer</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00F - R0001 - Study Space - 58.69 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0002 - Careers Advisers Office - 12.8 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0003 - Entry - 24.9 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0004 - Administration - Clerical - 13.67 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0005 - Communications Cupboard - 13.99 m2</b>		

No Asbestos		
<b>B00F - R0006 - Computer Learning Space - 66.79 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0007 - Computer Store - 10.72 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0008 - Duplicating Workroom - 4.99 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0009 - Main Area - 419.09 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0010 - Workroom - 74.31 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0011 - Seminar - 12.8 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0012 - Seminar - 12.77 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0013 - Seminar - 12.69 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0014 - Staff - Toilet - 5.52 m2</b>		
No Asbestos		
<b>B00F - R0015 - Toilets-Unisex - 5.43 m2</b>		
No Asbestos		
<b>B00F - R0016 - General Storeroom - 4.57 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0017 - Distribution Board Cupboard - .74 m2</b>		
		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00F - R0018 - Movement - 253.52 m2</b>		
No Asbestos		
<b>B00G - Pupil Facilities/General Learning - 2001 - Brick/Veneer</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00G - R0001 - General Learning Space - 57.22 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00G - R0002 - General Learning Space - 57.04 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00G - R0003 - Shower/Change - 24.01 m2</b>		
No Asbestos		
<b>B00G - R0004 - Shower/Change - 24.19 m2</b>		
No Asbestos		
<b>B00G - R0005 - Shower/Change - 24.01 m2</b>		
No Asbestos		
<b>B00G - R0006 - Toilets - Boys - 33.18 m2</b>		
No Asbestos		
<b>B00G - R0007 - Shower/Change - 18.15 m2</b>		
No Asbestos		
<b>B00G - R0008 - Shower/Change - 18.08 m2</b>		
No Asbestos		
<b>B00G - R0009 - Seminar - 20.79 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00G - R0010 - Sport Equipment Store - 20.53 m2</b>		

No Asbestos	
<b>B00G- R0011 - Fitness Laboratory - 102.72 m2</b>	
Floor Coverings Res/Textile	No Asbestos Found
<b>B00G- R0012 - Toilets - Girls - 33.43 m2</b>	
No Asbestos	
<b>B00G- R0013 - Shower/Change - 23.92 m2</b>	
No Asbestos	
<b>B00G- R0014 - Toilets - Boys - 48.43 m2</b>	
No Asbestos	
<b>B00G- R0015 - Toilets - Girls - 59.42 m2</b>	
No Asbestos	
<b>B00G- R0016 - Cleaning Store - Distributed - 3.46 m2</b>	
No Asbestos	
<b>B00G- R0017 - Staff - Toilet - 4.8 m2</b>	
No Asbestos	
<b>B00G- R0018 - Distribution Board Cupboard - .6 m2</b>	<b>Note: No inspection of live electrical installation</b>
No Asbestos	
<b>B00G- R0019 - Distribution Board Cupboard - .64 m2</b>	<b>Note: No inspection of live electrical installation</b>
No Asbestos	
<b>B00G- R0020 - Movement - 279.2 m2</b>	
No Asbestos	

## Demountables

### OS 844 12449 - Country Toilet - Reltc - Boys/Girls - Placement Date : 06-DEC-2019

No Asbestos Found

### OS 837 17113 - Hcap Shower/Change/Toilet - Placement Date : 23-JAN-2012

#### Exterior

Eaves Linings	Flat AC Sheeting	2.88m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

#### Interior

##### R1 - Disabled Shower/Toilet

Ceiling Structures/Linings	Flat AC Sheeting	18m2	Assumed Asbestos
End Wall Panel	Flat AC Sheeting	36m2	Assumed Asbestos
Toilet Partitions	Compressed AC Sheet	12m2	Assumed Asbestos