I refer to Alex Avenue Public School approved on the 21st May 2020.

In accordance, with condition C34 of the Development Consent, the following document has been submitted to the Planning Secretary for information:

SSD 9368 - C31 - Independent Environmental Construction Audit Report #1

As per the requirements of condition C35 the Department must be issued with a response from the proponent to the Independent Audit Report, therefore the following attachments are provided for your information:

- Attachment A Response to Independent Audit non-compliances
- Attachment B Response to Independent Audit recommendations

Additionally, in accordance, with condition C34(a) of the Development Consent and with at least 7 days' notice, please be advised that the Department intend to make the Construction Compliance Report publicly available on it's website, no sooner than 60 days following the submission of this letter.

## Attachment A – Response to Independent Audit non-compliances

CoC	Consent heading	Compliance Requirement	Auditor's Comments / Observations	Compliance Status	SINSW Response and
					Actions
A25	Access to Information	A25 a(i) requires the documents referred to in condition A2 be	At the time of the audit, the EIS, Response to	Non-compliant	Non-compliance noted.
		made publicly available on the Project's website at least 48	Submissions and Supplementary Response to		The required documents
		hours before the commencement of construction.	Submissions were not available on the project's		have been uploaded to
			website.		SINSW website on
					25/9/20. No further
			Publish the documents required by condition A25		action required.
			on the Projects website.		
					The NCR is closed



## Attachment B – Response to Independent Audit recommendations

Audit Improvement Opportunities	Audit Improvement Recommendations	Department of Education Actions	Evidence of actions
•	spill kits were not in place at the refuelling area and hazardous goods and storage/laydown area		Spill kits relocated during usage at time of audit and relocated to the designated spill kit locations, in compliance with the Recommendation.
	sediment fence along the western perimeter boundary of the site (interface with adjacent development) is not keyed in correctly and in places requires repair/ replacement.		Weekly environmental inspections are conducted.  During these inspections all areas are rectified regularly.

