

**Site Location:** 3A & 3B Smalls Road, Ryde, NSW  
**Prepared for:** Richard Crookes  
**Date prepared:** 5 December 2018  
**Our Ref:** 18/12/05/3BSRR  
**Report Type:** Certificate

This document has been prepared by Urban Arbor Pty Ltd in relation to tree protection at the development site.

Urban Arbor inspected the tree protection on 5 December 2018. All demolition works have been completed and tree protection has been installed as per the following points.

All tree protection has been installed in accordance with the Arboricultural Impact Assessment by Priority Tree Services dated 2 May 2018. The tree protection includes fencing and TPZ signage. See images A, B, C, D, E, F, G, H, I, J, K, L, M and N.

Photographs of the tree protection have been included in the following pages. If you have any questions in relation to this certificate feel free to contact me on the details below.

Regards,



Bryce Claassens  
0450 554 715  
8004 2802  
bryce@urbanarbor.com.au  
Diploma of Arboriculture (AQF5)  
Cert III in Landscape Construction  
QTRA Registered User  
Member Arboriculture Australia

## Photographs



Image A: Tree protection fencing installed adjacent to tree 145 - 153.



Image B: Tree protection fencing installed adjacent to tree 158, 159, 160, 161, 162, 169, 170, 171 and 172.



Image C: Tree protection fencing installed adjacent to tree 163, 164 and 165.



Image D: Tree protection fencing installed adjacent to tree 154, 155 and 173.



Image E: Tree protection fencing installed adjacent to tree 101, 102, 133, 134 and 134A.



Image F: Tree protection fencing installed adjacent to tree 97, 98, 99 and 100.



Image G: Tree protection fencing installed adjacent to tree 94, 95, 96 and 121A.



Image H: Tree protection fencing installed adjacent to tree 115 and 116.



Image I: Tree protection fencing installed adjacent to tree 108, 109, 110, 111, 111A and 119.



Image J: Tree protection fencing installed adjacent to tree 117 and 118, showing failure of lowest primary branch on tree 117.



Image K: Tree protection fencing installed adjacent to tree 120, 141 and 142.



Image L: Tree protection fencing installed adjacent to tree 70, 70A, 71, 72, 73, 75 and 198.



Image M: Tree protection fencing installed adjacent to tree 182.



Image N: TPZ signage used on site.