



40m

Crack damage to the kerb and gutter.



50m

General views of the road surface, kerb and gutter.





50m

General views of the road surface, kerb and gutter.







50m

General views of the road surface, kerb and gutter.





60m

General views of the road surface, kerb and gutter.



60m

General views of the road surface, kerb and gutter.





60m

Crack damage to the kerb and gutter.







60m

Crack damage to the kerb and gutter.







70m

Gouging to the road surface.





70m

General views of the road surface, kerb and gutter.







70m

General views of the road surface, kerb and gutter.







70m

Views of the layback and gutter showing multiple cracks.







70m

Views of the layback and gutter showing multiple cracks.





80m

General views of the road surface, kerb and gutter.





80m

General views of the road surface, kerb and gutter.





90m

General views of the road surface, kerb and gutter.





90m

General views of the road surface, kerb and gutter.





90m

Crack damage to the kerb and gutter.







90m

Crack damage to the kerb and gutter.





100m

General views of the road surface, kerb and gutter.





100m

General views of the road surface, kerb and gutter.





100m

Various cracks and potholes to the road surface.







100m

Various cracks and potholes to the road surface.





100m

Crack damage to the kerb and gutter.





100m

Crack damage to the kerb and gutter.



The following inspection is of the road surface, kerb and gutter to the eastern side of Allambie Road starting from the intersection of Sunlea Place and heading towards the intersection of Arnhem Road.





0m

General views of the road surface, kerb and gutter.







0m

Crack damage noted to the kerb, gutter and stormwater drain.





0m

Crack damage noted to the kerb, gutter and stormwater drain.





10m

General views of the road surface, kerb and gutter.





10m

General views of the road surface, kerb and gutter.







10m

Crack damage noted to the kerb, gutter and layback.







10m

Crack damage noted to the kerb, gutter and layback.





20m

General views of the road surface, kerb and gutter.





20m

General views of the road surface, kerb and gutter.





20m

Crack damage to the kerb and gutter.







20m

Crack damage to the kerb and gutter.





30m

General views of the road surface, kerb and gutter.





30m

General views of the road surface, kerb and gutter.





30m

Crack damage to the kerb and gutter.

