Crack damage to the kerb and gutter.

General views of the road surface, kerb and gutter.


190m General views of the road surface, kerb and gutter.







General views of the road surface, kerb and gutter.














Views of the median strip, east of the roundabout.





The following inspection is of the footpath, kerb and gutter along the south side of Aquatic Drive starting at the entrance driveway of Arranounbai School and heading in an easterly direction towards the roundabout.




Om General views of the driveway crossover to Arranounbai School at the start point.





Om General views of the driveway crossover to Arranounbai School at the start point.





General views of the footpath, kerb and gutter.

10m Crack damage to the kerb and gutter. 12m View of the inspection lids.






20m Multiple cracks and damage to the kerb and gutter.







20m General views of the footpath, kerb and gutter.






26m Views of the tree and street sign to the Council strip.








General views of the footpath, kerb and gutter.





30m Various cracks throughout the kerb and gutter.




33m View of the inspection lid to the footpath.




General views of the footpath, kerb and gutter.






Various cracks throughout the kerb and gutter.



Views of the telegraph pole and tree to the Council strip.



45m General views of the footpath, kerb and gutter.





50m General views of the footpath, kerb and gutter.











