

90m

General views of the road surface.







100m

General views of the road surface.





100m

General views of the road surface.





110m

General views of the road surface.





110m

General views of the road surface.





120m

General views of the road surface.





120m

General views of the road surface.





130m

General views of the road surface.







130m

General views of the road surface.







130m

Crocodile cracking to the road surface.







130m

Crocodile cracking to the road surface.





140m


General views of the road surface.





140m

General views of the road surface.







150m

General views of the road surface.





150m

General views of the road surface.





160m

General views of the road surface at the end point.







160m

General views of the road surface at the end point.







160m

Crack damage throughout the road surface.





160m

Crack damage throughout the road surface.







The following inspection is of the kerb, gutter and road surface to the north side of Aquatic Drive starting at number 4 – 6 Aquatic Drive, heading east and finishing at the roundabout at the intersection of Aquatic Drive and Allambie Road.






Crack damage throughout the driveway, layback and gutter servicing number 4 – 6 Aquatic Drive.







Crack damage throughout the driveway, layback and gutter servicing number 4 – 6 Aquatic Drive.







Crack damage throughout the road surface fronting number 4 – 6 Aquatic Drive.





Crack damage throughout the road surface fronting number 4 – 6 Aquatic Drive.







Crack damage throughout the road surface fronting number 4 – 6 Aquatic Drive.



7m

Crack damage to the kerb and gutter.







10m

Crack damage throughout the road surface.







10m

Crack damage throughout the road surface.





15m

General views of the kerb, gutter and road surface.





15m

General views of the kerb, gutter and road surface.





15m

Crack damage to the kerb and gutter.





20m

General views of the kerb, gutter and road surface.







20m

General views of the kerb, gutter and road surface.







20m

Crack damage throughout the kerb and gutter.







20m

Crack damage throughout the kerb and gutter.







30m

General views of the kerb, gutter and road surface.





30m

General views of the kerb, gutter and road surface.





30m

Crack damage throughout the kerb and gutter.





30m

Crack damage throughout the kerb and gutter.





40m

General views of the kerb, gutter and road surface.





40m

General views of the kerb, gutter and road surface.

