

13m General view of the fencing and footpath.





































General views of the fencing and footpath at the end point..





The following inspection is of the driveway, kerb and gutter starting at the black fence at Arranounbai School and heading in a northerly direction towards Aquatic Drive.




0m General views of the road surface at the start point.





General views of the road surface at the start point. 0m





General views of the road surface, kerb and gutter looking towards Aquatic Drive from the start point.





Om General views of the road surface, kerb and gutter looking towards Aquatic Drive from the start point.






















Crack damage to the kerb, gutter and road surface to the western side of the driveway.





Crack damage to the kerb, gutter and road surface to the western side of the driveway.





Crack damage to the kerb, gutter and road surface to the western side of the driveway.





















Crack damage to the kerb, gutter and road surface.





















70m Crack damage to the road surface.





