

Cammeray Public School

Works notification | 21 March 2024

Dear staff, parents and carers,

On Monday 11 March, fragments of cement material suspected to contain asbestos were found in the grassed area in the northwestern boundary of Cammeray Public School.

The area was fenced off and made out of bounds. The fragments were removed for testing.

Testing confirmed that one of the fragments contained bonded asbestos, which means that it was attached to other materials such as cement or vinyl and cannot be crumbled by light pressure.

NSW Health explains that if bonded asbestos is mixed with cement or other hard bonding materials, and in good condition, it is likely to be low risk.

Cammeray Public School has a site-specific asbestos management plan for known asbestos in the ground. The fragments were found in an area listed on this plan.

On Friday 15 March, the area was inspected by an independent hygienist to ensure that there were no more fragments remaining. The school will be issued a clearance certificate and before the area is reopened.

Work was done in accordance with work, health and safety laws and the NSW Department of Education's Asbestos Management Plan. All work was completed by licensed and accredited asbestos contractors and monitored by occupational hygienists in strict accordance with all applicable legislation, regulations, policies, and guidelines.

The health, safety and wellbeing of the school and the local community are our highest priority.

If you have any questions about this work, please contact the NSW Department of Education on the details below.

Thank you for your cooperation during this important work.

