

Denman Public School

Works notification | 8 August 2023

Dear staff and parents/carers,

We identified 3 cracked windows in Building A and one cracked window in Building G at Denman Public School. The window frames are suspected to contain asbestos material, however the frames themselves were undamaged and the rooms remain safe for occupation.

We are following all the advice and protocols of independent asbestos hygienists and other experts.

Testing will be conducted by an independent hygienist to confirm the nature of the material and if remediation is needed.

If necessary, this area will be remediated in accordance with SafeWork NSW regulations and the NSW Department of Education's Asbestos Management Plan. All work will be completed by licensed and accredited independent asbestos contractors and monitored by occupational hygienists in strict accordance with all applicable legislation, regulations, policies, and guidelines.

The rooms will be inspected to ensure they have been fully remediated, and the school will receive a clearance certificate before they are reopened to students and staff following any required remediation work.

The health, safety, and wellbeing of the school and local community is our highest priority, and we will continue to keep the community updated.

Thank you for your understanding during this important work.

