

Glenvale School, North Entrance Campus

Works notification | 24 June 2025

Dear staff, parents, carers and neighbours,

Following periods of recent heavy rain, on Tuesday 10 June 2025, 2 small fragments of suspected asbestos-containing material were found on the ground on the southern corner of staff carpark at Glenvale School, North Entrance Campus.

The area where the fragments were found is not accessed by students and is identified on the school's site-specific asbestos management plan (SSAMP).

The area was fenced off and made inaccessible to students and staff. An independent hygienist was engaged to undertake testing, install air monitoring and provide advice.

Testing by the independent hygienist confirmed the fragments contained bonded asbestos. Site inspection work involved inspecting the ground and clearing the area for use.

NSW Health explains that "living or working with asbestos, or just being around it, is a low risk to your health as long as the asbestos is in good condition and not damaged".

The inspection occurred on Wednesday 11 June 2025 with safety measures in place. The independent hygienist provided clearance, and the outdoor area was reopened.

All work was completed by licensed asbestos contractors and inspected by an independent hygienist in accordance with work health and safety laws and the NSW Department of Education's Asbestos Management Plan.

The health, safety and wellbeing of all members of our school and the local community are our highest priorities.

Thank you for your cooperation during this important work.



Email: schoolinfrastructure@det.nsw.edu.au
Phone: 1300 482 651
www.schoolinfrastructure.nsw.gov.au

