

# Glenvale School, North Entrance Campus

## Works notification | 26 November 2025

Dear staff, parents and carers,

A cracked window has been temporarily secured in the large, southernmost classroom in Building G at Glenvale School, North Entrance Campus.

The putty in the window frame contains bonded asbestos. NSW Health explains that “living or working with asbestos, or just being around it, is a low risk to your health as long as the asbestos is in good condition and not damaged”.

School operations are not affected as the window is boarded up and the area is secure.

The window will be replaced this Saturday, 29 November under the guidance of an independent hygienist who will issue a clearance certificate when work is done.

The location of the broken window is not in an area identified on the School Asbestos Management Plan (SAMP). The plan will be updated to include this recent find as required.

All work will be done in accordance with work health and safety laws and the NSW Department of Education’s Asbestos Management Plan. Safety measures will be in place while work is being done. All work will be completed by licensed asbestos contractors and inspected by independent hygienists.

The health, safety, and wellbeing of all members of our school and the local community are our highest priorities. We will keep the community updated.



Email: [schoolinfrastructure@det.nsw.edu.au](mailto:schoolinfrastructure@det.nsw.edu.au)  
Phone: 1300 482 651  
[schoolinfrastructure.nsw.gov.au](http://schoolinfrastructure.nsw.gov.au)