Ku-ring-gai High School

Works notification | 14 March 2024

Dear staff, parents and carers,

During a routine site inspection at Ku-ring-gai High School on Sunday 3 March 2024, it was discovered the tarp on the roof in the Building L function room needed replacing. Upon further inspection it was discovered the eaves of the roof had been damaged and also needed to be replaced.

This building contains known asbestos in ceiling sheets as per the school's asbestos register.

The area was immediately fenced off and made out of bounds.

Work took place to replace the eaves on Friday 8 March, outside of school hours. After the work was completed, the area was inspected by the independent hygienist and the school was issued with a clearance certificate. The area has now been reopened.

All work was done in accordance with work, health and safety laws and the NSW Department of Education's Asbestos Management Plan. All work was completed by licensed and accredited asbestos contractors and monitored by independent hygienists in strict accordance with all applicable legislation, regulations, policies, and guidelines.

The health, safety, and wellbeing of the school and local community is our highest priority.

Thank you for your cooperation during this important work.

School Infrastructure NSW

Email: schoolinfrastructure@det.nsw.edu.au

Phone: 1300 482 651

www.schoolinfrastructure.nsw.gov.au



