

# Hunter School of Performing Arts

## Works notification

**22 October 2020**

Dear parents/carers,

Upcoming maintenance works at Hunter School of Performing Arts will require working with asbestos containing material. Testing conducted by an independent hygienist has confirmed that the material is bonded asbestos, which means it is attached to other material such as cement or vinyl and cannot be crumbled by light pressure.

As a precaution, the area has been cordoned off and will remain out of bounds to students and staff until remediation is completed.

The area will be remediated in accordance with the Department of Education's Asbestos Management Plan and SafeWork NSW regulations. All work will be completed by licensed and accredited asbestos contractors, and monitored by occupational hygienists in strict accordance with all applicable legislation, regulations, policies and guidelines.

The material is scheduled to be remediated from Block A on Thursday 29 October 2020. All asbestos containing material will be removed outside of school hours.

Testing will be completed to ensure the area has been fully remediated. The school will receive a clearance certificate before the area is open to students and staff. We will keep you informed if further material is found which requires removal.

The health, safety, and well-being of the school and the local community is our highest priority. Please be assured that the removal of this material will not pose a risk to the local community.

Thank you for your cooperation during this important work.

**For more information contact:**

School Infrastructure NSW  
Email: [schoolinfrastructure@det.nsw.edu.au](mailto:schoolinfrastructure@det.nsw.edu.au)  
Phone: 1300 482 651  
[www.schoolinfrastructure.nsw.gov.au](http://www.schoolinfrastructure.nsw.gov.au)