

Telarah Public School

Works notification | 28 July 2026

Dear staff, parents, and carers,

The health, safety, and wellbeing of all members of our school and the local community are our highest priorities.

On Monday 20 July 2026, a small hole was identified in the external wall lining of Building B at Telarah Public School

The wall lining in this building is known to contain bonded asbestos, as listed on the School Asbestos Management Plan.

As a precaution, the area was immediately isolated and an independent hygienist was engaged to undertake testing and provide advice.

Work to repair the hole and clean the nearby artificial grass took place on Wednesday 22 July 2026 outside of school hours. An independent hygienist inspected the area afterwards and provided clearance for it to be reopened.

Safety measures were in place during this work. All work was done in accordance with work health and safety laws and the NSW Department of Education's Asbestos Management Plan.

Asbestos was used widely in Australian building materials before 1990. We manage the presence of asbestos in NSW public schools by maintaining an Asbestos Management Plan for each school and engaging independent hygienists for expert advice.

If you have any questions about this, please contact the NSW Department of Education using the details below.

Thank you for your understanding and support during this important work.



Email: schoolinfrastructure@det.nsw.edu.au
Phone: 1300 482 651
www.schoolinfrastructure.nsw.gov.au