

Morrisset High School

Works notification | 9 June 2026

Dear staff, parents and carers,

The health, safety, and wellbeing of all members of our school and the local community are our highest priorities.

On Tuesday 9 June 2026, a cracked window was identified in a Building 3A classroom at Morrisset High School

The putty material in this window is known to contain bonded asbestos, as listed on the School Asbestos Management Plan.

The glass was immediately secured and an independent hygienist was engaged to conduct air monitoring and provide advice. The putty material is currently undisturbed and in good condition.

All air monitoring to date across the site has returned results below the minimum detectable limit, which means it is consistent with acceptable levels in ambient air (i.e. <0.01 fibres/mL) as per SafeWork NSW guidelines.

Work to remove the asbestos-containing putty and replace the glass will take on Saturday 13 June 2026.

All work will be done in accordance with work, health and safety laws. All work will be completed by experienced contractors and inspected by independent hygienists.

If you have any questions about this, please contact the NSW Department of Education on the details below.

Thank you for your understanding and support during this important work.



Email: schoolinfrastructure@det.nsw.edu.au
Phone: 1300 482 651
www.schoolinfrastructure.nsw.gov.au