

# Asbestos Register

(Hazardous Materials and Risk Assessment)

|                        |                                |
|------------------------|--------------------------------|
| School:                | Huskisson Public School (2199) |
| Region:                | Southern NSW AMU               |
| State Electorate:      | South Coast                    |
| Local Government Area: | Shoalhaven                     |

|                   |                      |
|-------------------|----------------------|
| Last Reviewed By: | Greencap 25-AUG-2016 |
| Last Revised By:  |                      |

|  |           |
|--|-----------|
| Historical Fibro In Grounds Investigations/Events  | <b>No</b> |
| <p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p> |           |

2199 - Huskisson Public School  
Site Plan (12662)



# Preface to Asbestos Register

## Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
  - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
  - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
  - o Any wall cavity
  - o Sub floor area, particularly formwork for slabs in/on ground,
  - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.  
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

## Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

## Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

## Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

## Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>  
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

## Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

### 3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

| Rating                     | Description  |
|----------------------------|--|
| Good condition (1)         | For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles  |
| Minimal damage (2)         | For non-friable asbestos that has a very small amount of damage, eg hairline cracks.   |
| Some damage / unsealed (3) | For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed. |
| Poor condition (4)         | For non-friable asbestos that has extensive damage. Visible asbestos debris  |
| Friable asbestos (5)       | Any occurrence of friable asbestos   |

| Product   | Material Description                       | Extent | Location                | Material Condition   | Risk Status | Remediation Priority | Result   |
|---|--|--------|-------------------------|----------------------|-------------|----------------------|--|
| <b>B00A - General Learning - 1969 - Brick/Veneer</b>  |  |        |                         |                      |             |                      |  |
| <b>Exterior</b>   |  |        |                         |                      |             |                      |  |
| Ceiling Voids - Raked Ceiling   | No Asbestos Found                          |        |                         |                      |             |                      |  |
| Underfloor Voids - Slab on Ground   | No Asbestos Found                          |        |                         |                      |             |                      |  |
| Gable Verge Lining  | Flat AC Sheeting                           |        |                         |                      |             |                      |  |
| Wall Linings Internal - Infill  | Flat AC Sheeting                           | 24     | Above and below windows | Good Condition (1)   | Low (1)     | Low Priority (2-3)   | Chrysotile (white asbestos)                            |
| Eaves Linings   | Flat AC Sheeting                           | 20m2   | South                   | Good Condition (1)   | Low (1)     | Low Priority (2-3)   | Chrysotile (white asbestos) , Amosite (brown asbestos) |
| <b>Interior</b>   |  |        |                         |                      |             |                      |  |
| <b>B00A - R0001 - Personal Effects Storage - 5.99 m2</b>  |  |        |                         |                      |             |                      |  |
| Floor Coverings Res/Textile   | Vinyl Tiles                                | 6m2    | Throughout              | Good Condition (1)   | Low (1)     | Low Priority (2-3)   | Chrysotile (white asbestos)                            |
| <b>B00A - R0002 - Distribution Board - .59 m2</b> <span style="float: right;"><b>Note: No inspection of live electrical installation</b></span> |  |        |                         |                      |             |                      |  |
| No Asbestos   |  |        |                         |                      |             |                      |  |
| <b>B00A - R0003 - Home Base - 57.28 m2</b>  |  |        |                         |                      |             |                      |  |
| Plant / Equipment - Thermacon Heater  | Encapsulated Asbestos material within unit | 3      | South, East             | Friable Asbestos (5) | Low (1)     | Low Priority (2-3)   | Assumed Asbestos                                       |
| <b>B00A - R0004 - Home Base Store - 5.97 m2</b>   |  |        |                         |                      |             |                      |  |
| No Asbestos   |  |        |                         |                      |             |                      |  |
| <b>B00A - R0007 - Toilets - Boys/Girls - 3.64 m2</b>  |  |        |                         |                      |             |                      |  |
| Wall Linings Internal   | Vinyl Sheet                                |        |                         |                      |             |                      |  |
| <b>B00A - R0008 - Personal Effects Storage - 6.26 m2</b>  |  |        |                         |                      |             |                      |  |
| Floor Coverings Res/Textile   | Vinyl Tiles                                | 7m2    | Throughout              | Good Condition (1)   | Low (1)     | Low Priority (2-3)   | Chrysotile (white asbestos)                            |
| <b>B00A - R0009 - Home Base Store - 2.72 m2</b>   |  |        |                         |                      |             |                      |  |
| Floor Coverings Res/Textile   | Vinyl Tiles                                | 3m2    | Throughout              | Good Condition (1)   | Low (1)     | Low Priority (2-3)   | Chrysotile (white asbestos)                            |
| <b>B00A - R0010 - External Movement - 43.37 m2</b>  |  |        |                         |                      |             |                      |  |
| Ceiling Structures/Linings  | Flat AC Sheeting                           | 41m2   | Throughout              | Minimal Damage (2)   | Low (1)     | Low Priority (2-3)   | Chrysotile (white asbestos) , Amosite (brown asbestos) |
| <b>B00A - R0012 - Home Base - 85.99 m2</b>  |  |        |                         |                      |             |                      |  |
| Plant / Equipment - Thermacon Heater  | Encapsulated Asbestos material within unit | 4      | Variable positions      | Friable Asbestos (5) | Low (1)     | Low Priority (2-3)   | Assumed Asbestos                                       |
| <b>B00B - Administration/Staff Facilities - 1969 - Brick/Veneer</b>   |  |        |                         |                      |             |                      |  |
| <b>Exterior</b>   |  |        |                         |                      |             |                      |  |
| Gable Verge Lining  | Flat AC Sheeting                           |        |                         |                      |             |                      |  |
| Wall Linings Internal - Infill  | Flat AC Sheeting                           | 12     | Above and below windows | Good Condition (1)   | Low (1)     | Low Priority (2-3)   | Chrysotile (white asbestos)                            |
| Eaves Linings   | Flat AC Sheeting                           | 20m2   | East                    | Good Condition (1)   | Low (1)     | Low Priority (2-3)   | Chrysotile (white asbestos) , Amosite (brown asbestos) |
| Ceiling Voids - Raked Ceiling   | No Asbestos Found                          |        |                         |                      |             |                      |  |
| Underfloor Voids - Slab on Ground   | No Asbestos Found                          |        |                         |                      |             |                      |  |
| <b>Interior</b>   |  |        |                         |                      |             |                      |  |
| <b>B00B - R0004 - Distribution Board - .6 m2</b> <span style="float: right;"><b>Note: No inspection of live electrical installation</b></span>  |  |        |                         |                      |             |                      |  |
| No Asbestos   |  |        |                         |                      |             |                      |  |
| <b>B00B - R0010 - Clerical Office - 11.58 m2</b>  |  |        |                         |                      |             |                      |  |
| No Asbestos   |  |        |                         |                      |             |                      |  |
| <b>B00B - R0011 - External Movement - 48.78 m2</b>  |  |        |                         |                      |             |                      |  |

|  |  |      |                         |                      |         |                    |   |
|--|--|------|-------------------------|----------------------|---------|--------------------|---|
| Ceiling Structures/Linings   | Flat AC Sheeting                           | 46m2 | Throughout              | Minimal Damage (2)   | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos), Amosite (brown asbestos) |
| <b>B00B - R0012 - Staff Room - 31.85 m2</b>                          |  |      |                         |                      |         |                    |   |
| No Asbestos  |  |      |                         |                      |         |                    |   |
| <b>B00B - R0013 - Staff Room Annexe - 8.62 m2</b>                    |  |      |                         |                      |         |                    |   |
| No Asbestos  |  |      |                         |                      |         |                    |   |
| <b>B00B - R0014 - Interview - 13.58 m2</b>                           |  |      |                         |                      |         |                    |   |
| No Asbestos  |  |      |                         |                      |         |                    |   |
| <b>B00B - R0015 - Interview - 13.58 m2</b>                           |  |      |                         |                      |         |                    |   |
| No Asbestos  |  |      |                         |                      |         |                    |   |
| <b>B00B - R0016 - Principal - 16.14 m2</b>                           |  |      |                         |                      |         |                    |   |
| No Asbestos  |  |      |                         |                      |         |                    |   |
| <b>B00B - R0017 - Security Store - 13.27 m2</b>                      |  |      |                         |                      |         |                    |   |
| No Asbestos  |  |      |                         |                      |         |                    |   |
| <b>B00B - R0018 - Clerical Office - 12.95 m2</b>                     |  |      |                         |                      |         |                    |   |
| No Asbestos  |  |      |                         |                      |         |                    |   |
| <b>B00B - R0019 - Entry Vestibule - 14.99 m2</b>                     |  |      |                         |                      |         |                    |   |
| No Asbestos  |  |      |                         |                      |         |                    |   |
| <b>B00B - R0020 - Movement - 12.9 m2</b>                             |  |      |                         |                      |         |                    |   |
| No Asbestos  |  |      |                         |                      |         |                    |   |
| <b>B00B - R0021 - Sick Bay - 8.29 m2</b>                             |  |      |                         |                      |         |                    |   |
| No Asbestos  |  |      |                         |                      |         |                    |   |
| <b>B00B - R0022 - Disabled Toilet - 5.02 m2</b>                      |  |      |                         |                      |         |                    |   |
| Wall Linings Internal  | Flat AC Sheeting                           |      |                         |                      |         |                    |   |
| <b>B00B - R0023 - Staff Toilet - 5.28 m2</b>                         |  |      |                         |                      |         |                    |   |
| Wall Linings Internal  | Flat AC Sheeting                           |      |                         |                      |         |                    |   |
| <b>B00B - R0024 - Staff Toilet - 4.38 m2</b>                         |  |      |                         |                      |         |                    |   |
| Wall Linings Internal  | Flat AC Sheeting                           |      |                         |                      |         |                    |   |
| <b>B00B - R0025 - Staff Toilet - 4.37 m2</b>                         |  |      |                         |                      |         |                    |   |
| Wall Linings Internal  | Flat AC Sheeting                           |      |                         |                      |         |                    |   |
| <b>B00B - R0026 - Staff Kitchen - 6.42 m2</b>                        |  |      |                         |                      |         |                    |   |
| No Asbestos  |  |      |                         |                      |         |                    |   |
| <b>B00C - General Learning/Pupil Facilities - 1969 - Brick/Block</b> |  |      |                         |                      |         |                    |   |
| <b>Exterior</b>  |  |      |                         |                      |         |                    |   |
| Ceiling Voids - Raked Ceiling  | No Asbestos Found                          |      |                         |                      |         |                    |   |
| Underfloor Voids - Slab on Ground                                    | No Asbestos Found                          |      |                         |                      |         |                    |   |
| Gable Verge Lining   | Flat AC Sheeting                           |      |                         |                      |         |                    |   |
| Wall Linings Internal - Infill                                       | Flat AC Sheeting                           | 20   | Above and below windows | Good Condition (1)   | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos)                           |
| Eaves Linings  | Flat AC Sheeting                           | 20m2 | West                    | Good Condition (1)   | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos), Amosite (brown asbestos) |
| <b>Interior</b>  |  |      |                         |                      |         |                    |   |
| <b>B00C - R0004 - Personal Effects Storage - 13.63 m2</b>            |  |      |                         |                      |         |                    |   |
| No Asbestos  |  |      |                         |                      |         |                    |   |
| <b>B00C - R0005 - General Storeroom - 6.63 m2</b>                    |  |      |                         |                      |         |                    |   |
| No Asbestos  |  |      |                         |                      |         |                    |   |
| <b>B00C - R0006 - Home Base - 54.4 m2</b>                            |  |      |                         |                      |         |                    |   |
| Plant / Equipment - Thermocon Heater                                 | Encapsulated Asbestos material within unit | 3    | Variable positions      | Friable Asbestos (5) | Low (1) | Low Priority (2-3) | Assumed Asbestos                                      |
| <b>B00C - R0007 - Home Base Store - 6.69 m2</b>                      |  |      |                         |                      |         |                    |   |
| No Asbestos  |  |      |                         |                      |         |                    |   |

| <b>B00C - R0008 - Toilets - Boys - 28.03 m2</b>            |                     |      |                                 |                    |         |                    |  |
|--|---------------------|------|---------------------------------|--------------------|---------|--------------------|--|
| Ceiling Structures/Linings                                 | Flat AC Sheeting    | 29m2 | Throughout                      | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) , Amosite (brown asbestos) |
| Partition Walls (Cubicles)                                 | Compressed AC Sheet | 12m2 | Throughout                      | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos)                            |
| <b>B00C - R0009 - Main Switch Board - 3.17 m2</b>          |                     |      |                                 |                    |         |                    |  |
| Electrical - Mounting Board                                | Resinous Board      | 1    | East                            | Minimal Damage (2) | Low (1) | Low Priority (2-3) | Assumed Asbestos                                       |
| Ceiling Structures/Linings                                 | Flat AC Sheeting    | 4m2  | Throughout                      | Minimal Damage (2) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) , Amosite (brown asbestos) |
| <b>B00C - R0010 - Toilets - Girls - 24.5 m2</b>            |                     |      |                                 |                    |         |                    |  |
| Ceiling Structures/Linings                                 | Flat AC Sheeting    | 25m2 | Throughout                      | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) , Amosite (brown asbestos) |
| Partition Walls (Cubicles)                                 | Compressed AC Sheet | 15m2 | Throughout                      | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos)                            |
| <b>B00C - R0011 - Cleaning Distributed Store - 2.22 m2</b> |                     |      |                                 |                    |         |                    |  |
| Ceiling Structures/Linings                                 | Flat AC Sheeting    | 3m2  | Throughout                      | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) , Amosite (brown asbestos) |
| <b>B00C - R0012 - General Storeroom - 5.27 m2</b>          |                     |      |                                 |                    |         |                    |  |
| Ceiling Structures/Linings                                 | Flat AC Sheeting    | 6m2  | Throughout                      | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) , Amosite (brown asbestos) |
| <b>B00C - R0013 - Cleaning Supplies - 5.82 m2</b>          |                     |      |                                 |                    |         |                    |  |
| Ceiling Structures/Linings                                 | Flat AC Sheeting    | 6m2  | Throughout                      | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) , Amosite (brown asbestos) |
| <b>B00C - R0015 - General Storeroom - 25.32 m2</b>         |                     |      |                                 |                    |         |                    |  |
| Ceiling Structures/Linings                                 | Flat AC Sheeting    | 26m2 | Throughout                      | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) , Amosite (brown asbestos) |
| Wall Linings Internal                                      | Flat AC Sheeting    | 30m2 | North, East, Variable positions | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) , Amosite (brown asbestos) |
| <b>B00C - R0016 - External Movement - 68.29 m2</b>         |                     |      |                                 |                    |         |                    |  |
| Ceiling Structures/Linings                                 | Flat AC Sheeting    | 64m2 | Throughout                      | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) , Amosite (brown asbestos) |
| <b>B00C - R0017 - External Movement - .71 m2</b>           |                     |      |                                 |                    |         |                    |  |
| Ceiling Structures/Linings                                 | Flat AC Sheeting    | 1m2  | Throughout                      | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) , Amosite (brown asbestos) |
| <b>B00C - R0018 - General Storeroom - 22.17 m2</b>         |                     |      |                                 |                    |         |                    |  |
| Ceiling Structures/Linings                                 | Flat AC Sheeting    | 23m2 | Throughout                      | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) , Amosite (brown asbestos) |
| Wall Linings Internal                                      | Flat AC Sheeting    | 20m2 | Variable positions              | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) , Amosite (brown asbestos) |
| <b>B00C - R0020 - Reading Area - 18.4 m2</b>               |                     |      |                                 |                    |         |                    |  |
| No Asbestos  |                     |      |                                 |                    |         |                    |  |
| <b>B00C - R0021 - Drinking Facilities - 22.58 m2</b>       |                     |      |                                 |                    |         |                    |  |
| No Asbestos  |                     |      |                                 |                    |         |                    |  |
| <b>B00C - R0022 - Home Base - 56.29 m2</b>                 |                     |      |                                 |                    |         |                    |  |
| No Asbestos  |                     |      |                                 |                    |         |                    |  |
| <b>B00D - Administration - 1970 - Brick/Block</b>          |                     |      |                                 |                    |         |                    |  |
| <b>Exterior</b>  |                     |      |                                 |                    |         |                    |  |
| Ceiling Voids - Raked Ceiling                              | No Asbestos Found   |      |                                 |                    |         |                    |  |
| Underfloor Voids - Slab on Ground                          | No Asbestos Found   |      |                                 |                    |         |                    |  |
| Eaves Linings  | Flat AC Sheeting    | 8m2  | Throughout                      | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) , Amosite (brown asbestos) |
| Wall Linings Internal - Infill                             | Flat AC Sheeting    | 1    | Above door                      | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) , Amosite (brown asbestos) |
| <b>Interior</b>  |                     |      |                                 |                    |         |                    |  |

|  |                   |  |
|--|-------------------|--|
| <b>B00D - R0001 - General Storeroom - 18.65 m2</b>       |                   |  |
| No Asbestos  |                   |  |
| <b>B00E - Library - 2010 - Fibre Cement Clad</b>         |                   |  |
| <b>Exterior</b>  |                   |  |
| Underfloor Voids - Slab on Ground                        | No Asbestos Found |  |
| Ceiling Voids  | No Asbestos Found |  |
| <b>Interior</b>  |                   |  |
| <b>B00E - R0001 - Movement - 31.18 m2</b>                |                   |  |
| No Asbestos  |                   |  |
| <b>B00E - R0002 - Reading Area - 91.94 m2</b>            |                   |  |
| No Asbestos  |                   |  |
| <b>B00E - R0003 - Library Office/Workroom - 20.46 m2</b> |                   |  |
| No Asbestos  |                   |  |
| <b>B00E - R0004 - Communications Room - 8.4 m2</b>       |                   |  |
| No Asbestos  |                   |  |
| <b>B00E - R0005 - Security Store - 9.89 m2</b>           |                   |  |
| No Asbestos  |                   |  |

## Demountables

### OS 606 13183 - Learning Unit - Standard With P.A.A A/C - Placement Date : 04-JAN-2017

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

### OS 810 13581 - FSU/Shelter/Stores - Placement Date : 30-JUN-1995

#### Exterior

|               |                     |         |                  |
|---------------|---------------------|---------|------------------|
| Eaves Linings | Flat AC Sheeting    | 25.92m2 | Assumed Asbestos |
| Landing       | Compressed AC Sheet | 1.2m2   | Assumed Asbestos |
| Step Treads   | Compressed AC Sheet | 1.08m2  | Assumed Asbestos |

#### Interior

##### R1- Canteen

|                            |                  |      |                  |
|----------------------------|------------------|------|------------------|
| End Wall Panel             | Flat AC Sheeting | 18m2 | Assumed Asbestos |
| Ceiling Structures/Linings | Flat AC Sheeting | 28m2 | Assumed Asbestos |

##### R2- Covered Area

|                            |                  |       |                  |
|----------------------------|------------------|-------|------------------|
| End Wall Panel             | Flat AC Sheeting | 18m2  | Assumed Asbestos |
| Ceiling Structures/Linings | Flat AC Sheeting | 109m2 | Assumed Asbestos |

##### R3- Store

|                            |                  |     |                  |
|----------------------------|------------------|-----|------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 4m2 | Assumed Asbestos |
|----------------------------|------------------|-----|------------------|

##### R4- Sports Store

|                            |                  |      |                  |
|----------------------------|------------------|------|------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 10m2 | Assumed Asbestos |
|----------------------------|------------------|------|------------------|

##### R5- Garden Store

|                            |                  |     |                  |
|----------------------------|------------------|-----|------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 8m2 | Assumed Asbestos |
|----------------------------|------------------|-----|------------------|

##### R6- Change Room

|                            |                  |     |                  |
|----------------------------|------------------|-----|------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 3m2 | Assumed Asbestos |
|----------------------------|------------------|-----|------------------|

##### R7- Store

|                            |                  |     |                  |
|----------------------------|------------------|-----|------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 2m2 | Assumed Asbestos |
|----------------------------|------------------|-----|------------------|

### NS 101 13718 - Learning Unit - Double Primary/PAA - Placement Date : 11-DEC-2006

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

### OS 606 17092 - Learning Unit - Standard With P.A.A A/C - Placement Date : 04-JAN-2017

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found