


Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Hillsborough Public School (4318)
Region:	Hunter/Central Coast AMU
State Electorate:	Charlestown
Local Government Area:	Lake Macquarie

Last Reviewed By:	WSP 13-JUN-2015
Last Revised By:	AECOM 25-JUN-2020

Historical Fibro In Grounds Investigations/Events	No
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - Administration/Library - 1977 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	35.00m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	
External Wall Structure - Cladding	Flat AC Sheeting	20.00	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00A - R0001 - Principal - 21.14 m2							
No Asbestos							
B00A - R0002 - Duplicating Workroom - 12.43 m2							
No Asbestos							
B00A - R0003 - Clerical Office - 12.69 m2							
No Asbestos							
B00A - R0004 - External Movement - 20.29 m2							
No Asbestos							
B00A - R0005 - Entry Vestibule - 15.94 m2							
No Asbestos							
B00A - R0006 - Deputy Principal - 12.61 m2							
No Asbestos							
B00A - R0007 - Sick Bay - 9.12 m2							
No Asbestos							
B00A - R0008 - Staff Toilet - 8.92 m2							
No Asbestos							
B00A - R0009 - Staff Toilet - 7.56 m2							
No Asbestos							
B00A - R0010 - Interview - 12.61 m2							
No Asbestos							
B00A - R0011 - Movement - 12.44 m2							
No Asbestos							
B00A - R0012 - Staff Room - 70.37 m2							
No Asbestos							
B00A - R0013 - General Storeroom - 13.2 m2							
No Asbestos							
B00A - R0014 - Distribution Board - 3.4 m2							
						Note: No inspection of live electrical installation	
Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0015 - Cleaning Distributed Store - 3.37 m2							
B00A - R0017 - Disabled Toilet - 10.04 m2							
No Asbestos							
B00A - R0018 - Uniform Shop - 14.7 m2							
No Asbestos							
B00A - R0019 - Staff Room Annexe - 12.1 m2							
No Asbestos							
B00A - R0021 - External Movement - 23.05 m2							
No Asbestos							
B00A - R0022 - External Movement - 9.32 m2							
No Asbestos							

B00A - R0023 - Movement - 9.8 m2							
No Asbestos							
B00A - R0024 - Movement - 21.69 m2							
No Asbestos							
B00A - R0025 - External Stairs - 10.26 m2							
No Asbestos							
B00A - R0026 - Movement - 8.52 m2							
No Asbestos							
B00A - R0027 - External Movement - 2.22 m2							
No Asbestos							
B00A - R1001 - External Movement - 25.56 m2							
Ceiling Structures/Linings	Flat AC Sheeting	26m2	Throughout	Some Damage - Unsealed (3)	Medium (2)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R1002 - Library Office/Workroom - 25.15 m2							
No Asbestos							
B00A - R1003 - Toilets - Girls - 3.55 m2							
No Asbestos							
B00A - R1004 - Movement - 15.39 m2							
No Asbestos							
B00A - R1005 - Distribution Board - 2.16 m2							
Note: No inspection of live electrical installation							
Partition Walls (Cubicles)	Compressed AC Sheet	3.00m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)	
Floor Coverings Res/Textile	Textile	4.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R1006 - Toilets - Boys - 3.56 m2							
No Asbestos							
B00A - R1007 - Cleaning Distributed Store - 2.18 m2							
Floor Coverings Res/Textile	Textile	4.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R1011 - Library Office/Workroom - 9.19 m2							
No Asbestos							
B00A - R1012 - K.L.A. Store - 12.43 m2							
No Asbestos							
B00A - R1013 - Reading Area - 221.48 m2							
No Asbestos							
B00A - R1014 - Special Programs Room - 27.07 m2							
No Asbestos							
B00A - R1015 - Special Programs Room - 34.85 m2							
No Asbestos							
B00A - R1016 - External Stairs - 21.99 m2							
Ceiling Structures/Linings	Flat AC Sheeting	60.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - General Learning - 1977 - Brick/Block							
Exterior							
External Wall Structure - Cladding	Flat AC Sheeting	32.00	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Eaves Linings	Flat AC Sheeting	150.00m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Eaves Linings	Flat AC Sheeting	150.00m2	East & West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						

Interior							
B00B - R0001 - Home Base - 56.04 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
B00B - R0002 - Home Base Store - 4.27 m2							
No Asbestos							
B00B - R0003 - Personal Effects Storage - 23.81 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00B - R0004 - External Movement - 13.23 m2							
Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
B00B - R0005 - Home Base Store - 4.27 m2							
No Asbestos							
B00B - R0006 - Home Base - 56.19 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
B00B - R0007 - Home Base - 55.88 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
B00B - R0008 - Home Base Store - 4.33 m2							
No Asbestos							
B00B - R0010 - External Movement - 13.34 m2							
Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
B00B - R0011 - Home Base Store - 4.27 m2							
No Asbestos							
B00B - R0012 - Home Base - 55.81 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
B00B - R0013 - Personal Effects Storage - 14.74 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00B - R0014 - Toilets - Boys/Disabled Cubicle - 8.68 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00C - General Learning/Pupil Facilities - 1977 - Brick/Veneer							
Exterior							
Eaves Linings	Flat AC Sheeting	52.00m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids - Slab on Ground	Non Accessible Area						
Interior							
B00C - R0001 - Home Base - 56.96 m2							
No Asbestos							
B00C - R0002 - Home Base Store - 4.28 m2							
No Asbestos							
B00C - R0003 - External Movement - 5.33 m2							
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0004 - Movement - 19.08 m2							
No Asbestos							

B00C - R0005 - Home Base Store - 4.23 m2							
No Asbestos							
B00C - R0006 - Home Base - 57.6 m2							
No Asbestos							
B00C - R0007 - General Storeroom - 26.87 m2							
No Asbestos							
B00C - R0008 - General Storeroom - 4.8 m2							
No Asbestos							
B00C - R0009 - Movement - 3.54 m2							
No Asbestos							
B00D - General Learning/Pupil Facilities - 1972 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	40m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
External Wall Structure - Cladding	Flat AC Sheeting	20.00	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids - Slab on Ground	Non Accessible Area						
Interior							
B00D - R0001 - Toilets - Boys - 7.85 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	7m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00D - R0002 - Movement - 18.46 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00D - R0003 - General Storeroom - 5.97 m2							
No Asbestos							
B00D - R0004 - Toilets - Girls - 7.99 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	7m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00D - R0005 - Craft Store - 7.36 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00D - R0006 - Home Base Store - 4.61 m2							
No Asbestos							
B00D - R0007 - Practical Activities - 1hb - 3.61 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00D - R0008 - Home Base - 50.74 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
B00D - R0009 - Home Base - 65.26 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
B00D - R0010 - Practical Activities - 1hb - 7.48 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00D - R0011 - External Movement - 4.75 m2							

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Wall Linings Internal	Flat AC Sheeting						
B00D - R0012 - External Movement - 7.04 m2							
Wall Linings Internal	Flat AC Sheeting						
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
B00F - Administration - 1963 - Timber							
Exterior							
Eaves Linings	Flat AC Sheeting	20m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Wall Cladding	Flat AC Sheeting						
Interior							
B00F - R0001 - Movement - 16.91 m2							
Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00F - R0002 - Craft Store - 8.79 m2							
No Asbestos							
B00F - R0004 - Movement - 11.5 m2							
No Asbestos							
B00F - R0005 - General Storeroom - 16.67 m2							
No Asbestos							
B00F - R0006 - General Storeroom - 10.91 m2							
No Asbestos							
B00F - R0007 - Clerical Office - 10.43 m2							
No Asbestos							
B00F - R0008 - Main Switch Board - .3 m2							
No Asbestos							
B00G - Communal Facilities/Pupil Facilities - 1977 - Brick/Block							
Exterior							
Wall Cladding	Flat AC Sheeting						
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00G - R0001 - External Movement - 68.68 m2							
Ceiling Structures/Linings	Flat AC Sheeting	70m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G - R0002 - Communal Space - 242.25 m2							
No Asbestos							
B00G - R0003 - Raised Platform - 45.8 m2							
Ceiling Structures/Linings	Flat AC Sheeting	46m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G - R0004 - Hall Chair Store - 12.32 m2							
Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G - R0006 - Canteen Office/Store - 3.37 m2							

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G- R0007 - Canteen Office/Store - 4.73 m2							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	10m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G- R0008 - Canteen - 33.91 m2							
Ceiling Structures/Linings	Flat AC Sheeting	34m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles	34m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G- R0009 - External Movement - 37.64 m2							
Ceiling Structures/Linings	Flat AC Sheeting	38m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G- R0010 - Distribution Board - 1.54 m2							
Note: No inspection of live electrical installation							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	2m2	South & East	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)	Chrysotile (white asbestos)
B00G- R0011 - Toilets - Boys - 9.07 m2							
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet	8m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G- R0012 - Toilets - Girls - 9.55 m2							
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet	8m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G- R0013 - General Storeroom - 12.25 m2							
No Asbestos							
B00G- R0014 - External Movement - 31.29 m2							
Ceiling Structures/Linings	Flat AC Sheeting	32m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G- R0015 - Movement - 58.47 m2							
No Asbestos							
B00G- R0016 - Cleaning Distributed Store - 2.73 m2							
No Asbestos							
B00G- R0017 - Cleaning Distributed Store - .71 m2							
No Asbestos							
B00H - Pupil Facilities - 1975 - Brick/Block							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids - Slab on Ground	Non Accessible Area						
Eaves Linings	Flat AC Sheeting	11.00m2	Northeast and southwest	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Interior							
B00H- R0001 - Toilets - Girls - 26.18 m2							
Ceiling Structures/Linings	Flat AC Sheeting	27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00H- R0002 - Cleaning Distributed Store - 1.56 m2							

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00H - R0003 - Movement - 19.92 m2							
Ceiling Structures/Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00H - R0004 - Sports Store - 11.2 m2							
Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00H - R0005 - Toilets - Boys - 24.1 m2							
Ceiling Structures/Linings	Flat AC Sheeting	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00H - R0006 - General Assistant/Bulk Store - 12.14 m2							
Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00H - R0007 - External Movement - 17.47 m2							
Ceiling Structures/Linings	Flat AC Sheeting	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00I - Other-After School Care - 2010 - Steel							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	Flat AC Sheeting	2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)	Chrysotile (white asbestos)
Interior							
B00I - R0001 - External Movement - 10.81 m2							
No Asbestos							
B00I - R0002 - Child Care Centre - 91.95 m2							
No Asbestos							
B00I - R0003 - Staff Kitchen - 12.05 m2							
No Asbestos							
B00I - R0004 - General Storeroom - 5.77 m2							
No Asbestos							
B00I - R0005 - General Storeroom - 3.49 m2							
No Asbestos							
B00I - R0006 - Toilets - Girls - 2.21 m2							
No Asbestos							
B00I - R0007 - Disabled Toilet - 4.14 m2							
No Asbestos							
B00I - R0008 - Toilets - Boys - 2.19 m2							
No Asbestos							
B00I - R0009 - Practical Activities - 17.38 m2							
No Asbestos							
B00I - R0010 - Staff Toilet - 1.65 m2							
No Asbestos							
B00I - R0011 - Clerical Office - 12 m2							
No Asbestos							
B00J - General Learning - 2010 - Brick/Veneer							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids - Slab on Ground	Non Accessible Area						
Interior							
B00J - R0001 - External Movement - 86.35 m2							
No Asbestos							

B00J - R0002 - Practical Activities - 1hb - 18.89 m2	
No Asbestos	
B00J - R0003 - Home Base Store - 6.14 m2	
No Asbestos	
B00J - R0004 - Home Base - 60.28 m2	
No Asbestos	
B00J - R0005 - Withdrawal Space - 2hb - 11.55 m2	
No Asbestos	
B00J - R0006 - Practical Activities - 1hb - 18.94 m2	
No Asbestos	
B00J - R0007 - Home Base - 60.28 m2	
No Asbestos	
B00J - R0008 - Home Base Store - 6.14 m2	
No Asbestos	
B00J - R0009 - Practical Activities - 1hb - 18.89 m2	
No Asbestos	
B00J - R0010 - Home Base Store - 6.14 m2	
No Asbestos	
B00J - R0011 - Home Base - 60.28 m2	
No Asbestos	
B00J - R0012 - Withdrawal Space - 2hb - 11.55 m2	
No Asbestos	
B00J - R0013 - Practical Activities - 1hb - 18.94 m2	
No Asbestos	
B00J - R0014 - Home Base - 60.28 m2	
No Asbestos	
B00J - R0015 - Home Base Store - 6.14 m2	
No Asbestos	

Demountables

There are no Demountable(s) Located at this school as per the AMS records as of 09-Sep-2020