


Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Hay War Memorial High School (8119)
Region:	Southern NSW AMU
State Electorate:	Murray
Local Government Area:	Hay

Last Reviewed By:	WSP 12-JUL-2016
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	No
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>

<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - Various - 1972 - Brick/Block							
Exterior							
Underfloor Voids - Slab on Ground	No Asbestos Found						
Ceiling Voids	Non Accessible Area						
Interior							
B00A - R0001 - Cleaning Supplies Store - 15.08 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Floor Coverings Res/Textile	Vinyl Tiles						
Wall Linings Internal	Flat AC Sheeting						
B00A - R0002 - Sport Equipment Store - 11.37 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00A - R0003 - Shower/Change - 21.74 m2							
Ceiling Structures/Linings	Compressed AC Sheet	3m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00A - R0004 - Toilets-Girls - 32.46 m2							
Wall Linings Internal	Flat AC Sheeting						
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0005 - Student Drinking Facilities - 111.09 m2							
Wall Linings Internal	Compressed AC Sheet						
B00A - R0006 - Student Canteen - 39.95 m2							
No Asbestos							
B00A - R0007 - Staff - Toilet - 6.16 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
Plant / Equipment - Incinerator	Insulation Material	1	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
B00A - R0008 - Pantry - 5.83 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
Floor Coverings Res/Textile	Vinyl Tiles	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0009 - Distribution Board Cupboard - .45 m2							
						Note: No inspection of live electrical installation	
No Asbestos							
B00A - R0010 - Toilets-Boys - 32.4 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Partition Walls (Cubicles)	Compressed AC Sheet	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting						
B00A - R0011 - Shower/Change - 18.99 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						

B00A - R0012 - Sport Equipment Store - 13.94 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00A - R0013 - Staff Study - 14.99 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0014 - Movement - 76.24 m2							
Partition Walls (Cubicles)	Compressed AC Sheet						
B00A - R0015 - Movement - 45.51 m2							
Partition Walls (Cubicles)	Compressed AC Sheet						
B00A - R0016 - Stairs - 9.53 m2							
No Asbestos							
B00A - R0017 - Stairs - 9.57 m2							
No Asbestos							
B00A - R1001 - Art Learning Space - 76.95 m2							
No Asbestos							
B00A - R1002 - Kiln Space - 13.37 m2							
No Asbestos							
B00A - R1003 - Resources Store - 7.59 m2							
No Asbestos							
B00A - R1004 - Movement - 54.9 m2							
No Asbestos							
B00A - R1005 - Materials Technology L.S. - 79.21 m2							
No Asbestos							
B00A - R1006 - Resource/Project Store - 3.77 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R1007 - Dust Extraction Space - 4.22 m2							
No Asbestos							
B00A - R1008 - Materials Store - 17.27 m2							
No Asbestos							
B00A - R1009 - Music Store - 21.91 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R1010 - Cleaning Store - Distributed - 3.14 m2							
No Asbestos							
B00A - R1011 - Distribution Board Cupboard - .45 m2							
				Note: No inspection of live electrical installation			
Electrical - Mounting Board	Resinous Board	1	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R1012 - Music Learning Space - 65.75 m2							
No Asbestos							
B00A - R1013 - Stairs - 9.51 m2							
No Asbestos							
B00A - R1014 - Stairs - 9.34 m2							
No Asbestos							
B00C - General Learning/Administration - 1923 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	100m2	North facing, South facing, East facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Crocidolite (blue asbestos)

Wall Cladding	Flat AC Sheeting	20m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Crocidolite (blue asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00C - R0001 - General Learning Space - 55.12 m2							
No Asbestos							
B00C - R0002 - General Learning Space - 48.84 m2							
No Asbestos							
B00C - R0003 - General Storeroom - 3.83 m2							
Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Clerical Error - No Sample Taken
B00C - R0004 - Public Entry - 24.32 m2							
Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Clerical Error - No Sample Taken
B00C - R0007 - Movement - 23.72 m2							
Ceiling Structures/Linings	Flat AC Sheeting	24m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Crocidolite (blue asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Crocidolite (blue asbestos)
B00C - R0008 - Principal Office - 14.19 m2							
No Asbestos							
B00C - R0009 - Staff - Toilet - 2.88 m2							
Floor Coverings Res/Textile	Vinyl Tiles	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Clerical Error - No Sample Taken
Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Clerical Error - No Sample Taken
B00C - R0010 - General Storeroom - 1.48 m2							
Floor Coverings Res/Textile	Vinyl Tiles	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Clerical Error - No Sample Taken
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Clerical Error - No Sample Taken
B00C - R0011 - Duplicating Workroom - 14.12 m2							
No Asbestos							
B00C - R0012 - Computer Learning Space - 48.83 m2							
No Asbestos							
B00C - R0013 - General Learning Space - 54.84 m2							
No Asbestos							
B00C - R0014 - Movement - 6 m2							
Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Crocidolite (blue asbestos)
Electrical - Mounting Board	Resinous Board	1	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0015 - General Learning Space - 54.85 m2							
No Asbestos							
B00C - R0016 - General Learning Space - 49.04 m2							
No Asbestos							

B00C - R0017 - General Storeroom - 17.34 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00C - R0018 - Movement - 60.72 m2							
No Asbestos							
B00C - R0019 - Multi-Purpose Space - 121.7 m2							
No Asbestos							
B00C - R0020 - General Storeroom - 11.53 m2							
Wall Linings Internal	Flat AC Sheeting						
B00C - R0021 - General Storeroom - 12.35 m2							
Wall Linings Internal	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00C - R0022 - Garden Store Room - 12.35 m2							
Wall Linings Internal	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00C - R0023 - General Assistants - 17.09 m2							
No Asbestos							
B00C - R0025 - General Storeroom - 7.94 m2							
Floor Coverings Res/Textile	Vinyl Tiles	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0026 - Cleaning Store - Distributed - 8.84 m2							
Floor Coverings Res/Textile	Vinyl Tiles	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0027 - Staff Study - 22.31 m2							
No Asbestos							
B00C - R0028 - Commonroom - 59.21 m2							
No Asbestos							
B00C - R0029 - Staff Kitchen - 7.69 m2							
No Asbestos							
B00C - R0030 - Staff - Toilet - 9.29 m2							
No Asbestos							
B00C - R0031 - Staff - Toilet - 3.7 m2							
No Asbestos							
B00C - R0032 - Movement - 217.39 m2							
Floor Coverings Res/Textile	Vinyl Tiles	0.5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Clerical Error - No Sample Taken
Wall Linings Internal - Electrical Box/ Cabinet	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting						
B00C - R0033 - Movement - 4.94 m2							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Crocidolite (blue asbestos)
B00C - R0034 - Movement - 3.8 m2							
No Asbestos							
B00C - R0035 - Stairs - 2.22 m2							
No Asbestos							
B00C - R0036 - Clerical Office - 26.61 m2							
No Asbestos							
B00C - R0037 - Audio Visual Workroom - 14.4 m2							

No Asbestos		
B00C - R0038 - Deputy Principal - 14.52 m2		
No Asbestos		
B00C - R0039 - Movement - 2.91 m2		
No Asbestos		
B00C - R1001 - Staff Study - 13.76 m2		
No Asbestos		
B00C - R1002 - General Storeroom - 6.46 m2		
Floor Coverings Res/Textile	Vinyl Tiles	
B00C - R1003 - Staff Study - 14.36 m2		
No Asbestos		
B00C - R1004 - Darkroom Space - 13.42 m2		
No Asbestos		
B00C - R1005 - Staff Study - 9.51 m2		
No Asbestos		
B00C - R1006 - Movement - 17.8 m2		
No Asbestos		
B00C - R1007 - Staff Study - 14.08 m2		
No Asbestos		
B00C - R1008 - Stairs - 9.31 m2		
No Asbestos		
B00G - Agricultural Science - 1984 - Metal Shed		
Exterior		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00G - R0001 - Machine Storage - 24.11 m2		
No Asbestos		
B00K - Various - 1982 - Brick/Veneer		
Exterior		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Eaves Linings	Flat AC Sheeting	
Ceiling Voids	No Asbestos Found	
Interior		
B00K - R0001 - Food Technology L.S. - 102.91 m2		
No Asbestos		
B00K - R0002 - Movement - 12.48 m2		
Ceiling Structures/Linings	Flat AC Sheeting	
B00K - R0003 - Computer Learning Space - 50.12 m2		
No Asbestos		
B00K - R0004 - Staff Study - 20.52 m2		
No Asbestos		
B00K - R0005 - Computer Learning Space - 67.11 m2		
No Asbestos		
B00K - R0006 - Materials Store - 9.38 m2		
No Asbestos		
B00K - R0007 - Computer Resource - 10.46 m2		
No Asbestos		

B00K - R0008 - Distribution Board Cupboard - 1.12 m2							Note: No inspection of live electrical installation
Ceiling Structures/Linings	Flat AC Sheeting						
B00K - R0009 - Cleaning Store - Distributed - 1.98 m2							
No Asbestos							
B00K - R0010 - Staff - Toilet - 4.44 m2							
No Asbestos							
B00K - R0011 - Staff Study - 24.64 m2							
No Asbestos							
B00K - R0012 - Toilets-Boys - 19.04 m2							
No Asbestos							
B00K - R0013 - Toilets-Girls - 19.25 m2							
Plant / Equipment - Incinerator	Insulation Material	1	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
B00K - R0014 - General Learning Space - 45.81 m2							
No Asbestos							
B00K - R0015 - General Learning Space - 45.74 m2							
No Asbestos							
B00K - R0016 - General Learning Space - 45.95 m2							
No Asbestos							
B00K - R0017 - General Learning Space - 46.08 m2							
No Asbestos							
B00K - R0018 - Senior Study - 25.81 m2							
No Asbestos							
B00K - R0019 - General Storeroom - 5.81 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00K - R0020 - Staff Study - 30.9 m2							
No Asbestos							
B00K - R0021 - Laboratory L.S. - 78.93 m2							
No Asbestos							
B00K - R0022 - Growing/Breeding - 15.31 m2							
No Asbestos							
B00K - R0023 - Staff Study - 15.25 m2							
No Asbestos							
B00K - R0024 - General Storeroom - 4.84 m2							
No Asbestos							
B00K - R0025 - Food/Research Space - 10.05 m2							
No Asbestos							
B00K - R0026 - Laundry - 15.31 m2							
No Asbestos							
B00K - R0027 - Movement - 116.16 m2							
No Asbestos							
B00K - R0028 - Movement - 7.35 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00K - R0029 - Movement - 2.32 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00K - R0030 - Movement - 9.27 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00K - R0031 - Movement - 7.76 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00K - R0032 - Movement - 10.99 m2							
Ceiling Structures/Linings	Flat AC Sheeting						

B00L - Multi Purpose Facilities - 2003 - Brick/Veneer

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00L - M0001 - Plant - 28.59 m2

No Asbestos

B00L - M0002 - Plant - 29.19 m2

No Asbestos

B00L - M0003 - Plant - 15.09 m2

No Asbestos

B00L - M0004 - Plant - 14.67 m2

No Asbestos

B00L - R0001 - Toilets - Boys - 18.46 m2

No Asbestos

B00L - R0002 - Toilets - Girls - 18.41 m2

No Asbestos

B00L - R0003 - Staff Kitchen - 21.12 m2

No Asbestos

B00L - R0004 - Movement - 14.46 m2

No Asbestos

B00L - R0005 - Movement - 38.77 m2

No Asbestos

B00L - R0006 - Movement - 27.53 m2

No Asbestos

B00L - R0007 - Movement - 14.59 m2

No Asbestos

B00L - R0008 - Sport Equipment Store - 24.7 m2

No Asbestos

B00L - R0009 - Chair Store - 33.46 m2

No Asbestos

B00L - R0010 - Stage - 76.95 m2

No Asbestos

B00L - R0011 - Multi-Purpose Space - 607.68 m2

No Asbestos

B00L - R0012 - Cleaning Supplies Store - 4.78 m2

No Asbestos

B00L - R0013 - Toilets - Girls - 14.34 m2

No Asbestos

B00L - R0014 - Main Switchroom - 10.59 m2

No Asbestos

B00L - R0015 - Toilets - Boys - 14.59 m2

No Asbestos

B00L - R0016 - Toilets-Disabled - 4.95 m2

No Asbestos

B00L - R0017 - Distribution Board Cupboard - 2.2 m2

Note: No inspection of live electrical installation

No Asbestos

B00L - R0018 - Movement - 80.18 m2

No Asbestos

B00L - R0019 - Movement - 49.15 m2

No Asbestos

B00L - R0020 - Movement - 3.44 m2		
No Asbestos		
B00L - R0021 - Movement - 3.44 m2		
No Asbestos		
B00L - R0022 - Movement - 3.46 m2		
No Asbestos		
B00L - R0023 - Movement - 3.46 m2		
No Asbestos		
B00M - Other - 2008 - Steel		
Exterior		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00M - R0001 - Sports Store - 57.21 m2		
No Asbestos		
B00M - R0002 - General Storeroom - 80.26 m2		
No Asbestos		
B00N - Technological & Applied Studies - 2009 - Brick/Veneer		
Exterior		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00N - R0001 - General Learning Space - Type 9 - 54.39 m2		
No Asbestos		
B00N - R0002 - Practical Activities - 8.86 m2		
No Asbestos		
B00N - R0003 - Practical Activities - 8.93 m2		
No Asbestos		
B00N - R0004 - General Learning Space - Type 8 - 54.17 m2		
No Asbestos		
B00N - R0005 - Metal Technology Bay - 11.86 m2		
No Asbestos		
B00N - R0006 - Plant - 8.61 m2		
No Asbestos		
B00N - R0007 - Distribution Board Cupboard - .59 m2		
No Asbestos		
B00N - R0008 - G.L.S. Store - 50.81 m2		
No Asbestos		
B00N - R0009 - G.L.S. Store - 35.91 m2		
No Asbestos		
B00N - R0010 - Dust Extraction Space - 12.39 m2		
No Asbestos		
B00N - R0011 - G.L.S. Store - 12.74 m2		
No Asbestos		
B00N - R0012 - Materials Workshop - Type 2 - 84.39 m2		
No Asbestos		
B00N - R0013 - Materials Workshop - Type 3 - 121.94 m2		
No Asbestos		
B00N - R0014 - External Movement - 35.67 m2		

Note: No inspection of live electrical installation

No Asbestos		
B00N - R0015 - External Movement - 33.84 m2		
No Asbestos		
B00N - R0016 - External Movement - 35.98 m2		
No Asbestos		
B00O - Science Learning - 2009 - Brick/Veneer		
Exterior		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00O - R0001 - Science Laboratory - 100.45 m2		
No Asbestos		
B00O - R0002 - General Learning Space - Type 3 - 49.11 m2		
No Asbestos		
B00O - R0003 - G.L.S. Store - 9.76 m2		
No Asbestos		
B00O - R0004 - General Learning Space - Type 3 - 49.11 m2		
No Asbestos		
B00O - R0005 - Botany/Zoology - 9.76 m2		
No Asbestos		
B00O - R0006 - Communication Space - 16.19 m2		
No Asbestos		
B00O - R0007 - Botany/Zoology - 18.7 m2		
No Asbestos		
B00O - R0008 - Botany/Zoology - 14.45 m2		
No Asbestos		
B00O - R0009 - Chemical Store - 11.66 m2		
No Asbestos		
B00O - R0010 - Apparatus Store - 15.03 m2		
No Asbestos		
B00O - R0011 - Distribution Board Cupboard - .82 m2		
		Note: No inspection of live electrical installation
No Asbestos		
B00O - R0012 - Plant - 7.61 m2		
No Asbestos		
B00O - R0013 - Preparation - 30.23 m2		
No Asbestos		
B00O - R0014 - External Movement - 147 m2		
No Asbestos		
B00P - Library - 2009 - Brick/Veneer		
Exterior		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00P - R0001 - Main Area - 137.99 m2		
No Asbestos		
B00P - R0002 - Library Administration - 13 m2		
No Asbestos		
B00P - R0003 - G.L.S. Store - 17.67 m2		
No Asbestos		

B00P - R0004 - Main Switch Board Cupboard - .6 m2	
No Asbestos	
B00P - R0005 - Seminar/Study - 40.49 m2	
No Asbestos	
B00P - R0006 - Seminar - 12.95 m2	
No Asbestos	
B00P - R0007 - Seminar - 12.95 m2	
No Asbestos	
B00P - R0008 - Communication Space - 10.93 m2	
No Asbestos	
B00P - R0009 - Plant - 5.71 m2	
No Asbestos	
B00P - R0010 - Toilets-Disabled - 6.69 m2	
No Asbestos	
B00P - R0011 - Entry - 26.45 m2	
No Asbestos	
B00P - R0012 - External Movement - 7.83 m2	
No Asbestos	
B00P - R0013 - External Movement - 6.74 m2	
No Asbestos	
B00Q - General Learning - 2010 - Brick/Veneer	
Exterior	
Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found
Interior	
B00Q - R0001 - Computer Learning Space - 91.86 m2	
No Asbestos	
B00Q - R0002 - Seminar - Type 2 - 19.12 m2	
No Asbestos	
B00Q - R0003 - Resources Store - 10.01 m2	
No Asbestos	
B00Q - R0004 - Computer Store - 9.11 m2	
No Asbestos	
B00Q - R0005 - External Movement - 29.46 m2	
No Asbestos	

Demountables

There are no Demountable(s) Located at this school as per the AMS records as of 09-Sep-2020