


# Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Hunter Sports High School (8233)
Region:	Hunter/Central Coast AMU
State Electorate:	Charlestown
Local Government Area:	Lake Macquarie

Last Reviewed By:	WSP 30-JUN-2017
Last Revised By:	AECOM 23-JUN-2020

Historical Fibro In Grounds Investigations/Events	<b>Yes</b>
Please refer to the latest site specific Asbestos Management Plans available from the Department's website (Refer to Note 2).	



# Preface to Asbestos Register

## Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
  - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
  - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
  - o Any wall cavity
  - o Sub floor area, particularly formwork for slabs in/on ground,
  - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.  
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

## Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

## Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

## Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

## Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>

<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

## Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

### 3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
<b>B00N - Storage - 2005 - Metal Shed</b>							
<b>Exterior</b>							
Ceiling Voids	No Asbestos Found						
Underfloor Voids - Slab on Ground	Non Accessible Area						
<b>Interior</b>							
<b>B00N - R0001 - General Assistants - 53.01 m2</b>							
No Asbestos							
<b>B00P - Physical Education - 2009 - Steel</b>							
<b>Exterior</b>							
Ceiling Voids - Flat Roof	No Asbestos Found						
Underfloor Voids - Slab on Ground	Non Accessible Area						
<b>Interior</b>							
<b>B00P - R0001 - Change - 56.94 m2</b>							
No Asbestos							
<b>B00P - R0002 - Movement - 24.55 m2</b>							
No Asbestos							
<b>B00Q - Physical Education - 2012 - Brick/Veneer</b>							
<b>Exterior</b>							
Ceiling Voids - Raked Ceiling	No Asbestos Found						
Underfloor Voids - Slab on Ground	Non Accessible Area						
<b>Interior</b>							
<b>B00Q - R0001 - Toilets-Boys - 26.11 m2</b>							
No Asbestos							
<b>B00Q - R0002 - Distribution Board Cupboard - 3.22 m2</b>							
No Asbestos							<b>Note: No inspection of live electrical installation</b>
<b>B00Q - R0003 - Large Equipment Store - 39.71 m2</b>							
No Asbestos							
<b>B00Q - R0004 - Toilets-Girls - 34.94 m2</b>							
No Asbestos							
<b>B00Q - R0005 - Chair Store - 38.72 m2</b>							
No Asbestos							
<b>B00Q - R0006 - Fitness Laboratory - 102.42 m2</b>							
No Asbestos							
<b>B00Q - R0007 - Seminar - 21.56 m2</b>							
No Asbestos							
<b>B00Q - R0008 - Fitness Store - 26 m2</b>							
No Asbestos							
<b>B00Q - R0009 - Staff Study - 36.66 m2</b>							
No Asbestos							
<b>B00Q - R0010 - First Aid - 25.13 m2</b>							
No Asbestos							
<b>B00Q - R0011 - External Movement - 36.73 m2</b>							
No Asbestos							
<b>B00Q - R0012 - Access Staff Shower/Toilet - 9.3 m2</b>							
No Asbestos							
<b>B00Q - R0013 - Plant - .62 m2</b>							
No Asbestos							
<b>B00Q - R0014 - Cleaning Store - Distributed - 3.69 m2</b>							
No Asbestos							

<b>B00Q - R0015 - First Aid - 18.53 m2</b>		
No Asbestos		
<b>B00Q - R0016 - Communications Cupboard - 1.18 m2</b>		
No Asbestos		
<b>B00Q - R0017 - Staff - Toilet - 6.14 m2</b>		
No Asbestos		
<b>B00Q - R0018 - Stairs - 10.22 m2</b>		
No Asbestos		
<b>B00Q - R0019 - Change - 33.68 m2</b>		
No Asbestos		
<b>B00Q - R0020 - Change - 36.75 m2</b>		
No Asbestos		
<b>B00Q - R0021 - Change - 36.75 m2</b>		
No Asbestos		
<b>B00Q - R0022 - Change - 33.04 m2</b>		
No Asbestos		
<b>B00Q - R0023 - Stairs - 9.42 m2</b>		
No Asbestos		
<b>B00Q - R0024 - Store - 6.82 m2</b>		
No Asbestos		
<b>B00Q - R0025 - Gymnasium - 1263.74 m2</b>		
No Asbestos		
<b>B00Q - R1001 - Movement - 173.73 m2</b>		
No Asbestos		
<b>B00Q - R1002 - Movement - 56.38 m2</b>		
No Asbestos		
<b>B00Q - R1003 - Stairs - 8.35 m2</b>		
No Asbestos		
<b>B00Q - R1004 - Stairs - 10.56 m2</b>		
No Asbestos		
<b>B00R - Storage - 2015 - Steel</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	Non Accessible Area	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00R - R0001 - Bulk Store - 79.33 m2</b>		
No Asbestos		
<b>B00R - R0002 - Movement - 7.38 m2</b>		
No Asbestos		
<b>B00R - R0003 - Bulk Store - 79.91 m2</b>		
No Asbestos		
<b>B00S - Multi Purpose Facilities - 2018 - Brick/Veneer</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	Non Accessible Area	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00S - R0001 - Gymnasium - 711.32 m2</b>		
No Asbestos		
<b>B00S - R0002 - Plant - .54 m2</b>		
No Asbestos		
<b>B00S - R0003 - Communications Cupboard - 16.85 m2</b>		

No Asbestos		
<b>B00S - R0004 - Distribution Board Cupboard - 1 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00S - R0005 - Movement - 6.72 m2</b>		
No Asbestos		
<b>B00S - R0006 - Gymnasium - 144.57 m2</b>		
No Asbestos		
<b>B00S - R0007 - Movement - 22.49 m2</b>		
No Asbestos		
<b>B00S - R0008 - Access Student Shower/Toilet/Change - 6.25 m2</b>		
No Asbestos		
<b>B00S - R0009 - Staff - Toilet - 2.51 m2</b>		
No Asbestos		
<b>B00S - R0010 - Staff - Toilet - 2.51 m2</b>		
No Asbestos		
<b>B00S - R0011 - Toilets-Disabled - 5.18 m2</b>		
No Asbestos		
<b>B00S - R0012 - Staff - Toilet - 3.1 m2</b>		
No Asbestos		
<b>B00S - R0013 - Staff Shower - 3.1 m2</b>		
No Asbestos		
<b>B00S - R0014 - Control Room - 9.42 m2</b>		
No Asbestos		
<b>B00S - R0015 - Store - 22.36 m2</b>		
No Asbestos		
<b>B00S - R0016 - Outdoor Equipment Store - 20.21 m2</b>		
No Asbestos		
<b>B00S - R0017 - Chair Store - 47.87 m2</b>		
No Asbestos		
<b>B00S - R0018 - Large Equipment Store - 24.88 m2</b>		
No Asbestos		
<b>B00S - R0019 - Office/Store - 14.04 m2</b>		
No Asbestos		
<b>B00S - R0020 - Student Canteen - 53.54 m2</b>		
No Asbestos		
<b>B00S - R0021 - Store - 25.99 m2</b>		
No Asbestos		
<b>B00S - R0022 - External Movement - 101.7 m2</b>		
No Asbestos		
<b>B00S - R0023 - Plant - .66 m2</b>		
No Asbestos		
<b>B00S - R0024 - External Movement - 58.58 m2</b>		
No Asbestos		
<b>B00T - Administration/General Learning - 2018 - Concrete Framed</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	Non Accessible Area	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00T - R0001 - General Learning Space - Type 6 - 57.9 m2</b>		
No Asbestos		
<b>B00T - R0002 - Store - 7.63 m2</b>		

No Asbestos	
<b>B00T - R0003 - Seminar - 28.03 m2</b>	
No Asbestos	
<b>B00T - R0004 - General Learning Space - Type 4 - 61.67 m2</b>	
No Asbestos	
<b>B00T - R0005 - General Learning Space - Type 7 - 61.34 m2</b>	
No Asbestos	
<b>B00T - R0006 - Seminar - 23.91 m2</b>	
No Asbestos	
<b>B00T - R0007 - General Learning Space - Type 6 - 66.36 m2</b>	
No Asbestos	
<b>B00T - R0008 - Kitchen - Type 1 - 100.5 m2</b>	
No Asbestos	
<b>B00T - R0009 - Preparation - 22.5 m2</b>	
No Asbestos	
<b>B00T - R0010 - Store - 12.15 m2</b>	
No Asbestos	
<b>B00T - R0011 - Laundry - 11.17 m2</b>	
No Asbestos	
<b>B00T - R0012 - Pantry - 17.85 m2</b>	
No Asbestos	
<b>B00T - R0013 - Kitchen - Type 1 - 102.12 m2</b>	
No Asbestos	
<b>B00T - R0014 - Movement - 6.58 m2</b>	
No Asbestos	
<b>B00T - R0015 - Stairs - 31.5 m2</b>	
No Asbestos	
<b>B00T - R0016 - Staff - Toilet - 2.11 m2</b>	
No Asbestos	
<b>B00T - R0017 - Staff - Toilet - 2.12 m2</b>	
No Asbestos	
<b>B00T - R0018 - Toilets-Girls - 38.49 m2</b>	
No Asbestos	
<b>B00T - R0019 - Toilets-Disabled - 6.38 m2</b>	
No Asbestos	
<b>B00T - R0020 - Toilets-Boys - 33.74 m2</b>	
No Asbestos	
<b>B00T - R0021 - Store - 10.26 m2</b>	
No Asbestos	
<b>B00T - R0022 - Plant - 11.08 m2</b>	
No Asbestos	
<b>B00T - R0023 - General Learning Space - Type 8 - 50.76 m2</b>	
No Asbestos	
<b>B00T - R0024 - Materials Workshop - Type 2 - 7.4 m2</b>	
No Asbestos	
<b>B00T - R0025 - Project Store - Type 1 - 42.32 m2</b>	
No Asbestos	
<b>B00T - R0026 - Archive Store - 23.62 m2</b>	
No Asbestos	
<b>B00T - R0027 - Cleaning Supplies Store - 7.36 m2</b>	
No Asbestos	
<b>B00T - R0028 - Materials Workshop - Type 2 - 26.39 m2</b>	

No Asbestos	
<b>B00T - R0029 - Materials Workshop - Type 3 - 131.63 m2</b>	
No Asbestos	
<b>B00T - R0030 - General Learning Space - Type 9 - 59.11 m2</b>	
No Asbestos	
<b>B00T - R0031 - General Learning Space - Type 9 - 59.16 m2</b>	
No Asbestos	
<b>B00T - R0032 - Materials Store - Type 1 - 69.93 m2</b>	
No Asbestos	
<b>B00T - R0033 - Outdoor Workshop - 97.96 m2</b>	
No Asbestos	
<b>B00T - R0034 - Dust Extraction Space - 8.03 m2</b>	
No Asbestos	
<b>B00T - R0035 - Materials Store - Type 1 - 25.23 m2</b>	
No Asbestos	
<b>B00T - R0036 - Workshop Area - 140.81 m2</b>	
No Asbestos	
<b>B00T - R0037 - General Learning Space - Type 8 - 58.43 m2</b>	
No Asbestos	
<b>B00T - R0038 - Project Store - Type 1 - 43.35 m2</b>	
No Asbestos	
<b>B00T - R0040 - Garden Store Room - 18.01 m2</b>	
No Asbestos	
<b>B00T - R0041 - Store - 6.94 m2</b>	
No Asbestos	
<b>B00T - R0042 - Movement - 21.86 m2</b>	
No Asbestos	
<b>B00T - R0043 - External Movement - 480.75 m2</b>	
No Asbestos	
<b>B00T - R0044 - Movement - 4.04 m2</b>	
No Asbestos	
<b>B00T - R0045 - Lift - 2.62 m2</b>	
No Asbestos	
<b>B00T - R0046 - Movement - 6.71 m2</b>	
No Asbestos	
<b>B00T - R0047 - L.P.G Store - .87 m2</b>	
No Asbestos	
<b>B00T - R0048 - Welding Area - 11.3 m2</b>	
No Asbestos	
<b>B00T - R0049 - Outdoor Workshop - 105.08 m2</b>	
No Asbestos	
<b>B00T - R0050 - External Stairs - 13.64 m2</b>	
No Asbestos	
<b>B00T - R0051 - External Stairs - 13.57 m2</b>	
No Asbestos	
<b>B00T - R0052 - Covered Area - 443.67 m2</b>	
No Asbestos	
<b>B00T - R1001 - General Learning Space - 60.23 m2</b>	
No Asbestos	
<b>B00T - R1002 - Access Student Shower/Toilet/Change - 6.07 m2</b>	
No Asbestos	

<b>B00T - R1003 - Laundry - 6.34 m2</b>	
No Asbestos	
<b>B00T - R1004 - Access Student Shower/Toilet/Change - 13.57 m2</b>	
No Asbestos	
<b>B00T - R1005 - Movement - 77.19 m2</b>	
No Asbestos	
<b>B00T - R1006 - General Learning Space - Type 1 - 58.29 m2</b>	
No Asbestos	
<b>B00T - R1007 - General Learning Space - Type 1 - 59.09 m2</b>	
No Asbestos	
<b>B00T - R1008 - General Learning Space - Type 1 - 58.92 m2</b>	
No Asbestos	
<b>B00T - R1009 - Movement - 38.12 m2</b>	
No Asbestos	
<b>B00T - R1010 - General Learning Space - Type 1 - 57.96 m2</b>	
No Asbestos	
<b>B00T - R1011 - General Learning Space - Type 1 - 55.36 m2</b>	
No Asbestos	
<b>B00T - R1012 - Stairs - 15.92 m2</b>	
No Asbestos	
<b>B00T - R1013 - Movement - 9.2 m2</b>	
No Asbestos	
<b>B00T - R1014 - Movement - 23.63 m2</b>	
No Asbestos	
<b>B00T - R1015 - Staff - Toilet - 4.01 m2</b>	
No Asbestos	
<b>B00T - R1016 - Staff - Toilet - 3.1 m2</b>	
No Asbestos	
<b>B00T - R1017 - G.L.S. Store - 14.77 m2</b>	
No Asbestos	
<b>B00T - R1018 - G.L.S. Store - 14.88 m2</b>	
No Asbestos	
<b>B00T - R1019 - General Learning Space - Type 3 - 81.55 m2</b>	
No Asbestos	
<b>B00T - R1020 - Seminar - 26.65 m2</b>	
No Asbestos	
<b>B00T - R1021 - Store - 7.72 m2</b>	
No Asbestos	
<b>B00T - R1022 - General Learning Space - Type 3 - 67.34 m2</b>	
No Asbestos	
<b>B00T - R1023 - General Learning Space - Type 3 - 74.51 m2</b>	
No Asbestos	
<b>B00T - R1024 - Seminar - 33.06 m2</b>	
No Asbestos	
<b>B00T - R1025 - General Learning Space - Type 3 - 74.39 m2</b>	
No Asbestos	
<b>B00T - R1026 - Science Laboratory - 101.51 m2</b>	
No Asbestos	
<b>B00T - R1027 - Preparation - 22.15 m2</b>	
No Asbestos	
<b>B00T - R1028 - Chemical Store - 13.64 m2</b>	



No Asbestos	
<b>B00T - R1029 - Apparatus Storage - 15.52 m2</b>	
No Asbestos	
<b>B00T - R1030 - Apparatus Storage - 59.31 m2</b>	
No Asbestos	
<b>B00T - R1033 - Science Laboratory - 103.63 m2</b>	
No Asbestos	
<b>B00T - R1034 - General Learning Space - Type 1 - 59 m2</b>	
No Asbestos	
<b>B00T - R1035 - General Learning Space - Type 1 - 59.65 m2</b>	
No Asbestos	
<b>B00T - R1036 - General Learning Space - Type 1 - 59.86 m2</b>	
No Asbestos	
<b>B00T - R1037 - Seminar - 37.82 m2</b>	
No Asbestos	
<b>B00T - R1038 - General Learning Space - Type 1 - 61.75 m2</b>	
No Asbestos	
<b>B00T - R1039 - General Learning Space - Type 1 - 59.02 m2</b>	
No Asbestos	
<b>B00T - R1040 - Movement - 18.61 m2</b>	
No Asbestos	
<b>B00T - R1041 - General Learning Space - Type 1 - 59.72 m2</b>	
No Asbestos	
<b>B00T - R1042 - General Learning Space - 60.25 m2</b>	
No Asbestos	
<b>B00T - R1043 - General Learning Space - 59.7 m2</b>	
No Asbestos	
<b>B00T - R1044 - Project Store - Type 1 - 6.08 m2</b>	
No Asbestos	
<b>B00T - R1045 - Cleaning Store - Distributed - 2.08 m2</b>	
No Asbestos	
<b>B00T - R1046 - Distribution Board Cupboard - .79 m2</b>	<b>Note: No inspection of live electrical installation</b>
No Asbestos	
<b>B00T - R1047 - Principal Office - 20.53 m2</b>	
No Asbestos	
<b>B00T - R1048 - Interview/Meeting - 12.56 m2</b>	
No Asbestos	
<b>B00T - R1049 - Interview/Meeting - 14.38 m2</b>	
No Asbestos	
<b>B00T - R1050 - Interview/Office - Type 1 - 12.11 m2</b>	
No Asbestos	
<b>B00T - R1051 - Visitors Office - 12.36 m2</b>	
No Asbestos	
<b>B00T - R1052 - Public Reception - 52.58 m2</b>	
No Asbestos	
<b>B00T - R1053 - Store - 8.41 m2</b>	
No Asbestos	
<b>B00T - R1054 - Administration - Clerical - 89.5 m2</b>	
No Asbestos	
<b>B00T - R1055 - Clinic - 13.88 m2</b>	
No Asbestos	
<b>B00T - R1056 - Access Staff Shower/Toilet - 6.11 m2</b>	

No Asbestos	
<b>B00T - R1057 - Clinic - 13.3 m2</b>	
No Asbestos	
<b>B00T - R1058 - Student Waiting - 11.44 m2</b>	
No Asbestos	
<b>B00T - R1059 - Deputy Principal Office - 13.39 m2</b>	
No Asbestos	
<b>B00T - R1060 - Deputy Principal Office - 13.09 m2</b>	
No Asbestos	
<b>B00T - R1061 - Tea Room - 5.64 m2</b>	
No Asbestos	
<b>B00T - R1062 - Staff - Toilet - 3.67 m2</b>	
No Asbestos	
<b>B00T - R1063 - Staff - Toilet - 3.67 m2</b>	
No Asbestos	
<b>B00T - R1064 - Communications Cupboard - 4.7 m2</b>	
No Asbestos	
<b>B00T - R1065 - Distribution Board Cupboard - 1.6 m2</b>	<b>Note: No inspection of live electrical installation</b>
No Asbestos	
<b>B00T - R1066 - Deputy Principal Office - 13.49 m2</b>	
No Asbestos	
<b>B00T - R1067 - Movement - 36.78 m2</b>	
No Asbestos	
<b>B00T - R1068 - Stairs - 16.22 m2</b>	
No Asbestos	
<b>B00T - R1069 - Administration - Executive - 12.93 m2</b>	
No Asbestos	
<b>B00T - R1070 - Movement - 21.71 m2</b>	
No Asbestos	
<b>B00T - R1071 - Outdoor Learning Space - Type 1 - 42.47 m2</b>	
No Asbestos	
<b>B00T - R1072 - Staff - Toilet - 3.1 m2</b>	
No Asbestos	
<b>B00T - R1073 - Staff - Toilet - 3.1 m2</b>	
No Asbestos	
<b>B00T - R1074 - External Movement - 135.69 m2</b>	
No Asbestos	
<b>B00T - R1075 - External Movement - 300.23 m2</b>	
No Asbestos	
<b>B00T - R1077 - Lift - 2.62 m2</b>	
No Asbestos	
<b>B00T - R1078 - External Movement - 23.57 m2</b>	
No Asbestos	
<b>B00T - R1079 - External Movement - 32.14 m2</b>	
No Asbestos	
<b>B00T - R1080 - Staff - Toilet - 3.89 m2</b>	
No Asbestos	
<b>B00T - R1081 - Movement - 11.81 m2</b>	
No Asbestos	
<b>B00T - R1082 - Outdoor Learning Area - 44.76 m2</b>	
No Asbestos	
<b>B00T - R1083 - External Movement - 47.62 m2</b>	

No Asbestos	
<b>B00T - R1084 - Stairs - 15.37 m2</b>	
No Asbestos	
<b>B00T - R1085 - External Stairs - 13.83 m2</b>	
No Asbestos	
<b>B00T - R1086 - External Stairs - 13.99 m2</b>	
No Asbestos	
<b>B00T - R2002 - Staff Lounge - 126.08 m2</b>	
No Asbestos	
<b>B00T - R2003 - Staff Study - 394.41 m2</b>	
No Asbestos	
<b>B00T - R2004 - Toilet - Lobby - 16.9 m2</b>	
No Asbestos	
<b>B00T - R2005 - Access Staff Shower/Toilet - 5.95 m2</b>	
No Asbestos	
<b>B00T - R2006 - Staff - Toilet - 2.75 m2</b>	
No Asbestos	
<b>B00T - R2007 - Staff - Toilet - 2.75 m2</b>	
No Asbestos	
<b>B00T - R2008 - Staff - Toilet - 3 m2</b>	
No Asbestos	
<b>B00T - R2009 - Staff - Toilet - 3.2 m2</b>	
No Asbestos	
<b>B00T - R2010 - Staff - Toilet - 2.74 m2</b>	
No Asbestos	
<b>B00T - R2011 - Cleaning Store - Distributed - 2.74 m2</b>	
No Asbestos	
<b>B00T - R2013 - Interview/Meeting - 12.15 m2</b>	
No Asbestos	
<b>B00T - R2014 - Interview/Meeting - 12.15 m2</b>	
No Asbestos	
<b>B00T - R2015 - Interview/Meeting - 12.15 m2</b>	
No Asbestos	
<b>B00T - R2016 - Interview/Meeting - 11.72 m2</b>	
No Asbestos	
<b>B00T - R2017 - General Learning Space - Type 1 - 58.65 m2</b>	
No Asbestos	
<b>B00T - R2018 - Seminar - 10.15 m2</b>	
No Asbestos	
<b>B00T - R2019 - Store - 9.41 m2</b>	
No Asbestos	
<b>B00T - R2020 - General Learning Space - Type 1 - 58.93 m2</b>	
No Asbestos	
<b>B00T - R2021 - Seminar - 20.87 m2</b>	
No Asbestos	
<b>B00T - R2022 - General Learning Space - Type 1 - 58.65 m2</b>	
No Asbestos	
<b>B00T - R2023 - Store - 10.72 m2</b>	
No Asbestos	
<b>B00T - R2024 - Seminar - 11.84 m2</b>	
No Asbestos	

<b>B00T - R2025 - Shared Learning Space - 68.45 m2</b>		
No Asbestos		
<b>B00T - R2026 - General Learning Space - Type 1 - 58.49 m2</b>		
No Asbestos		
<b>B00T - R2027 - General Learning Space - Type 1 - 58.01 m2</b>		
No Asbestos		
<b>B00T - R2028 - Store - 16.27 m2</b>		
No Asbestos		
<b>B00T - R2029 - Seminar - 14.81 m2</b>		
No Asbestos		
<b>B00T - R2031 - General Learning Space - Type 1 - 63.26 m2</b>		
No Asbestos		
<b>B00T - R2032 - General Learning Space - Type 1 - 59.33 m2</b>		
No Asbestos		
<b>B00T - R2033 - General Learning Space - Type 1 - 62.77 m2</b>		
No Asbestos		
<b>B00T - R2034 - Seminar - 25.77 m2</b>		
No Asbestos		
<b>B00T - R2035 - General Learning Space - Type 1 - 61.88 m2</b>		
No Asbestos		
<b>B00T - R2036 - Shared Learning Space - 91.67 m2</b>		
No Asbestos		
<b>B00T - R2037 - Movement - 76.6 m2</b>		
No Asbestos		
<b>B00T - R2038 - Stairs - 36.53 m2</b>		
No Asbestos		
<b>B00T - R2039 - Movement - 7.33 m2</b>		
No Asbestos		
<b>B00T - R2040 - Stairs - 20.54 m2</b>		
No Asbestos		
<b>B00T - R2041 - Movement - 86.6 m2</b>		
No Asbestos		
<b>B00U - Library/General Learning - 2018 - Brick/Veneer</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	Non Accessible Area	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00U - R0001 - Toilets-Boys - 30.84 m2</b>		
No Asbestos		
<b>B00U - R0002 - Student Shower - 45.63 m2</b>		
No Asbestos		
<b>B00U - R0003 - Toilet - Lobby - 9.43 m2</b>		
No Asbestos		
<b>B00U - R0004 - Store - .69 m2</b>		
No Asbestos		
<b>B00U - R0005 - Shower - 44.99 m2</b>		
No Asbestos		
<b>B00U - R0006 - Toilets-Girls - 29.99 m2</b>		
No Asbestos		
<b>B00U - R0007 - Store - 15.85 m2</b>		
No Asbestos		

<b>B00U - R1001 - Performance Workshop - 97.87 m2</b>	
No Asbestos	
<b>B00U - R1002 - Practice/Seminar - 9.67 m2</b>	
No Asbestos	
<b>B00U - R1003 - Performing Arts Store - 15.9 m2</b>	
No Asbestos	
<b>B00U - R1004 - Practice/Seminar - 10.18 m2</b>	
No Asbestos	
<b>B00U - R1005 - General Learning Space - Type 1 - 58.42 m2</b>	
No Asbestos	
<b>B00U - R1006 - Movement - 8.84 m2</b>	
No Asbestos	
<b>B00U - R1007 - General Learning Space - 59.44 m2</b>	
No Asbestos	
<b>B00U - R1009 - Visual Arts Workshop - 52.82 m2</b>	
No Asbestos	
<b>B00U - R1010 - General Learning Space - Type 12 - 60.11 m2</b>	
No Asbestos	
<b>B00U - R1011 - Visual Arts Store - 19.85 m2</b>	
No Asbestos	
<b>B00U - R1012 - Visual Arts Store - 24.84 m2</b>	
No Asbestos	
<b>B00U - R1013 - Visual Arts Workshop - 53.08 m2</b>	
No Asbestos	
<b>B00U - R1014 - Kiln Space - 8.75 m2</b>	
No Asbestos	
<b>B00U - R1015 - Pottery Store - 11.05 m2</b>	
No Asbestos	
<b>B00U - R1016 - Cleaning Store - Distributed - 4.32 m2</b>	
No Asbestos	
<b>B00U - R1017 - General Learning Space - Type 1 - 63.17 m2</b>	
No Asbestos	
<b>B00U - R1018 - Seminar - 17.57 m2</b>	
No Asbestos	
<b>B00U - R1019 - General Learning Space - 101.4 m2</b>	
No Asbestos	
<b>B00U - R1020 - General Learning Space - Type 1 - 61.67 m2</b>	
No Asbestos	
<b>B00U - R1021 - Movement - 37.32 m2</b>	
No Asbestos	
<b>B00U - R1022 - G.L.S. Store - 16.39 m2</b>	
No Asbestos	
<b>B00U - R1023 - Seminar - 17.77 m2</b>	
No Asbestos	
<b>B00U - R1024 - General Learning Space - 59.2 m2</b>	
No Asbestos	
<b>B00U - R1025 - General Learning Space - 75.71 m2</b>	
No Asbestos	
<b>B00U - R1026 - Seminar - 27.83 m2</b>	
No Asbestos	
<b>B00U - R1027 - Seminar - 26.26 m2</b>	
No Asbestos	

<b>B00U - R1028 - Study Space - 33.59 m2</b>	
No Asbestos	
<b>B00U - R1029 - Study Space - 33.75 m2</b>	
No Asbestos	
<b>B00U - R1030 - External Movement - 40.92 m2</b>	
No Asbestos	
<b>B00U - R1031 - Toilets-Unisex - 3.11 m2</b>	
No Asbestos	
<b>B00U - R1032 - Toilets-Unisex - 3.11 m2</b>	
No Asbestos	
<b>B00U - R1033 - Toilets-Unisex - 3.01 m2</b>	
No Asbestos	
<b>B00U - R1034 - Toilets-Unisex - 3.2 m2</b>	
No Asbestos	
<b>B00U - R1035 - Toilets-Unisex - 3.22 m2</b>	
No Asbestos	
<b>B00U - R1036 - Tea Room - 8.41 m2</b>	
No Asbestos	
<b>B00U - R1037 - Access Student Shower/Toilet/Change - 6.42 m2</b>	
No Asbestos	
<b>B00U - R1038 - Computer Store - 10.47 m2</b>	
No Asbestos	
<b>B00U - R1039 - Computer Learning Space - 64.76 m2</b>	
No Asbestos	
<b>B00U - R1040 - Movement - 12.15 m2</b>	
No Asbestos	
<b>B00U - R1041 - System Administrators Office - 13.11 m2</b>	
No Asbestos	
<b>B00U - R1042 - Toilets-Disabled - 7.13 m2</b>	
No Asbestos	
<b>B00U - R1043 - Toilets-Unisex - 4.36 m2</b>	
No Asbestos	
<b>B00U - R1044 - Seminar - 12.97 m2</b>	
No Asbestos	
<b>B00U - R1045 - Seminar - 12.99 m2</b>	
No Asbestos	
<b>B00U - R1046 - Careers Advisers Office - 13.1 m2</b>	
No Asbestos	
<b>B00U - R1047 - Movement - 19.45 m2</b>	
No Asbestos	
<b>B00U - R1048 - Library Administration - 19.3 m2</b>	
No Asbestos	
<b>B00U - R1049 - Main Area - 260.92 m2</b>	
No Asbestos	
<b>B00U - R1050 - External Movement - 153.11 m2</b>	
No Asbestos	
<b>B00U - R1051 - Distribution Board Cupboard - 1.17 m2</b>	<b>Note: No inspection of live electrical installation</b>
No Asbestos	
<b>B00U - R1052 - External Movement - 387.1 m2</b>	
No Asbestos	
<b>B00U - R1053 - External Movement - 3.49 m2</b>	
No Asbestos	

<b>B00U - R1054 - External Movement - 3.53 m2</b>		
No Asbestos		
<b>B00U - R1055 - Practice/Seminar - 10.48 m2</b>		
No Asbestos		
<b>B00V - Storage - 2015 - Metal Shed</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	Non Accessible Area	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00V - R0001 - Bulk Store - 29.62 m2</b>		
No Asbestos		
<b>B00V - R0002 - Bulk Store - 11.61 m2</b>		
No Asbestos		
<b>B00W - Storage - 2015 - Metal Shed</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	Non Accessible Area	
Ceiling Voids - Raked Ceiling	No Asbestos Found	
<b>Interior</b>		
<b>B00W - R0001 - Gymnasium - 65.33 m2</b>		
No Asbestos		

## Demountables

There are no Demountable(s) Located at this school as per the AMS records as of 09-Sep-2020