


# Asbestos Register

(Hazardous Materials and Risk Assessment)

<b>School:</b>	<b>Heathcote High School (8246)</b>
<b>Region:</b>	<b>Sydney AMU</b>
<b>State Electorate:</b>	<b>Heathcote</b>
<b>Local Government Area:</b>	<b>Sutherland</b>

<b>Last Reviewed By:</b>	<b>AECOM 30-OCT-2014</b>
<b>Last Revised By:</b>	

<b>Historical Fibro In Grounds Investigations/Events</b>	<b>Yes</b>
Please refer to the latest site specific Asbestos Management Plans available from the Department's website (Refer to Note 2).	



# Preface to Asbestos Register

## Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
  - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
  - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
  - o Any wall cavity
  - o Sub floor area, particularly formwork for slabs in/on ground,
  - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.  
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

## Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

## Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

## Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

## Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>  
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

## Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

### 3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
<b>B00A - Administration/Multi Purpose Facilities - 1988 - Brick/Veneer</b>							
<b>Exterior</b>							
Eaves Linings	Flat AC Sheeting						
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00A - R0002 - Staff - Toilet - 7.29 m2</b>							
No Asbestos							
<b>B00A - R0003 - Schools As Community Centres Program - 5.04 m2</b>							
No Asbestos							
<b>B00A - R0006 - Secure Storeroom - 18.17 m2</b>							
No Asbestos							
<b>B00A - R0007 - Clinic - 15.97 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0008 - Office/Store - 11.94 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0009 - Distribution Board Cupboard - .57 m2</b>						<b>Note: No inspection of live electrical installation</b>	
No Asbestos							
<b>B00A - R0010 - Change - 13.73 m2</b>							
No Asbestos							
<b>B00A - R0011 - Change - 15.41 m2</b>							
No Asbestos							
<b>B00A - R0012 - Printing/Photocopying - 31.84 m2</b>							
No Asbestos							
<b>B00A - R0013 - Movement - 15.83 m2</b>							
No Asbestos							
<b>B00A - R0016 - Multi-Purpose Space - 318.59 m2</b>							
No Asbestos							
<b>B00A - R0017 - Stage - 99.18 m2</b>							
No Asbestos							
<b>B00A - R0020 - Administration - Clerical - 12.43 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0021 - Administration - Clerical - 46.66 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0022 - Deputy Principal Office - 13.11 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0023 - Public Entry - 23.33 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0024 - Principal Office - 19.99 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0025 - Ancillary Staff - 15.62 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0026 - Staff - Toilet - 3.58 m2</b>							
No Asbestos							

<b>B00A - R0027 - Staff - Toilet - 3.61 m2</b>							
No Asbestos							
<b>B00A - R0028 - Deputy Principal Office - 16.02 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0029 - Movement - 14.68 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0030 - Pupil Entry - 12.01 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0032 - General Storeroom - 11.16 m2</b>							
No Asbestos							
<b>B00A - R0033 - Other-Vacant - .63 m2</b>							
No Asbestos							
<b>B00A - R0034 - Access Student Shower/Toilet/Change - 16.01 m2</b>							
No Asbestos							
<b>B00A - R0035 - Plant - .91 m2</b>							
No Asbestos							
<b>B00A - R0036 - Movement - 32.29 m2</b>							
No Asbestos							
<b>B00A - R0037 - Public Reception - 43.02 m2</b>							
No Asbestos							
<b>B00A - R0038 - External Movement - 3.91 m2</b>							
No Asbestos							
<b>B00A - R0039 - External Movement - 178.49 m2</b>							
No Asbestos							
<b>B00A - R0040 - External Movement - 37.09 m2</b>							
No Asbestos							
<b>B00A - R0041 - External Movement - 10.66 m2</b>							
No Asbestos							
<b>B00A - R9001 - Archive Store - 7.22 m2</b>							
No Asbestos							
<b>B00A - R9002 - External Movement - 2.5 m2</b>							
No Asbestos							
<b>B00A - R9003 - Sport Equipment Store - 10.35 m2</b>							
No Asbestos							
<b>B00A - R9005 - General Assistants - 27.96 m2</b>							
No Asbestos							
<b>B00A - R9006 - General Storeroom - 26.87 m2</b>							
No Asbestos							
<b>B00A - R9007 - Sport Equipment Store - 18.26 m2</b>							
No Asbestos							
<b>B00B - General Learning/Science Learning - 1989 - Brick/Veneer</b>							
<b>Exterior</b>							
Eaves Linings	Flat AC Sheeting	40m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00B - R0003 - Garden Store Room - 3.12 m2</b>							
No Asbestos							
<b>B00B - R0004 - Movement - 23.03 m2</b>							

Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )							
<b>B00B - R0006 - Chemical Store - 11.87 m2</b>								
No Asbestos								
<b>B00B - R0007 - Cleaning Store - Distributed - 3.69 m2</b>								
No Asbestos								
<b>B00B - R0008 - Resources Store - 3.35 m2</b>								
No Asbestos								
<b>B00B - R0009 - Movement - 25.53 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )							
<b>B00B - R0010 - General Learning Space - 53.44 m2</b>								
Floor Coverings Res/Textile	No Asbestos Found							
<b>B00B - R0011 - General Learning Space - 53.44 m2</b>								
No Asbestos								
<b>B00B - R0012 - Laboratory L.S. - 65.37 m2</b>								
No Asbestos								
<b>B00B - R0013 - Distribution Board Cupboard - .73 m2</b>								
<b>Note: No inspection of live electrical installation</b>								
No Asbestos								
<b>B00B - R0014 - Apparatus Store - 15.99 m2</b>								
No Asbestos								
<b>B00B - R0018 - Plant - 3.24 m2</b>								
No Asbestos								
<b>B00B - R0019 - Staff Study - 35.58 m2</b>								
Ceiling Structures/Linings	Flat AC Sheeting	35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00B - R0020 - Tea Room - 3.81 m2</b>								
Ceiling Structures/Linings	Compressed AC Sheet	3.8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00B - R0021 - General Storeroom - 4.28 m2</b>								
No Asbestos								
<b>B00B - R0022 - Staff - Toilet - 6.5 m2</b>								
No Asbestos								
<b>B00B - R0023 - Stairs - 1.78 m2</b>								
No Asbestos								
<b>B00B - R0024 - Laboratory L.S. - 48.66 m2</b>								
No Asbestos								
<b>B00B - R0025 - General Learning Space - 43.08 m2</b>								
No Asbestos								
<b>B00B - R0026 - Preparation - Science - 40.19 m2</b>								
No Asbestos								
<b>B00B - R0027 - Plant - .62 m2</b>								
No Asbestos								
<b>B00B - R0028 - Resources Store - 20.82 m2</b>								
No Asbestos								
<b>B00B - R0029 - Laboratory L.S. - 50.12 m2</b>								
No Asbestos								
<b>B00B - R0030 - General Learning Space - 49.98 m2</b>								
No Asbestos								
<b>B00B - R0031 - Stairs - 1.6 m2</b>								
No Asbestos								
<b>B00B - R1001 - General Learning Space - 53.74 m2</b>								

Floor Coverings Res/Textile	No Asbestos Found						
<b>B00B - R1002 - Careers Advisers Office - 14.36 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00B - R1004 - Interview/Office - Type 1 - 14.32 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00B - R1005 - Distribution Board Cupboard - .42 m2</b>							
No Asbestos							<b>Note: No inspection of live electrical installation</b>
<b>B00B - R1007 - General Learning Space - 53.44 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00B - R1008 - Resources Store - 10.76 m2</b>							
No Asbestos							
<b>B00B - R1009 - General Learning Space - 67.15 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00B - R1010 - Performance Store - 7.26 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00B - R1011 - Performance Store - 4.04 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00B - R1013 - Resources Store - 22.01 m2</b>							
No Asbestos							
<b>B00B - R1014 - General Learning Space - 53.52 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00B - R1015 - Movement - 61.69 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00B - R1016 - General Learning Space - 49.69 m2</b>							
No Asbestos							
<b>B00B - R1017 - Handwashing Facilities - 3.77 m2</b>							
No Asbestos							
<b>B00B - R1018 - Plant - .41 m2</b>							
No Asbestos							
<b>B00B - R1019 - Staff Study - 51 m2</b>							
No Asbestos							
<b>B00B - R1020 - Tea Room - 1.92 m2</b>							
No Asbestos							
<b>B00B - R1021 - Stairs - 8.28 m2</b>							
No Asbestos							
<b>B00B - R1022 - Stairs - 8.03 m2</b>							
No Asbestos							
<b>B00B - R1023 - General Learning Space - 56.65 m2</b>							
No Asbestos							
<b>B00B - R1024 - Resources Store - 4.01 m2</b>							
No Asbestos							
<b>B00C - General Learning/Staff Facilities - 1989 - Brick/Veneer</b>							
<b>Exterior</b>							
Eaves Linings	Flat AC Sheeting	40m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00C - R0001 - General Learning Space - 53.51 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )	
<b>B00C - R0002 - Staff - Toilet - 5.55 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )	
<b>B00C - R0003 - Staff - Toilet - 5.64 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )	
<b>B00C - R0004 - Cleaning Store - Distributed - 4.17 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )	
<b>B00C - R0005 - Resources Store - 26.57 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )	
<b>B00C - R0006 - Computer Learning Space - 80.87 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 70 - 120 m2) - ( X8 )	
<b>B00C - R0007 - Communication Space - 8.82 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )	
<b>B00C - R0008 - Computer Store - 10.3 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )	
<b>B00C - R0009 - Distribution Board Cupboard - .65 m2</b>		
		<b>Note: No inspection of live electrical installation</b>
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )	
<b>B00C - R0010 - Resources Store - 21.07 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )	
<b>B00C - R0011 - Computer Learning Space - 53.59 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )	
<b>B00C - R0012 - Computer Learning Space - 53.81 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )	
<b>B00C - R0013 - Resources Store - 3.41 m2</b>		
No Asbestos		
<b>B00C - R0014 - Interview/Office - Type 1 - 13.21 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )	
<b>B00C - R0015 - General Storeroom - 3.99 m2</b>		
No Asbestos		
<b>B00C - R0017 - Interview/Meeting - 13.06 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R0019 - Cleaning Store - Distributed - 2.99 m2</b>		
No Asbestos		
<b>B00C - R0020 - General Learning Space - 53.74 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )	
<b>B00C - R0021 - Movement - 100.87 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )	

<b>B00C - R0022 - Main Switchroom - 8.62 m2</b>		
No Asbestos		
<b>B00C - R0023 - Special Education Support Centre - 24.62 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )	
<b>B00C - R0024 - Tea Room - 2.23 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )	
<b>B00C - R0025 - Plant - .34 m2</b>		
No Asbestos		
<b>B00C - R0026 - Senior Study - 20.73 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )	
<b>B00C - R0027 - Handwashing Facilities - 1.84 m2</b>		
Ceiling Structures/Linings	No Asbestos Found	
<b>B00C - R0028 - Stairs - 1.77 m2</b>		
No Asbestos		
<b>B00C - R0029 - Stairs - 1.44 m2</b>		
No Asbestos		
<b>B00C - R1004 - Distribution Board Cupboard - .38 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00C - R1005 - Resources Store - 21.44 m2</b>		
No Asbestos		
<b>B00C - R1006 - General Learning Space - 53.37 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R1007 - General Learning Space - 53.74 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R1008 - Interview/Office - Type 1 - 14.32 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R1009 - Resources Store - 14.25 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R1012 - General Learning Space - 53.66 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R1013 - Movement - 60.26 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R1014 - Plant - .35 m2</b>		
No Asbestos		
<b>B00C - R1015 - Staff Study - 50.77 m2</b>		
No Asbestos		
<b>B00C - R1016 - Tea Room - 1.94 m2</b>		
No Asbestos		
<b>B00C - R1017 - General Learning Space - 70.36 m2</b>		
No Asbestos		
<b>B00C - R1018 - Handwashing Facilities - 3.35 m2</b>		
No Asbestos		
<b>B00C - R1019 - Commonroom - 107.55 m2</b>		
No Asbestos		
<b>B00C - R1020 - Staff Kitchen - 6.61 m2</b>		



No Asbestos		
<b>B00C - R1021 - Seminar - 19.44 m2</b>		
No Asbestos		
<b>B00C - R1022 - Stairs - 7.69 m2</b>		
No Asbestos		
<b>B00C - R1023 - Stairs - 7.85 m2</b>		
No Asbestos		
<b>B00D - General Learning/Art/Music - 1988 - Brick/Veneer</b>		
<b>Exterior</b>		
Eaves Linings	Flat AC Sheeting	
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00D - R0002 - Resources Store - 8.81 m2</b>		
No Asbestos		
<b>B00D - R0003 - Practice/Seminar - 9.26 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )	
<b>B00D - R0004 - Staff - Toilet - 5.16 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )	
<b>B00D - R0006 - Resources Store - 19.48 m2</b>		
No Asbestos		
<b>B00D - R0007 - Apparatus Store - 19.25 m2</b>		
No Asbestos		
<b>B00D - R0009 - Preparation - Science - 24.4 m2</b>		
No Asbestos		
<b>B00D - R0010 - Distribution Board Cupboard - .56 m2</b>		
		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00D - R0011 - Laboratory L.S. - 83.83 m2</b>		
No Asbestos		
<b>B00D - R0012 - Apparatus Store - 12.13 m2</b>		
No Asbestos		
<b>B00D - R0013 - Staff - Toilet - 5.15 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )	
<b>B00D - R0015 - Distribution Board Cupboard - .69 m2</b>		
		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00D - R0017 - Seminar - 25.85 m2</b>		
No Asbestos		
<b>B00D - R0019 - Art Learning Space - 66.67 m2</b>		
No Asbestos		
<b>B00D - R0020 - Art Learning Space - 66.74 m2</b>		
No Asbestos		
<b>B00D - R0021 - Workshop - 60.72 m2</b>		
No Asbestos		
<b>B00D - R0022 - Art Learning Space - 66.72 m2</b>		
No Asbestos		
<b>B00D - R0023 - Multi Media Workshop - 8.75 m2</b>		
Ceiling Structures/Linings	No Asbestos Found	
<b>B00D - R0025 - Movement - 96.71 m2</b>		

Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )	
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R0027 - External Movement - 70.73 m2</b>		
Ceiling Structures/Linings	No Asbestos Found	
<b>B00D - R0028 - Cleaning Store - Distributed - 4.15 m2</b>		
No Asbestos		
<b>B00D - R0029 - Performance Store - 17 m2</b>		
No Asbestos		
<b>B00D - R0030 - Movement - 133.82 m2</b>		
No Asbestos		
<b>B00D - R0031 - Handwashing Facilities - .68 m2</b>		
No Asbestos		
<b>B00D - R0032 - Stairs - .95 m2</b>		
No Asbestos		
<b>B00D - R0033 - Stairs - 4.63 m2</b>		
No Asbestos		
<b>B00D - R0034 - Stairs - 1.55 m2</b>		
No Asbestos		
<b>B00D - R0035 - Laboratory L.S. - 39.11 m2</b>		
No Asbestos		
<b>B00D - R0036 - General Learning Space - 43.21 m2</b>		
No Asbestos		
<b>B00D - R0037 - Laboratory L.S. - 43.51 m2</b>		
No Asbestos		
<b>B00D - R0038 - General Learning Space - 39.56 m2</b>		
No Asbestos		
<b>B00D - R0039 - Stairs - 1.52 m2</b>		
No Asbestos		
<b>B00D - R0040 - Stairs - 4.73 m2</b>		
No Asbestos		
<b>B00D - R0041 - Movement - 57.4 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )	
<b>B00D - R0042 - Resources Store - 9.48 m2</b>		
No Asbestos		
<b>B00D - R0043 - Computer Learning Space - 47.47 m2</b>		
No Asbestos		
<b>B00D - R0044 - Resources Store - 7.01 m2</b>		
No Asbestos		
<b>B00D - R0045 - Darkroom Space - 1.33 m2</b>		
No Asbestos		
<b>B00D - R0046 - Dark Room - 24.02 m2</b>		
No Asbestos		
<b>B00D - R0047 - External Movement - 8.49 m2</b>		
No Asbestos		
<b>B00D - R0048 - External Movement - 4.15 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )	
<b>B00D - R0049 - External Movement - 4.14 m2</b>		
No Asbestos		

<b>B00D - R0050 - Stairs - 9.1 m2</b>		
No Asbestos		
<b>B00D - R1001 - Resources Store - 4.14 m2</b>		
No Asbestos		
<b>B00D - R1004 - Seminar - 25.48 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R1005 - General Learning Space - 65.85 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R1006 - Practice/Seminar - 25.23 m2</b>		
No Asbestos		
<b>B00D - R1007 - Music Learning Space - 79.05 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R1008 - Music Store - 24.63 m2</b>		
No Asbestos		
<b>B00D - R1009 - Distribution Board Cupboard - .46 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00D - R1010 - General Learning Space - 52.14 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R1011 - Cleaning Store - Distributed - 3.08 m2</b>		
No Asbestos		
<b>B00D - R1012 - General Learning Space - 51.92 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R1013 - Resources Store - 8.95 m2</b>		
No Asbestos		
<b>B00D - R1014 - Staff Study - 55.07 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R1015 - Resources Store - 4.1 m2</b>		
No Asbestos		
<b>B00D - R1016 - Distribution Board Cupboard - .46 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00D - R1017 - General Learning Space - 52.14 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R1018 - General Learning Space - 52.21 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R1019 - General Learning Space - 52.21 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R1020 - General Learning Space - 52.14 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R1021 - General Learning Space - 52.29 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R1023 - Movement - 89.53 m2</b>		
No Asbestos		
<b>B00D - R1024 - Movement - 13.26 m2</b>		
Ceiling Structures/Linings	No Asbestos Found	

<b>B00D - R1025 - Movement - 11.02 m2</b>							
Ceiling Structures/Linings	No Asbestos Found						
<b>B00D - R1026 - Stairs - 11.46 m2</b>							
No Asbestos							
<b>B00D - R1027 - Stairs - 11.34 m2</b>							
No Asbestos							
<b>B00D - R1028 - Staff Study - 48.6 m2</b>							
No Asbestos							
<b>B00D - R1029 - Tea Room - 3.13 m2</b>							
No Asbestos							
<b>B00D - R1030 - Handwashing Facilities - .38 m2</b>							
No Asbestos							
<b>B00D - R1031 - Movement - 5.7 m2</b>							
No Asbestos							
<b>B00D - R1032 - Stairs - 14.91 m2</b>							
No Asbestos							
<b>B00D - R1033 - Movement - 125.35 m2</b>							
No Asbestos							
<b>B00D - R1034 - Stairs - 15.85 m2</b>							
No Asbestos							
<b>B00E - Pupil Facilities/Technological &amp; Applied Studies - 1988 - Brick/Veneer</b>							
<b>Exterior</b>							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00E - R0001 - Toilets-Girls - 70.3 m2</b>							
No Asbestos							
<b>B00E - R0002 - Food Technology L.S. - 107.21 m2</b>							
No Asbestos							
<b>B00E - R0003 - Preparation - 29.91 m2</b>							
No Asbestos							
<b>B00E - R0004 - Resources Store - 18.02 m2</b>							
No Asbestos							
<b>B00E - R0005 - Food Technology L.S. - 107.38 m2</b>							
No Asbestos							
<b>B00E - R0006 - Laundry - 5.66 m2</b>							
No Asbestos							
<b>B00E - R0007 - Distribution Board Cupboard - .99 m2</b>							
					<b>Note: No inspection of live electrical installation</b>		
Electrical - Mounting Board	Encapsulated Asbestos material within unit	2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	<b>Assumed Asbestos</b>
<b>B00E - R0009 - Staff - Toilet - 3.62 m2</b>							
No Asbestos							
<b>B00E - R0011 - Tea Room - 13.58 m2</b>							
No Asbestos							
<b>B00E - R0012 - Uniform Shop - 13.42 m2</b>							
No Asbestos							
<b>B00E - R0013 - General Storeroom - 5.09 m2</b>							
No Asbestos							
<b>B00E - R0014 - Machine Storage - 12.89 m2</b>							
No Asbestos							
<b>B00E - R0015 - Main Switchroom - 8.26 m2</b>							

No Asbestos		
<b>B00E - R0016 - Design L.S. - 78.97 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R0017 - Resources Store - 3.99 m2</b>		
No Asbestos		
<b>B00E - R0019 - Cleaning Store - Distributed - 18.95 m2</b>		
No Asbestos		
<b>B00E - R0020 - Toilets-Boys - 68.28 m2</b>		
No Asbestos		
<b>B00E - R0021 - Cleaning Supplies Store - 6.7 m2</b>		
No Asbestos		
<b>B00E - R0022 - Cleaning Supplies Store - 4.72 m2</b>		
No Asbestos		
<b>B00E - R0023 - Student Canteen - 47.02 m2</b>		
No Asbestos		
<b>B00E - R0024 - Pantry - 8.16 m2</b>		
No Asbestos		
<b>B00E - R0025 - Garden Store Room - 6.54 m2</b>		
No Asbestos		
<b>B00E - R0026 - Staff - Toilet - 3.35 m2</b>		
No Asbestos		
<b>B00E - R0027 - Staff - Toilet - 3.34 m2</b>		
No Asbestos		
<b>B00E - R0028 - Office/Store - 15.05 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R0030 - Covered Area - 88.23 m2</b>		
No Asbestos		
<b>B00E - R0031 - Staff Study - 49.5 m2</b>		
No Asbestos		
<b>B00E - R0032 - Design L.S. - 74.06 m2</b>		
No Asbestos		
<b>B00E - R0033 - Handwashing Facilities - 5.55 m2</b>		
No Asbestos		
<b>B00E - R0034 - External Movement - 6.39 m2</b>		
No Asbestos		
<b>B00E - R0035 - External Movement - 388.38 m2</b>		
No Asbestos		
<b>B00F - Technological &amp; Applied Studies - 1988 - Brick/Block</b>		
<b>Exterior</b>		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00F - M0001 - Materials Store - 24.41 m2</b>		
No Asbestos		
<b>B00F - M0002 - Resources Store - 18.9 m2</b>		
No Asbestos		
<b>B00F - M0003 - Project Store - Type 1 - 12.2 m2</b>		
No Asbestos		
<b>B00F - M0004 - Project Store - Type 1 - 12.33 m2</b>		
No Asbestos		

<b>B00F - M0005 - Movement - .92 m2</b>							
No Asbestos							
<b>B00F - M0006 - Stairs - 1.5 m2</b>							
No Asbestos							
<b>B00F - R0001 - Materials Technology L.S. - 93.44 m2</b>							
No Asbestos							
<b>B00F - R0002 - Materials Store - 15.57 m2</b>							
No Asbestos							
<b>B00F - R0003 - Metal Technology Bay - 35.21 m2</b>							
No Asbestos							
<b>B00F - R0004 - Materials Technology L.S. - 93.63 m2</b>							
No Asbestos							
<b>B00F - R0006 - Resources Store - 3.14 m2</b>							
No Asbestos							
<b>B00F - R0007 - Welding Area - 10.25 m2</b>							
No Asbestos							
<b>B00F - R0008 - Distribution Board Cupboard - .74 m2</b>							<b>Note: No inspection of live electrical installation</b>
No Asbestos							
<b>B00F - R0009 - Project Store - Type 1 - 2.32 m2</b>							
No Asbestos							
<b>B00F - R0010 - L.P.G Store - 1.59 m2</b>							
No Asbestos							
<b>B00F - R0011 - Materials Store - 33.06 m2</b>							
No Asbestos							
<b>B00F - R0013 - Wood Technology Bay - 35.79 m2</b>							
No Asbestos							
<b>B00F - R0014 - Dust Extraction Space - 11.89 m2</b>							
No Asbestos							
<b>B00F - R0016 - Design/Technology L.S. - 67.16 m2</b>							
No Asbestos							
<b>B00F - R0017 - Computer Resource - 27.19 m2</b>							
No Asbestos							
<b>B00F - R0018 - Design/Technology L.S. - 65.02 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00F - R0020 - Distribution Board Cupboard - .73 m2</b>							<b>Note: No inspection of live electrical installation</b>
No Asbestos							
<b>B00F - R0021 - Staff - Toilet - 3.74 m2</b>							
No Asbestos							
<b>B00F - R0022 - External Movement - 5.35 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	<b>Assumed Asbestos</b>
<b>B00F - R0024 - Staff Study - 29.43 m2</b>							
No Asbestos							
<b>B00F - R0025 - Tea Room - 1.16 m2</b>							
No Asbestos							
<b>B00F - R0026 - Materials Technology L.S. - 89.12 m2</b>							
No Asbestos							
<b>B00F - R0027 - Handwashing Facilities - 1.04 m2</b>							
No Asbestos							
<b>B00F - R0028 - Materials Technology L.S. - 89.98 m2</b>							
No Asbestos							

<b>B00F - R0029 - Handwashing Facilities - .9 m2</b>		
No Asbestos		
<b>B00F - R0030 - Class Tools Storage - 5.61 m2</b>		
No Asbestos		
<b>B00F - R0031 - Workshop - 83.24 m2</b>		
No Asbestos		
<b>B00F - R0032 - Stairs - 2.15 m2</b>		
No Asbestos		
<b>B00F - R0033 - External Movement - 7.28 m2</b>		
No Asbestos		
<b>B00F - R0034 - External Movement - 142.1 m2</b>		
No Asbestos		
<b>B00G - Library - 1987 - Brick/Veneer</b>		
<b>Exterior</b>		
Eaves Linings	Flat AC Sheeting	
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00G - R0001 - Plant - 8.65 m2</b>		
No Asbestos		
<b>B00G - R0002 - Tiered Learning Area - 68.17 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00G - R0003 - General Storeroom - 2.72 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00G - R0004 - System Administrators Office - 28.11 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00G - R0005 - Main Area - 377.91 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00G - R0006 - Archive Store - 11.6 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00G - R0008 - Seminar - 13.03 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00G - R0011 - External Movement - 104.48 m2</b>		
Ceiling Structures/Linings	Flat AC Sheeting	
<b>B00G - R0012 - Interview/Office - Type 1 - 13.53 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00G - R0013 - Toilets-Boys - 3.68 m2</b>		
No Asbestos		
<b>B00G - R0014 - Toilets-Girls - 3.73 m2</b>		
No Asbestos		
<b>B00G - R0015 - Distribution Board Cupboard - 1.38 m2</b>		
No Asbestos		<b>Note: No inspection of live electrical installation</b>
<b>B00G - R0016 - Cleaning Store - Distributed - 1.62 m2</b>		
No Asbestos		
<b>B00G - R0017 - Library Administration - 34.99 m2</b>		
No Asbestos		

<b>B00G - R0018 - Tea Room - 5.02 m2</b>	
No Asbestos	
<b>B00G - R0019 - Study Space - 26.77 m2</b>	
No Asbestos	
<b>B00G - R0020 - External Movement - 5.96 m2</b>	
No Asbestos	
<b>B00H - Physical Education - 1990 - Brick/Block</b>	
<b>Exterior</b>	
Eaves Linings	Flat AC Sheeting
Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found
<b>Interior</b>	
<b>B00H - R0001 - External Movement - 8.46 m2</b>	
Ceiling Structures/Linings	Flat AC Sheeting
<b>B00H - R0002 - Gymnasium - 458.09 m2</b>	
No Asbestos	
<b>B00H - R0003 - External Movement - 8.41 m2</b>	
Ceiling Structures/Linings	Flat AC Sheeting
<b>B00H - R0004 - Change - 27.19 m2</b>	
No Asbestos	
<b>B00H - R0005 - Staff - Toilet - 5.57 m2</b>	
No Asbestos	
<b>B00H - R0006 - Change - 27.28 m2</b>	
No Asbestos	
<b>B00H - R0007 - External Movement - 8.44 m2</b>	
Ceiling Structures/Linings	Flat AC Sheeting
<b>B00H - R0008 - External Movement - 8.49 m2</b>	
Ceiling Structures/Linings	Flat AC Sheeting
<b>B00H - R0009 - Distribution Board Cupboard - .63 m2</b>	
No Asbestos	<b>Note: No inspection of live electrical installation</b>
<b>B00H - R0015 - Plant - .23 m2</b>	
No Asbestos	
<b>B00H - R0016 - Sport Equipment Store - 35.79 m2</b>	
No Asbestos	
<b>B00H - R0017 - Staff Study - 24.17 m2</b>	
No Asbestos	
<b>B00I - Storage - 2000 - Metal Shed</b>	
<b>Exterior</b>	
No Asbestos	
<b>Interior</b>	
<b>B00I - R0001 - Machine Storage - 52.08 m2</b>	
No Asbestos	
<b>B00I - R0002 - General Storeroom - 17.03 m2</b>	
No Asbestos	
<b>B00J - Other - 2011 - Timber Shed</b>	
<b>Exterior</b>	
No Asbestos	
<b>Interior</b>	



**B00J - R0001 - Cleaning Store - Distributed - 5.98 m2**

No Asbestos

**Demountables**

**OS 600 12051 - Learning Unit - Small - Placement Date : 15-DEC-2016**

No Asbestos Found

**OS 971 80074 - Shed - Container (Garden/Sports/Bulk) - Placement Date : 30-JUN-1995**

No Asbestos Found