

Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Holsworthy High School (8564)
Region:	South Western Sydney AMU
State Electorate:	Holsworthy
Local Government Area:	Liverpool

Last Reviewed By:	Greencap 14-DEC-2017
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	No
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	

8564 - Holsworthy High School
Site Plan (11010)



1:2,320

Printed: 21-Mar-2020

Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - Administration - 1983 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting						
Wall Linings Internal - Infill	Flat AC Sheeting						
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00A - R0001 - Movement - 97.43 m2							
No Asbestos							
B00A - R0002 - Deputy Principal Office - 11.53 m2							
No Asbestos							
B00A - R0003 - Clinic - Boys - 12.25 m2							
No Asbestos							
B00A - R0004 - Toilets-Boys - 2.4 m2							
No Asbestos							
B00A - R0005 - Toilets-Girls - 2.42 m2							
No Asbestos							
B00A - R0006 - Clinic - Girls - 12.18 m2							
No Asbestos							
B00A - R0007 - Deputy Principal Office - 15.48 m2							
No Asbestos							
B00A - R0009 - Administration - Clerical - 43.08 m2							
No Asbestos							
B00A - R0010 - Printing/Photocopying - 24.14 m2							
No Asbestos							
B00A - R0011 - Secure Storeroom - 16.21 m2							
No Asbestos							
B00A - R0012 - Distribution Board Cupboard - 1.08 m2							
						Note: No inspection of live electrical installation	
Ceiling Structures/Linings	Flat AC Sheeting						
B00A - R0013 - Interview/Office - Type 1 - 12.18 m2							
No Asbestos							
B00A - R0014 - Staff - Toilet - 5.95 m2							
No Asbestos							
B00A - R0015 - Staff - Toilet - 5.93 m2							
No Asbestos							
B00A - R0016 - Interview/Office - Type 1 - 12.22 m2							
No Asbestos							
B00A - R0017 - Principal Office - 22.83 m2							
No Asbestos							
B00A - R0018 - Interview/Meeting - 12.36 m2							
No Asbestos							
B00A - R0019 - Leading Teacher - 12.32 m2							
No Asbestos							
B00A - R0020 - External Movement - 15.33 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00A - R0021 - External Movement - 3.72 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00A - R0022 - External Movement - 3.76 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00A - R0024 - Ancillary Staff - 22.42 m2							

No Asbestos		
B00A - R0025 - Tea Room - 2.4 m2		
No Asbestos		
B00B - Technological & Applied Studies/Music - 1983 - Brick/Block		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Interior		
B00B - R0001 - Movement - 81.64 m2		
No Asbestos		
B00B - R0002 - Textiles Technology L.S. - 73.99 m2		
No Asbestos		
B00B - R0003 - Textiles Technology L.S. - 74.16 m2		
No Asbestos		
B00B - R0004 - Resources Store - 10.3 m2		
No Asbestos		
B00B - R0005 - Laundry - 15.17 m2		
No Asbestos		
B00B - R0006 - Food Technology L.S. - 105.59 m2		
No Asbestos		
B00B - R0007 - Preparation - Materials - 19.32 m2		
No Asbestos		
B00B - R0008 - Food Technology L.S. - 105.71 m2		
No Asbestos		
B00B - R0009 - Resources Store - 3.1 m2		
No Asbestos		
B00B - R0011 - Garden Store Room - 11.92 m2		
No Asbestos		
B00B - R0012 - General Storeroom - 19.13 m2		
Ceiling Structures/Linings	Flat AC Sheeting	
B00B - R0013 - External Movement - 87.88 m2		
No Asbestos		
B00B - R0014 - Movement - 22.97 m2		
No Asbestos		
B00B - R0015 - Covered Area - 47.37 m2		
Ceiling Structures/Linings	Flat AC Sheeting	
B00B - R0016 - External Stairs - 9.64 m2		
Ceiling Structures/Linings	Flat AC Sheeting	
B00B - R0017 - Stairs - 9.83 m2		
Ceiling Structures/Linings	Flat AC Sheeting	
B00B - R0018 - Staff Study - 15.93 m2		
No Asbestos		
B00B - R0019 - Tea Room - 6.35 m2		
No Asbestos		
B00B - R0020 - Lift - 1.45 m2		
No Asbestos		
B00B - R0021 - Plant - 1.86 m2		
No Asbestos		
B00B - R1001 - Movement - 43.01 m2		
No Asbestos		

B00B - R1002 - Staff Study - 25.37 m2		
No Asbestos		
B00B - R1004 - Music Store - 16.39 m2		
No Asbestos		
B00B - R1005 - Distribution Board Cupboard - .96 m2		Note: No inspection of live electrical installation
Ceiling Structures/Linings	Flat AC Sheeting	
B00B - R1007 - Music Learning Space - 53.62 m2		
No Asbestos		
B00B - R1008 - Practice/Seminar - 24.54 m2		
No Asbestos		
B00B - R1009 - Music Learning Space - 79.41 m2		
No Asbestos		
B00B - R1010 - External Movement - 7.7 m2		
Ceiling Structures/Linings	Flat AC Sheeting	
B00B - R1011 - Movement - 9.55 m2		
Ceiling Structures/Linings	Flat AC Sheeting	
B00B - R1012 - External Stairs - 14.3 m2		
Ceiling Structures/Linings	Flat AC Sheeting	
B00B - R1013 - Stairs - 14.22 m2		
Ceiling Structures/Linings	Flat AC Sheeting	
B00B - R1014 - Staff Study - 15.35 m2		
No Asbestos		
B00B - R1015 - Tea Room - 1.35 m2		
No Asbestos		
B00B - R1016 - Toilet - Lobby - 2.91 m2		
No Asbestos		
B00B - R1017 - Toilets-Boys - 14.33 m2		
No Asbestos		
B00C - Multi Purpose Facilities/Physical Education - 1983 - Brick/Block		
Exterior		
Eaves Linings	Flat AC Sheeting	
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Interior		
B00C - M0033 - Plant - 3.54 m2		
No Asbestos		
B00C - M0034 - Control Room - 5.76 m2		
No Asbestos		
B00C - M0035 - Plant - 3.6 m2		
No Asbestos		
B00C - R0001 - Student Canteen - 67.81 m2		
No Asbestos		
B00C - R0004 - Chair Store - 22.96 m2		
No Asbestos		
B00C - R0005 - Sport Equipment Store - 23.05 m2		
No Asbestos		
B00C - R0006 - Fitness Laboratory - 35.54 m2		
No Asbestos		
B00C - R0011 - General Storeroom - 30.5 m2		
No Asbestos		
B00C - R0012 - Toilet - Lobby - 8.14 m2		

No Asbestos							
B00C - R0013 - Toilets-Boys - 12.06 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0014 - Toilet - Lobby - 8.12 m2							
No Asbestos							
B00C - R0015 - Toilets-Girls - 11.92 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0016 - Performance Store - 30.7 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	30m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0017 - Shower - 31.79 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	20m2	East	Mnimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0019 - Cleaning Store - Distributed - 4.79 m2							
No Asbestos							
B00C - R0020 - Distribution Board Cupboard - .97 m2							Note: No inspection of live electrical installation
Ceiling Structures/Linings	Flat AC Sheeting						
B00C - R0021 - Tea Room - 11.26 m2							
No Asbestos							
B00C - R0022 - General Assistants - 11.27 m2							
No Asbestos							
B00C - R0023 - Garden Store Room - 7.13 m2							
No Asbestos							
B00C - R0024 - Machine Storage - 15.42 m2							
No Asbestos							
B00C - R0025 - General Storeroom - 13.59 m2							
No Asbestos							
B00C - R0026 - Stage - 76.48 m2							
No Asbestos							
B00C - R0027 - Movement - 62.16 m2							
No Asbestos							
B00C - R0028 - Movement - 18.46 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00C - R0029 - External Movement - 6.55 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00C - R0030 - External Movement - 6.51 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00C - R0031 - External Movement - 10.08 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00C - R0032 - Covered Area - 122.42 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00C - R0036 - Lift - 1.68 m2							
No Asbestos							
B00C - R0037 - Multi-Purpose Space - 468.93 m2							
No Asbestos							
B00C - R0038 - Movement - 4.62 m2							
No Asbestos							
B00C - R0039 - Movement - 4.84 m2							
No Asbestos							
B00C - R0040 - Toilet - Lobby - 2.67 m2							
No Asbestos							

B00C - R0041 - Toilets-Girls - 14.54 m2							
No Asbestos							
B00C - R0042 - Toilet - Lobby - 4.44 m2							
No Asbestos							
B00C - R0043 - Toilets-Boys - 18.35 m2							
No Asbestos							
B00C - R0045 - Office/Store - 3.7 m2							
No Asbestos							
B00C - R0046 - Staff - Toilet - 1.97 m2							
No Asbestos							
B00C - R0047 - Staff Study - 28.07 m2							
No Asbestos							
B00C - R0048 - Staff Kitchen - 3.08 m2							
No Asbestos							
B00C - R0049 - Staff Study - 15.41 m2							
No Asbestos							
B00C - R0050 - Sport Equipment Store - 7.35 m2							
No Asbestos							
B00D - Library/Pupil Facilities - 1983 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting						
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00D - R0001 - Main Area - 269.43 m2							
No Asbestos							
B00D - R0003 - Seminar - 12.22 m2							
No Asbestos							
B00D - R0004 - Seminar - 12.22 m2							
No Asbestos							
B00D - R0005 - Audio Visual Workroom - 43.46 m2							
No Asbestos							
B00D - R0006 - Librarian - 11.81 m2							
No Asbestos							
B00D - R0008 - Resources Store - 10.97 m2							
No Asbestos							
B00D - R0010 - Access Student Shower/Toilet/Change - 10.46 m2							
No Asbestos							
B00D - R0011 - Toilets-Disabled - 7.05 m2							
No Asbestos							
B00D - R0012 - Staff - Toilet - 3.6 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	3m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00D - R0013 - Main Switchroom - 15.44 m2							
Floor Coverings Res/Textile	Compressed AC Sheet	3m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00D - R0014 - Toilets-Girls - 14.15 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	15m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00D - R0015 - Toilets-Boys - 14.37 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	6m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

B00D - R0017 - External Stairs - 6.69 m2							
No Asbestos							
B00D - R0018 - Student Drinking Facilities - 21.16 m2							
No Asbestos							
B00D - R0019 - Stairs - 9.22 m2							
No Asbestos							
B00D - R0021 - General Storeroom - 7.67 m2							
No Asbestos							
B00D - R0022 - Computer Store - 7.18 m2							
No Asbestos							
B00D - R0023 - Student Drinking Facilities - 12.83 m2							
No Asbestos							
B00D - R0024 - External Movement - 146.27 m2							
No Asbestos							
B00D - R0025 - External Movement - 124.96 m2							
No Asbestos							
B00D - R0026 - Library Administration - 40.08 m2							
No Asbestos							
B00D - R0027 - Tea Room - 5.82 m2							
No Asbestos							
B00D - R0028 - General Storeroom - 8.89 m2							
No Asbestos							
B00D - R0029 - General Storeroom - 13.73 m2							
No Asbestos							
B00D - R0030 - General Storeroom - 1.3 m2							
No Asbestos							
B00D - R0031 - Lift - 1.45 m2							
No Asbestos							
B00D - R1002 - Toilets-Boys - 12.08 m2							
No Asbestos							
B00D - R1003 - Toilets-Girls - 12.18 m2							
No Asbestos							
B00D - R1004 - Distribution Board Cupboard - .79 m2							Note: No inspection of live electrical installation
Ceiling Structures/Linings	Flat AC Sheeting						
B00D - R1005 - Careers Advisers Office - 14.11 m2							
No Asbestos							
B00D - R1006 - Toilets-Boys - 14.22 m2							
No Asbestos							
No Asbestos							
B00D - R1007 - Cleaning Store - Distributed - 3.39 m2							
No Asbestos							
B00D - R1008 - Interview/Office - Type 1 - 11.32 m2							
No Asbestos							
B00D - R1010 - Staff Study - 12.25 m2							
No Asbestos							
B00D - R1011 - Study Space - 12.15 m2							
No Asbestos							
B00D - R1012 - Toilets-Girls - 14.17 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	15m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00D - R1013 - External Movement - 262.77 m2							
No Asbestos							

B00D - R1014 - Study Space - 125 m2		
No Asbestos		
B00D - R1015 - External Stairs - 10.82 m2		
No Asbestos		
B00D - R1016 - Stairs - 13.33 m2		
No Asbestos		
B00D - R1017 - Senior Study - 81.31 m2		
No Asbestos		
B00D - R1018 - Tea Room - 2.34 m2		
No Asbestos		
B00D - R1019 - Staff Kitchen - 25.43 m2		
No Asbestos		
B00D - R1020 - Commonroom - 98.23 m2		
No Asbestos		
B00E - General Learning - 1983 - Brick/Block		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Eaves Linings	Flat AC Sheeting	
Interior		
B00E - R0001 - Cleaning Store - Distributed - 5.33 m2		
No Asbestos		
B00E - R0002 - Distribution Board Cupboard - .79 m2		Note: No inspection of live electrical installation
No Asbestos		
B00E - R0004 - General Learning Space - 46.01 m2		
No Asbestos		
B00E - R0005 - General Learning Space - 46.65 m2		
No Asbestos		
B00E - R0007 - General Learning Space - 45.96 m2		
No Asbestos		
B00E - R0008 - General Learning Space - 46.52 m2		
No Asbestos		
B00E - R0009 - Staff Study - 22.58 m2		
No Asbestos		
B00E - R0010 - Resources Store - 5.32 m2		
No Asbestos		
B00E - R0012 - External Movement - 81.55 m2		
No Asbestos		
B00E - R0013 - Stairs - 11.84 m2		
Ceiling Structures/Linings	Flat AC Sheeting	
B00E - R0014 - Movement - 6.84 m2		
No Asbestos		
B00E - R0015 - Staff Study - 17.64 m2		
No Asbestos		
B00E - R0016 - Tea Room - 1.58 m2		
No Asbestos		
B00E - R0017 - Movement - 69.18 m2		
No Asbestos		
B00E - R0018 - Handwashing Facilities - 2.36 m2		
No Asbestos		
B00E - R1001 - Distribution Board Cupboard - .81 m2		Note: No inspection of live electrical installation

Ceiling Structures/Linings	Flat AC Sheeting	
Electrical - Backing Board	Resinous Board	
B00E - R1002 - General Learning Space - 42.74 m2		
No Asbestos		
B00E - R1003 - General Learning Space - 46.44 m2		
No Asbestos		
B00E - R1005 - General Learning Space - 46.24 m2		
No Asbestos		
B00E - R1006 - General Learning Space - 51.7 m2		
No Asbestos		
B00E - R1007 - Staff Study - 21.3 m2		
No Asbestos		
B00E - R1008 - Resources Store - 4.93 m2		
No Asbestos		
B00E - R1010 - Movement - 33.34 m2		
Ceiling Structures/Linings	Flat AC Sheeting	
B00E - R1011 - Stairs - 15.76 m2		
Ceiling Structures/Linings	Flat AC Sheeting	
B00E - R1012 - Staff Study - 21.75 m2		
No Asbestos		
B00E - R1013 - Tea Room - 1.38 m2		
No Asbestos		
B00E - R1014 - Movement - 52.03 m2		
No Asbestos		
B00E - R1015 - Handwashing Facilities - 3.1 m2		
No Asbestos		
B00F - General Learning - 1983 - Brick/Block		
Exterior		
Eaves Linings	Flat AC Sheeting	
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Interior		
B00F - R0001 - External Movement - 33.51 m2		
No Asbestos		
B00F - R0002 - Distribution Board Cupboard - .82 m2		
No Asbestos		Note: No inspection of live electrical installation
B00F - R0003 - Cleaning Store - Distributed - 5.18 m2		
No Asbestos		
B00F - R0004 - Resources Store - 5.13 m2		
No Asbestos		
B00F - R0005 - Staff Study - 22.83 m2		
No Asbestos		
B00F - R0006 - General Learning Space - 46.3 m2		
No Asbestos		
B00F - R0007 - General Learning Space - 46.17 m2		
No Asbestos		
B00F - R0009 - General Learning Space - 45.95 m2		
No Asbestos		
B00F - R0010 - General Learning Space - 46.51 m2		
No Asbestos		
B00F - R0012 - External Movement - 37.45 m2		

No Asbestos		
B00F - R0013 - Stairs - 11.56 m2		
No Asbestos		
B00F - R0014 - Movement - 69.77 m2		
No Asbestos		
B00F - R0015 - Handwashing Facilities - 1.8 m2		
No Asbestos		
B00F - R0016 - Staff Study - 18.22 m2		
No Asbestos		
B00F - R0017 - Tea Room - 1.31 m2		
No Asbestos		
B00F - R1001 - Movement - 33.61 m2		
Ceiling Structures/Linings	Flat AC Sheeting	
B00F - R1003 - General Storeroom - 4.9 m2		
No Asbestos		
No Asbestos		
B00F - R1004 - Seminar - Type 1 - 20.9 m2		
No Asbestos		
B00F - R1005 - General Learning Space - 51.78 m2		
No Asbestos		
B00F - R1006 - General Learning Space - 46.3 m2		
No Asbestos		
B00F - R1007 - Movement - 55.42 m2		
No Asbestos		
B00F - R1008 - General Learning Space - 44.52 m2		
No Asbestos		
B00F - R1009 - General Learning Space - 43.03 m2		
No Asbestos		
B00F - R1010 - Distribution Board Cupboard - .71 m2		
Note: No inspection of live electrical installation		
Ceiling Structures/Linings	Flat AC Sheeting	
B00F - R1011 - External Stairs - 15.75 m2		
Ceiling Structures/Linings	Flat AC Sheeting	
B00F - R1012 - Staff Study - 22 m2		
No Asbestos		
B00F - R1013 - Tea Room - 1.38 m2		
No Asbestos		
B00G - Art/Computer Learning - 1983 - Brick/Block		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Interior		
B00G - R0001 - External Movement - 118.06 m2		
Ceiling Structures/Linings	Flat AC Sheeting	
B00G - R0002 - Art Entry/Display - 65.19 m2		
No Asbestos		
B00G - R0004 - Art Learning Space - 56.24 m2		
Floor Coverings Res/Textile	Vinyl Sheet	
B00G - R0005 - Workroom - 47.79 m2		
No Asbestos		
B00G - R0006 - Kiln Space - 9.15 m2		
No Asbestos		

B00G - R0007 - Art Learning Space - 57.04 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
B00G - R0008 - Resources Store - 18.23 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
B00G - R0009 - Distribution Board Cupboard - 1.33 m2						Note: No inspection of live electrical installation	
No Asbestos							
B00G - R0010 - Toilets-Girls - 19.65 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	15m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G - R0011 - Stairs - 9.35 m2							
No Asbestos							
B00G - R0012 - External Movement - 98.09 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00G - R0013 - Staff Study - 17.1 m2							
No Asbestos							
B00G - R0014 - Tea Room - 1.41 m2							
No Asbestos							
B00G - R1001 - Movement - 37.41 m2							
No Asbestos							
B00G - R1002 - Computer Learning Space - 56.82 m2							
No Asbestos							
B00G - R1003 - Computer Learning Space - 58.03 m2							
No Asbestos							
B00G - R1004 - Distribution Board Cupboard - .67 m2						Note: No inspection of live electrical installation	
Ceiling Structures/Linings	Flat AC Sheeting						
B00G - R1005 - Computer Store - 17.53 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00G - R1006 - Computer Store - 6.96 m2							
No Asbestos							
B00G - R1007 - Project Store - Type 1 - 21.35 m2							
No Asbestos							
B00G - R1008 - Stairs - 14.52 m2							
No Asbestos							
B00H - Technological & Applied Studies - 1983 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting						
Wall Cladding	Flat AC Sheeting						
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00H - R0001 - Toilets-Boys - 18.3 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	6m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00H - R0002 - Distribution Board Cupboard - 1.2 m2						Note: No inspection of live electrical installation	
Ceiling Structures/Linings	Flat AC Sheeting						
B00H - R0006 - Design L.S. - 50.5 m2							
No Asbestos							
B00H - R0007 - Resources Store - 31.44 m2							
No Asbestos							
B00H - R0009 - Staff Study - 21.22 m2							

No Asbestos		
B00H - R0010 - Resources Store - .92 m2		
No Asbestos		
B00H - R0011 - Cleaning Store - Distributed - 3.16 m2		
No Asbestos		
B00H - R0013 - Metal Technology Bay - 31.29 m2		
No Asbestos		
B00H - R0014 - Welding Area - 5.71 m2		
No Asbestos		
B00H - R0015 - Wood Technology L.S. - 103.51 m2		
No Asbestos		
B00H - R0016 - Wood Technology Bay - 22.37 m2		
No Asbestos		
B00H - R0017 - Wood Technology L.S. - 103.1 m2		
No Asbestos		
B00H - R0018 - Materials Store - 55.8 m2		
No Asbestos		
B00H - R0019 - Metal Technology L.S. - 97.08 m2		
No Asbestos		
B00H - R0020 - External Movement - 21.44 m2		
Ceiling Structures/Linings	Flat AC Sheeting	
B00H - R0021 - External Movement - 2.1 m2		
Ceiling Structures/Linings	Flat AC Sheeting	
B00H - R0022 - External Movement - 14.28 m2		
Ceiling Structures/Linings	Flat AC Sheeting	
B00H - R0023 - Metal Technology L.S. - 76.52 m2		
No Asbestos		
B00H - R0026 - Design/Technology L.S. - 71.66 m2		
No Asbestos		
B00H - R0027 - Dust Extraction Space - 9.56 m2		
No Asbestos		
B00H - R0028 - Staff Study - 24.59 m2		
No Asbestos		
B00H - R0029 - Tea Room - 1.23 m2		
No Asbestos		
B00H - R0030 - Movement - 110.24 m2		
No Asbestos		
B00J - Science Learning - 1983 - Brick/Block		
Exterior		
Eaves Linings	Flat AC Sheeting	
Wall Cladding	Flat AC Sheeting	
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Interior		
B00J - R0001 - Movement - 143.27 m2		
No Asbestos		
B00J - R0002 - Chemical Store - 10.53 m2		
No Asbestos		
B00J - R0003 - Resources Store - 34.72 m2		
No Asbestos		
B00J - R0004 - Cleaning Store - Distributed - 3.01 m2		

No Asbestos							
B00J - R0005 - Distribution Board Cupboard - .8 m2							Note: No inspection of live electrical installation
Ceiling Structures/Linings	Flat AC Sheeting						
B00J - R0006 - Laboratory L.S. - 80.13 m2							
No Asbestos							
B00J - R0007 - Preparation - Science - 47.72 m2							
No Asbestos							
B00J - R0008 - Laboratory L.S. - 80.13 m2							
No Asbestos							
B00J - R0009 - Laboratory L.S. - 79.95 m2							
No Asbestos							
B00J - R0010 - Growing/Breeding - 21.57 m2							
No Asbestos							
B00J - R0011 - Preparation - Science - 47.29 m2							
No Asbestos							
B00J - R0012 - Laboratory L.S. - 80.04 m2							
No Asbestos							
B00J - R0014 - Laboratory L.S. - 84.85 m2							
No Asbestos							
B00J - R0015 - Preparation - Science - 50.39 m2							
No Asbestos							
B00J - R0016 - Laboratory L.S. - 85.12 m2							
No Asbestos							
B00J - R0017 - External Movement - 22.89 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00J - R0018 - External Movement - 6.77 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00J - R0019 - External Movement - 22.27 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00J - R0020 - Staff Study - 19.67 m2							
No Asbestos							
B00J - R0021 - Tea Room - 10.58 m2							
No Asbestos							
B00K - Pupil Facilities - 1983 - Brick/Block							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00K - R0001 - Toilets-Girls - 18.43 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	15m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00K - R0002 - Distribution Board Cupboard - 1.33 m2							Note: No inspection of live electrical installation
Ceiling Structures/Linings	Flat AC Sheeting						
B00M - Storage - 2005 - Brick/Block							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00M - R0001 - General Storeroom - 7.72 m2							
No Asbestos							
B00P - Performance Learning - 2011 - Brick/Veneer							

Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Interior		
B00P - R0001 - Performance Workspace - 185.93 m2		
No Asbestos		
B00P - R0002 - Office/Store - 7.83 m2		
No Asbestos		
B00P - R0003 - Toilets-Boys - 3.64 m2		
No Asbestos		
B00P - R0004 - Toilets-Boys - 3.64 m2		
No Asbestos		
B00P - R0005 - Toilets-Girls - 3.64 m2		
No Asbestos		
B00P - R0006 - Toilets-Girls - 3.64 m2		
No Asbestos		
B00P - R0007 - External Movement - 32.87 m2		
No Asbestos		
B00X - Building Services - 1995 - Brick/Block		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Interior		
B00X - R0001 - Plant - 7.52 m2		
No Asbestos		
B00Y - Building Services - 1995 - Brick/Block		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Interior		
B00Y - R0001 - Plant - 1.9 m2		
No Asbestos		
B00Z - Other-Commercial - 2005 - Fibre Cement Clad		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Interior		
B00Z - R0001 - Other-Commercial - 149.7 m2		
No Asbestos		

Demountables

There are no Demountable(s) Located at this school as per the AMS records as of 09-Sep-2020