

Asbestos Register

(Hazardous Materials and Risk Assessment)

| | |
|-------------------------------|-----------------------------------|
| School: | Jamison High School (8559) |
| Region: | Western Sydney AMU |
| State Electorate: | Penrith |
| Local Government Area: | Penrith |

| | |
|--------------------------|-----------------|
| Last Reviewed By: | WSP 07-FEB-2017 |
| Last Revised By: | |

| | |
|--|-----------|
| Historical Fibro In Grounds Investigations/Events | No |
| <p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p> | |



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>

<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

| Rating | Description |
|----------------------------|--|
| Good condition (1) | For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles |
| Minimal damage (2) | For non-friable asbestos that has a very small amount of damage, eg hairline cracks. |
| Some damage / unsealed (3) | For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed. |
| Poor condition (4) | For non-friable asbestos that has extensive damage. Visible asbestos debris |
| Friable asbestos (5) | Any occurrence of friable asbestos |

| Product | Material Description | Extent | Location | Material Condition | Risk Status | Remediation Priority | Result |
|---|----------------------|--------|----------|--------------------|-------------|----------------------|--------|
| B00A - Multi Purpose Facilities - 1984 - Brick/Block | | | | | | | |
| Exterior | | | | | | | |
| Wall Cladding | Flat AC Sheeting | | | | | | |
| Eaves Linings | Flat AC Sheeting | | | | | | |
| Wall Linings Internal - Infill | Flat AC Sheeting | | | | | | |
| Ceiling Voids | No Asbestos Found | | | | | | |
| Underfloor Voids | No Asbestos Found | | | | | | |
| Interior | | | | | | | |
| B00A - R0001 - Multi-Purpose Space - 115.56 m2 | | | | | | | |
| No Asbestos | | | | | | | |
| B00A - R0002 - Multi-Purpose Space - 85.57 m2 | | | | | | | |
| No Asbestos | | | | | | | |
| B00A - R0003 - Multi-Purpose Space - 85.05 m2 | | | | | | | |
| No Asbestos | | | | | | | |
| B00A - R0004 - Chair Store - 11.73 m2 | | | | | | | |
| No Asbestos | | | | | | | |
| B00A - R0005 - Chair Store - 11.73 m2 | | | | | | | |
| No Asbestos | | | | | | | |
| B00A - R0006 - Garden Store Room - 8.76 m2 | | | | | | | |
| No Asbestos | | | | | | | |
| B00A - R0007 - General Assistants - 13.95 m2 | | | | | | | |
| No Asbestos | | | | | | | |
| B00A - R0008 - Chair Store - 21.21 m2 | | | | | | | |
| No Asbestos | | | | | | | |
| B00A - R0010 - Toilets-Disabled - 4.41 m2 | | | | | | | |
| No Asbestos | | | | | | | |
| B00A - R0011 - General Storeroom - 8.1 m2 | | | | | | | |
| No Asbestos | | | | | | | |
| B00A - R0012 - Student Canteen - 61.33 m2 | | | | | | | |
| No Asbestos | | | | | | | |
| B00A - R0013 - Toilets-Boys - 12.35 m2 | | | | | | | |
| Partition Walls (Cubicles) | Compressed AC Sheet | | | | | | |
| B00A - R0014 - Toilets-Girls - 12.35 m2 | | | | | | | |
| Partition Walls (Cubicles) | Compressed AC Sheet | | | | | | |
| B00A - R0015 - Interview/Office - Type 1 - 14.36 m2 | | | | | | | |
| No Asbestos | | | | | | | |
| B00A - R0016 - Staff Shower - 5.94 m2 | | | | | | | |
| No Asbestos | | | | | | | |
| B00A - R0017 - Sport Equipment Store - 17.56 m2 | | | | | | | |
| No Asbestos | | | | | | | |
| B00A - R0018 - Movement - 160.79 m2 | | | | | | | |
| Ceiling Structures/Linings | Flat AC Sheeting | | | | | | |
| B00A - R0019 - Movement - 10.94 m2 | | | | | | | |
| Ceiling Structures/Linings | Flat AC Sheeting | | | | | | |
| B00A - R0020 - Distribution Board Cupboard - 5.23 m2 | | | | | | | |
| No Asbestos | | | | | | | |
| B00A - R0021 - Sport Equipment Store - 46.45 m2 | | | | | | | |
| No Asbestos | | | | | | | |
| B00A - R0022 - Shower/Change - 60.54 m2 | | | | | | | |
| Partition Walls (Cubicles) | Compressed AC Sheet | | | | | | |

Note: No inspection of live electrical installation

| | | |
|--|---------------------|--|
| B00A - R0023 - Shower/Change - 55.01 m2 | | |
| Partition Walls (Cubicles) | Compressed AC Sheet | |
| B00A - R0024 - Stage - 101.32 m2 | | |
| No Asbestos | | |
| B00A - R0025 - Multi-Purpose Space - 466.34 m2 | | |
| No Asbestos | | |
| B00A - R0026 - Movement - 52.79 m2 | | |
| No Asbestos | | |
| B00A - R0027 - Garden Store Room - 12.25 m2 | | |
| No Asbestos | | |
| B00A - R0028 - Cleaning Store - Distributed - 11.2 m2 | | |
| No Asbestos | | |
| B00A - R0029 - Staff - Toilet - 6.93 m2 | | |
| Partition Walls (Cubicles) | Compressed AC Sheet | |
| B00A - R0030 - Staff - Toilet - 6.93 m2 | | |
| Partition Walls (Cubicles) | Compressed AC Sheet | |
| B00A - R0031 - Multi-Purpose Space - 52.2 m2 | | |
| No Asbestos | | |
| B00A - R0032 - Cleaning Supplies Store - 25.02 m2 | | |
| No Asbestos | | |
| B00A - R0034 - Movement - 13.86 m2 | | |
| Ceiling Structures/Linings | Flat AC Sheeting | |
| B00A - R0035 - External Movement - 339.34 m2 | | |
| No Asbestos | | |
| B00A - R0036 - External Movement - 143.17 m2 | | |
| Ceiling Structures/Linings | Flat AC Sheeting | |
| B00A - R0037 - External Movement - 24.47 m2 | | |
| Ceiling Structures/Linings | Flat AC Sheeting | |
| B00A - R0038 - External Movement - 16.65 m2 | | |
| Ceiling Structures/Linings | Flat AC Sheeting | |
| B00A - R0039 - External Movement - 16.65 m2 | | |
| Ceiling Structures/Linings | Flat AC Sheeting | |
| B00B - Administration - 1984 - Brick/Block | | |
| Exterior | | |
| Wall Cladding | Flat AC Sheeting | |
| Eaves Linings | Flat AC Sheeting | |
| Wall Linings Internal - Infill | Flat AC Sheeting | |
| Underfloor Voids | No Asbestos Found | |
| Ceiling Voids | No Asbestos Found | |
| Interior | | |
| B00B - R0001 - Principal Office - 22.13 m2 | | |
| No Asbestos | | |
| B00B - R0002 - Administration - Clerical - 43.67 m2 | | |
| No Asbestos | | |
| B00B - R0003 - Duplicating Workroom - 27.96 m2 | | |
| No Asbestos | | |
| B00B - R0004 - Interview/Office - Type 1 - 14.31 m2 | | |
| No Asbestos | | |
| B00B - R0005 - Deputy Principal Office - 18.39 m2 | | |
| No Asbestos | | |
| B00B - R0006 - Deputy Principal Office - 12.58 m2 | | |

| | | |
|--|------------------|--|
| No Asbestos | | |
| B00B - R0011 - Distribution Board Cupboard - .9 m2 | | Note: No inspection of live electrical installation |
| No Asbestos | | |
| B00B - R0014 - Staff - Toilet - 2.7 m2 | | |
| No Asbestos | | |
| B00B - R0015 - Staff - Toilet - 2.94 m2 | | |
| No Asbestos | | |
| B00B - R0017 - Security Store - 16.89 m2 | | |
| No Asbestos | | |
| B00B - R0019 - Design L.S. - 74.47 m2 | | |
| No Asbestos | | |
| B00B - R0020 - Food Technology L.S. - 104.16 m2 | | |
| No Asbestos | | |
| B00B - R0021 - Pantry - 16.97 m2 | | |
| No Asbestos | | |
| B00B - R0022 - Food Technology L.S. - 104.45 m2 | | |
| No Asbestos | | |
| B00B - R0023 - Staff Study - 41.29 m2 | | |
| No Asbestos | | |
| B00B - R0024 - Design L.S. - 68.07 m2 | | |
| No Asbestos | | |
| B00B - R0025 - Laundry - 17.91 m2 | | |
| No Asbestos | | |
| B00B - R0026 - Staff - Toilet - 2.1 m2 | | |
| No Asbestos | | |
| B00B - R0027 - Toilets-Disabled - 5.6 m2 | | |
| No Asbestos | | |
| B00B - R0028 - Movement - 82.77 m2 | | |
| No Asbestos | | |
| B00B - R0029 - Movement - 73.24 m2 | | |
| No Asbestos | | |
| B00B - R0030 - External Movement - 29.87 m2 | | |
| No Asbestos | | |
| B00B - R0031 - External Movement - 3.77 m2 | | |
| Ceiling Structures/Linings | Flat AC Sheeting | |
| B00B - R0032 - External Movement - 2.17 m2 | | |
| Ceiling Structures/Linings | Flat AC Sheeting | |
| B00B - R0033 - Ancillary Staff - 11.78 m2 | | |
| No Asbestos | | |
| B00B - R0034 - Movement - 42.54 m2 | | |
| No Asbestos | | |
| B00B - R0035 - General Storeroom - 1.63 m2 | | |
| No Asbestos | | |
| B00B - R0036 - Distribution Board Cupboard - .74 m2 | | Note: No inspection of live electrical installation |
| No Asbestos | | |
| B00B - R0037 - Movement - 30.98 m2 | | |
| No Asbestos | | |
| B00B - R0038 - Deputy Principal Office - 12.8 m2 | | |
| No Asbestos | | |
| B00B - R0039 - Disabled Toilet - 3.66 m2 | | |
| No Asbestos | | |
| B00B - R0040 - Clinic - Girls - 8.38 m2 | | |

| | | |
|--|-------------------|--|
| No Asbestos | | |
| B00B - R0041 - Clinic - Boys - 7.43 m2 | | |
| No Asbestos | | |
| B00B - R0042 - General Storeroom - .94 m2 | | |
| No Asbestos | | |
| B00B - R0043 - Movement - 6.25 m2 | | |
| No Asbestos | | |
| B00B - R0045 - Movement - 29.99 m2 | | |
| No Asbestos | | |
| B00B - R1001 - General Learning Space - 46.5 m2 | | |
| No Asbestos | | |
| B00B - R1002 - General Learning Space - 46.37 m2 | | |
| No Asbestos | | |
| B00B - R1003 - General Learning Space - 47.27 m2 | | |
| No Asbestos | | |
| B00B - R1004 - General Learning Space - 47.94 m2 | | |
| No Asbestos | | |
| B00B - R1005 - Staff Study - 40.6 m2 | | |
| No Asbestos | | |
| B00B - R1006 - General Learning Space - 48.28 m2 | | |
| No Asbestos | | |
| B00B - R1007 - General Learning Space - 46.71 m2 | | |
| No Asbestos | | |
| B00B - R1008 - General Learning Space - 46.44 m2 | | |
| No Asbestos | | |
| B00B - R1009 - General Learning Space - 46.45 m2 | | |
| No Asbestos | | |
| B00B - R1010 - Interview/Office - Type 1 - 13.66 m2 | | |
| No Asbestos | | |
| B00B - R1011 - Distribution Board Cupboard - .64 m2 | | Note: No inspection of live electrical installation |
| No Asbestos | | |
| B00B - R1012 - Security Store - 5.07 m2 | | |
| No Asbestos | | |
| B00B - R1013 - Security Store - 5.85 m2 | | |
| No Asbestos | | |
| B00B - R1014 - General Storeroom - 24.49 m2 | | |
| No Asbestos | | |
| B00B - R1015 - General Storeroom - 24.58 m2 | | |
| No Asbestos | | |
| B00B - R1016 - Movement - 198.5 m2 | | |
| No Asbestos | | |
| B00C - Library - 1984 - Brick/Block | | |
| Exterior | | |
| Wall Cladding | Flat AC Sheeting | |
| Eaves Linings | Flat AC Sheeting | |
| Wall Linings Internal - Infill | Flat AC Sheeting | |
| Underfloor Voids | No Asbestos Found | |
| Ceiling Voids | No Asbestos Found | |
| Interior | | |
| B00C - R0001 - General Learning Space - 74.51 m2 | | |
| No Asbestos | | |

| | |
|---|---------------------|
| B00C - R0002 - G.L.S. Store - 10.63 m2 | |
| No Asbestos | |
| B00C - R0003 - Main Switchroom - 10.94 m2 | |
| No Asbestos | |
| B00C - R0004 - Sport Equipment Store - 11.33 m2 | |
| No Asbestos | |
| B00C - R0005 - G.L.S. Store - 11.29 m2 | |
| No Asbestos | |
| B00C - R0006 - Commonroom - 120.48 m2 | |
| No Asbestos | |
| B00C - R0007 - Staff - Toilet - 3.15 m2 | |
| No Asbestos | |
| B00C - R0009 - Toilets-Boys - 20.48 m2 | |
| Partition Walls (Cubicles) | Compressed AC Sheet |
| B00C - R0010 - Cleaning Store - Distributed - 2.38 m2 | |
| No Asbestos | |
| B00C - R0011 - External Movement - 53.04 m2 | |
| No Asbestos | |
| B00C - R0012 - Cleaning Store - Distributed - 2.55 m2 | |
| No Asbestos | |
| B00C - R0013 - Toilets-Girls - 20.66 m2 | |
| Partition Walls (Cubicles) | Compressed AC Sheet |
| B00C - R0014 - External Movement - 53.6 m2 | |
| No Asbestos | |
| B00C - R0015 - Movement - 190.02 m2 | |
| No Asbestos | |
| B00C - R0016 - Ramp - 56.34 m2 | |
| No Asbestos | |
| B00C - R0017 - Stairs - 10.6 m2 | |
| No Asbestos | |
| B00C - R0018 - External Movement - 17.89 m2 | |
| No Asbestos | |
| B00C - R0019 - External Stairs - 17.03 m2 | |
| No Asbestos | |
| B00C - R0020 - Movement - 10.45 m2 | |
| No Asbestos | |
| B00C - R0021 - Cleaning Store - Distributed - 11.08 m2 | |
| No Asbestos | |
| B00C - R0022 - Sport Equipment Store - 11.4 m2 | |
| No Asbestos | |
| B00C - R1001 - Cleaning Store - Distributed - 3.27 m2 | |
| No Asbestos | |
| B00C - R1002 - Librarian - 53.05 m2 | |
| No Asbestos | |
| B00C - R1003 - Librarian - 13.54 m2 | |
| No Asbestos | |
| B00C - R1004 - Main Area - 380.29 m2 | |
| No Asbestos | |
| B00C - R1005 - Seminar - 13.54 m2 | |
| No Asbestos | |
| B00C - R1006 - Seminar - 11.32 m2 | |

| | | |
|---|---------------------|--|
| No Asbestos | | |
| B00C - R1007 - Audio Visual Workroom - 44.2 m2 | | |
| No Asbestos | | |
| B00C - R1008 - Distribution Board Cupboard - .7 m2 | | Note: No inspection of live electrical installation |
| No Asbestos | | |
| B00C - R1009 - Staff - Toilet - 2.38 m2 | | |
| No Asbestos | | |
| B00C - R1010 - Toilets-Girls - 20.48 m2 | | |
| Partition Walls (Cubicles) | Compressed AC Sheet | |
| B00C - R1011 - Toilets-Boys - 2.38 m2 | | |
| No Asbestos | | |
| B00C - R1012 - Cleaning Store - Distributed - 20.48 m2 | | |
| No Asbestos | | |
| B00C - R1013 - Movement - 121.22 m2 | | |
| No Asbestos | | |
| B00C - R1014 - Cleaning Store - Distributed - 2.31 m2 | | |
| No Asbestos | | |
| B00C - R1015 - Toilets-Girls - 20.7 m2 | | |
| Partition Walls (Cubicles) | Compressed AC Sheet | |
| B00C - R1016 - Staff - Toilet - 2.31 m2 | | |
| No Asbestos | | |
| B00C - R1017 - Toilets-Boys - 20.7 m2 | | |
| Partition Walls (Cubicles) | Compressed AC Sheet | |
| B00C - R1018 - Movement - 224.12 m2 | | |
| No Asbestos | | |
| B00C - R1019 - Ramp - 32.5 m2 | | |
| No Asbestos | | |
| B00C - R1020 - Movement - 51.05 m2 | | |
| No Asbestos | | |
| B00C - R1021 - Stairs - 20.32 m2 | | |
| No Asbestos | | |
| B00C - R1022 - Stairs - 20.79 m2 | | |
| No Asbestos | | |
| B00D - General Learning - 1984 - Brick/Block | | |
| Exterior | | |
| Wall Cladding | Flat AC Sheeting | |
| Eaves Linings | Flat AC Sheeting | |
| Wall Linings Internal - Infill | Flat AC Sheeting | |
| Ceiling Voids | No Asbestos Found | |
| Underfloor Voids | No Asbestos Found | |
| Interior | | |
| B00D - R0001 - Staff Study - 25.4 m2 | | |
| No Asbestos | | |
| B00D - R0002 - Staff Study - 25.4 m2 | | |
| No Asbestos | | |
| B00D - R0003 - General Learning Space - 46.11 m2 | | |
| No Asbestos | | |
| B00D - R0004 - General Learning Space - 46.17 m2 | | |
| No Asbestos | | |
| B00D - R0005 - Interview/Office - Type 1 - 13.59 m2 | | |
| No Asbestos | | |

| | |
|--|--|
| B00D - R0006 - General Storeroom - 24.48 m2 | |
| No Asbestos | |
| B00D - R0007 - Security Store - 5.78 m2 | |
| No Asbestos | |
| B00D - R0008 - Distribution Board Cupboard - .63 m2 | Note: No inspection of live electrical installation |
| No Asbestos | |
| B00D - R0009 - Security Store - 5.07 m2 | |
| No Asbestos | |
| B00D - R0010 - Seminar - 24.57 m2 | |
| No Asbestos | |
| B00D - R0011 - General Learning Space - 40.25 m2 | |
| No Asbestos | |
| B00D - R0012 - General Learning Space - 46.03 m2 | |
| No Asbestos | |
| B00D - R0013 - General Learning Space - 46.23 m2 | |
| No Asbestos | |
| B00D - R0014 - General Learning Space - 38.41 m2 | |
| No Asbestos | |
| B00D - R0015 - General Learning Space - 48.01 m2 | |
| No Asbestos | |
| B00D - R0016 - General Learning Space - 48.28 m2 | |
| No Asbestos | |
| B00D - R0017 - Movement - 230.16 m2 | |
| No Asbestos | |
| B00E - General Learning - 1984 - Brick/Block | |
| Exterior | |
| Wall Cladding | Flat AC Sheeting |
| Eaves Linings | Flat AC Sheeting |
| Wall Linings Internal - Infill | Flat AC Sheeting |
| Underfloor Voids | No Asbestos Found |
| Ceiling Voids | No Asbestos Found |
| Interior | |
| B00E - R0001 - General Learning Space - 40.32 m2 | |
| No Asbestos | |
| B00E - R0002 - General Learning Space - 46.24 m2 | |
| No Asbestos | |
| B00E - R0003 - General Learning Space - 46.24 m2 | |
| No Asbestos | |
| B00E - R0004 - General Learning Space - 38.06 m2 | |
| No Asbestos | |
| B00E - R0005 - General Learning Space - 48.21 m2 | |
| No Asbestos | |
| B00E - R0006 - General Learning Space - 48.08 m2 | |
| No Asbestos | |
| B00E - R0007 - Staff Study - 37.07 m2 | |
| No Asbestos | |
| B00E - R0008 - General Learning Space - 46.1 m2 | |
| No Asbestos | |
| B00E - R0009 - General Learning Space - 46.23 m2 | |
| No Asbestos | |
| B00E - R0010 - Interview/Office - T-type 1 - 13.59 m2 | |

| | | |
|--|-------------------|--|
| No Asbestos | | |
| B00E - R0011 - General Storeroom - 24.64 m2 | | |
| No Asbestos | | |
| B00E - R0012 - Security Store - 5.9 m2 | | |
| No Asbestos | | |
| B00E - R0013 - Security Store - 5.01 m2 | | |
| No Asbestos | | |
| B00E - R0014 - Distribution Board Cupboard - .62 m2 | | |
| | | Note: No inspection of live electrical installation |
| No Asbestos | | |
| B00E - R0015 - General Storeroom - 24.57 m2 | | |
| No Asbestos | | |
| B00E - R0016 - Movement - 227.75 m2 | | |
| No Asbestos | | |
| B00F - Science Learning - 1984 - Brick/Block | | |
| Exterior | | |
| Wall Cladding | Flat AC Sheeting | |
| Eaves Linings | Flat AC Sheeting | |
| Wall Linings Internal - Infill | Flat AC Sheeting | |
| Underfloor Voids | No Asbestos Found | |
| Ceiling Voids | No Asbestos Found | |
| Interior | | |
| B00F - R0001 - Staff Study - 22.21 m2 | | |
| No Asbestos | | |
| B00F - R0002 - Staff Study - 23.22 m2 | | |
| No Asbestos | | |
| B00F - R0003 - Cleaning Store - Distributed - 1.79 m2 | | |
| No Asbestos | | |
| B00F - R0004 - Staff Study - 41.98 m2 | | |
| No Asbestos | | |
| B00F - R0005 - General Storeroom - 12.83 m2 | | |
| No Asbestos | | |
| B00F - R0006 - Staff Study - 13.61 m2 | | |
| No Asbestos | | |
| B00F - R0007 - Cleaning Supplies Store - 18.07 m2 | | |
| No Asbestos | | |
| B00F - R0008 - Distribution Board Cupboard - .81 m2 | | |
| | | Note: No inspection of live electrical installation |
| No Asbestos | | |
| B00F - R0009 - Laboratory L.S. - 79.1 m2 | | |
| No Asbestos | | |
| B00F - R0010 - Preparation - 31.35 m2 | | |
| No Asbestos | | |
| B00F - R0011 - Laboratory L.S. - 78.4 m2 | | |
| No Asbestos | | |
| B00F - R0012 - Chemical Store - 12.13 m2 | | |
| No Asbestos | | |
| B00F - R0013 - Growing/Breeding - 8.84 m2 | | |
| No Asbestos | | |
| B00F - R0014 - Laboratory L.S. - 79.2 m2 | | |
| No Asbestos | | |
| B00F - R0015 - Preparation - 39.24 m2 | | |
| No Asbestos | | |

| | | |
|--|------------------|--|
| B00F - R0016 - Laboratory L.S. - 78.12 m2 | | |
| No Asbestos | | |
| B00F - R0017 - Laboratory L.S. - 84.15 m2 | | |
| No Asbestos | | |
| B00F - R0018 - Preparation - 30.2 m2 | | |
| No Asbestos | | |
| B00F - R0019 - Laboratory L.S. - 80.01 m2 | | |
| No Asbestos | | |
| B00F - R0020 - Apparatus Store - 37.05 m2 | | |
| No Asbestos | | |
| B00F - R0021 - Movement - 183.21 m2 | | |
| No Asbestos | | |
| B00F - R0022 - Movement - 34.96 m2 | | |
| No Asbestos | | |
| B00F - R0023 - External Movement - 2.28 m2 | | |
| No Asbestos | | |
| B00F - R0024 - External Movement - 294.4 m2 | | |
| No Asbestos | | |
| B00F - R1001 - General Learning Space - 46.1 m2 | | |
| No Asbestos | | |
| B00F - R1002 - General Learning Space - 46.24 m2 | | |
| No Asbestos | | |
| B00F - R1003 - General Learning Space - 46.85 m2 | | |
| No Asbestos | | |
| B00F - R1004 - General Learning Space - 48.28 m2 | | |
| No Asbestos | | |
| B00F - R1005 - Staff Study - 39.9 m2 | | |
| No Asbestos | | |
| B00F - R1006 - General Learning Space - 48.28 m2 | | |
| No Asbestos | | |
| B00F - R1007 - General Learning Space - 46.84 m2 | | |
| No Asbestos | | |
| B00F - R1008 - General Learning Space - 46.51 m2 | | |
| No Asbestos | | |
| B00F - R1009 - General Learning Space - 46.51 m2 | | |
| No Asbestos | | |
| B00F - R1010 - Interview/Office - Type 1 - 13.59 m2 | | |
| No Asbestos | | |
| B00F - R1011 - General Storeroom - 24.53 m2 | | |
| No Asbestos | | |
| B00F - R1012 - Security Store - 4.99 m2 | | |
| No Asbestos | | |
| B00F - R1013 - Distribution Board Cupboard - .62 m2 | | Note: No inspection of live electrical installation |
| No Asbestos | | |
| B00F - R1014 - Serviced Learning Space - 30.91 m2 | | |
| No Asbestos | | |
| B00F - R1015 - Movement - 199.4 m2 | | |
| No Asbestos | | |
| B00F - R1017 - External Movement - 3.06 m2 | | |
| Wall Linings Internal | Flat AC Sheeting | |
| B00F - R1018 - Covered Area - 48.16 m2 | | |
| No Asbestos | | |

B00G - Technological & Applied Studies - 1984 - Brick/Block

Exterior

| | | |
|--------------------------------|-------------------|--|
| Wall Cladding | Flat AC Sheeting | |
| Eaves Linings | Flat AC Sheeting | |
| Wall Linings Internal - Infill | Flat AC Sheeting | |
| Underfloor Voids | No Asbestos Found | |
| Ceiling Voids | No Asbestos Found | |

Interior

B00G- R0001 - Music Learning Space - 78.22 m2

No Asbestos

B00G- R0002 - Staff Study - 24.58 m2

No Asbestos

B00G- R0003 - Practice/Seminar - 22 m2

No Asbestos

B00G- R0004 - Music Learning Space - 60.62 m2

No Asbestos

B00G- R0005 - Music Store - 17.59 m2

No Asbestos

B00G- R0006 - Music Store - 12.42 m2

No Asbestos

B00G- R0007 - Movement - 26.97 m2

No Asbestos

B00G- R0008 - External Movement - 2.23 m2

Ceiling Structures/Linings Flat AC Sheeting

B00G- R0009 - Movement - .85 m2

Ceiling Structures/Linings Flat AC Sheeting

B00G- R0010 - Movement - 16.22 m2

Wall Linings Internal Flat AC Sheeting

Ceiling Structures/Linings Flat AC Sheeting

B00G- R0011 - Toilets-Boys - 13.48 m2

Partition Walls (Cubicles) Compressed AC Sheet

B00G- R0012 - Cleaning Store - Distributed - 3.67 m2

No Asbestos

B00G- R0013 - Staff - Toilet - 3.67 m2

No Asbestos

B00G- R0014 - Toilets-Girls - 11.59 m2

Partition Walls (Cubicles) Compressed AC Sheet

B00G- R0017 - Design L.S. - 54.73 m2

No Asbestos

B00G- R0018 - External Movement - 4.56 m2

Ceiling Structures/Linings Flat AC Sheeting

B00G- R0019 - Art Learning Space - 61.92 m2

No Asbestos

B00G- R0020 - Art Learning Space - 60.73 m2

No Asbestos

B00G- R0021 - Staff Study - 20.67 m2

No Asbestos

B00G- R0022 - Bulk Store - 20.5 m2

No Asbestos

B00G- R0023 - Resources - 21.72 m2

No Asbestos

| | |
|--|--|
| B00G - R0024 - Security Store - 5.78 m2 | |
| No Asbestos | |
| B00G - R0025 - Movement - 87.89 m2 | |
| No Asbestos | |
| B00G - R0026 - Distribution Board Cupboard - .74 m2 | Note: No inspection of live electrical installation |
| No Asbestos | |
| B00G - R0027 - Art Learning Space - 61.75 m2 | |
| No Asbestos | |
| B00G - R0028 - Darkroom Space - 61.92 m2 | |
| No Asbestos | |
| B00G - R0029 - Kiln Space - 27.14 m2 | |
| No Asbestos | |
| B00G - R0030 - Art Learning Space - 57.16 m2 | |
| No Asbestos | |
| B00G - R0031 - Staff Study - 27.21 m2 | |
| No Asbestos | |
| B00G - R0032 - Materials Store - 14.95 m2 | |
| No Asbestos | |
| B00G - R0033 - Materials Store - 31.55 m2 | |
| No Asbestos | |
| B00G - R0034 - Materials Technology L.S. - 93.05 m2 | |
| No Asbestos | |
| B00G - R0035 - Dust Extraction Space - 9.96 m2 | |
| No Asbestos | |
| B00G - R0036 - Wood Technology Bay - 29.89 m2 | |
| No Asbestos | |
| B00G - R0037 - Materials Technology L.S. - 90.23 m2 | |
| No Asbestos | |
| B00G - R0040 - Distribution Board Cupboard - 1.46 m2 | Note: No inspection of live electrical installation |
| No Asbestos | |
| B00G - R0042 - External Movement - 8.69 m2 | |
| Ceiling Structures/Linings | Flat AC Sheeting |
| B00G - R0043 - Materials Technology L.S. - 91.98 m2 | |
| No Asbestos | |
| B00G - R0044 - Materials Store - 30.16 m2 | |
| No Asbestos | |
| B00G - R0045 - Materials Technology L.S. - 88.62 m2 | |
| No Asbestos | |
| B00G - R0046 - Movement - 74.85 m2 | |
| No Asbestos | |
| B00G - R0047 - External Movement - 278.91 m2 | |
| Ceiling Structures/Linings | Flat AC Sheeting |
| B00G - R0048 - Metal Technology Bay - 32.8 m2 | |
| No Asbestos | |
| B00G - R0049 - Welding/Hot Metals Area - 5.43 m2 | |
| No Asbestos | |
| B00G - R0050 - Welding/Hot Metals Area - 4.35 m2 | |
| No Asbestos | |
| B00G - R0051 - Materials Workshop - Type 2 - 35.43 m2 | |
| No Asbestos | |
| B00G - R0052 - Computer Room - 81.54 m2 | |
| No Asbestos | |

B00H - Agricultural Science - 1984 - Brick/Block

Exterior

| | | |
|--------------------------------|-------------------|--|
| Wall Cladding | Flat AC Sheeting | |
| Wall Linings Internal - Infill | Flat AC Sheeting | |
| Underfloor Voids | No Asbestos Found | |
| Ceiling Voids | No Asbestos Found | |

Interior

B00H - R0001 - Machine Storage - 36.65 m2

No Asbestos

B00H - R0002 - Plant Space - 9.67 m2

No Asbestos

B00H - R0003 - Animal Space - 25.2 m2

No Asbestos

B00H - R0005 - Distribution Board Cupboard - .41 m2

Note: No inspection of live electrical installation

No Asbestos

B00H - R0006 - Agriculture Covered Area - 25.49 m2

No Asbestos

B00H - R0007 - Agriculture Covered Area - 13 m2

No Asbestos

B00H - R0008 - General Storeroom - 3.71 m2

No Asbestos

B00H - R0009 - Movement - 12.43 m2

| | | |
|----------------------------|------------------|--|
| Wall Linings Internal | Flat AC Sheeting | |
| Ceiling Structures/Linings | Flat AC Sheeting | |

B00H - R0010 - Staff Study - 4.51 m2

| | | |
|----------------------------|------------------|--|
| Wall Linings Internal | Flat AC Sheeting | |
| Ceiling Structures/Linings | Flat AC Sheeting | |

B00I - General Learning - 2009 - Brick/Veneer

Exterior

| | | |
|------------------|-------------------|--|
| Ceiling Voids | No Asbestos Found | |
| Underfloor Voids | No Asbestos Found | |

Interior

B00I - R0001 - General Learning Space - 59.57 m2

No Asbestos

B00I - R0002 - Clinic - 47 m2

No Asbestos

B00I - R0003 - Movement - 41.07 m2

No Asbestos

B00I - R0004 - Clinic - 28.79 m2

No Asbestos

B00I - R0005 - Toilets-Disabled - 6.3 m2

No Asbestos

B00I - R0006 - Garden Store Room - 69.12 m2

No Asbestos

B00I - R0007 - Cleaning Supplies Store - 3.15 m2

No Asbestos

B00I - R0008 - Distribution Board Cupboard - .67 m2

Note: No inspection of live electrical installation

No Asbestos

B00I - R0009 - External Movement - 2.72 m2

No Asbestos

| | |
|--|--|
| B001 - R0010 - Clinic - 41.86 m2 | |
| No Asbestos | |
| B001 - R0011 - Access Staff Shower/Toilet - 4.73 m2 | |
| No Asbestos | |
| B001 - R0012 - External Movement - 12.35 m2 | |
| No Asbestos | |

Demountables

OS 601 12145 - Learning Unit - Standard/Withdrawal - Placement Date : 20-OCT-2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 601 13472 - Learning Unit - Standard/Withdrawal - Placement Date : 20-OCT-2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 601 19786 - Learning Unit - Standard/Withdrawal - Placement Date : 02-OCT-2019

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found