



# Preface to Asbestos Register

## Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
  - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
  - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
  - o Any wall cavity
  - o Sub floor area, particularly formwork for slabs in/on ground,
  - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.  
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

## Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

## Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

## Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

## Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>

<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

## Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

### 3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
<b>B00A - Administration/Staff Facilities - 1880 - Timber</b>							
<b>Exterior</b>							
Eaves Linings	Flat AC Sheeting	50m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	Flat AC Sheeting	1	Variable positions	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)	Chrysotile (white asbestos)
Underfloor Voids	Compressed AC Sheet						
<b>Interior</b>							
<b>B00A - R0002 - Sick Bay - 13.54 m2</b>							
No Asbestos							
<b>B00A - R0005 - Movement - 26.47 m2</b>							
No Asbestos							
<b>B00A - R0006 - Movement - 20.54 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	21m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	3m2	North facing, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00A - R0011 - Principal - 19.93 m2</b>							
No Asbestos							
<b>B00A - R0012 - Deputy Principal - 11.57 m2</b>							
No Asbestos							
<b>B00A - R0015 - Movement - 22.78 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	23m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00A - R0017 - Sick Bay - 10.73 m2</b>							
Wall Linings Internal	Flat AC Sheeting						
<b>B00A - R0018 - Access Shower/Toilet - 6.24 m2</b>							
Wall Linings Internal	Flat AC Sheeting						
<b>B00A - R0019 - Staff Toilet - 4.99 m2</b>							
Wall Linings Internal	Flat AC Sheeting						
<b>B00A - R0020 - Staff Kitchen - 9.54 m2</b>							
No Asbestos							
<b>B00A - R0021 - Staff Room - 57.18 m2</b>							
No Asbestos							
<b>B00A - R0022 - Clerical Office/Workroom - 47.81 m2</b>							
No Asbestos							
<b>B00A - R0023 - Communications Room - 4.95 m2</b>							
Floor Coverings Res/Textile	Compressed AC Sheet	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00A - R0024 - Main Switch Board - 2.37 m2</b>							
Floor Coverings Res/Textile	Compressed AC Sheet	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - General Learning - 1982 - Brick/Veneer</b>							
<b>Exterior</b>							
Underfloor Voids - Slab on Ground	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00B - R0004 - Distribution Board - .6 m2</b>							
						<b>Note: No inspection of live electrical installation</b>	
No Asbestos							

<b>B00B - R0005 - Movement - 85.66 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	86m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R0006 - Practical Activities - 1hb - 19.13 m2</b>							
No Asbestos							
<b>B00B - R0007 - Withdrawal Space - 2hb - 15.97 m2</b>							
No Asbestos							
<b>B00B - R0008 - Practical Activities - 1hb - 20.3 m2</b>							
No Asbestos							
<b>B00B - R0009 - Home Base Store - 7.85 m2</b>							
No Asbestos							
<b>B00B - R0010 - Home Base - 79.36 m2</b>							
No Asbestos							
<b>B00B - R0011 - Home Base - 75.01 m2</b>							
No Asbestos							
<b>B00B - R0012 - Home Base Store - 8.03 m2</b>							
No Asbestos							
<b>B00D - General Learning - 1971 - Brick/Block</b>							
<b>Exterior</b>							
Underfloor Voids - Slab on Ground	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00D - R0001 - Movement - 13.3 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00D - R0008 - Distribution Board - .94 m2</b>							
							<b>Note: No inspection of live electrical installation</b>
No Asbestos							
<b>B00D - R0009 - Movement - 97.38 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 70 - 120 m2) - ( X8 )						
<b>B00D - R0010 - Movement - 40.64 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00D - R0012 - Canteen Office/Store - 3.74 m2</b>							
Ceiling Structures/Linings	No Asbestos Found						
<b>B00D - R0013 - Staff Toilet - 3.43 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )						
<b>B00D - R0014 - Cleaning Supplies - 1.65 m2</b>							
No Asbestos							
<b>B00D - R0015 - Garden Store - 6.64 m2</b>							
Ceiling Structures/Linings	Non Accessible Area	m2					
<b>B00D - R0016 - Practical Activities - 1hb - 13.87 m2</b>							
No Asbestos							
<b>B00D - R0017 - Home Base - 71.83 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )						
<b>B00D - R0018 - Home Base Store - 7.59 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )						
<b>B00D - R0019 - Home Base Store - 7.15 m2</b>							

Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - ( X2 )							
<b>B00D - R0020 - Withdrawal Space - 2hb - 12.13 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - ( X2 )							
<b>B00D - R0021 - Home Base - 63.87 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )							
<b>B00D - R0022 - Practical Activities - 1hb - 13.43 m2</b>								
No Asbestos								
<b>B00D - R0023 - Movement - 3.45 m2</b>								
No Asbestos								
<b>B00D - R0024 - Movement - 5.03 m2</b>								
Wall Linings Internal	Flat AC Sheeting							
<b>B00D - R0025 - Security Store - 31.94 m2</b>								
Floor Coverings Res/Textile	Resinous Membrane	32m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00D - R0026 - Lift - 2.25 m2</b>								
No Asbestos								
<b>B00D - R0027 - Stairs - 18.19 m2</b>								
No Asbestos								
<b>B00D - R1001 - Distribution Board - 1.55 m2</b>							<b>Note: No inspection of live electrical installation</b>	
No Asbestos								
<b>B00D - R1015 - Stairs - 18.19 m2</b>								
No Asbestos								
<b>B00D - R1016 - Movement - 78.99 m2</b>								
No Asbestos								
<b>B00D - R1017 - Home Base Store - 7.01 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - ( X2 )							
<b>B00D - R1018 - Withdrawal Space - 1hb - 10.13 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )							
<b>B00D - R1019 - Home Base - 60.78 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )							
<b>B00D - R1020 - Practical Activities - 1hb - 18.82 m2</b>								
No Asbestos								
<b>B00D - R1021 - Practical Activities - 1hb - 19.68 m2</b>								
No Asbestos								
<b>B00D - R1022 - Home Base - 60.04 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )							
<b>B00D - R1023 - Withdrawal Space - 1hb - 8.28 m2</b>								
No Asbestos								
<b>B00D - R1024 - Home Base Store - 5.64 m2</b>								
No Asbestos								
<b>B00D - R1025 - Special Programs Room - 44 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )							
<b>B00D - R1026 - Access Shower/Toilet - 7.96 m2</b>								
No Asbestos								
<b>B00D - R1027 - Lift - 2.25 m2</b>								
No Asbestos								

<b>B00D - R9001 - Movement - 20.13 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	21m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00D - R9002 - Special Programs Room - 48.89 m2</b>							
No Asbestos							
<b>B00D - R9003 - Duplicating Workroom - 3.4 m2</b>							
No Asbestos							
<b>B00D - R9004 - Computer Learning Space - 36.21 m2</b>							
No Asbestos							
<b>B00D - R9005 - Withdrawal Space - 1hb - 16.89 m2</b>							
No Asbestos							
<b>B00D - R9006 - Movement - 13.22 m2</b>							
No Asbestos							
<b>B00D - R9007 - Movement - 13.5 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00D - R9008 - Movement - 18.26 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	19m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	10m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00D - R9009 - Distribution Board - 1.08 m2</b>						<b>Note: No inspection of live electrical installation</b>	
No Asbestos							
<b>B00D - R9010 - Welding Area - 21.57 m2</b>							
No Asbestos							
<b>B00D - R9011 - Cleaning Supplies - 3.6 m2</b>							
No Asbestos							
<b>B00D - R9012 - Materials Technology L.S. - 127.83 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	128m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00D - R9013 - Materials Store - 15.05 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	16m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00D - R9014 - Stairs - 12.73 m2</b>							
No Asbestos							
<b>B00D - R9015 - Lift - 2.25 m2</b>							
No Asbestos							
<b>B00D - R9016 - Movement - 7.28 m2</b>							
No Asbestos							
<b>B00E - Library/Communal Facilities - 1983 - Brick/Block</b>							
<b>Exterior</b>							
Underfloor Voids - Slab on Ground	No Asbestos Found						
Eaves Linings	Flat AC Sheeting	100m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00E - R0001 - Cleaning Supplies - 10.4 m2</b>							
No Asbestos							
<b>B00E - R0002 - Distribution Board - 1.45 m2</b>						<b>Note: No inspection of live electrical installation</b>	
No Asbestos							
<b>B00E - R0004 - Staff Toilet - 9.6 m2</b>							
Partition Walls (Cubicles)	Compressed AC Sheet	6m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

<b>B00E - R0005 - Staff Toilet - 6.06 m2</b>							
Partition Walls (Cubicles)	Compressed AC Sheet	6m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00E - R0006 - Cleaning Supplies - 5.25 m2</b>							
No Asbestos							
<b>B00E - R0008 - Reading Area - 282.77 m2</b>							
No Asbestos							
<b>B00E - R0010 - Library Office/Workroom - 24.52 m2</b>							
No Asbestos							
<b>B00E - R0011 - General Storeroom - 12.37 m2</b>							
No Asbestos							
<b>B00E - R0013 - Covered Outdoor Learning Area - 74.01 m2</b>							
No Asbestos							
<b>B00E - R0014 - K.L.A. Store - 24.64 m2</b>							
No Asbestos							
<b>B00E - R0015 - Movement - 61.78 m2</b>							
No Asbestos							
<b>B00E - R9001 - Special Programs Room - 199.35 m2</b>							
No Asbestos							
<b>B00E - R9002 - General Storeroom - 9.76 m2</b>							
No Asbestos							
<b>B00E - R9003 - Sports Store - 51.23 m2</b>							
No Asbestos							
<b>B00E - R9004 - General Assistant/Bulk Store - 10.57 m2</b>							
Floor Coverings Res/Textile	Vinyl Sheet						
<b>B00E - R9005 - Movement - 66.74 m2</b>							
No Asbestos							
<b>B00E - R9006 - Distribution Board - 1.09 m2</b>							
No Asbestos							
<b>B00E - R9008 - Movement - 46.18 m2</b>							
Ceiling Structures/Linings	No Asbestos Found						
<b>B00G - Pupil Facilities - 1966 - Brick/Block</b>							
<b>Exterior</b>							
Underfloor Voids - Slab on Ground	No Asbestos Found						
Eaves Linings	Flat AC Sheeting	20m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00G - R0001 - General Storeroom - 14.48 m2</b>							
No Asbestos							
<b>B00G - R0002 - Toilets - Girls - 34.69 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	35m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00G - R0003 - Toilets - Boys - 35.73 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	36m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00G - R0004 - Garden Store - 7.09 m2</b>							
No Asbestos							
<b>B00G - R0005 - Movement - 41.48 m2</b>							
No Asbestos							

## B00H - General Learning - 1966 - Brick/Block

### Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	

### Interior

#### B00H - R0016 - Distribution Board - .28 m2 Note: No inspection of live electrical installation

No Asbestos

#### B00H - R0017 - Movement - 78.12 m2

No Asbestos

#### B00H - R0018 - Home Base Store - 6.56 m2

No Asbestos

#### B00H - R0019 - Withdrawal Space - 1hb - 9.52 m2

No Asbestos

#### B00H - R0020 - Home Base - 79.79 m2

No Asbestos

#### B00H - R0021 - Practical Activities - 1hb - 18.15 m2

No Asbestos

#### B00H - R0022 - Home Base - 71.62 m2

No Asbestos

#### B00H - R0023 - Withdrawal Space - 1hb - 8.92 m2

No Asbestos

#### B00H - R0024 - Home Base Store - 6.32 m2

No Asbestos

#### B00H - R0025 - Access Shower/Toilet - 6.77 m2

Ceiling Structures/Linings	Flat AC Sheeting	
----------------------------	------------------	--

#### B00H - R0026 - Practical Activities - 1hb - 18.75 m2

No Asbestos

## B00J - General Learning - 1966 - Brick/Block

### Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found						
Eaves Linings	Flat AC Sheeting	100m2	Perimeter of building	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						

### Interior

#### B00J - M0001 - Home Base Store - 13.78 m2

No Asbestos

#### B00J - R0001 - Personal Effects Storage - 12.68 m2

Ceiling Structures/Linings	Flat AC Sheeting	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
----------------------------	------------------	------	--------------	--------------------	---------	--------------------	-----------------------------

#### B00J - R0002 - Home Base - 63.45 m2

No Asbestos

#### B00J - R0003 - Movement - 18.93 m2

No Asbestos

#### B00J - R0004 - Withdrawal Space - 1hb - 13.58 m2

No Asbestos

#### B00J - R0005 - Home Base Store - 6.07 m2

No Asbestos

#### B00J - R0006 - Home Base - 63.06 m2

No Asbestos



<b>B00J - R0007 - Music Store - 6.08 m2</b>		
No Asbestos		
<b>B00J - R0008 - Practical Activities - 1hb - 54.92 m2</b>		
No Asbestos		
<b>B00J - R0009 - Home Base Store - 2.61 m2</b>		
No Asbestos		
<b>B00J - R0010 - Movement - 18.93 m2</b>		
No Asbestos		
<b>B00J - R0011 - Covered Outdoor Learning Area - 155.13 m2</b>		
No Asbestos		
<b>B00J - R9001 - Movement - 43.8 m2</b>		
No Asbestos		
<b>B00J - R9002 - Distribution Board - .92 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00J - R9003 - Craft Store - 23.9 m2</b>		
No Asbestos		
<b>B00J - R9004 - Sports Store - 24 m2</b>		
No Asbestos		
<b>B00K - Shed - 1950 - Timber Shed</b>		
<b>Exterior</b>		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00K - R0001 - Canteen Covered Area - 17.25 m2</b>		
No Asbestos		
<b>B00L - Communal Facilities/Pupil Facilities - 2003 - Brick/Veneer</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	No Asbestos Found	
No Asbestos		
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00L - R0001 - Covered Outdoor Learning Area - 219.24 m2</b>		
No Asbestos		
<b>B00L - R0002 - Canteen - 27.53 m2</b>		
Wall Linings Internal	Flat AC Sheeting	
<b>B00L - R0003 - Canteen Office/Store - 9.55 m2</b>		
Wall Linings Internal	Flat AC Sheeting	
<b>B00L - R0004 - Movement - 23.43 m2</b>		
No Asbestos		
<b>B00L - R0005 - Communal/Performance Store - 8.73 m2</b>		
Wall Linings Internal	Flat AC Sheeting	
<b>B00L - R0006 - Movement - 4.76 m2</b>		
No Asbestos		
<b>B00L - R0007 - Cleaning Supplies - 6.87 m2</b>		
Wall Linings Internal	Flat AC Sheeting	
<b>B00L - R0008 - Sports Store - 6.22 m2</b>		
Wall Linings Internal	Flat AC Sheeting	
<b>B00L - R0009 - Communications Cupboard - 1.83 m2</b>		
Wall Linings Internal	Flat AC Sheeting	
<b>B00L - R0010 - Toilets - Girls - 10.29 m2</b>		

Wall Linings Internal	Flat AC Sheeting	
<b>B00L - R0011 - Distribution Board - .54 m2</b>		<b>Note: No inspection of live electrical installation</b>
Wall Linings Internal	Flat AC Sheeting	
<b>B00L - R0012 - Special Programs Room - 146.64 m2</b>		
No Asbestos		
<b>B00L - R0013 - Movement - 22.26 m2</b>		
No Asbestos		
<b>B00L - R0014 - Raised Platform - 46.74 m2</b>		
No Asbestos		
<b>B00L - R0015 - Movement - 6.43 m2</b>		
No Asbestos		
<b>B00L - R0016 - Hall Chair Store - 8.73 m2</b>		
Wall Linings Internal	Flat AC Sheeting	
<b>B00L - R0017 - P.E Store - 12.44 m2</b>		
Wall Linings Internal	Flat AC Sheeting	
<b>B00L - R0018 - Toilets - Boys - 10.79 m2</b>		
Wall Linings Internal	Flat AC Sheeting	
<b>B00L - R0019 - Cleaning Distributed Store - 2.89 m2</b>		
Wall Linings Internal	Flat AC Sheeting	
<b>B00L - R0020 - Access Shower/Toilet - 5.01 m2</b>		
Wall Linings Internal	Flat AC Sheeting	
<b>B00M - Other/Pupil Facilities - 2014 - Brick/Block</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00M - R0001 - Toilets - Girls - 29.72 m2</b>		
No Asbestos		
<b>B00M - R0002 - Staff Toilet - 5.28 m2</b>		
No Asbestos		
<b>B00M - R0003 - Disabled Toilet - 5.56 m2</b>		
No Asbestos		
<b>B00M - R0004 - Plant - 5.71 m2</b>		
No Asbestos		
<b>B00M - R0005 - Toilets - Boys - 27.99 m2</b>		
No Asbestos		
<b>B00M - R0006 - Other-Not Used - 26.98 m2</b>		
No Asbestos		
<b>B00M - R0007 - External Movement - 39.37 m2</b>		
No Asbestos		
<b>B00N - Other/Staff Facilities - 2014 - Steel</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00N - R0001 - Sports Store - 35.75 m2</b>		
No Asbestos		
<b>B00N - R0002 - Staff Kitchen - 1.65 m2</b>		
No Asbestos		
<b>B00N - R0003 - Staff Toilet - 3.84 m2</b>		

No Asbestos							
<b>B00N - R0004 - External Movement - 17.64 m2</b>							
No Asbestos							
<b>B00N - R0005 - External Movement - 2.63 m2</b>							
No Asbestos							
<b>B040 - Shed - 1962 - Timber</b>							
<b>Exterior</b>							
Underfloor Voids - Slab on Ground	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
<b>Interior</b>							
<b>B040 - R0001 - Movement - 16.42 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	17m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B040 - R0002 - Garden Store - 14.46 m2</b>							
No Asbestos							
<b>B040 - R0003 - Plant Space - 14.59 m2</b>							
No Asbestos							
<b>B040 - R0004 - Plant Space - 19.53 m2</b>							
No Asbestos							
<b>B040 - R0005 - Toilets - Boys - 5.29 m2</b>							
Wall Linings Internal	Flat AC Sheeting						

## Demountables

There are no Demountable(s) Located at this school as per the AMS records as of 09-Sep-2020