


# Asbestos Register

(Hazardous Materials and Risk Assessment)

|                        |                                |
|------------------------|--------------------------------|
| School:                | Khancoban Public School (4270) |
| Region:                | Southern NSW AMU               |
| State Electorate:      | Albury                         |
| Local Government Area: | Snowy Valleys                  |

|                   |                 |
|-------------------|-----------------|
| Last Reviewed By: | WSP 14-FEB-2017 |
| Last Revised By:  |                 |

|   |    |
|---|----|
| Historical Fibro In Grounds Investigations/Events   | No |
| No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance. |    |



# Preface to Asbestos Register

## Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
  - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
  - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
  - o Any wall cavity
  - o Sub floor area, particularly formwork for slabs in/on ground,
  - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.  
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

## Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

## Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

## Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

## Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>  
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

## Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

### 3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

| Rating                     | Description  |
|----------------------------|--|
| Good condition (1)         | For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles  |
| Minimal damage (2)         | For non-friable asbestos that has a very small amount of damage, eg hairline cracks.   |
| Some damage / unsealed (3) | For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed. |
| Poor condition (4)         | For non-friable asbestos that has extensive damage. Visible asbestos debris  |
| Friable asbestos (5)       | Any occurrence of friable asbestos   |

| Product  | Material Description | Extent | Location                   | Material Condition | Risk Status | Remediation Priority | Result   |
|--|----------------------|--------|----------------------------|--------------------|-------------|----------------------|--|
| <b>B00A - Administration/General Learning - 1963 - Brick/Block</b> |                      |        |                            |                    |             |                      |  |
| <b>Exterior</b>  |                      |        |                            |                    |             |                      |  |
| Underfloor Voids   | Requires Inspection  |        |                            |                    |             |                      |  |
| Ceiling Voids - Raked Ceiling                                      | No Asbestos Found    |        |                            |                    |             |                      |  |
| Eaves Linings  | Flat AC Sheeting     | 50m2   | South western wing         | Good Condition (1) | Low (1)     | Low Priority (2-3)   | Chrysotile (white asbestos)                            |
| Eaves Linings  | Flat AC Sheeting     | 200m2  | Northern and Eastern wings | Good Condition (1) | Low (1)     | Low Priority (2-3)   | Chrysotile (white asbestos)                            |
| Underfloor Voids - Stored / Debris Material                        | AC Fragments/Debris  | 50     | Throughout                 | Minimal Damage (2) | Low (1)     | Low Priority (2-3)   | Chrysotile (white asbestos) , Amosite (brown asbestos) |
| Underfloor Voids - Stored / Debris Material                        | AC Fragments/Debris  | 50     | Throughout                 | Minimal Damage (2) | Low (1)     | Low Priority (2-3)   | Chrysotile (white asbestos)                            |
| <b>Interior</b>  |                      |        |                            |                    |             |                      |  |
| <b>B00A - R0001 - Garden Store - 16.91 m2</b>                      |                      |        |                            |                    |             |                      |  |
| No Asbestos  |                      |        |                            |                    |             |                      |  |
| <b>B00A - R0002 - Garden Store - 5.92 m2</b>                       |                      |        |                            |                    |             |                      |  |
| Ceiling Structures/Linings   | Flat AC Sheeting     | 6m2    | All surfaces               | Good Condition (1) | Low (1)     | Low Priority (2-3)   | Chrysotile (white asbestos)                            |
| <b>B00A - R0003 - Toilets - Boys - 29.59 m2</b>                    |                      |        |                            |                    |             |                      |  |
| Partition Walls (Cubicles)   | Compressed AC Sheet  | 5m2    | All surfaces               | Good Condition (1) | Low (1)     | Low Priority (2-3)   | Chrysotile (white asbestos) , Amosite (brown asbestos) |
| Ceiling Structures/Linings   | Flat AC Sheeting     | 30m2   | All surfaces               | Good Condition (1) | Low (1)     | Low Priority (2-3)   | Chrysotile (white asbestos)                            |
| <b>B00A - R0004 - Toilets - Boys - 29.41 m2</b>                    |                      |        |                            |                    |             |                      |  |
| Partition Walls (Cubicles)   | Compressed AC Sheet  | 6m2    | All surfaces               | Good Condition (1) | Low (1)     | Low Priority (2-3)   | Chrysotile (white asbestos) , Amosite (brown asbestos) |
| Ceiling Structures/Linings   | Flat AC Sheeting     | 30m2   | All surfaces               | Good Condition (1) | Low (1)     | Low Priority (2-3)   | Chrysotile (white asbestos)                            |
| <b>B00A - R0005 - Shower/Change - 29.55 m2</b>                     |                      |        |                            |                    |             |                      |  |
| Partition Walls (Cubicles)   | Compressed AC Sheet  | 8m2    | All surfaces               | Good Condition (1) | Low (1)     | Low Priority (2-3)   | Chrysotile (white asbestos) , Amosite (brown asbestos) |
| Ceiling Structures/Linings   | Flat AC Sheeting     | 30m2   | All surfaces               | Good Condition (1) | Low (1)     | Low Priority (2-3)   | Chrysotile (white asbestos)                            |
| <b>B00A - R0006 - Toilets - Girls - 29.65 m2</b>                   |                      |        |                            |                    |             |                      |  |
| Partition Walls (Cubicles)   | Compressed AC Sheet  | 12m2   | All surfaces               | Good Condition (1) | Low (1)     | Low Priority (2-3)   | Chrysotile (white asbestos) , Amosite (brown asbestos) |
| Ceiling Structures/Linings   | Flat AC Sheeting     | 30m2   | All surfaces               | Good Condition (1) | Low (1)     | Low Priority (2-3)   | Chrysotile (white asbestos)                            |
| <b>B00A - R0007 - External Movement - 49.04 m2</b>                 |                      |        |                            |                    |             |                      |  |
| Wall Linings Internal  | Compressed AC Sheet  |        |                            |                    |             |                      |  |
| Ceiling Structures/Linings   | Flat AC Sheeting     | 20m2   | Eave lining and Porch      | Good Condition (1) | Low (1)     | Low Priority (2-3)   | Chrysotile (white asbestos)                            |
| <b>B00A - R0008 - Movement - 85.19 m2</b>                          |                      |        |                            |                    |             |                      |  |
| No Asbestos  |                      |        |                            |                    |             |                      |  |
| <b>B00A - R0009 - External Movement - 1.36 m2</b>                  |                      |        |                            |                    |             |                      |  |

|  |                  |      |                            |                    |         |                    |                             |
|--|------------------|------|----------------------------|--------------------|---------|--------------------|-----------------------------|
| Ceiling Structures/Linings                               | Flat AC Sheeting | 2m2  | All surfaces               | Good Condition (1) | Low (1) | Low Priority (2-3) | Assumed Asbestos            |
| <b>B00A - R0010 - External Movement - 1.36 m2</b>        |                  |      |                            |                    |         |                    |                             |
| Ceiling Structures/Linings                               | Flat AC Sheeting | 2m2  | All surfaces               | Good Condition (1) | Low (1) | Low Priority (2-3) | Assumed Asbestos            |
| <b>B00A - R0011 - Entry Vestibule - 22.93 m2</b>         |                  |      |                            |                    |         |                    |                             |
| No Asbestos  |                  |      |                            |                    |         |                    |                             |
| <b>B00A - R0012 - External Movement - 1.52 m2</b>        |                  |      |                            |                    |         |                    |                             |
| Ceiling Structures/Linings                               | Flat AC Sheeting | 2m2  | All surfaces               | Good Condition (1) | Low (1) | Low Priority (2-3) | Assumed Asbestos            |
| <b>B00A - R0013 - Craft Store - 6.81 m2</b>              |                  |      |                            |                    |         |                    |                             |
| No Asbestos  |                  |      |                            |                    |         |                    |                             |
| <b>B00A - R0014 - Staff Room - 21.14 m2</b>              |                  |      |                            |                    |         |                    |                             |
| No Asbestos  |                  |      |                            |                    |         |                    |                             |
| <b>B00A - R0015 - Principal - 9.25 m2</b>                |                  |      |                            |                    |         |                    |                             |
| Wall Linings Internal                                    | Flat AC Sheeting | 2m2  | Infill panel behind sink   | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B00A - R0016 - Duplicating Workroom - 10.98 m2</b>    |                  |      |                            |                    |         |                    |                             |
| No Asbestos  |                  |      |                            |                    |         |                    |                             |
| <b>B00A - R0017 - Home Base Store - 6.15 m2</b>          |                  |      |                            |                    |         |                    |                             |
| Floor Coverings Res/Textile                              | Vinyl Tiles      |      |                            |                    |         |                    |                             |
| <b>B00A - R0018 - Home Base - 56.14 m2</b>               |                  |      |                            |                    |         |                    |                             |
| No Asbestos  |                  |      |                            |                    |         |                    |                             |
| <b>B00A - R0019 - External Movement - .57 m2</b>         |                  |      |                            |                    |         |                    |                             |
| Ceiling Structures/Linings                               | Flat AC Sheeting | 1m2  | All surfaces               | Good Condition (1) | Low (1) | Low Priority (2-3) | Assumed Asbestos            |
| <b>B00A - R0020 - Movement - 24.8 m2</b>                 |                  |      |                            |                    |         |                    |                             |
| Ceiling Structures/Linings                               | Flat AC Sheeting | 25m2 | All surfaces               | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B00A - R0021 - Home Base - 53.4 m2</b>                |                  |      |                            |                    |         |                    |                             |
| Wall Linings Internal - Infill                           | Flat AC Sheeting | 2m2  | Benind heater              | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B00A - R0022 - Home Base - 53.77 m2</b>               |                  |      |                            |                    |         |                    |                             |
| Wall Linings Internal - Infill                           | Flat AC Sheeting | 2m2  | Benind heater              | Good Condition (1) | Low (1) | Low Priority (2-3) | Assumed Asbestos            |
| <b>B00A - R0026 - External Movement - 1 m2</b>           |                  |      |                            |                    |         |                    |                             |
| Ceiling Structures/Linings                               | Flat AC Sheeting | 1m2  | All surfaces               | Good Condition (1) | Low (1) | Low Priority (2-3) | Assumed Asbestos            |
| <b>B00A - R0027 - Movement - 58.26 m2</b>                |                  |      |                            |                    |         |                    |                             |
| Wall Linings Internal                                    | Flat AC Sheeting | 10m2 | Adjacent to Room 19 and 20 | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B00A - R0028 - Personal Effects Storage - 7.43 m2</b> |                  |      |                            |                    |         |                    |                             |
| Wall Linings Internal                                    | Flat AC Sheeting | 3m2  | Infill panel behind sink   | Good Condition (1) | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B00A - R0029 - Clerical Office - 19.41 m2</b>         |                  |      |                            |                    |         |                    |                             |
| No Asbestos  |                  |      |                            |                    |         |                    |                             |
| <b>B00A - R0030 - Main Switch Board - 4.4 m2</b>         |                  |      |                            |                    |         |                    |                             |

|  |  |      |  |                      |         |                    |                             |
|--|--|------|--|----------------------|---------|--------------------|-----------------------------|
| Electrical - Mounting Board                                | Resinous Board                             | 1    | All surfaces                           | Good Condition (1)   | Low (1) | Low Priority (2-3) | Assumed Asbestos            |
| Ceiling Structures/Linings                                 | Flat AC Sheeting                           | 5m2  | All surfaces                           | Good Condition (1)   | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Wall Linings Internal                                      | Flat AC Sheeting                           | 14m2 | South facing, East facing, West facing | Good Condition (1)   | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B00A - R0031 - Staff Toilet - 4.58 m2</b>               |  |      |  |                      |         |                    |                             |
| Ceiling Structures/Linings                                 | Flat AC Sheeting                           | 5m2  | All surfaces                           | Good Condition (1)   | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Plant / Equipment - Incinerator                            | Encapsulated Asbestos material within unit | 1    | All surfaces                           | Friable Asbestos (5) | Low (1) | Low Priority (2-3) | Assumed Asbestos            |
| <b>B00A - R0032 - Staff Toilet - 4.45 m2</b>               |  |      |  |                      |         |                    |                             |
| Ceiling Structures/Linings                                 | Flat AC Sheeting                           | 5m2  | All surfaces                           | Good Condition (1)   | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B00A - R0033 - External Movement - 1.52 m2</b>          |  |      |  |                      |         |                    |                             |
| Ceiling Structures/Linings                                 | Flat AC Sheeting                           | 2m2  | All surfaces                           | Good Condition (1)   | Low (1) | Low Priority (2-3) | Assumed Asbestos            |
| <b>B00A - R0034 - Home Base Store - 9.92 m2</b>            |  |      |  |                      |         |                    |                             |
| Wall Linings Internal                                      | Flat AC Sheeting                           | 4m2  | Infill panel behind sink               | Good Condition (1)   | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B00A - R0035 - Movement - 2.93 m2</b>                   |  |      |  |                      |         |                    |                             |
| No Asbestos  |  |      |  |                      |         |                    |                             |
| <b>B00A - R0036 - Home Base - 57.01 m2</b>                 |  |      |  |                      |         |                    |                             |
| No Asbestos  |  |      |  |                      |         |                    |                             |
| <b>B00A - R0037 - Home Base - 85.16 m2</b>                 |  |      |  |                      |         |                    |                             |
| No Asbestos  |  |      |  |                      |         |                    |                             |
| <b>B00A - R0038 - Toilets - Boys/Girls - 2.77 m2</b>       |  |      |  |                      |         |                    |                             |
| Wall Linings Internal                                      | Flat AC Sheeting                           | 1m2  | Infill panel below window              | Good Condition (1)   | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B00A - R0039 - Personal Effects Storage - 10.74 m2</b>  |  |      |  |                      |         |                    |                             |
| Wall Linings Internal                                      | Flat AC Sheeting                           | 1m2  | Infill panel behind sink               | Good Condition (1)   | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B00A - R0040 - Movement - 76.44 m2</b>                  |  |      |  |                      |         |                    |                             |
| Wall Linings Internal                                      | Flat AC Sheeting                           | 50m2 | South facing, West facing              | Good Condition (1)   | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B00A - R0041 - External Movement - 1.45 m2</b>          |  |      |  |                      |         |                    |                             |
| Ceiling Structures/Linings                                 | Flat AC Sheeting                           | 2m2  | All surfaces                           | Good Condition (1)   | Low (1) | Low Priority (2-3) | Assumed Asbestos            |
| <b>B00A - R0042 - External Movement - 1.46 m2</b>          |  |      |  |                      |         |                    |                             |
| Ceiling Structures/Linings                                 | Flat AC Sheeting                           | 2m2  | All surfaces                           | Good Condition (1)   | Low (1) | Low Priority (2-3) | Assumed Asbestos            |
| <b>B00A - R0043 - Cleaning Distributed Store - 4.83 m2</b> |  |      |  |                      |         |                    |                             |
| Wall Linings Internal                                      | Flat AC Sheeting                           | 6m2  | West facing                            | Good Condition (1)   | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings                                 | Flat AC Sheeting                           | 5m2  | All surfaces                           | Good Condition (1)   | Low (1) | Low Priority (2-3) | Chrysotile (white asbestos) |

|  |                     |      |              |                      |            |                    |                             |
|--|---------------------|------|--------------|----------------------|------------|--------------------|-----------------------------|
| <b>B00A - R0044 - Plant - 8.38 m2</b>                              |                     |      |              |                      |            |                    |                             |
| Plumbing / Pipework  | Insulation Material | 10   | All surfaces | Friable Asbestos (5) | Medium (2) | Low Priority (2-3) | Chrysotile (white asbestos) |
| Ceiling Structures/Linings   | Flat AC Sheeting    | 15m2 | All surfaces | Good Condition (1)   | Low (1)    | Low Priority (2-3) | Chrysotile (white asbestos) |
| <b>B00A - R0045 - Canteen - 61.02 m2</b>                           |                     |      |              |                      |            |                    |                             |
| No Asbestos  |                     |      |              |                      |            |                    |                             |
| <b>B00B - Communal Facilities/Pupil Facilities - 1960 - Timber</b> |                     |      |              |                      |            |                    |                             |
| <b>Exterior</b>  |                     |      |              |                      |            |                    |                             |
| Ceiling Voids - Raked Ceiling                                      | No Asbestos Found   |      |              |                      |            |                    |                             |
| Underfloor Voids   | No Asbestos Found   |      |              |                      |            |                    |                             |
| <b>Interior</b>  |                     |      |              |                      |            |                    |                             |
| <b>B00B - R0001 - Communal Space - 108.49 m2</b>                   |                     |      |              |                      |            |                    |                             |
| No Asbestos  |                     |      |              |                      |            |                    |                             |
| <b>B00B - R0002 - Music Store - 9.02 m2</b>                        |                     |      |              |                      |            |                    |                             |
| No Asbestos  |                     |      |              |                      |            |                    |                             |
| <b>B00B - R0003 - Movement - 14.86 m2</b>                          |                     |      |              |                      |            |                    |                             |
| No Asbestos  |                     |      |              |                      |            |                    |                             |
| <b>B00B - R0004 - Canteen - 9.6 m2</b>                             |                     |      |              |                      |            |                    |                             |
| No Asbestos  |                     |      |              |                      |            |                    |                             |
| <b>B00C - Residential Facilities - 1965 - Brick/Veneer</b>         |                     |      |              |                      |            |                    |                             |
| <b>Exterior</b>  |                     |      |              |                      |            |                    |                             |
| Underfloor Voids   | Requires Inspection |      |              |                      |            |                    |                             |
| Ceiling Voids  | Requires Inspection |      |              |                      |            |                    |                             |
| <b>Interior</b>  |                     |      |              |                      |            |                    |                             |
| <b>B00C - R0001 - Residence - Movement - 7.97 m2</b>               |                     |      |              |                      |            |                    |                             |
| Requires Inspection  |                     |      |              |                      |            |                    |                             |
| <b>B00C - R0002 - Residence - Laundry - 4.17 m2</b>                |                     |      |              |                      |            |                    |                             |
| Requires Inspection  |                     |      |              |                      |            |                    |                             |
| <b>B00C - R0003 - Residence - Pantry - 2.26 m2</b>                 |                     |      |              |                      |            |                    |                             |
| Requires Inspection  |                     |      |              |                      |            |                    |                             |
| <b>B00C - R0004 - Residence - Kitchen - 10.26 m2</b>               |                     |      |              |                      |            |                    |                             |
| Requires Inspection  |                     |      |              |                      |            |                    |                             |
| <b>B00C - R0005 - Residence - Lounge - 25.49 m2</b>                |                     |      |              |                      |            |                    |                             |
| Requires Inspection  |                     |      |              |                      |            |                    |                             |
| <b>B00C - R0006 - Residence - Movement - 3.89 m2</b>               |                     |      |              |                      |            |                    |                             |
| Requires Inspection  |                     |      |              |                      |            |                    |                             |
| <b>B00C - R0007 - Residence - Bathroom - 5.54 m2</b>               |                     |      |              |                      |            |                    |                             |
| Requires Inspection  |                     |      |              |                      |            |                    |                             |
| <b>B00C - R0008 - Residence - Toilet - 1.85 m2</b>                 |                     |      |              |                      |            |                    |                             |
| Requires Inspection  |                     |      |              |                      |            |                    |                             |
| <b>B00C - R0009 - Residence - Bedroom - 13.89 m2</b>               |                     |      |              |                      |            |                    |                             |
| Requires Inspection  |                     |      |              |                      |            |                    |                             |
| <b>B00C - R0010 - Residence - Bedroom - 10.65 m2</b>               |                     |      |              |                      |            |                    |                             |
| Requires Inspection  |                     |      |              |                      |            |                    |                             |
| <b>B00C - R0011 - Residence - Bedroom - 10.61 m2</b>               |                     |      |              |                      |            |                    |                             |
| Requires Inspection  |                     |      |              |                      |            |                    |                             |
| <b>B00C - R0012 - Residence - Bedroom - 14.36 m2</b>               |                     |      |              |                      |            |                    |                             |
| Requires Inspection  |                     |      |              |                      |            |                    |                             |

**B0C1 - Residential Facilities - 1965 - Fibre Clad Shed**

**Exterior**

|                  |                     |  |  |  |  |  |  |
|------------------|---------------------|--|--|--|--|--|--|
| Underfloor Voids | Requires Inspection |  |  |  |  |  |  |
| Ceiling Voids    | Requires Inspection |  |  |  |  |  |  |

**Interior**

**B0C1 - R0001 - Residence - Garage - 19.15 m2**

|                     |  |  |  |  |  |  |  |
|---------------------|--|--|--|--|--|--|--|
| Requires Inspection |  |  |  |  |  |  |  |
|---------------------|--|--|--|--|--|--|--|

## Demountables

There are no Demountable(s) Located at this school as per the AMS records as of 09-Sep-2020