


# Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Kings Langley Public School (4528)
Region:	Western Sydney AMU
State Electorate:	Seven Hills
Local Government Area:	Blacktown

Last Reviewed By:	Greencap 11-DEC-2017
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	<b>No</b>
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	



# Preface to Asbestos Register

## Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
  - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
  - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
  - o Any wall cavity
  - o Sub floor area, particularly formwork for slabs in/on ground,
  - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.  
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

## Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

## Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

## Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

## Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>

<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

## Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

### 3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
<b>B001 - General Learning/Tiered Learning - 1981 - Brick/Block</b>							
<b>Exterior</b>							
Ceiling Voids - Raked Ceiling	Non Accessible Area						
Underfloor Voids - Slab on Ground	Non Accessible Area						
<b>Interior</b>							
<b>B001 - R0001 - External Movement - 6.35 m2</b>							
No Asbestos							
<b>B001 - R0002 - Plant - 7.4 m2</b>							
No Asbestos							
<b>B001 - R0003 - Special Programs Room - 42.93 m2</b>							
No Asbestos							
<b>B001 - R0004 - External Movement - 11.78 m2</b>							
No Asbestos							
<b>B001 - R0005 - Special Programs Store - 3.55 m2</b>							
No Asbestos							
<b>B001 - R0006 - Withdrawal Space - 1hb - 8.37 m2</b>							
No Asbestos							
<b>B001 - R0007 - Home Base - 60.92 m2</b>							
No Asbestos							
<b>B001 - R0008 - External Movement - 41.71 m2</b>							
No Asbestos							
<b>B001 - R0009 - Distribution Board - .9 m2</b>							
						<b>Note: No inspection of live electrical installation</b>	
Electrical - Backing Board	Resinous Board						
<b>B001 - R0010 - Home Base Store - 4.26 m2</b>							
No Asbestos							
<b>B001 - R0011 - Home Base Store - 3.73 m2</b>							
No Asbestos							
<b>B001 - R0012 - Home Base - 60.61 m2</b>							
No Asbestos							
<b>B001 - R0013 - Withdrawal Space - 1hb - 8.73 m2</b>							
No Asbestos							
<b>B001 - R0014 - Movement - 19.78 m2</b>							
No Asbestos							
<b>B001 - R0015 - Home Base - 60.66 m2</b>							
No Asbestos							
<b>B001 - R0016 - Home Base Store - 4.1 m2</b>							
No Asbestos							
<b>B001 - R0017 - Security Store - 4.05 m2</b>							
No Asbestos							
<b>B001 - R0018 - Practical Activities - 1hb - 35.16 m2</b>							
No Asbestos							
<b>B001 - R0019 - External Movement - 32.9 m2</b>							
No Asbestos							
<b>B001 - R0020 - Practical Activities - 1hb - 22.56 m2</b>							
No Asbestos							
<b>B001 - R0021 - Security Store - 3.66 m2</b>							
No Asbestos							
<b>B001 - R0022 - Cleaning Distributed Store - 1.49 m2</b>							

No Asbestos		
<b>B002 - General Learning - 1981 - Brick/Block</b>		
<b>Exterior</b>		
Ceiling Voids - Raked Ceiling	Non Accessible Area	
Underfloor Voids - Slab on Ground	Non Accessible Area	
<b>Interior</b>		
<b>B002 - R0001 - External Movement - 9.17 m2</b>		
No Asbestos		
<b>B002 - R0002 - Home Base - 60.77 m2</b>		
No Asbestos		
<b>B002 - R0003 - Home Base Store - 4.05 m2</b>		
No Asbestos		
<b>B002 - R0004 - Security Store - 4.05 m2</b>		
No Asbestos		
<b>B002 - R0005 - Practical Activities - 1hb - 34.54 m2</b>		
No Asbestos		
<b>B002 - R0006 - External Movement - 32.95 m2</b>		
No Asbestos		
<b>B002 - R0007 - Practical Activities - 1hb - 35.27 m2</b>		
No Asbestos		
<b>B002 - R0008 - Security Store - 4.05 m2</b>		
No Asbestos		
<b>B002 - R0009 - Home Base Store - 4.05 m2</b>		
No Asbestos		
<b>B002 - R0010 - Home Base - 60.84 m2</b>		
No Asbestos		
<b>B002 - R0011 - External Movement - 9.13 m2</b>		
No Asbestos		
<b>B002 - R0012 - Withdrawal Space - 1hb - 11.97 m2</b>		
No Asbestos		
<b>B002 - R0013 - Home Base - 60.75 m2</b>		
No Asbestos		
<b>B002 - R0014 - External Movement - 35.33 m2</b>		
No Asbestos		
<b>B002 - R0015 - Distribution Board - .93 m2</b>		
<b>Note: No inspection of live electrical installation</b>		
Electrical - Backing Board	Resinous Board	
<b>B002 - R0016 - Home Base Store - 4.32 m2</b>		
No Asbestos		
<b>B002 - R0017 - General Storeroom - 3.78 m2</b>		
No Asbestos		
<b>B002 - R0018 - Cleaning Distributed Store - 1.51 m2</b>		
No Asbestos		
<b>B002 - R0019 - Home Base - 60.77 m2</b>		
No Asbestos		
<b>B002 - R0020 - Withdrawal Space - 1hb - 11.97 m2</b>		
No Asbestos		
<b>B003 - General Learning - 1981 - Brick/Block</b>		
<b>Exterior</b>		
Ceiling Voids - Raked Ceiling	Non Accessible Area	

Underfloor Voids - Slab on Ground	Non Accessible Area	
<b>Interior</b>		
<b>B003 - R0001 - External Movement - 9.13 m2</b>		
No Asbestos		
<b>B003 - R0002 - Home Base - 60.75 m2</b>		
No Asbestos		
<b>B003 - R0003 - Home Base Store - 4.05 m2</b>		
No Asbestos		
<b>B003 - R0004 - Security Store - 4.05 m2</b>		
No Asbestos		
<b>B003 - R0005 - Practical Activities - 1hb - 35.63 m2</b>		
No Asbestos		
<b>B003 - R0006 - External Movement - 32.82 m2</b>		
No Asbestos		
<b>B003 - R0007 - Cleaning Distributed Store - 1.51 m2</b>		
No Asbestos		
<b>B003 - R0008 - Kiln Room - 34.43 m2</b>		
No Asbestos		
<b>B003 - R0009 - Security Store - 4.05 m2</b>		
No Asbestos		
<b>B003 - R0010 - Home Base Store - 4.05 m2</b>		
No Asbestos		
<b>B003 - R0011 - Home Base - 60.91 m2</b>		
No Asbestos		
<b>B003 - R0012 - External Movement - 9.19 m2</b>		
No Asbestos		
<b>B003 - R0013 - Withdrawal Space - 1hb - 11.95 m2</b>		
No Asbestos		
<b>B003 - R0014 - Home Base - 60.68 m2</b>		
No Asbestos		
<b>B003 - R0015 - External Movement - 35.51 m2</b>		
No Asbestos		
<b>B003 - R0016 - Distribution Board - .89 m2</b>		
<b>Note: No inspection of live electrical installation</b>		
Electrical - Backing Board	Resinous Board	
<b>B003 - R0017 - Home Base Store - 4.34 m2</b>		
No Asbestos		
<b>B003 - R0018 - Home Base Store - 3.81 m2</b>		
No Asbestos		
<b>B003 - R0019 - Home Base - 60.67 m2</b>		
No Asbestos		
<b>B003 - R0020 - Withdrawal Space - 1hb - 11.98 m2</b>		
No Asbestos		
<b>B004 - General Learning/Pupil Facilities - 1981 - Brick/Block</b>		
<b>Exterior</b>		
Ceiling Voids - Raked Ceiling	Non Accessible Area	
Underfloor Voids - Slab on Ground	Non Accessible Area	
<b>Interior</b>		
<b>B004 - R0001 - Security Store - 4.25 m2</b>		
No Asbestos		

<b>B004 - R0002 - General Storeroom - 4.13 m2</b>							
No Asbestos							
<b>B004 - R0003 - Home Base - 60.85 m2</b>							
No Asbestos							
<b>B004 - R0004 - Movement - 19.9 m2</b>							
No Asbestos							
<b>B004 - R0005 - Withdrawal Space - 1hb - 8.82 m2</b>							
No Asbestos							
<b>B004 - R0006 - Home Base - 60.63 m2</b>							
No Asbestos							
<b>B004 - R0007 - External Movement - 40.96 m2</b>							
No Asbestos							
<b>B004 - R0008 - Distribution Board - .91 m2</b>							<b>Note: No inspection of live electrical installation</b>
Electrical - Backing Board	Resinous Board						
<b>B004 - R0009 - Home Base - 60.76 m2</b>							
No Asbestos							
<b>B004 - R0010 - Withdrawal Space - 1hb - 7.88 m2</b>							
No Asbestos							
<b>B004 - R0011 - External Movement - 52.21 m2</b>							
No Asbestos							
<b>B004 - R0012 - Toilets - Boys - 20.24 m2</b>							
No Asbestos							
<b>B004 - R0013 - General Storeroom - 2.1 m2</b>							
No Asbestos							
<b>B004 - R0014 - Toilets - Girls - 18.55 m2</b>							
No Asbestos							
<b>B004 - R0015 - Disabled Toilet - 7.3 m2</b>							
No Asbestos							
<b>B004 - R0016 - Security Store - 2.73 m2</b>							
No Asbestos							
<b>B004 - R0017 - Practical Activities - 1hb - 22.55 m2</b>							
No Asbestos							
<b>B004 - R0018 - External Movement - 32.95 m2</b>							
No Asbestos							
<b>B004 - R0019 - Cleaning Distributed Store - 1.51 m2</b>							
No Asbestos							
<b>B004 - R0020 - Home Base Store - 3.78 m2</b>							
No Asbestos							
<b>B004 - R0021 - Home Base Store - 4.35 m2</b>							
No Asbestos							
<b>B004 - R0022 - Practical Activities - 1hb - 35.22 m2</b>							
No Asbestos							
<b>B005 - Library/Building Services - 1981 - Brick/Block</b>							
<b>Exterior</b>							
Ceiling Voids - Raked Ceiling	Non Accessible Area						
Underfloor Voids - Slab on Ground	Non Accessible Area						
Eaves Linings	Flat AC Sheeting	12m2	North, South, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Eaves Linings	Flat AC Sheeting	12m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
<b>Interior</b>							

<b>B005 - R0001 - Reading Area - 192.04 m2</b>							
No Asbestos							
<b>B005 - R0002 - Cleaning Distributed Store - 3.38 m2</b>							
No Asbestos							
<b>B005 - R0003 - Distribution Board - 1.09 m2</b>						<b>Note: No inspection of live electrical installation</b>	
Electrical - Backing Board	Resinous Board						
<b>B005 - R0004 - External Movement - 27.95 m2</b>							
No Asbestos							
<b>B005 - R0005 - K.L.A. Store - 12.82 m2</b>							
No Asbestos							
<b>B005 - R0006 - Cleaning Supplies - 12.66 m2</b>							
Non Accessible							
Non Accessible							
<b>B005 - R0007 - Reading Area - 33.4 m2</b>							
No Asbestos							
<b>B005 - R0008 - Library Office/Workroom - 30.26 m2</b>							
No Asbestos							
<b>B005 - R0010 - External Movement - 45.35 m2</b>							
No Asbestos							
<b>B006 - Administration - 1981 - Brick/Block</b>							
<b>Exterior</b>							
Ceiling Voids - Raked Ceiling	Non Accessible Area						
Underfloor Voids - Slab on Ground	Non Accessible Area						
Eaves Linings	Flat AC Sheeting	25m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Eaves Linings	Flat AC Sheeting	25m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
<b>Interior</b>							
<b>B006 - R0001 - Staff Room Annexe - 28.07 m2</b>							
No Asbestos							
<b>B006 - R0002 - Staff Room - 58.58 m2</b>							
No Asbestos							
<b>B006 - R0003 - Distribution Board - 1.08 m2</b>						<b>Note: No inspection of live electrical installation</b>	
Material - Stored / Debris Material	Flat AC Sheeting						
<b>B006 - R0004 - Duplicating Workroom - 32.96 m2</b>							
No Asbestos							
<b>B006 - R0005 - Security Store - 13.71 m2</b>							
No Asbestos							
<b>B006 - R0006 - Staff Room Annexe - 12.88 m2</b>							
No Asbestos							
<b>B006 - R0007 - Entry Vestibule - 20.12 m2</b>							
No Asbestos							
<b>B006 - R0008 - External Movement - 35.84 m2</b>							
No Asbestos							
<b>B006 - R0009 - Staff Room Annexe - 12.91 m2</b>							
No Asbestos							
<b>B006 - R0010 - Sick Bay - 8.94 m2</b>							
No Asbestos							
<b>B006 - R0011 - Security Store - 9.87 m2</b>							
No Asbestos							

<b>B006 - R0012 - Principal - 17.15 m2</b>							
No Asbestos							
<b>B006 - R0013 - Clerical Office/Workroom - 13.05 m2</b>							
No Asbestos							
<b>B006 - R0014 - Cleaning Distributed Store - 2.1 m2</b>							
No Asbestos							
<b>B006 - R0015 - Staff Toilet - 4.34 m2</b>							
No Asbestos							
<b>B006 - R0016 - Staff Toilet - 4.36 m2</b>							
No Asbestos							
<b>B006 - R0017 - Movement - 43.32 m2</b>							
No Asbestos							
<b>B006 - R0018 - Clerical Office - 13.69 m2</b>							
No Asbestos							
<b>B006 - R0019 - External Movement - 22.61 m2</b>							
No Asbestos							
<b>B006 - R0020 - External Movement - 98.58 m2</b>							
No Asbestos							
<b>B007 - Communal Facilities - 1981 - Brick/Block</b>							
<b>Exterior</b>							
Ceiling Voids - Raked Ceiling	Non Accessible Area						
Underfloor Voids - Slab on Ground	Non Accessible Area						
Eaves Linings	Flat AC Sheeting	30m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Eaves Linings	Flat AC Sheeting	30m2	East, West, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
<b>Interior</b>							
<b>B007 - R0001 - External Movement - 224.5 m2</b>							
No Asbestos							
<b>B007 - R0002 - Disabled Toilet - 5.64 m2</b>							
No Asbestos							
<b>B007 - R0003 - Music Store - 9.76 m2</b>							
No Asbestos							
<b>B007 - R0004 - Entry Vestibule - 5.11 m2</b>							
No Asbestos							
<b>B007 - R0005 - Hall Chair Store - 16.78 m2</b>							
No Asbestos							
<b>B007 - R0006 - Communal Space - 199.5 m2</b>							
No Asbestos							
<b>B007 - R0007 - Cleaning Distributed Store - .72 m2</b>							
No Asbestos							
<b>B007 - R0008 - Cleaning Supplies - 10.03 m2</b>							
No Asbestos							
<b>B007 - R0009 - Raised Platform - 54.83 m2</b>							
No Asbestos							
<b>B007 - R0010 - Movement - 2.54 m2</b>							
No Asbestos							
<b>B007 - R0011 - General Assistant/Bulk Store - 16.17 m2</b>							
No Asbestos							
<b>B007 - R0012 - Toilets - Girls - 10.72 m2</b>							
No Asbestos							



<b>B007 - R0013 - Main Switch Board - 7.47 m2</b>		
Electrical - Backing Board	Resinous Board	
<b>B007 - R0014 - Toilets - Boys - 10.64 m2</b>		
No Asbestos		
<b>B007 - R0015 - Movement - 2.53 m2</b>		
No Asbestos		
<b>B007 - R0016 - General Assistant/Bulk Store - 12.93 m2</b>		
No Asbestos		
<b>B007 - R0017 - P.E Store - 16.84 m2</b>		
No Asbestos		
<b>B007 - R0018 - Canteen Office/Store - 7.1 m2</b>		
No Asbestos		
<b>B007 - R0019 - Canteen - 43.96 m2</b>		
No Asbestos		
<b>B007 - R0020 - Canteen Office/Store - 5.8 m2</b>		
No Asbestos		
<b>B007 - R0021 - Plant - 1.23 m2</b>		
No Asbestos		
<b>B007 - R0022 - Cleaning Distributed Store - 5.26 m2</b>		
No Asbestos		
<b>B008 - Pupil Facilities - 1981 - Brick/Block</b>		
<b>Exterior</b>		
Ceiling Voids - Raked Ceiling	Non Accessible Area	
Underfloor Voids - Slab on Ground	Non Accessible Area	
<b>Interior</b>		
<b>B008 - R0001 - Toilets - Girls - 16.86 m2</b>		
No Asbestos		
<b>B008 - R0002 - Drinking Facilities - 2.46 m2</b>		
No Asbestos		
<b>B008 - R0003 - Toilets - Boys - 17.74 m2</b>		
No Asbestos		
<b>B008 - R0004 - Cleaning Distributed Store - 1.56 m2</b>		
No Asbestos		
<b>B009 - Pupil Facilities - 1981 - Brick/Block</b>		
<b>Exterior</b>		
Ceiling Voids - Raked Ceiling	Non Accessible Area	
Underfloor Voids - Slab on Ground	Non Accessible Area	
<b>Interior</b>		
<b>B009 - R0001 - Toilets - Girls - 17.03 m2</b>		
No Asbestos		
<b>B009 - R0002 - Drinking Facilities - 2.44 m2</b>		
No Asbestos		
<b>B009 - R0003 - Toilets - Boys - 17.75 m2</b>		
No Asbestos		
<b>B009 - R0004 - Cleaning Distributed Store - 1.57 m2</b>		
No Asbestos		
<b>B010 - General Learning - 2005 - Fibre Cement Clad</b>		
<b>Exterior</b>		

Underfloor Voids - Slab on Ground	Non Accessible Area	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B010 - R0001 - External Movement - 38.49 m2</b>		
No Asbestos		
<b>B010 - R0002 - Practical Activities - 1hb - 19.39 m2</b>		
No Asbestos		
<b>B010 - R0003 - Home Base Store - 6.02 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B010 - R0004 - Home Base - 59.2 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B010 - R0005 - Withdrawal Space - 2hb - 11.36 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B010 - R0006 - Home Base - 59.19 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B010 - R0007 - Home Base Store - 6.02 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B010 - R0008 - Practical Activities - 1hb - 19.41 m2</b>		
No Asbestos		
<b>B011 - General Learning - 2007 - Steel</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	Non Accessible Area	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B011 - R0001 - Special Programs Room - 62.05 m2</b>		
No Asbestos		
<b>B011 - R0002 - External Movement - 17.22 m2</b>		
No Asbestos		
<b>B012 - General Learning - 2010 - Brick/Veneer</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	Non Accessible Area	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B012 - R0001 - External Movement - 90.48 m2</b>		
No Asbestos		
<b>B012 - R0002 - Home Base Store - 6.22 m2</b>		
No Asbestos		
<b>B012 - R0003 - Home Base - 59.39 m2</b>		
No Asbestos		
<b>B012 - R0004 - Withdrawal Space - 2hb - 11.26 m2</b>		
No Asbestos		
<b>B012 - R0005 - Home Base - 59.58 m2</b>		
No Asbestos		

<b>B012 - R0006 - Home Base Store - 6.22 m2</b>		
No Asbestos		
<b>B012 - R0007 - Home Base Store - 6.22 m2</b>		
No Asbestos		
<b>B012 - R0008 - Home Base - 59.42 m2</b>		
No Asbestos		
<b>B012 - R0009 - Withdrawal Space - 2hb - 11.29 m2</b>		
No Asbestos		
<b>B012 - R0010 - Home Base - 59.45 m2</b>		
No Asbestos		
<b>B012 - R0011 - Home Base Store - 6.25 m2</b>		
No Asbestos		
<b>B012 - R0012 - Practical Activities - 1hb - 18.65 m2</b>		
No Asbestos		
<b>B012 - R0013 - Practical Activities - 1hb - 18.63 m2</b>		
No Asbestos		
<b>B012 - R0014 - Practical Activities - 1hb - 18.63 m2</b>		
No Asbestos		
<b>B012 - R0015 - Practical Activities - 1hb - 18.43 m2</b>		
No Asbestos		
<b>B013 - General Learning - 2010 - Brick/Veneer</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	Non Accessible Area	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B013 - R0001 - External Movement - 45.98 m2</b>		
No Asbestos		
<b>B013 - R0002 - Home Base Store - 6.22 m2</b>		
No Asbestos		
<b>B013 - R0003 - Home Base - 59.61 m2</b>		
No Asbestos		
<b>B013 - R0004 - Withdrawal Space - 2hb - 11.36 m2</b>		
No Asbestos		
<b>B013 - R0005 - Home Base - 59.66 m2</b>		
No Asbestos		
<b>B013 - R0006 - Home Base Store - 6.22 m2</b>		
No Asbestos		
<b>B013 - R0007 - Practical Activities - 1hb - 18.6 m2</b>		
No Asbestos		
<b>B013 - R0008 - Practical Activities - 1hb - 18.65 m2</b>		
No Asbestos		
<b>B014 - Pre-School Facilities - 2010 - Steel</b>		
<b>Exterior</b>		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	Non Accessible Area	
<b>Interior</b>		
<b>B014 - R0001 - External Movement - 8.47 m2</b>		
No Asbestos		

<b>B014 - R0002 - Movement - 19.58 m2</b>	
No Asbestos	
<b>B014 - R0003 - Clerical Office - Pre - 18.45 m2</b>	
No Asbestos	
<b>B014 - R0004 - Other-Non Government Pre-Sch - 92.9 m2</b>	
No Asbestos	
<b>B014 - R0005 - Practical Activities - Pre - 105.72 m2</b>	
No Asbestos	
<b>B014 - R0006 - Kitchen - Pre - 8.86 m2</b>	
No Asbestos	
<b>B014 - R0007 - General Storeroom - Pre - 8.24 m2</b>	
No Asbestos	
<b>B014 - R0008 - Practical Activities - Pre - 51.07 m2</b>	
No Asbestos	
<b>B014 - R0009 - Toilets - Boys/Girls - Pre - 10.44 m2</b>	
No Asbestos	
<b>B014 - R0010 - Cleaning Distributed Store - .73 m2</b>	
No Asbestos	
<b>B014 - R0011 - Laundry - Pre - 9.94 m2</b>	
No Asbestos	
<b>B014 - R0012 - Toilets - Boys - 1.57 m2</b>	
No Asbestos	
<b>B014 - R0013 - Toilets - Girls - 1.57 m2</b>	
No Asbestos	
<b>B014 - R0014 - Toilets - Boys/Girls - Pre - 2.93 m2</b>	
No Asbestos	
<b>B014 - R0015 - Practical Activities - Pre - 53.97 m2</b>	
No Asbestos	
<b>B014 - R0016 - Other-Non Government Pre-Sch - 45.08 m2</b>	
No Asbestos	
<b>B014 - R0017 - Other-Non Government Pre-Sch - 47 m2</b>	
No Asbestos	
<b>B014 - R0018 - Practical Activities - Pre - 53.21 m2</b>	
No Asbestos	
<b>B014 - R0019 - General Storeroom - Pre - 8.58 m2</b>	
No Asbestos	
<b>B014 - R0020 - Child Care Centre - 8.44 m2</b>	
No Asbestos	
<b>B014 - R0021 - Disabled Shower/Toilet - 5.13 m2</b>	
No Asbestos	

## Demountables

### OS 602 10311 - Learning Unit - Standard With P.A.A. - Placement Date : 27-MAY-1994

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

#### Exterior

Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

#### Interior

##### R1- Learning space/withdrawal/entry

Ceiling Structures/Linings	Flat AC Sheeting	70m2	Assumed Asbestos
----------------------------	------------------	------	------------------

##### R2- Home Base Store

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Assumed Asbestos

### OS 602 10666 - Learning Unit - Standard With P.A.A. - Placement Date : 02-JAN-2009

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

### OS 750 11879 - Learning Unit - ESL - Placement Date : 18-MAR-2015

No Asbestos Found

### OS 602 13547 - Learning Unit - Standard With P.A.A. - Placement Date : 20-DEC-2012

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

### OS 602 14322 - Learning Unit - Standard With P.A.A. - Placement Date : 30-JUN-1995

#### Exterior

Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

#### Interior

##### R1- Learning space/withdrawal/entry

Ceiling Structures/Linings	Flat AC Sheeting	70m2	Assumed Asbestos
----------------------------	------------------	------	------------------

##### R2- Home Base Store

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Assumed Asbestos

### OS 602 14328 - Learning Unit - Standard With P.A.A. - Placement Date : 30-JUN-1995

#### Exterior

Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

#### Interior

##### R1- Learning space/withdrawal/entry

Ceiling Structures/Linings	Flat AC Sheeting	70m2	Assumed Asbestos
----------------------------	------------------	------	------------------

##### R2- Home Base Store

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Assumed Asbestos