

Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Katoomba Public School (4546)
Region:	Western Sydney AMU
State Electorate:	Blue Mountains
Local Government Area:	Blue Mountains

Last Reviewed By:	WSP 25-NOV-2016
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	Yes
Please refer to the latest site specific Asbestos Management Plans available from the Department's website (Refer to Note 2).	

4546 - Katoomba Public School
Site Plan (13199)



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>

<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - Administration/General Learning - 1902 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	100m2	Throughout, Upper & Lower	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Interior							
B00A - R0001 - Home Base - 58.96 m2							
No Asbestos							
B00A - R0002 - Home Base Store - 6.04 m2							
No Asbestos							
B00A - R0003 - Withdrawal Space - 1hb - 11.15 m2							
No Asbestos							
B00A - R0004 - Home Base Store - 6.01 m2							
No Asbestos							
B00A - R0005 - Home Base - 59.43 m2							
No Asbestos							
B00A - R0006 - Toilets - Girls - 10.89 m2							
No Asbestos							
B00A - R0007 - Practical Activities - 1hb - 54.74 m2							
No Asbestos							
B00A - R0008 - Practical Activities - 1hb - 48.84 m2							
No Asbestos							
B00A - R0009 - Practical Activities - 1hb - 37.17 m2							
No Asbestos							
B00A - R0010 - Toilets - Boys - 10.48 m2							
No Asbestos							
B00A - R0011 - Home Base - 59.12 m2							
No Asbestos							
B00A - R0012 - Home Base Store - 6.15 m2							
No Asbestos							
B00A - R0013 - Withdrawal Space - 1hb - 11.25 m2							
No Asbestos							
B00A - R0014 - Home Base Store - 6.15 m2							
No Asbestos							
B00A - R0015 - Home Base - 60.45 m2							
No Asbestos							
B00A - R0016 - Movement - 54.44 m2							
No Asbestos							
B00A - R0017 - General Storeroom - 3.12 m2							
No Asbestos							
B00A - R0018 - Disabled Shower/Toilet - 10.98 m2							
No Asbestos							
B00A - R0019 - Cleaning Distributed Store - 2.67 m2							
No Asbestos							
B00A - R0020 - Movement - 10.04 m2							
No Asbestos							
B00A - R0021 - Movement - 2.99 m2							
No Asbestos							

B00A - R0022 - Withdrawal Space - 1hb - 15.88 m2	
No Asbestos	
B00A - R0023 - Distribution Board - .89 m2	
Note: No inspection of live electrical installation	
Ceiling Structures/Linings	Flat AC Sheeting
B00A - R0024 - Practical Activities - M - 1hb - 13.99 m2	
No Asbestos	
B00A - R0025 - Home Base - M - 45.87 m2	
No Asbestos	
B00A - R0026 - Movement - 19.66 m2	
No Asbestos	
B00A - R0027 - Movement - 7.94 m2	
No Asbestos	
B00A - R0028 - General Storeroom - 2.46 m2	
No Asbestos	
B00A - R0029 - Practical Activities - 1hb - 14.47 m2	
No Asbestos	
B00A - R0030 - Home Base - 46.14 m2	
No Asbestos	
B00A - R0031 - Staff Toilet - 4.55 m2	
No Asbestos	
B00A - R0032 - Staff Toilet - 4.33 m2	
No Asbestos	
B00A - R0033 - Cleaning Distributed Store - .96 m2	
No Asbestos	
B00A - R0034 - Toilets - Girls - 12.29 m2	
No Asbestos	
B00A - R0035 - Cleaning Distributed Store - 2.9 m2	
No Asbestos	
B00A - R0036 - Movement - 14.28 m2	
No Asbestos	
B00A - R0037 - Duplicating Workroom - 29.59 m2	
No Asbestos	
B00A - R0038 - Clerical Office - 16.73 m2	
No Asbestos	
B00A - R0039 - Sick Bay - 6.46 m2	
No Asbestos	
B00A - R0040 - Movement - 2.85 m2	
No Asbestos	
B00A - R0041 - Entry Vestibule - 14.62 m2	
No Asbestos	
B00A - R0042 - Movement - 6.19 m2	
No Asbestos	
B00A - R0043 - Principal - 26.36 m2	
No Asbestos	
B00A - R0044 - Interview - 14.82 m2	
No Asbestos	
B00A - R0045 - Deputy Principal - 13.76 m2	
No Asbestos	
B00A - R0046 - Interview - 16.02 m2	
No Asbestos	
B00A - R0047 - Distribution Board - .73 m2	
Note: No inspection of live electrical installation	

No Asbestos							
B00A - R0048 - Community Clinic - 14.48 m2							
No Asbestos							
B00A - R0049 - Community Clinic - 9.05 m2							
No Asbestos							
B00A - R0050 - Community Clinic - 6.27 m2							
No Asbestos							
B00A - R0051 - Movement - .96 m2							
No Asbestos							
B00A - R0052 - Uniform Shop - 2.71 m2							
No Asbestos							
B00A - R0053 - Movement - 13.39 m2							
No Asbestos							
B00A - R0054 - Movement - 53.81 m2							
No Asbestos							
B00A - R0055 - Movement - 74.33 m2							
Ceiling Structures/Linings	Flat AC Sheeting	75m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0056 - Movement - 66.38 m2							
Ceiling Structures/Linings	Flat AC Sheeting	67m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0057 - Movement - 11.27 m2							
No Asbestos							
B00A - R0058 - Movement - 10.73 m2							
No Asbestos							
B00A - R0059 - Stairs - 7.1 m2							
No Asbestos							
B00A - R0060 - Stairs - 2.24 m2							
No Asbestos							
B00A - R0061 - Stairs - 2.48 m2							
No Asbestos							
B00A - R0062 - Stairs - 2.83 m2							
No Asbestos							
B00A - R0063 - Movement - 68.02 m2							
Wall Linings Internal - Infill	Flat AC Sheeting						
B00A - R1001 - Home Base - 65.48 m2							
No Asbestos							
B00A - R1002 - Home Base Store - 5.34 m2							
No Asbestos							
B00A - R1003 - Withdrawal Space - 1hb - 12.44 m2							
No Asbestos							
B00A - R1004 - General Storeroom - 3.58 m2							
No Asbestos							
B00A - R1005 - Home Base Store - 5.38 m2							
No Asbestos							
B00A - R1006 - Practical Activities - 1hb - 38.66 m2							
No Asbestos							
B00A - R1007 - Movement - 4.29 m2							
No Asbestos							
B00A - R1008 - Home Base - 62.54 m2							
No Asbestos							
B00A - R1009 - Cleaning Distributed Store - 3.71 m2							

No Asbestos							
B00A - R1010 - Special Programs Room - 26.1 m2							
No Asbestos							
B00A - R1011 - Distribution Board - .9 m2							Note: No inspection of live electrical installation
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R1012 - General Storeroom - 8.88 m2							
No Asbestos							
B00A - R1013 - Plant - 3.65 m2							
No Asbestos							
B00A - R1014 - Movement - 25.77 m2							
No Asbestos							
B00A - R1015 - General Storeroom - 4.68 m2							
No Asbestos							
B00A - R1016 - General Storeroom - 36.2 m2							
No Asbestos							
B00A - R1017 - Toilets - Boys - 4.03 m2							
No Asbestos							
B00A - R1018 - Toilets - Girls - 4.03 m2							
No Asbestos							
B00A - R1019 - Special Programs Room - 44.5 m2							
No Asbestos							
B00A - R1020 - Practical Activities - 1hb - 22.6 m2							
No Asbestos							
B00A - R1021 - Home Base - 64.06 m2							
No Asbestos							
B00A - R1022 - Withdrawal Space - 1hb - 12.01 m2							
No Asbestos							
B00A - R1023 - Interview - 13.4 m2							
No Asbestos							
B00A - R1024 - Personal Effects Storage - 13.8 m2							
No Asbestos							
B00A - R1025 - Practical Activities - 1hb - 30.16 m2							
No Asbestos							
B00A - R1026 - Home Base - 64.25 m2							
No Asbestos							
B00A - R1027 - General Storeroom - 15.6 m2							
No Asbestos							
B00A - R1028 - Staff Room - 68.92 m2							
No Asbestos							
B00A - R1029 - Distribution Board - 1.12 m2							Note: No inspection of live electrical installation
No Asbestos							
B00A - R1030 - Staff Toilet - 3.49 m2							
No Asbestos							
B00A - R1031 - Staff Toilet - 3.06 m2							
No Asbestos							
B00A - R1032 - Staff Shower/Change - 6.97 m2							
No Asbestos							
B00A - R1033 - Staff Shower/Change - 8.29 m2							
No Asbestos							
B00A - R1034 - Movement - 12.27 m2							
No Asbestos							

B00A - R1035 - Stairs - 6.84 m2		
No Asbestos		
B00A - R1036 - Stairs - 9.23 m2		
No Asbestos		
B00A - R1037 - Stairs - 8.33 m2		
No Asbestos		
B00A - R1038 - Stairs - 7.62 m2		
No Asbestos		
B00A - R1039 - Plant - .7 m2		
No Asbestos		
B00B - Communal Facilities/Pupil Facilities - 1980 - Brick/Block		
Exterior		
Ceiling Voids - Raked Ceiling	Non Accessible Area	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00B - R0001 - Movement - 42.7 m2		
No Asbestos		
B00B - R0002 - Communal Space - 196.29 m2		
No Asbestos		
B00B - R0003 - P.E Store - 12.85 m2		
No Asbestos		
B00B - R0004 - Plant - 4.92 m2		
No Asbestos		
B00B - R0005 - Distribution Board - 1.39 m2		
No Asbestos		
B00B - R0006 - Hall Chair Store - 7.22 m2		
No Asbestos		
B00B - R0007 - Movement - 19 m2		
No Asbestos		
B00B - R0008 - Movement - 2.33 m2		
No Asbestos		
B00B - R0009 - Raised Platform - 76.05 m2		
No Asbestos		
B00B - R0010 - Movement - 30.17 m2		
No Asbestos		
B00B - R0011 - Canteen - 27.16 m2		
No Asbestos		
B00B - R0012 - Movement - 16.74 m2		
No Asbestos		
B00B - R0013 - Canteen Office/Store - 5.02 m2		
No Asbestos		
B00B - R0014 - Canteen Office/Store - 1.77 m2		
No Asbestos		
B00B - R0015 - Staff Toilet - 1.8 m2		
No Asbestos		
B00B - R0016 - Canteen Office/Store - 4.96 m2		
No Asbestos		
B00B - R0017 - Movement - 1.68 m2		
No Asbestos		
B00B - R0018 - General Assistant/Bulk Store - 14.36 m2		
No Asbestos		

Note: No inspection of live electrical installation

No Asbestos	
B00B - R0019 - General Assistant/Bulk Store - 8.64 m2	
No Asbestos	
B00B - R0020 - Cleaning Supplies - 8.53 m2	
No Asbestos	
B00B - R0021 - Movement - 5.81 m2	
No Asbestos	
B00B - R0022 - General Storeroom - 15.31 m2	
No Asbestos	
B00B - R0023 - Movement - 2.87 m2	
No Asbestos	
B00B - R0024 - Movement - 6.67 m2	
No Asbestos	
B00B - R0025 - Movement - 14.24 m2	
No Asbestos	
B00B - R0026 - Movement - 35.5 m2	
No Asbestos	
B00C - Library/Pupil Facilities - 1980 - Brick/Block	
Exterior	
Ceiling Voids - Raked Ceiling	Non Accessible Area
Underfloor Voids - Slab on Ground	No Asbestos Found
Interior	
B00C - R0001 - Special Programs Room - 47.42 m2	
No Asbestos	
B00C - R0002 - Library Office/Workroom - 18.34 m2	
No Asbestos	
B00C - R0003 - Library Office/Workroom - 10.12 m2	
No Asbestos	
B00C - R0004 - K.L.A. Store - 12.75 m2	
No Asbestos	
B00C - R0005 - Reading Area - 195.51 m2	
No Asbestos	
B00C - R0006 - Craft Store - 13.07 m2	
No Asbestos	
B00C - R0007 - Toilets - Boys - 10.04 m2	
No Asbestos	
B00C - R0008 - Main Switch Board - 8.18 m2	
No Asbestos	
B00C - R0009 - Kiln Room - 13.31 m2	
No Asbestos	
B00C - R0010 - General Assistant/Bulk Store - 28.84 m2	
No Asbestos	
B00C - R0011 - Movement - 1.71 m2	
No Asbestos	
B00C - R0013 - Seminar/Study - 8.7 m2	
No Asbestos	
B00C - R0014 - Seminar/Study - 8.64 m2	
No Asbestos	
B00C - R0015 - Cleaning Distributed Store - 1.51 m2	
No Asbestos	

B00C - R0016 - Toilets - Boys - 10.29 m2		
No Asbestos		
B00C - R0017 - Toilets - Girls - 8.84 m2		
No Asbestos		
B00C - R0018 - Movement - 70.56 m2		
No Asbestos		
B00C - R0019 - Movement - 21.86 m2		
No Asbestos		
B00C - R0020 - Movement - 6.3 m2		
No Asbestos		
B00C - R0021 - Movement - 85.18 m2		
No Asbestos		
B00D - General Learning/Pupil Facilities - 1980 - Brick/Veneer		
Exterior		
Ceiling Voids - Raked Ceiling	Non Accessible Area	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00D - R0001 - Movement - 30.57 m2		
No Asbestos		
B00D - R0002 - Practical Activities - 1hb - 25.77 m2		
No Asbestos		
B00D - R0003 - Home Base Store - 5.68 m2		
No Asbestos		
B00D - R0004 - Home Base - 56.96 m2		
No Asbestos		
B00D - R0005 - Withdrawal Space - 1hb - 12.35 m2		
No Asbestos		
B00D - R0006 - Home Base - 56.57 m2		
No Asbestos		
B00D - R0007 - Home Base Store - 5.68 m2		
No Asbestos		
B00D - R0008 - Personal Effects Storage - 15.56 m2		
No Asbestos		
B00D - R0009 - Movement - 21.63 m2		
No Asbestos		
B00D - R0010 - Practical Activities - 1hb - 26.02 m2		
No Asbestos		
B00D - R0011 - Home Base - 57.92 m2		
No Asbestos		
B00D - R0012 - Withdrawal Space - 1hb - 12.42 m2		
No Asbestos		
B00D - R0013 - Home Base Store - 5.71 m2		
No Asbestos		
B00D - R0014 - Home Base - 58 m2		
No Asbestos		
B00D - R0015 - Home Base Store - 5.71 m2		
No Asbestos		
B00D - R0016 - Distribution Board - 1.73 m2		
No Asbestos		
B00D - R0017 - Cleaning Distributed Store - 3.68 m2		

Note: No inspection of live electrical installation

No Asbestos		
B00D - R0018 - Disabled Toilet - 8.19 m2		
No Asbestos		
B00D - R0019 - Toilets - Boys - 10.37 m2		
No Asbestos		
B00D - R0020 - Personal Effects Storage - 8.02 m2		
No Asbestos		
B00D - R0021 - Movement - 13.88 m2		
No Asbestos		
B00D - R0022 - Practical Activities - 1hb - 38.47 m2		
No Asbestos		
B00D - R0023 - Movement - 23.99 m2		
No Asbestos		
B00D - R0024 - Staff Room Annexe - 14.47 m2		
No Asbestos		
B00D - R0025 - Movement - 16.43 m2		
No Asbestos		
B00D - R0026 - Movement - 5.76 m2		
No Asbestos		
B00E - General Learning/Pupil Facilities - 1980 - Brick/Veneer		
Exterior		
Ceiling Voids - Raked Ceiling	Non Accessible Area	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00E - R0001 - Movement - 30.52 m2		
No Asbestos		
B00E - R0002 - Practical Activities - 1hb - 25.74 m2		
No Asbestos		
B00E - R0003 - Home Base Store - 5.68 m2		
No Asbestos		
B00E - R0004 - Home Base - 56.84 m2		
No Asbestos		
B00E - R0005 - Withdrawal Space - 1hb - 12.28 m2		
No Asbestos		
B00E - R0006 - Home Base - 56.56 m2		
No Asbestos		
B00E - R0007 - Home Base Store - 5.68 m2		
No Asbestos		
B00E - R0008 - Personal Effects Storage - 15.41 m2		
No Asbestos		
B00E - R0009 - Movement - 21.69 m2		
No Asbestos		
B00E - R0010 - Practical Activities - 1hb - 25.95 m2		
No Asbestos		
B00E - R0011 - Home Base - 57.94 m2		
No Asbestos		
B00E - R0012 - Withdrawal Space - 1hb - 12.35 m2		
No Asbestos		
B00E - R0013 - Home Base Store - 5.68 m2		
No Asbestos		

B00E - R0014 - Home Base - 58.08 m2		
No Asbestos		
B00E - R0015 - Home Base Store - 5.68 m2		
No Asbestos		
B00E - R0016 - Distribution Board - 1.35 m2		Note: No inspection of live electrical installation
No Asbestos		
B00E - R0017 - Cleaning Distributed Store - 4.09 m2		
No Asbestos		
B00E - R0018 - Toilets - Girls - 8.09 m2		
No Asbestos		
B00E - R0019 - Personal Effects Storage - 8.09 m2		
No Asbestos		
B00E - R0020 - Movement - 13.72 m2		
No Asbestos		
B00E - R0021 - Practical Activities - 1hb - 43.35 m2		
No Asbestos		
B00E - R0022 - Movement - 18.29 m2		
No Asbestos		
B00E - R0023 - Staff Room Annexe - 14.5 m2		
No Asbestos		
B00E - R0024 - Movement - 16.71 m2		
No Asbestos		
B00E - R0025 - Movement - 5.87 m2		
No Asbestos		
B00F - Support Unit - 1980 - Steel		
Exterior		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00F - R0005 - Communal Space - 276.5 m2		
No Asbestos		
B00F - R0006 - Covered Outdoor Learning Area - 139.1 m2		
No Asbestos		

Demountables

There are no Demountable(s) Located at this school as per the AMS records as of 09-Sep-2020