

Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Kiama High School (8171)
Region:	Southern NSW AMU
State Electorate:	Kiama
Local Government Area:	Kiama

Last Reviewed By:	AECOM 18-JUN-2015
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	Yes
Please refer to the latest site specific Asbestos Management Plans available from the Department's website (Refer to Note 2).	

8171 - Kiama High School
Site Plan (12579)



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>

<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - Administration/General Learning - 1967 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	120m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00A - R0002 - Main Switchroom - 8.21 m2							
No Asbestos							
B00A - R0008 - Distribution Board Cupboard - 1.21 m2							
No Asbestos							
B00A - R0009 - Cleaning Store - Distributed - 6.11 m2							
No Asbestos							
B00A - R0010 - Toilets-Boys - 25.62 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Partition Walls (Cubicles)	Compressed AC Sheet						
B00A - R0011 - Staff - Toilet - 5.6 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00A - R0012 - Laboratory L.S. - 86.02 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (70 - 120 m2) - (X8)						
B00A - R0013 - Preparation - 28.61 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00A - R0014 - Staff Study - 9.59 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00A - R0017 - Distribution Board Cupboard - 1.04 m2							
No Asbestos							
B00A - R0028 - Clinic-Toilets - 3.14 m2							
No Asbestos							
B00A - R0029 - General Storeroom - 7.69 m2							
No Asbestos							
B00A - R0033 - Administration - Clerical - 18.72 m2							
No Asbestos							
B00A - R0034 - Principal Office - 23.78 m2							
No Asbestos							
B00A - R0035 - Movement - 7.42 m2							
No Asbestos							
B00A - R0036 - Interview/Office - Type 1 - 17.14 m2							
No Asbestos							
B00A - R0037 - Interview/Office - Type 1 - 17.05 m2							
No Asbestos							
B00A - R0038 - Administration - Clerical - 26.29 m2							
No Asbestos							
B00A - R0039 - Clinic - Girls - 13.88 m2							
No Asbestos							
B00A - R0040 - Clinic-Toilets - 3.38 m2							

No Asbestos							
B00A - R0041 - Clinic - Boys - 13.02 m2							
No Asbestos							
B00A - R0042 - Administration - Clerical - 61.85 m2							
No Asbestos							
B00A - R0043 - Movement - 117.05 m2							
No Asbestos							
B00A - R0044 - External Movement - 17.12 m2							
No Asbestos							
B00A - R0045 - Movement - 21.61 m2							
No Asbestos							
B00A - R0046 - Stairs - 2.16 m2							
No Asbestos							
B00A - R0047 - Administration - Clerical - 5.1 m2							
No Asbestos							
B00A - R0048 - Staff - Toilet - 4.67 m2							
No Asbestos							
B00A - R0049 - Disabled Toilet - 5.29 m2							
No Asbestos							
B00A - R0050 - Staff - Toilet - 4.7 m2							
No Asbestos							
B00A - R0051 - Security Store - 11.74 m2							
No Asbestos							
B00A - R0052 - Movement - 51.89 m2							
Floor Coverings Res/Textile	Vinyl Tiles	52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
B00A - R0053 - Deputy Principal Office - 14.74 m2							
No Asbestos							
B00A - R0054 - Deputy Principal Office - 14.91 m2							
No Asbestos							
B00A - R0055 - Interview/Office - Type 1 - 14.85 m2							
No Asbestos							
B00A - R0056 - Duplicating Workroom - 18.9 m2							
No Asbestos							
B00A - R0057 - External Movement - 84.25 m2							
No Asbestos							
B00A - R0058 - Movement - 58.75 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
B00A - R0059 - Apparatus Storage - 19.51 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00A - R0060 - Laboratory L.S. - 86.22 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (70 - 120 m2) - (X8)						
B00A - R0061 - General Learning Space - 44.21 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
B00A - R1001 - Music Learning Space - 52.42 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						

B00A - R1002 - Music Store - 6.46 m2							
No Asbestos							
B00A - R1003 - Music Store - 6.12 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00A - R1004 - Music Store - 6.09 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00A - R1005 - Music Learning Space - 52.42 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
B00A - R1006 - Music Store - 6.25 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00A - R1007 - Music Store - 6.19 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00A - R1008 - Staff Study - 24.58 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00A - R1009 - Movement - 108.29 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (70 - 120 m2) - (X8)						
B00A - R1010 - Distribution Board Cupboard - 1.21 m2							
							Note: No inspection of live electrical installation
No Asbestos							
B00A - R1011 - General Storeroom - 6.04 m2							
No Asbestos							
B00A - R1012 - Toilets-Girls - 25.54 m2							
Ceiling Structures/Linings	Flat AC Sheeting	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Partition Walls (Cubides)	Compressed AC Sheet						
B00A - R1013 - Staff - Toilet - 4.95 m2							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R1014 - Staff Study - 52.63 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
B00A - R1015 - Staff Study - 21.52 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00A - R1016 - General Storeroom - 3.58 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00A - R1017 - General Learning Space - 52.34 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
B00A - R1018 - General Learning Space - 52.41 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
B00A - R1019 - General Learning Space - 52.56 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
B00A - R1020 - Distribution Board Cupboard - .77 m2							
							Note: No inspection of live electrical installation
No Asbestos							
B00A - R1021 - Computer Learning Space - 51.27 m2							

Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)							
B00A - R1022 - General Learning Space - 52.41 m2								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)							
B00A - R1023 - General Storeroom - 6.46 m2								
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00A - R1024 - Movement - 57.67 m2								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)							
B00E - General Learning/Art - 1954 - Timber								
Exterior								
Eaves Linings	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	No Asbestos Found							
Underfloor Voids	No Asbestos Found							
Interior								
B00E - R0001 - Staff Study - 29.56 m2								
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00E - R0002 - General Learning Space - 58.05 m2								
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	58m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00E - R0003 - Movement - 9.45 m2								
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00E - R0004 - Art Learning Space - 53.94 m2								
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00E - R0005 - General Storeroom - 19.71 m2								
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00E - R0006 - General Learning Space - 54.24 m2								
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00E - R0007 - General Learning Space - 54.24 m2								
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	55m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00E - R0008 - Staff Study - 22.5 m2								
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00E - R0009 - Movement - 76.84 m2								
Ceiling Structures/Linings	Flat AC Sheeting	77m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)	

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	77m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00F - Technological & Applied Studies - 1980 - Brick/Block							
Exterior							
Ceiling Voids - Raked Ceiling	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Interior							
B00F - M0009 - Movement - 60.83 m2							
No Asbestos							
B00F - M0010 - Darkroom Space - 22.49 m2							
No Asbestos							
B00F - M0011 - Design L.S. - 51.53 m2							
No Asbestos							
B00F - M0012 - Computer Learning Space - 46.1 m2							
No Asbestos							
B00F - M0019 - Toilets-Boys - 21.62 m2							
No Asbestos							
B00F - M0020 - Toilets-Girls - 21.55 m2							
No Asbestos							
B00F - M0021 - Toilets-Disabled - 2.31 m2							
No Asbestos							
B00F - M0022 - Cleaning Store - Distributed - 1.03 m2							
No Asbestos							
B00F - M0023 - Staff - Toilet - 9.05 m2							
No Asbestos							
B00F - M0024 - Staff - Toilet - 7.5 m2							
No Asbestos							
B00F - M0025 - External Movement - 105.36 m2							
Ceiling Structures/Linings	Flat AC Sheeting	106m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00F - M0026 - Maintenance Bulk Store - 5.85 m2							
No Asbestos							
B00F - M1008 - Cleaning Store - Distributed - 2.98 m2							
No Asbestos							
B00F - M1009 - Distribution Board Cupboard - 1.02 m2							
No Asbestos							Note: No inspection of live electrical installation
B00F - M1010 - General Learning Space - 46.99 m2							
No Asbestos							
B00F - M1011 - General Learning Space - 47.88 m2							
No Asbestos							
B00F - M1012 - General Learning Space - 45.96 m2							
No Asbestos							
B00F - M1013 - General Learning Space - 47.6 m2							
No Asbestos							
B00F - M1014 - General Storeroom - 22.7 m2							
No Asbestos							
B00F - M1015 - General Storeroom - 4.33 m2							
No Asbestos							
B00F - M1016 - Staff Study - 27.45 m2							

No Asbestos							
B00F - M1017 - Movement - 95.77 m2							
No Asbestos							
B00F - R0001 - Materials Store - 31.26 m2							
No Asbestos							
B00F - R0002 - Materials Technology L.S. - 81.01 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00F - R0003 - Materials Technology L.S. - 123.49 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00F - R0004 - Welding Area - 6.72 m2							
No Asbestos							
B00F - R0005 - Staff Study - 17.11 m2							
No Asbestos							
B00F - R0006 - General Storeroom - .91 m2							
No Asbestos							
B00F - R0007 - Distribution Board Cupboard - .9 m2							Note: No inspection of live electrical installation
Wall Linings Internal	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00F - R0008 - Cleaning Store - Distributed - 6.34 m2							
No Asbestos							
B00F - R0009 - Movement - 23.78 m2							
No Asbestos							
B00F - R0013 - Staff Study - 23.51 m2							
No Asbestos							
B00F - R0014 - Materials Technology L.S. - 107.05 m2							
No Asbestos							
B00F - R0015 - Wood Technology Bay - 18.44 m2							
No Asbestos							
B00F - R0016 - Materials Technology L.S. - 108.06 m2							
No Asbestos							
B00F - R0017 - Movement - 139.47 m2							
No Asbestos							
B00F - R0018 - Movement - 60.43 m2							
No Asbestos							
B00F - R1001 - Food Technology L.S. - 102.79 m2							
No Asbestos							
B00F - R1002 - Staff Study - 30.94 m2							
No Asbestos							
B00F - R1003 - Design L.S. - 69.82 m2							
No Asbestos							
B00F - R1004 - Design L.S. - 69.66 m2							
No Asbestos							
B00F - R1005 - Materials Store - 11.98 m2							
No Asbestos							
B00F - R1006 - Cleaning Store - Distributed - 7.88 m2							
No Asbestos							
B00F - R1007 - Distribution Board Cupboard - .84 m2							Note: No inspection of live electrical installation
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

Wall Linings Internal	Flat AC Sheeting	4m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00F - R1018 - Laundry - 10.09 m2							
No Asbestos							
B00F - R1019 - Food/Research Space - 17.9 m2							
No Asbestos							
B00F - R1020 - Food Technology L.S. - 102.3 m2							
No Asbestos							
B00F - R1021 - Materials Store - 22.23 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00F - R1022 - Movement - 100.84 m2							
No Asbestos							
B00G - Pupil Facilities/Physical Education - 1971 - Brick/Block							
Exterior							
Ceiling Voids - Raked Ceiling	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00G - R0001 - Toilets-Girls - 21.25 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G - R0002 - Movement - 79.89 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (70 - 120 m2) - (X8)						
B00G - R0003 - Gymnasium - 309.06 m2							
No Asbestos							
B00G - R0004 - Sport Equipment Store - 21.36 m2							
No Asbestos							
B00G - R0005 - General Storeroom - 8.2 m2							
No Asbestos							
B00G - R0006 - Student Canteen - 45.72 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00G - R0007 - Distribution Board Cupboard - .88 m2							
						Note: No inspection of live electrical installation	
No Asbestos							
B00G - R0008 - Cleaning Store - Distributed - 1.02 m2							
No Asbestos							
B00G - R0009 - Toilets-Boys - 20.19 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G - R0010 - Sport Equipment Store - 20.36 m2							
No Asbestos							
B00G - R0011 - Staff - Toilet - 3.15 m2							
No Asbestos							
B00G - R0012 - Maintenance Bulk Store - 5.14 m2							
No Asbestos							
B00G - R0013 - Movement - 50.53 m2							
No Asbestos							
B00G - R0014 - Stairs - 6.36 m2							
No Asbestos							
B00G - R0015 - Movement - 46.03 m2							

No Asbestos								
B00G - R0016 - Stairs - 6.35 m2								
No Asbestos								
B00G - R1001 - General Storeroom - 9.12 m2								
No Asbestos								
B00G - R1003 - Movement - 16.58 m2								
No Asbestos								
B00G - R1004 - Gymnasium - 33.6 m2								
No Asbestos								
B00G - R1005 - Movement - 16.67 m2								
No Asbestos								
B00G - R1007 - Staff Change - 9.02 m2								
No Asbestos								
B00G - R1008 - Sport Equipment Store - 7.85 m2								
No Asbestos								
B00G - R1009 - Shower/Change - 61.8 m2								
Partition Walls (Cubides)	Compressed AC Sheet	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00G - R1010 - Shower/Change - 61.92 m2								
Partition Walls (Cubides)	Compressed AC Sheet	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00G - R1011 - Staff Change - 7.73 m2								
No Asbestos								
B00G - R1012 - Plant - 3.51 m2								
No Asbestos								
B00G - R1013 - Plant - 3.51 m2								
No Asbestos								
B00G - R1014 - Stairs - 6.35 m2								
No Asbestos								
B00G - R1015 - Movement - 46.03 m2								
No Asbestos								
B00G - R1016 - Stairs - 21.77 m2								
No Asbestos								
B00G - R1017 - Movement - 34.26 m2								
No Asbestos								
B00H - Multi Purpose Facilities/Performing Arts - 1960 - Concrete Framed								
Exterior								
Eaves Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Eaves Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos	
Ceiling Voids - Raked Ceiling	No Asbestos Found							
Underfloor Voids	Non Accessible Area							
Interior								
B00H - M0001 - General Storeroom - 11.28 m2								
No Asbestos								
B00H - M0002 - Control Room - 11.71 m2								
No Asbestos								
B00H - R0001 - Multi-Purpose Space - 264.24 m2								

No Asbestos							
B00H - R0002 - Cleaning Store - Distributed - 6 m2							
No Asbestos							
B00H - R0003 - Toilets-Girls - 6.97 m2							
No Asbestos							
B00H - R0004 - Student Canteen - 4.9 m2							
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00H - R0005 - Toilets-Boys - 5.09 m2							
No Asbestos							
B00H - R0006 - Movement - 14.39 m2							
No Asbestos							
B00H - R0007 - Stage - 53.81 m2							
No Asbestos							
B00H - R0008 - Movement - 30.96 m2							
No Asbestos							
B00H - R0009 - External Movement - 10.42 m2							
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00H - R0010 - Performance Workspace - 60.33 m2							
No Asbestos							
B00H - R0011 - Toilets-Girls - 6.12 m2							
No Asbestos							
B00H - R0012 - General Storeroom - 7.33 m2							
No Asbestos							
B00H - R0013 - Toilets-Boys - 5.02 m2							
No Asbestos							
B00H - R0014 - Performing Arts Changeroom - 23.68 m2							
No Asbestos							
B00H - R0015 - General Storeroom - 10.37 m2							
No Asbestos							
B00H - R0016 - General Storeroom - 9.82 m2							
No Asbestos							
B00H - R0017 - Plant - 16.51 m2							
No Asbestos							
B00H - R0018 - External Movement - 4.83 m2							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00H - R9001 - Garden Store Room - 19.53 m2							
No Asbestos							
B00H - R9002 - Garden Store Room - 19.95 m2							
No Asbestos							
B00H - R9003 - General Assistants - 51.83 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00J - Library/Science Learning - 1980 - Brick/Block							
Exterior							
Ceiling Voids - Raked Ceiling	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						

Interior	
B00J - R0001 - Staff Study - 23.29 m2	
Floor Coverings Res/Textile	Vinyl Tiles
B00J - R0002 - Chemical Store - 9.67 m2	
No Asbestos	
B00J - R0003 - Movement - 76.32 m2	
No Asbestos	
B00J - R0004 - Apparatus Store - 25.23 m2	
No Asbestos	
B00J - R0005 - External Movement - 5.97 m2	
No Asbestos	
B00J - R0006 - Laboratory L.S. - 80.64 m2	
No Asbestos	
B00J - R0007 - Preparation - 48.46 m2	
No Asbestos	
B00J - R0008 - Laboratory L.S. - 79.01 m2	
No Asbestos	
B00J - R0009 - External Movement - 3.23 m2	
No Asbestos	
B00J - R0010 - Distribution Board Cupboard - .63 m2	
Note: No inspection of live electrical installation	
No Asbestos	
B00J - R0011 - Laboratory L.S. - 80.64 m2	
No Asbestos	
B00J - R0012 - Preparation - 47.91 m2	
No Asbestos	
B00J - R0013 - Laboratory L.S. - 80.82 m2	
No Asbestos	
B00J - R0014 - External Movement - 2.38 m2	
No Asbestos	
B00J - R1001 - Main Area - 412.92 m2	
No Asbestos	
B00J - R1002 - Workroom - 45.77 m2	
Floor Coverings Res/Textile	Vinyl Tiles
B00J - R1003 - Librarian - 11.79 m2	
No Asbestos	
B00J - R1004 - Audio Visual Workroom - 42.27 m2	
No Asbestos	
B00J - R1005 - Cleaning Store - Distributed - 2.39 m2	
Floor Coverings Res/Textile	Vinyl Tiles
B00J - R1006 - Clinic - Boys - 9.89 m2	
No Asbestos	
B00J - R1007 - Clinic - Girls - 13.1 m2	
Floor Coverings Res/Textile	Vinyl Tiles
B00J - R1008 - Deputy Principal Office - 12.93 m2	
Floor Coverings Res/Textile	Vinyl Tiles
B00J - R1009 - Administration - Clerical - 11.62 m2	
No Asbestos	
B00J - R1010 - Movement - 25.52 m2	

No Asbestos		
B00J - R1011 - Distribution Board Cupboard - .69 m2		Note: No inspection of live electrical installation
No Asbestos		
B00J - R1012 - Plant - 1.25 m2		
No Asbestos		
B00J - R1013 - Pupil Entry - 2.95 m2		
No Asbestos		
B00J - R1014 - Seminar - 10.39 m2		
No Asbestos		
B00J - R1015 - Seminar - 10.26 m2		
No Asbestos		
B00J - R1016 - Seminar - 10.59 m2		
No Asbestos		
B00K - Mechanical Services - 1954 - Brick/Block		
Exterior		
Ceiling Voids - Flat Roof	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00K - R0001 - Dust Extraction Space - 8.62 m2		
No Asbestos		
B00L - General Learning/Computer Learning - 2004 - Brick/Veneer		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Interior		
B00L - R0001 - Computer Learning Space - 65.02 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00L - R0002 - Computer Learning Space - 64.62 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00L - R0003 - Cleaning Store - Distributed - 2.25 m2		
No Asbestos		
B00L - R0004 - General Storeroom - 21.83 m2		
No Asbestos		
B00L - R0005 - Distribution Board Cupboard - .75 m2		Note: No inspection of live electrical installation
No Asbestos		
B00L - R0006 - General Learning Space - 59.58 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00L - R0007 - General Learning Space - 57.94 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00L - R0008 - Seminar - 25.53 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00L - R0009 - General Learning Space - 58.72 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00L - R0010 - General Learning Space - 57.94 m2		
Floor Coverings Res/Textile	No Asbestos Found	

B00L - R0011 - Distribution Board Cupboard - .7 m2		Note: No inspection of live electrical installation
No Asbestos		
B00L - R0012 - External Movement - 5.25 m2		
No Asbestos		
B00L - R0013 - Movement - 15.31 m2		
No Asbestos		
B00L - R0014 - Stairs - 3 m2		
No Asbestos		
B00L - R0015 - Movement - 159.77 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00L - R0016 - Covered Area - 62.55 m2		
No Asbestos		
B00L - R0017 - External Movement - 42.49 m2		
No Asbestos		
B00L - R1001 - Computer Learning Space - 64.78 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00L - R1002 - Computer Learning Space - 64.69 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00L - R1003 - Cleaning Store - Distributed - 2.25 m2		
No Asbestos		
B00L - R1004 - General Storeroom - 21.85 m2		
No Asbestos		
B00L - R1005 - Distribution Board Cupboard - .75 m2		Note: No inspection of live electrical installation
No Asbestos		
B00L - R1006 - General Learning Space - 59.03 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00L - R1007 - General Learning Space - 59.03 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00L - R1008 - Seminar - 24.01 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00L - R1009 - General Learning Space - 58.94 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00L - R1010 - General Learning Space - 59.66 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00L - R1011 - Distribution Board Cupboard - .68 m2		Note: No inspection of live electrical installation
No Asbestos		
B00L - R1012 - Movement - 4.1 m2		
No Asbestos		
B00L - R1013 - Movement - 7.5 m2		
No Asbestos		
B00L - R1014 - Stairs - 14.22 m2		
No Asbestos		
B00L - R1015 - Movement - 160.82 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00M - General Learning/Staff Facilities - 2007 - Brick/Veneer		

Exterior	
Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found
Interior	
B00M - R0001 - Music Learning Space - 59.51 m2	
No Asbestos	
B00M - R0002 - Music Learning Space - 60.29 m2	
No Asbestos	
B00M - R0003 - General Learning Space - 60.01 m2	
No Asbestos	
B00M - R0004 - General Learning Space - 59.98 m2	
No Asbestos	
B00M - R0005 - Change - 21.66 m2	
No Asbestos	
B00M - R0006 - Change - 22.51 m2	
No Asbestos	
B00M - R0007 - Cleaning Store - Distributed - 3.24 m2	
No Asbestos	
B00M - R0008 - Seminar - 20.36 m2	
No Asbestos	
B00M - R0009 - Fitness Laboratory - 96.61 m2	
No Asbestos	
B00M - R0010 - Fitness Store - 19.88 m2	
No Asbestos	
B00M - R0011 - Music Store - 19.46 m2	
No Asbestos	
B00M - R0012 - Performance Workshop - 52.77 m2	
No Asbestos	
B00M - R0013 - Practice/Seminar - 19.02 m2	
No Asbestos	
B00M - R0015 - External Movement - 129.46 m2	
No Asbestos	
B00M - R0016 - Movement - 3.29 m2	
No Asbestos	
B00M - R0017 - External Movement - 20.21 m2	
No Asbestos	
B00M - R0018 - External Movement - 19.38 m2	
No Asbestos	
B00M - R0019 - External Stairs - 1.14 m2	
No Asbestos	
B00M - R0020 - External Stairs - .81 m2	
No Asbestos	
B00M - R0021 - External Movement - 12.94 m2	
No Asbestos	
B00M - R0022 - Lift - 2.1 m2	
No Asbestos	
B00M - R0023 - Handwashing Facilities - 4.32 m2	
No Asbestos	
B00M - R0024 - External Movement - 25.11 m2	
No Asbestos	
B00M - R0025 - Performance Workshop - 52.85 m2	

No Asbestos	
B00M - R0026 - Distribution Board Cupboard - .8 m2	Note: No inspection of live electrical installation
No Asbestos	
B00M - R1001 - Art Learning Space - 59.21 m2	
No Asbestos	
B00M - R1002 - Art Learning Space - 59.21 m2	
No Asbestos	
B00M - R1003 - Interview/Office - Type 1 - 12.51 m2	
No Asbestos	
B00M - R1004 - Interview/Office - Type 1 - 12.75 m2	
No Asbestos	
B00M - R1005 - Art Learning Space - 59.12 m2	
No Asbestos	
B00M - R1006 - Art Learning Space - 58.36 m2	
No Asbestos	
B00M - R1007 - Visual Arts Workshop - 99.7 m2	
No Asbestos	
B00M - R1008 - Visual Arts Store - 24.7 m2	
No Asbestos	
B00M - R1009 - Visual Arts Store - 24.68 m2	
No Asbestos	
B00M - R1010 - Visual Arts Store - 19.6 m2	
No Asbestos	
B00M - R1011 - Visual Arts Store - 19.58 m2	
No Asbestos	
B00M - R1012 - Kiln Space - 4 m2	
No Asbestos	
B00M - R1013 - Pottery Store - 19.96 m2	
No Asbestos	
B00M - R1014 - Visual Arts Workshop - 99.33 m2	
No Asbestos	
B00M - R1015 - Distribution Board Cupboard - .82 m2	Note: No inspection of live electrical installation
No Asbestos	
B00M - R1016 - Movement - 3.15 m2	
No Asbestos	
B00M - R1017 - External Movement - 129.46 m2	
No Asbestos	
B00M - R1018 - External Movement - 15.63 m2	
No Asbestos	
B00M - R1019 - External Movement - 17.37 m2	
No Asbestos	
B00M - R1020 - External Stairs - .57 m2	
No Asbestos	
B00M - R1021 - External Movement - 20.21 m2	
No Asbestos	
B00M - R1022 - External Stairs - .81 m2	
No Asbestos	
B00M - R1023 - Lift - 2.1 m2	
No Asbestos	
B00M - R2001 - Preparation/Printing - 33.11 m2	
No Asbestos	
B00M - R2002 - Staff - Toilet - 4.26 m2	

No Asbestos	
B00M - R2003 - Staff - Toilet - 4.34 m2	
No Asbestos	
B00M - R2004 - Cleaning Store - Distributed - 3.61 m2	
No Asbestos	
B00M - R2005 - Staff - Toilet - 3.61 m2	
No Asbestos	
B00M - R2006 - Staff - Toilet - 3.61 m2	
No Asbestos	
B00M - R2007 - Toilets-Disabled - 6.27 m2	
No Asbestos	
B00M - R2008 - Interview/Office - Type 1 - 12.42 m2	
No Asbestos	
B00M - R2009 - Interview/Office - Type 1 - 12.42 m2	
No Asbestos	
B00M - R2010 - Movement - 68 m2	
No Asbestos	
B00M - R2011 - Staff Study - 196.03 m2	
No Asbestos	
B00M - R2012 - Staff Lounge - 91.13 m2	
No Asbestos	
B00M - R2013 - Staff Study - 196.44 m2	
No Asbestos	
B00M - R2014 - Distribution Board Cupboard - .72 m2	Note: No inspection of live electrical installation
No Asbestos	
B00M - R2015 - Movement - 3.59 m2	
No Asbestos	
B00M - R2016 - External Movement - 51.69 m2	
No Asbestos	
B00M - R2017 - Movement - 10.8 m2	
No Asbestos	
B00M - R2018 - External Movement - 13.75 m2	
No Asbestos	
B00M - R2019 - External Stairs - 18.12 m2	
No Asbestos	
B00M - R2020 - External Stairs - 20.23 m2	
No Asbestos	
B00M - R2021 - Lift - 2.1 m2	
No Asbestos	
B00M - R2022 - Staff Kitchen - 7.3 m2	
No Asbestos	
B00M - R2023 - Staff Kitchen - 7.28 m2	
No Asbestos	
B00N - Physical Education - 2011 - Brick/Veneer	
Exterior	
No Asbestos	
Interior	
B00N - R0001 - External Movement - 68.52 m2	
No Asbestos	
B00N - R0002 - Gymnasium - 632.18 m2	
No Asbestos	

B00N - R0003 - Chair Store - 33.75 m2	
No Asbestos	
B00N - R0004 - Large Equipment Store - 24.19 m2	
No Asbestos	
B00N - R0005 - No Access - .84 m2	
No Asbestos	
B00N - R0006 - Change - 29.08 m2	
No Asbestos	
B00N - R0007 - Change - 29.14 m2	
No Asbestos	
B00N - R0008 - Cleaning Store - Distributed - 3.26 m2	
No Asbestos	
B00N - R0009 - First Aid - 12.45 m2	
No Asbestos	
B00N - R0010 - Utility Space - .4 m2	
No Asbestos	
B00N - R0011 - Access Student Shower/Toilet/Change - 9.45 m2	
No Asbestos	
B00N - R0012 - Utility Space - .74 m2	
No Asbestos	
B00N - R9001 - Tiered Learning Area - 184.93 m2	
No Asbestos	

Demountables

OS 720 12130 - Science Laboratory/Prep Room - Placement Date : 30-JUN-1995

Exterior

Eaves Linings	Flat AC Sheeting	17.28m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

Interior

R1- Laboratory L.S.

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	90m2	Assumed Asbestos

R2- Preparation

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	19m2	Assumed Asbestos