


# Asbestos Register

(Hazardous Materials and Risk Assessment)

<b>School:</b>	<b>Kingscliff High School (8579)</b>
<b>Region:</b>	<b>North Coast AMU</b>
<b>State Electorate:</b>	<b>Tweed</b>
<b>Local Government Area:</b>	<b>Tweed</b>

Last Reviewed By:	WSP 08-OCT-2015
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	<b>No</b>
No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.	



# Preface to Asbestos Register

## Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
  - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
  - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
  - o Any wall cavity
  - o Sub floor area, particularly formwork for slabs in/on ground,
  - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.  
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

## Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

## Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

## Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

## Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>

<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

## Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

### 3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
<b>B00A - Administration - 1986 - Brick/Block</b>							
<b>Exterior</b>							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00A - R0001 - Movement - 37.48 m2</b>							
No Asbestos							
<b>B00A - R0002 - Movement - 50.79 m2</b>							
No Asbestos							
<b>B00A - R0003 - Clinic - Boys - 13.76 m2</b>							
No Asbestos							
<b>B00A - R0004 - Clinic - Girls - 13.76 m2</b>							
No Asbestos							
<b>B00A - R0005 - Administration - Clerical - 52.49 m2</b>							
No Asbestos							
<b>B00A - R0006 - Public Entry - 17.43 m2</b>							
No Asbestos							
<b>B00A - R0007 - Movement - 3.24 m2</b>							
No Asbestos							
<b>B00A - R0009 - Movement - 19.73 m2</b>							
No Asbestos							
<b>B00A - R0010 - Secure Storeroom - 18.51 m2</b>							
No Asbestos							
<b>B00A - R0011 - Deputy Principal Office - 17.06 m2</b>							
No Asbestos							
<b>B00A - R0012 - Interview/Office - Type 1 - 13.77 m2</b>							
No Asbestos							
<b>B00A - R0013 - Interview/Office - Type 1 - 13.54 m2</b>							
No Asbestos							
<b>B00A - R0015 - Principal Office - 20.01 m2</b>							
No Asbestos							
<b>B00A - R0016 - Distribution Board Cupboard - .97 m2</b>							
No Asbestos							<b>Note: No inspection of live electrical installation</b>
<b>B00A - R0018 - Cleaning Store - Distributed - 1.55 m2</b>							
No Asbestos							
<b>B00A - R0021 - Movement - 29.64 m2</b>							
No Asbestos							
<b>B00A - R0022 - Staff - Toilet - 2.09 m2</b>							
No Asbestos							
<b>B00A - R0023 - Toilet - Lobby - 2.04 m2</b>							
No Asbestos							
<b>B00A - R0024 - Staff - Toilet - 2.11 m2</b>							
No Asbestos							
<b>B00A - R0025 - Staff - Toilet - 2.15 m2</b>							
No Asbestos							
<b>B00A - R0026 - Toilet - Lobby - 1.98 m2</b>							
No Asbestos							
<b>B00A - R0027 - Toilet - Lobby - 2.02 m2</b>							
No Asbestos							
<b>B00A - R0028 - Interview/Meeting - 13.67 m2</b>							

Requires Inspection		
<b>B00A - R0029 - Interview/Meeting - 13.67 m2</b>		
Requires Inspection		
<b>B00A - R0030 - Staff Lounge - 15.89 m2</b>		
Requires Inspection		
<b>B00A - R0031 - Staff Kitchen - 4.65 m2</b>		
Requires Inspection		
<b>B00A - R0032 - External Movement - 3.16 m2</b>		
Requires Inspection		
<b>B00B - Pupil Facilities - 1986 - Brick/Veneer</b>		
<b>Exterior</b>		
Wall Cladding	Flat AC Sheeting	
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00B - R0001 - Student Canteen - 57.46 m2</b>		
Wall Linings Internal - Infill	Flat AC Sheeting	
<b>B00B - R0002 - General Storeroom - 7.02 m2</b>		
No Asbestos		
<b>B00B - R0003 - Cleaning Store - Distributed - 2.53 m2</b>		
No Asbestos		
<b>B00B - R0007 - External Movement - 327.48 m2</b>		
Requires Inspection		
<b>B00C - General Learning/Library - 1986 - Brick/Block</b>		
<b>Exterior</b>		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00C - R0009 - General Storeroom - 12.6 m2</b>		
No Asbestos		
<b>B00C - R0010 - Study Space - 14.72 m2</b>		
No Asbestos		
<b>B00C - R0012 - Distribution Board Cupboard - .97 m2</b>		
No Asbestos		
<b>B00C - R0013 - Cleaning Store - Distributed - 7.54 m2</b>		
No Asbestos		
<b>B00C - R0014 - General Learning Space - 47.01 m2</b>		
No Asbestos		
<b>B00C - R0015 - General Learning Space - 41.41 m2</b>		
No Asbestos		
<b>B00C - R0016 - General Learning Space - 46.78 m2</b>		
No Asbestos		
<b>B00C - R0017 - General Learning Space - 46.9 m2</b>		
No Asbestos		
<b>B00C - R0018 - General Storeroom - 17.56 m2</b>		
No Asbestos		
<b>B00C - R0019 - Distribution Board Cupboard - 1.03 m2</b>		
No Asbestos		
<b>B00C - R0020 - Toilets-Disabled - 3.2 m2</b>		
No Asbestos		
<b>B00C - R0021 - Tiered Learning Area - 67.57 m2</b>		

No Asbestos	
<b>B00C - R0022 - Staff Study - 14.84 m2</b>	
No Asbestos	
<b>B00C - R0023 - Interview/Office - Type 1 - 12.7 m2</b>	
No Asbestos	
<b>B00C - R0025 - General Learning Space - 46.89 m2</b>	
No Asbestos	
<b>B00C - R0026 - General Learning Space - 46.77 m2</b>	
No Asbestos	
<b>B00C - R0027 - General Learning Space - 41.55 m2</b>	
No Asbestos	
<b>B00C - R0028 - General Learning Space - 46.77 m2</b>	
No Asbestos	
<b>B00C - R0031 - Performing Arts Store - 17.53 m2</b>	
No Asbestos	
<b>B00C - R0032 - Distribution Board Cupboard - .81 m2</b>	<b>Note: No inspection of live electrical installation</b>
No Asbestos	
<b>B00C - R0033 - Cleaning Store - Distributed - 7.32 m2</b>	
No Asbestos	
<b>B00C - R0034 - Machine Storage - 14.36 m2</b>	
No Asbestos	
<b>B00C - R0035 - Distribution Board Cupboard - .98 m2</b>	<b>Note: No inspection of live electrical installation</b>
No Asbestos	
<b>B00C - R0036 - General Learning Space - 45.76 m2</b>	
No Asbestos	
<b>B00C - R0037 - General Learning Space - 41.35 m2</b>	
No Asbestos	
<b>B00C - R0038 - Staff Study - 14.88 m2</b>	
No Asbestos	
<b>B00C - R0039 - Study Space - 12.71 m2</b>	
No Asbestos	
<b>B00C - R0040 - General Learning Space - 46.78 m2</b>	
No Asbestos	
<b>B00C - R0041 - General Learning Space - 46.78 m2</b>	
No Asbestos	
<b>B00C - R0042 - Toilets-Girls - 11.48 m2</b>	
No Asbestos	
<b>B00C - R0043 - Toilets-Boys - 11.46 m2</b>	
No Asbestos	
<b>B00C - R0044 - Resources Store - 22.98 m2</b>	
No Asbestos	
<b>B00C - R0045 - General Learning Space - 39.46 m2</b>	
No Asbestos	
<b>B00C - R0048 - Cleaning Store - Distributed - 3.98 m2</b>	
No Asbestos	
<b>B00C - R0049 - Audio Visual Workroom - 7.77 m2</b>	
No Asbestos	
<b>B00C - R0050 - Seminar - 26.9 m2</b>	
No Asbestos	
<b>B00C - R0051 - Main Area - 384.27 m2</b>	
No Asbestos	

<b>B00C - R0052 - Seminar - 12.04 m2</b>									
No Asbestos									
<b>B00C - R0053 - Seminar - 22.88 m2</b>									
No Asbestos									
<b>B00C - R0055 - Movement - 84.64 m2</b>									
No Asbestos									
<b>B00C - R0056 - General Learning Space - 47.11 m2</b>									
No Asbestos									
<b>B00C - R0057 - General Learning Space - 47.28 m2</b>									
No Asbestos									
<b>B00C - R0058 - General Learning Space - 47.12 m2</b>									
No Asbestos									
<b>B00C - R0059 - Study Space - 15.16 m2</b>									
No Asbestos									
<b>B00C - R0060 - Distribution Board Cupboard - .8 m2</b>									
									<b>Note: No inspection of live electrical installation</b>
No Asbestos									
<b>B00C - R0061 - Security Store - 17.83 m2</b>									
No Asbestos									
<b>B00C - R0062 - Cleaning Store - Distributed - 5.05 m2</b>									
No Asbestos									
<b>B00C - R0063 - Careers Advisers Office - 27.69 m2</b>									
Requires Inspection									
<b>B00C - R0064 - Stairs - 6.68 m2</b>									
Requires Inspection									
<b>B00C - R0065 - Stairs - 6.92 m2</b>									
Requires Inspection									
<b>B00C - R0066 - Movement - 393.62 m2</b>									
Requires Inspection									
<b>B00C - R0067 - Stairs - 6.46 m2</b>									
Requires Inspection									
<b>B00C - R0069 - Stairs - 18.98 m2</b>									
Requires Inspection									
<b>B00C - R0070 - Stairs - 6.94 m2</b>									
Requires Inspection									
<b>B00C - R0071 - Staff Study - 36.58 m2</b>									
Requires Inspection									
<b>B00C - R0072 - Staff Kitchen - 8.21 m2</b>									
Requires Inspection									
<b>B00C - R0073 - Store - 8.17 m2</b>									
Requires Inspection									
<b>B00C - R0074 - Preparation/Printing - 10.99 m2</b>									
Requires Inspection									
<b>B00C - R0075 - Preparation/Printing - 11.46 m2</b>									
Requires Inspection									
<b>B00C - R0076 - Outdoor Learning Area - 18.28 m2</b>									
Requires Inspection									
<b>B00C - R0077 - General Learning Space - 63.79 m2</b>									
Requires Inspection									
<b>B00C - R0078 - Bulk Store - 16.85 m2</b>									
Requires Inspection									
<b>B00C - R0079 - Other - 12.24 m2</b>									
Requires Inspection									

<b>B00C - R0080 - Practical Activities - 19.96 m2</b>								
Requires Inspection								
<b>B00C - R0081 - Outdoor Learning Area - 22.37 m2</b>								
Requires Inspection								
<b>B00C - R0082 - General Learning Space - 62.61 m2</b>								
Requires Inspection								
<b>B00C - R0083 - Toilets-Disabled - 7.06 m2</b>								
Requires Inspection								
<b>B00C - R0084 - Toilets-Boys - 2.41 m2</b>								
Requires Inspection								
<b>B00C - R0085 - Toilets-Girls - 3.27 m2</b>								
Requires Inspection								
<b>B00C - R0086 - Laundry - 19.71 m2</b>								
Requires Inspection								
<b>B00C - R0087 - Store - 8.24 m2</b>								
Requires Inspection								
<b>B00C - R0088 - Bulk Store - 15.28 m2</b>								
Requires Inspection								
<b>B00C - R0089 - External Movement - 7.6 m2</b>								
Requires Inspection								
<b>B00C - R0090 - Shared Learning Space - 46.62 m2</b>								
Requires Inspection								
<b>B00C - R0091 - Outdoor Learning Area - 24.05 m2</b>								
Requires Inspection								
<b>B00C - R0092 - Movement - 343.85 m2</b>								
Requires Inspection								
<b>B00C - R1002 - Cleaning Store - Distributed - 2.59 m2</b>								
No Asbestos								
<b>B00C - R1004 - Movement - 154.92 m2</b>								
No Asbestos								
<b>B00C - R1005 - Toilets-Boys - 11.44 m2</b>								
No Asbestos								
<b>B00C - R1006 - Toilets-Girls - 11.44 m2</b>								
No Asbestos								
<b>B00C - R1007 - General Learning Space - 46.66 m2</b>								
No Asbestos								
<b>B00C - R1008 - General Learning Space - 46.51 m2</b>								
No Asbestos								
<b>B00C - R1009 - General Learning Space - 41.56 m2</b>								
No Asbestos								
<b>B00C - R1010 - Computer Resource - 12.71 m2</b>								
No Asbestos								
<b>B00C - R1011 - Staff Study - 14.84 m2</b>								
No Asbestos								
<b>B00C - R1012 - General Learning Space - 45.65 m2</b>								
No Asbestos								
<b>B00C - R1013 - Distribution Board Cupboard - .99 m2</b>								<b>Note: No inspection of live electrical installation</b>
No Asbestos								
<b>B00C - R1016 - Performance Workspace - 74.48 m2</b>								
No Asbestos								
<b>B00C - R1017 - Senior Study - 27.57 m2</b>								
No Asbestos								

<b>B00C - R1018 - Movement - 150.72 m2</b>			
No Asbestos			
<b>B00C - R1019 - Commonroom - 121.09 m2</b>			
No Asbestos			
<b>B00C - R1022 - Distribution Board Cupboard - .94 m2</b>			<b>Note: No inspection of live electrical installation</b>
No Asbestos			
<b>B00C - R1023 - General Learning Space - 45.68 m2</b>			
No Asbestos			
<b>B00C - R1024 - General Learning Space - 41.34 m2</b>			
No Asbestos			
<b>B00C - R1025 - Seminar - 12.6 m2</b>			
No Asbestos			
<b>B00C - R1026 - Resources - 14.72 m2</b>			
No Asbestos			
<b>B00C - R1027 - General Learning Space - 41.35 m2</b>			
No Asbestos			
<b>B00C - R1029 - Toilets-Boys - 11.64 m2</b>			
No Asbestos			
<b>B00C - R1030 - Toilets-Girls - 11.74 m2</b>			
No Asbestos			
<b>B00C - R1032 - Cleaning Store - Distributed - 2.89 m2</b>			
No Asbestos			
<b>B00C - R1034 - Movement - 53.53 m2</b>			
Ceiling Structures/Linings	Flat AC Sheeting		
<b>B00C - R1035 - General Learning Space - 47.12 m2</b>			
No Asbestos			
<b>B00C - R1036 - General Learning Space - 47.11 m2</b>			
No Asbestos			
<b>B00C - R1037 - General Learning Space - 47.11 m2</b>			
No Asbestos			
<b>B00C - R1038 - Distribution Board Cupboard - .84 m2</b>			<b>Note: No inspection of live electrical installation</b>
No Asbestos			
<b>B00C - R1039 - Staff Study - 38.93 m2</b>			
No Asbestos			
<b>B00C - R1040 - Staff - Toilet - 2.44 m2</b>			
No Asbestos			
<b>B00C - R1041 - Staff - Toilet - 2.64 m2</b>			
No Asbestos			
<b>B00C - R1042 - Toilet - Lobby - 3.48 m2</b>			
No Asbestos			
<b>B00C - R1043 - Toilet - Lobby - 3.77 m2</b>			
No Asbestos			
<b>B00C - R1044 - Staff - Toilet - 2.48 m2</b>			
No Asbestos			
<b>B00C - R1045 - Staff - Toilet - 2.57 m2</b>			
No Asbestos			
<b>B00C - R1046 - Toilet - Lobby - 3.53 m2</b>			
No Asbestos			
<b>B00C - R1047 - Toilet - Lobby - 3.66 m2</b>			
No Asbestos			
<b>B00C - R1048 - Staff Study - 38.72 m2</b>			
Requires Inspection			



<b>B00C - R1049 - Staff Kitchen - 4.35 m2</b>	
Requires Inspection	
<b>B00C - R1050 - Staff Study - 56.4 m2</b>	
Requires Inspection	
<b>B00C - R1051 - Staff Kitchen - 2.94 m2</b>	
Requires Inspection	
<b>B00C - R1052 - General Learning Space - 44.89 m2</b>	
Requires Inspection	
<b>B00C - R1053 - Practical Activities - 2.12 m2</b>	
Requires Inspection	
<b>B00C - R1054 - Staff Change - 6.94 m2</b>	
Requires Inspection	
<b>B00C - R1055 - Stairs - 6.46 m2</b>	
Requires Inspection	
<b>B00C - R1056 - Stairs - 6.68 m2</b>	
Requires Inspection	
<b>B00C - R1057 - Stairs - 6.92 m2</b>	
Requires Inspection	
<b>B00C - R1058 - Stairs - 18.98 m2</b>	
Requires Inspection	
<b>B00D - Technological &amp; Applied Studies/Art - 1986 - Brick/Block</b>	
<b>Exterior</b>	
Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found
<b>Interior</b>	
<b>B00D - R0001 - Movement - 56.81 m2</b>	
No Asbestos	
<b>B00D - R0002 - Toilets-Boys - 14.34 m2</b>	
No Asbestos	
<b>B00D - R0003 - Toilets-Girls - 14.34 m2</b>	
No Asbestos	
<b>B00D - R0004 - Materials Store - 31.37 m2</b>	
No Asbestos	
<b>B00D - R0005 - Materials Technology L.S. - 90.35 m2</b>	
No Asbestos	
<b>B00D - R0006 - Wood Technology Bay - 28.97 m2</b>	
No Asbestos	
<b>B00D - R0007 - Dust Extraction Space - 10.63 m2</b>	
No Asbestos	
<b>B00D - R0008 - Materials Technology L.S. - 89.01 m2</b>	
No Asbestos	
<b>B00D - R0009 - Metal Technology Bay - 71.29 m2</b>	
No Asbestos	
<b>B00D - R0010 - Welding Area - 2.97 m2</b>	
No Asbestos	
<b>B00D - R0011 - Materials Technology L.S. - 89.08 m2</b>	
No Asbestos	
<b>B00D - R0012 - Metal Technology Bay - 31.89 m2</b>	
No Asbestos	
<b>B00D - R0013 - Materials Technology L.S. - 90.44 m2</b>	
No Asbestos	

<b>B00D - R0014 - Materials Store - 13.67 m2</b>							
No Asbestos							
<b>B00D - R0015 - Staff Study - 28.12 m2</b>							
No Asbestos							
<b>B00D - R0016 - Resources Store - 17.1 m2</b>							
No Asbestos							
<b>B00D - R0017 - Staff Study - 24.32 m2</b>							
No Asbestos							
<b>B00D - R0018 - Seminar - 28.66 m2</b>							
No Asbestos							
<b>B00D - R0019 - Design L.S. - 58.29 m2</b>							
No Asbestos							
<b>B00D - R0020 - Design L.S. - 58.02 m2</b>							
No Asbestos							
<b>B00D - R0022 - Art Learning Space - 58.14 m2</b>							
No Asbestos							
<b>B00D - R0023 - Kiln Space - 62.46 m2</b>							
No Asbestos							
<b>B00D - R0024 - Art Learning Space - 58.15 m2</b>							
No Asbestos							
<b>B00D - R0025 - Cleaning Store - Distributed - 2.83 m2</b>							
No Asbestos							
<b>B00D - R0026 - Art Learning Space - 58.14 m2</b>							
No Asbestos							
<b>B00D - R0027 - Art Learning Space - 58.15 m2</b>							
No Asbestos							
<b>B00D - R0028 - Resources Space - 23.16 m2</b>							
No Asbestos							
<b>B00D - R0029 - Distribution Board Cupboard - 1.48 m2</b>						<b>Note: No inspection of live electrical installation</b>	
No Asbestos							
<b>B00D - R0030 - L.P.G. Store - 1.31 m2</b>							
No Asbestos							
<b>B00D - R0031 - Distribution Board Cupboard - 1.12 m2</b>						<b>Note: No inspection of live electrical installation</b>	
No Asbestos							
<b>B00D - R0032 - General Storeroom - 5.17 m2</b>							
No Asbestos							
<b>B00D - R0035 - Movement - 140.16 m2</b>							
No Asbestos							
<b>B00D - R0036 - Materials Technology L.S. - 98.64 m2</b>							
No Asbestos							
<b>B00D - R0037 - General Storeroom - 16.34 m2</b>							
No Asbestos							
<b>B00D - R0038 - General Storeroom - 1.59 m2</b>							
No Asbestos							
<b>B00D - R0039 - General Storeroom - 12.61 m2</b>							
No Asbestos							
<b>B00D - R0040 - Movement - 291.43 m2</b>							
Requires Inspection							
<b>B00D - R0041 - Store - 23.52 m2</b>							
Requires Inspection							
<b>B00F - Science/Music - 1986 - Brick/Block</b>							

<b>Exterior</b>			
Ceiling Voids	No Asbestos Found		
Underfloor Voids	No Asbestos Found		
<b>Interior</b>			
<b>B00F - R0001 - Laboratory L.S. - 79.62 m2</b>			
No Asbestos			
<b>B00F - R0002 - Preparation - 34.6 m2</b>			
No Asbestos			
<b>B00F - R0003 - Movement - 170.24 m2</b>			
No Asbestos			
<b>B00F - R0004 - Cleaning Store - Distributed - 1.66 m2</b>			
No Asbestos			
<b>B00F - R0005 - Distribution Board Cupboard - 1.56 m2</b>			
No Asbestos			<b>Note: No inspection of live electrical installation</b>
<b>B00F - R0006 - Laboratory L.S. - 79.61 m2</b>			
No Asbestos			
<b>B00F - R0007 - Laboratory L.S. - 80.51 m2</b>			
No Asbestos			
<b>B00F - R0008 - Movement - 44.32 m2</b>			
No Asbestos			
<b>B00F - R0011 - Chemical Store - 12.07 m2</b>			
No Asbestos			
<b>B00F - R0013 - Apparatus Store - 46.85 m2</b>			
No Asbestos			
<b>B00F - R0014 - Growing/Breeding - 8.08 m2</b>			
No Asbestos			
<b>B00F - R0015 - Movement - 6.67 m2</b>			
No Asbestos			
<b>B00F - R0016 - Laboratory L.S. - 79.8 m2</b>			
No Asbestos			
<b>B00F - R0017 - Laboratory L.S. - 79.79 m2</b>			
No Asbestos			
<b>B00F - R0018 - Preparation - 31.39 m2</b>			
No Asbestos			
<b>B00F - R0019 - Laboratory L.S. - 79.78 m2</b>			
No Asbestos			
<b>B00F - R0020 - Preparation - 46.4 m2</b>			
No Asbestos			
<b>B00F - R0021 - Staff Study - 16.11 m2</b>			
No Asbestos			
<b>B00F - R0022 - Movement - 107.09 m2</b>			
No Asbestos			
<b>B00F - R0023 - Staff Study - 32.11 m2</b>			
Requires Inspection			
<b>B00F - R0024 - Staff Kitchen - 8.8 m2</b>			
Requires Inspection			
<b>B00F - R0025 - External Movement - 33.57 m2</b>			
Requires Inspection			
<b>B00F - R0026 - Store - 5.37 m2</b>			
Requires Inspection			
<b>B00F - R0027 - Stairs - 13.92 m2</b>			

Requires Inspection							
<b>B00F - R0028 - Store - 5.25 m2</b>							
Requires Inspection							
<b>B00F - R0029 - Stairs - 15.2 m2</b>							
Requires Inspection							
<b>B00F - R1002 - Cleaning Store - Distributed - 2.75 m2</b>							
No Asbestos							
<b>B00F - R1003 - Staff Study - 14.93 m2</b>							
No Asbestos							
<b>B00F - R1004 - Music Store - 21.53 m2</b>							
No Asbestos							
<b>B00F - R1005 - Distribution Board Cupboard - 1.68 m2</b>							
Note: No inspection of live electrical installation							
No Asbestos							
<b>B00F - R1006 - Music Learning Space - 61.69 m2</b>							
No Asbestos							
<b>B00F - R1007 - Practice/Seminar - 25.56 m2</b>							
No Asbestos							
<b>B00F - R1008 - Music Learning Space - 76.23 m2</b>							
No Asbestos							
<b>B00F - R1009 - Practice/Seminar - 32.58 m2</b>							
No Asbestos							
<b>B00F - R1010 - Movement - 8.14 m2</b>							
Requires Inspection							
<b>B00F - R1011 - Stairs - 21.58 m2</b>							
Requires Inspection							
<b>B00F - R1012 - Movement - 73.83 m2</b>							
Requires Inspection							
<b>B00F - R1013 - Movement - 8.08 m2</b>							
Requires Inspection							
<b>B00F - R1014 - Stairs - 21.35 m2</b>							
Requires Inspection							
<b>B00G - Technological &amp; Applied Studies - 1986 - Brick/Block</b>							
<b>Exterior</b>							
Wall Cladding	Flat AC Sheeting						
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00G - R0001 - Movement - 127.3 m2</b>							
No Asbestos							
<b>B00G - R0002 - Main Switchroom - 17.88 m2</b>							
No Asbestos							
<b>B00G - R0003 - Staff - Toilet - 6.37 m2</b>							
No Asbestos							
<b>B00G - R0004 - Staff - Toilet - 6.37 m2</b>							
No Asbestos							
<b>B00G - R0005 - Materials Technology L.S. - 69.06 m2</b>							
No Asbestos							
<b>B00G - R0006 - Materials Technology L.S. - 69.06 m2</b>							
No Asbestos							
<b>B00G - R0007 - Laundry - 18.58 m2</b>							
No Asbestos							

<b>B00G - R0008 - Staff Study - 30.26 m2</b>		
No Asbestos		
<b>B00G - R0009 - Food Technology L.S. - 104.66 m2</b>		
No Asbestos		
<b>B00G - R0010 - Preparation - Materials - 28.22 m2</b>		
No Asbestos		
<b>B00G - R0011 - Food Technology L.S. - 104.66 m2</b>		
No Asbestos		
<b>B00H - Physical Education/Various - 1986 - Brick/Block</b>		
<b>Exterior</b>		
Wall Cladding	Flat AC Sheeting	
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00H - R0001 - Maintenance Bulk Store - 16.53 m2</b>		
No Asbestos		
<b>B00H - R0002 - Toilets-Disabled - 5.91 m2</b>		
No Asbestos		
<b>B00H - R0003 - General Storeroom - 6.41 m2</b>		
No Asbestos		
<b>B00H - R0004 - General Assistants - 13.17 m2</b>		
No Asbestos		
<b>B00H - R0005 - Movement - 112.78 m2</b>		
No Asbestos		
<b>B00H - R0006 - Cleaning Supplies Store - 17.98 m2</b>		
No Asbestos		
<b>B00H - R0007 - Staff Study - 27.92 m2</b>		
No Asbestos		
<b>B00H - R0008 - Movement - 5.81 m2</b>		
No Asbestos		
<b>B00H - R0009 - Toilets-Boys - 24.46 m2</b>		
No Asbestos		
<b>B00H - R0010 - Toilets-Girls - 24.53 m2</b>		
No Asbestos		
<b>B00H - R0011 - Movement - 5.76 m2</b>		
No Asbestos		
<b>B00H - R0012 - Sport Equipment Store - 24.47 m2</b>		
No Asbestos		
<b>B00H - R0013 - Movement - 3.69 m2</b>		
No Asbestos		
<b>B00H - R0014 - Movement - 25.93 m2</b>		
No Asbestos		
<b>B00H - R0015 - Shower/Change - 56.8 m2</b>		
No Asbestos		
<b>B00H - R0016 - Movement - 28.66 m2</b>		
No Asbestos		
<b>B00H - R0017 - Shower/Change - 56.89 m2</b>		
No Asbestos		
<b>B00H - R0018 - Movement - 3.67 m2</b>		
No Asbestos		
<b>B00H - R0019 - Stage - 98.98 m2</b>		

No Asbestos		
<b>B00H - R0020 - Staff Shower - 6.46 m2</b>		
No Asbestos		
<b>B00H - R0021 - Staff Study - 17.63 m2</b>		
No Asbestos		
<b>B00H - R0022 - Multi-Purpose Space - 494.73 m2</b>		
No Asbestos		
<b>B00H - R0023 - Movement - 5.66 m2</b>		
No Asbestos		
<b>B00H - R0024 - Sport Equipment Store - 38.31 m2</b>		
No Asbestos		
<b>B00H - R0025 - Cleaning Store - Distributed - 2.95 m2</b>		
No Asbestos		
<b>B00H - R0026 - Distribution Board Cupboard - 2.9 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00H - R0027 - Chair Store - 24.54 m2</b>		
No Asbestos		
<b>B00J - Senior Learning - 1997 - Brick/Veneer</b>		
<b>Exterior</b>		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00J - R0001 - General Learning Space - 56.1 m2</b>		
No Asbestos		
<b>B00J - R0002 - Main Switchroom - 1.88 m2</b>		
No Asbestos		
<b>B00J - R0003 - General Learning Space - 56.03 m2</b>		
No Asbestos		
<b>B00J - R0004 - General Learning Space - 56.43 m2</b>		
No Asbestos		
<b>B00J - R0005 - Communications Cupboard - .83 m2</b>		
No Asbestos		
<b>B00J - R0006 - General Learning Space - 56.77 m2</b>		
No Asbestos		
<b>B00J - R0007 - General Learning Space - 56.62 m2</b>		
No Asbestos		
<b>B00J - R0008 - Distribution Board Cupboard - .85 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00J - R0009 - Toilets-Girls - 26.91 m2</b>		
No Asbestos		
<b>B00J - R0010 - Toilets-Disabled - 4.9 m2</b>		
No Asbestos		
<b>B00J - R0011 - Toilets-Boys - 21.48 m2</b>		
No Asbestos		
<b>B00J - R0012 - Study Space - 13.64 m2</b>		
No Asbestos		
<b>B00J - R0013 - Secure Storeroom - 17.96 m2</b>		

No Asbestos		
<b>B00J - R0014 - Distribution Board Cupboard - .91 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00J - R0015 - Preparation - 30.9 m2</b>		
No Asbestos		
<b>B00J - R0016 - General Storeroom - 8.97 m2</b>		
Wall Linings Internal	Flat AC Sheeting	
<b>B00J - R0017 - Laboratory L.S. - 112.41 m2</b>		
No Asbestos		
<b>B00J - R0018 - Movement - 158.04 m2</b>		
No Asbestos		
<b>B00J - R0019 - Movement - 10.22 m2</b>		
No Asbestos		
<b>B00J - R0020 - L.P.G Store - 3.16 m2</b>		
No Asbestos		
<b>B00J - R0021 - Plant - 13.31 m2</b>		
No Asbestos		
<b>B00J - R0022 - Cleaning Store - Distributed - 3.82 m2</b>		
No Asbestos		
<b>B00J - R0023 - Stairs - 6.07 m2</b>		
No Asbestos		
<b>B00J - R0024 - Stairs - 13.36 m2</b>		
No Asbestos		
<b>B00J - R1001 - General Learning Space - 56.71 m2</b>		
No Asbestos		
<b>B00J - R1002 - Distribution Board Cupboard - .68 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00J - R1003 - General Learning Space - 56.14 m2</b>		
No Asbestos		
<b>B00J - R1004 - General Learning Space - 56 m2</b>		
No Asbestos		
<b>B00J - R1005 - Communications Cupboard - .71 m2</b>		
No Asbestos		
<b>B00J - R1006 - General Learning Space - 56.08 m2</b>		
No Asbestos		
<b>B00J - R1007 - General Learning Space - 55.99 m2</b>		
No Asbestos		
<b>B00J - R1008 - Distribution Board Cupboard - .7 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00J - R1009 - Computer Learning Space - 56.85 m2</b>		
No Asbestos		
<b>B00J - R1010 - Security Store - 18.69 m2</b>		
No Asbestos		
<b>B00J - R1011 - Cleaning Store - Distributed - 3.94 m2</b>		
No Asbestos		
<b>B00J - R1012 - Study Space - 14.37 m2</b>		
No Asbestos		
<b>B00J - R1013 - Staff Study - 119.62 m2</b>		
No Asbestos		
<b>B00J - R1014 - Staff - Toilet - 12.25 m2</b>		
No Asbestos		
<b>B00J - R1015 - Distribution Board Cupboard - .84 m2</b>		<b>Note: No inspection of live electrical installation</b>

No Asbestos		
<b>B00J - R1016 - Staff Study - 12.96 m2</b>		
No Asbestos		
<b>B00J - R1017 - Staff Study - 13.89 m2</b>		
No Asbestos		
<b>B00J - R1018 - Movement - 132.4 m2</b>		
Wall Linings Internal	Flat AC Sheeting	
Ceiling Structures/Linings	Flat AC Sheeting	
<b>B00J - R1019 - Movement - 16.72 m2</b>		
Ceiling Structures/Linings	Flat AC Sheeting	
<b>B00J - R1020 - Movement - 8.64 m2</b>		
No Asbestos		
<b>B00J - R1021 - Stairs - 13.36 m2</b>		
No Asbestos		
<b>B00J - R1022 - Stairs - 20.34 m2</b>		
No Asbestos		
<b>B00K - General Learning/Technological - 2016 - Steel</b>		
<b>Exterior</b>		
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00K - R0001 - Growing/Breeding - 35.92 m2</b>		
No Asbestos		
<b>B00K - R0002 - Toilets-Unisex - 7.19 m2</b>		
No Asbestos		
<b>B00K - R0003 - External Movement - 53.47 m2</b>		
No Asbestos		
<b>B00K - R0004 - Seminar - Type 1 - 57.68 m2</b>		
No Asbestos		
<b>B00K - R0005 - Growing/Breeding - 57.37 m2</b>		
No Asbestos		
<b>B00K - R0006 - External Movement - 26.08 m2</b>		
No Asbestos		
<b>B00L - Agricultural Science - 2015 - Greenhouse</b>		
<b>Exterior</b>		
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00L - R0001 - Plant Space - 18.59 m2</b>		
No Asbestos		
<b>B00M - Storage - 2010 - Metal Shed</b>		
<b>Exterior</b>		
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	



<b>Interior</b>		
<b>B00M - R0001 - General Storeroom - 18.34 m2</b>		
No Asbestos		
<b>B00N - Storage - 2010 - Metal Shed</b>		
<b>Exterior</b>		
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00N - R0001 - Store - 46.74 m2</b>		
No Asbestos		
<b>B0AG - Agricultural Science - 1986 - Brick/Block</b>		
<b>Exterior</b>		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
<b>Interior</b>		
<b>B0AG - R0001 - Growing/Breeding - 12.35 m2</b>		
No Asbestos		
<b>B0AG - R0002 - Animal Space - 23.47 m2</b>		
No Asbestos		
<b>B0AG - R0003 - Movement - 61.21 m2</b>		
No Asbestos		
<b>B0AG - R0004 - Class Tools Storage - 6.18 m2</b>		
No Asbestos		
<b>B0AG - R0005 - Machine Storage - 37.01 m2</b>		
No Asbestos		
<b>B0DS - Performing Arts - 1997 - Brick/Veneer</b>		
<b>Exterior</b>		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B0DS - R0001 - Performance Workspace - 196.22 m2</b>		
No Asbestos		
<b>B0DS - R0002 - Movement - 5.93 m2</b>		
No Asbestos		
<b>B0DS - R0003 - General Storeroom - 9.98 m2</b>		
No Asbestos		
<b>B0DS - R0004 - Staff Study - 4.62 m2</b>		
No Asbestos		
<b>B0DS - R0005 - Staff - Toilet - 2.11 m2</b>		
No Asbestos		

**Demountables**

**OS 830 10772 - Boys Shower/Change/Toilet - Placement Date : 06-OCT-2010**

No Asbestos Found

**OS 831 15308 - Girls Shower/Change/Toilet - Placement Date : 06-OCT-2010**

No Asbestos Found