

Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Lindsay Park Public School (4042)
Region:	Southern NSW AMU
State Electorate:	Keira
Local Government Area:	Wollongong

Last Reviewed By:	AECOM 18-JUN-2015
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	No
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00B - General Learning - 1975 - Brick/Veneer							
Exterior							
Eaves Linings	Flat AC Sheeting	40m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	50m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	Non Accessible Area						
Interior							
B00B - R0001 - Home Base - 56.03 m2							
No Asbestos							
B00B - R0002 - Home Base Store - 4.84 m2							
No Asbestos							
B00B - R0003 - Personal Effects Storage - 10.52 m2							
No Asbestos							
B00B - R0004 - Movement - 5.61 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00B - R0005 - Home Base - 56.02 m2							
No Asbestos							
B00B - R0006 - Home Base Store - 5.14 m2							
No Asbestos							
B00B - R0007 - Personal Effects Storage - 5.98 m2							
Floor Coverings Res/Textile	Vinyl Tiles	2m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0008 - Movement - 13.93 m2							
No Asbestos							
B00B - R0009 - General Storeroom - 6.95 m2							
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0010 - General Storeroom - 14.35 m2							
No Asbestos							
B00B - R0011 - Distribution Board - .44 m2							
						Note: No inspection of live electrical installation	
Wall Linings Internal	Flat AC Sheeting	7m2	South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00B - R0012 - Movement - 10.47 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00B - R0013 - Personal Effects Storage - 8.96 m2							
No Asbestos							
B00B - R0014 - Home Base - 56.41 m2							
No Asbestos							
B00B - R0015 - Home Base Store - 4.09 m2							
No Asbestos							
B00B - R0016 - Home Base - 55.93 m2							
No Asbestos							

B00B - R0017 - Home Base Store - 4 m2							
No Asbestos							
B00B - R0018 - Personal Effects Storage - 19.41 m2							
No Asbestos							
B00B - R0019 - Movement - 10.61 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00B - R0020 - Home Base - 56.55 m2							
No Asbestos							
B00B - R0021 - Home Base Store - 4.04 m2							
No Asbestos							
B00C - General Learning/Staff Facilities - 1975 - Timber							
Exterior							
Eaves Linings	Flat AC Sheeting	55m2	South, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Gable Verge Lining	Flat AC Sheeting	16m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Wall Linings Internal	Flat AC Sheeting						
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00C - R0001 - Deputy Principal - 17.39 m2							
No Asbestos							
B00C - R0002 - General Storeroom - 2.51 m2							
No Asbestos							
B00C - R0003 - Main Switch Board - .73 m2							
Wall Linings Internal	Flat AC Sheeting	5m2	North, South, East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0004 - Staff Room Annexe - 10.81 m2							
Wall Linings Internal	Flat AC Sheeting	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0005 - Movement - 2.46 m2							
Wall Linings Internal	Flat AC Sheeting						
Ceiling Structures/Linings	Flat AC Sheeting						
B00C - R0006 - Withdrawal Space - 1hb - 6.38 m2							
Wall Linings Internal	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0007 - Movement - 3.46 m2							
No Asbestos							
B00C - R0008 - Personal Effects Storage - 6.4 m2							
Wall Linings Internal	Flat AC Sheeting	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0009 - Home Base - 65.43 m2							

Wall Linings Internal	Flat AC Sheeting	48m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0010 - Home Base Store - 5.62 m2							
No Asbestos							
B00C - R0011 - Home Base - 90.79 m2							
No Asbestos							
B00C - R0012 - Home Base Store - 5.72 m2							
No Asbestos							
B00C - R0013 - Movement - 12.37 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00C - R0014 - Staff Toilet - 1.64 m2							
No Asbestos							
B00C - R0015 - Personal Effects Storage - 6.38 m2							
No Asbestos							
B00C - R0016 - Personal Effects Storage - 6.39 m2							
No Asbestos							
B00C - R0017 - Home Base - 65.62 m2							
No Asbestos							
B00C - R0018 - Home Base Store - 5.64 m2							
No Asbestos							
B00C - R0019 - Home Base - 65.54 m2							
No Asbestos							
B00C - R0021 - Staff Toilet - 5.56 m2							
Wall Linings Internal	Flat AC Sheeting						
B00C - R0022 - Movement - 1.98 m2							
Wall Linings Internal	Flat AC Sheeting						
Ceiling Structures/Linings	Flat AC Sheeting						
B00C - R0025 - Covered Outdoor Learning Area - 244.67 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00C - R0026 - Staff Room Annexe - 22.46 m2							
No Asbestos							
B00C - R0027 - Staff Kitchen - 10.59 m2							
No Asbestos							
B00C - R0028 - Staff Room - 31.27 m2							
No Asbestos							
B00D - Administration - 1975 - Timber							
Exterior							
Eaves Linings	Flat AC Sheeting	62m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Underfloor Voids	Non Accessible Area						
Ceiling Voids	No Asbestos Found						
Interior							
B00D - R0001 - Interview/Office - Type 1 - 20.35 m2							
No Asbestos							
B00D - R0002 - Principal - 19.8 m2							

No Asbestos							
B00D - R0003 - Movement - 7.1 m2							
No Asbestos							
B00D - R0004 - Cleaning Distributed Store - 2.85 m2							
No Asbestos							
B00D - R0005 - Staff Toilet - 5.36 m2							
Wall Linings Internal	Flat AC Sheeting						
B00D - R0006 - Entry Vestibule - 20.68 m2							
No Asbestos							
B00D - R0007 - General Storeroom - 13.59 m2							
No Asbestos							
B00D - R0008 - Sick Bay - 8.73 m2							
No Asbestos							
B00D - R0009 - Sick Bay - Shower/Toilet - 3.35 m2							
No Asbestos							
B00D - R0010 - Movement - 6.61 m2							
No Asbestos							
B00D - R0011 - Duplicating Workroom - 30.92 m2							
No Asbestos							
B00D - R0012 - Clerical Office - 26.28 m2							
No Asbestos							
B00D - R0014 - Practical Activities - 28.81 m2							
No Asbestos							
B00D - R0015 - External Movement - 28.7 m2							
No Asbestos							
B00G - Pupil Facilities/Building Services - 1975 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	24m2	North, South, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids - Flat Roof	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Interior							
B00G - R0001 - Cleaning Supplies - 5.26 m2							
Wall Linings Internal	Flat AC Sheeting	6m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G - R0002 - Movement - 18.89 m2							
No Asbestos							
B00G - R0003 - Canteen - 27.37 m2							
Wall Linings Internal	Flat AC Sheeting	4m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G - R0004 - Canteen Office/Store - 5.63 m2							
Wall Linings Internal	Flat AC Sheeting	6m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G - R0006 - Garden Store - 11.91 m2							
Wall Linings Internal	Flat AC Sheeting	10m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G - R0007 - Cleaning Distributed Store - 1.82 m2							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G - R0008 - Cleaning Distributed Store - 1.82 m2							
Floor Coverings Res/Textile	Vinyl Tiles	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	3m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G - R0009 - External Movement - 9.24 m2							
No Asbestos							
B00H - General Learning - 1975 - Timber							
Exterior							
Wall Linings Internal - Infill	Flat AC Sheeting	8	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Cladding	Flat AC Sheeting	62m2	West, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	Non Accessible Area						
Interior							
B00H - R0001 - Sports Store - 15.45 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00H - R0002 - Home Base Store - 3.54 m2							
Wall Linings Internal	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00H - R0003 - Withdrawal Space - 1hb - 5.18 m2							
Wall Linings Internal	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles						

B00H - R0004 - Movement - 2.15 m2							
Wall Linings Internal	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles						
B00H - R0005 - Special Programs Room - 31.41 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00H - R0006 - Home Base - 46.92 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	South, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00H - R0007 - Practical Activities - 1hb - 12.8 m2							
Wall Linings Internal	Flat AC Sheeting	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles						
B00H - R0008 - Movement - 4.33 m2							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00I - Pupil Facilities/Building Services - 1975 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting						
Gable Verge Lining	Flat AC Sheeting	16m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Underfloor Voids - Slab on Ground	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
Interior							
B00I - R0002 - Staff Toilet - 1.3 m2							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00I - R0003 - Toilets - Boys - 35.56 m2							
Ceiling Structures/Linings	Flat AC Sheeting	36m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00I - R0004 - Cleaning Distributed Store - 1.25 m2							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00I - R0005 - Kiln Room - 5.52 m2							
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00I - R0006 - General Assistant/Bulk Store - 5.66 m2							

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00I - R0007 - Sports Store - 13.93 m2							
Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00I - R0008 - Toilets - Girls - 31.07 m2							
Ceiling Structures/Linings	Flat AC Sheeting	31m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00J - Library - 1981 - Brick/Veneer							
Exterior							
Ceiling Voids - Raked Ceiling	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Interior							
B00J - R0001 - Reading Area - 226.23 m2							
No Asbestos							
B00J - R0002 - Library Office/Workroom - 24.37 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00J - R0003 - Distribution Board - 1.6 m2							
						Note: No inspection of live electrical installation	
Wall Linings Internal	Flat AC Sheeting	8m2	South, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00J - R0004 - External Movement - 146.25 m2							
No Asbestos							
B00J - R0005 - Security Store - 12.83 m2							
No Asbestos							
B00K - Pupil Facilities/Building Services - 1975 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	14m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Gable Verge Lining	Flat AC Sheeting	50m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Interior							
B00K - R0001 - Toilets - Boys - 37.4 m2							
Partition Walls (Cubicles)	Compressed AC Sheet						
Ceiling Structures/Linings	Flat AC Sheeting	38m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Linings Internal	Flat AC Sheeting	2m2	East, West, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00K - R0002 - Staff Toilet - 1.5 m2							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00K - R0003 - General Assistant/Bulk Store - 26.53 m2							

Wall Linings Internal	Flat AC Sheeting	1m2	West, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00K - R0004 - Movement - 11.85 m2							
Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Linings Internal	Flat AC Sheeting	5m2	East, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00K - R0005 - Staff Toilet - 1.47 m2							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Linings Internal	Flat AC Sheeting	1m2	West, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00K - R0006 - Toilets - Girls - 33.85 m2							
Wall Linings Internal	Flat AC Sheeting	2m2	East, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	34m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00K - R0007 - Cleaning Distributed Store - 2.35 m2							
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Linings Internal	Flat AC Sheeting	1m2	West, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00K - R0008 - General Storeroom - 17.99 m2							
Ceiling Structures/Linings	Flat AC Sheeting	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00K - R0009 - General Storeroom - 3.79 m2							
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00K - R0010 - General Storeroom - 14.05 m2							
Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00K - R0011 - External Movement - 91.8 m2							
No Asbestos							
B00L - Building Services - 1975 - Brick/Veneer							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Interior							
B00L - R0001 - General Assistant/Bulk Store - 28.82 m2							
No Asbestos							
B00M - General Learning - 2006 - Brick/Veneer							
Exterior							

Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Interior		
B00M - R0001 - Deputy Principal - 14.96 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00M - R0002 - Home Base Store - 6.71 m2		
No Asbestos		
B00M - R0003 - Practical Activities - 1hb - 11.76 m2		
No Asbestos		
B00M - R0004 - Movement - 3.39 m2		
No Asbestos		
B00M - R0005 - Home Base - 59.34 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00M - R0006 - Home Base - 62.19 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00M - R0007 - Practical Activities - 1hb - 7.17 m2		
No Asbestos		
B00M - R0008 - Home Base Store - 6.33 m2		
No Asbestos		
B00M - R0009 - Sports Store - 11.62 m2		
No Asbestos		
B00M - R0010 - General Storeroom - 18.05 m2		
No Asbestos		
B00M - R0011 - Disabled Toilet - 5.8 m2		
No Asbestos		
B00M - R0012 - Distribution Board - .68 m2		
No Asbestos		Note: No inspection of live electrical installation
B00M - R0013 - Movement - 12.95 m2		
No Asbestos		
B00M - R0014 - Home Base - 62.3 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00M - R0015 - Home Base Store - 5.94 m2		
No Asbestos		
B00M - R0016 - Practical Activities - 1hb - 6.98 m2		
No Asbestos		
B00M - R0017 - Movement - 5.52 m2		
No Asbestos		
B00M - R0018 - Home Base - 71.38 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00M - R0019 - Communications Room - 7.9 m2		
No Asbestos		
B00M - R0020 - External Movement - 15.72 m2		
No Asbestos		
B00M - R0021 - External Movement - 40.48 m2		
No Asbestos		
B00M - R0022 - External Movement - 14.39 m2		
No Asbestos		

B00N - Communal Facilities - 2010 - Brick/Veneer

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00N - R0001 - Communal Space - 145.12 m2

No Asbestos

B00N - R0002 - Raised Platform - 61.07 m2

No Asbestos

B00N - R0003 - Hall Chair Store - 9.55 m2

No Asbestos

B00N - R0004 - Communal/Performance Store - 9.6 m2

No Asbestos

B00N - R0005 - P.E. Store - 13 m2

No Asbestos

B00N - R0006 - Toilet - Lobby - 2.37 m2

No Asbestos

B00N - R0007 - Toilets - Girls - 7.31 m2

No Asbestos

B00N - R0008 - Sound Cupboard - 2.06 m2

No Asbestos

B00N - R0009 - Toilet - Lobby - 3.31 m2

No Asbestos

B00N - R0010 - Toilets - Boys - 5.71 m2

No Asbestos

B00N - R0011 - Cleaning Distributed Store - 3.51 m2

No Asbestos

B00N - R0012 - General Storeroom - 1.6 m2

No Asbestos

B00N - R0013 - Main Switch Board - 3.23 m2

No Asbestos

B00N - R0014 - Access Shower/Toilet/Change - 6.87 m2

No Asbestos

B00N - R0015 - Covered Outdoor Learning Area - 151.4 m2

No Asbestos

B00N - R0016 - Movement - 6.17 m2

No Asbestos

B00N - R0017 - Movement - 11.96 m2

No Asbestos

B00N - R0018 - Ramp - 12.59 m2

No Asbestos

Demountables

OS 602 13428 - Learning Unit - Standard With P.A.A. - Placement Date : 04-NOV-2015

No Asbestos Found

OS 602 15230 - Learning Unit - Standard With P.A.A. - Placement Date : 01-DEC-2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found