

# Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Laguna Street Public School (4230)
Region:	Sydney AMU
State Electorate:	Cronulla
Local Government Area:	Sutherland

Last Reviewed By:	AECOM 29-OCT-2014
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	<b>Yes</b>
Please refer to the latest site specific Asbestos Management Plans available from the Department's website (Refer to Note 2).	



# Preface to Asbestos Register

## Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
  - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
  - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
  - o Any wall cavity
  - o Sub floor area, particularly formwork for slabs in/on ground,
  - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.  
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

## Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

## Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

### Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

### Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>  
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

### Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

#### 3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
<b>B00B - Communal Facilities/Administration - 1961 - Brick/Block</b>							
<b>Exterior</b>							
Eaves Linings	Flat AC Sheeting	50m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	20m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00B - R0001 - Communal Space - 164.59 m2</b>							
No Asbestos							
<b>B00B - R0002 - Raised Platform - 35.47 m2</b>							
No Asbestos							
<b>B00B - R0004 - General Storeroom - 9.02 m2</b>							
No Asbestos							
<b>B00B - R0005 - Movement - 5.39 m2</b>							
No Asbestos							
<b>B00B - R0007 - Staff Room - 41.61 m2</b>							
No Asbestos							
<b>B00B - R0008 - Staff Toilet - 3.85 m2</b>							
Plant / Equipment - Incinerator	Encapsulated Asbestos material within unit	1	East facing	Friable Asbestos (5)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Wall Linings Internal	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R0009 - Staff Toilet - 3.85 m2</b>							
Wall Linings Internal	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R0010 - Sick Bay - 7.87 m2</b>							
No Asbestos							
<b>B00B - R0011 - Interview - 14.28 m2</b>							
No Asbestos							
<b>B00B - R0012 - Deputy Principal - 14.28 m2</b>							
No Asbestos							
<b>B00B - R0013 - Main Switch Board - 2.12 m2</b>							
No Asbestos							
<b>B00B - R0014 - General Storeroom - 3.77 m2</b>							
No Asbestos							
<b>B00B - R0015 - General Storeroom - 1.06 m2</b>							
No Asbestos							
<b>B00B - R0016 - Movement - 32.62 m2</b>							
No Asbestos							
<b>B00B - R0017 - Movement - 10.53 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R0018 - Duplicating Workroom - 8.9 m2</b>							
No Asbestos							
<b>B00B - R0019 - Movement - 3.23 m2</b>							
No Asbestos							
<b>B00B - R0020 - Clerical Office/Workroom - 15.62 m2</b>							
No Asbestos							
<b>B00B - R0021 - Principal - 21.09 m2</b>							

No Asbestos							
<b>B00B - R0022 - Staff Toilet - 3.73 m2</b>							
No Asbestos							
<b>B00B - R0023 - General Storeroom - 1.84 m2</b>							
No Asbestos							
<b>B00B - R0024 - External Movement - 9.76 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R0025 - External Movement - 16.42 m2</b>							
Ceiling Structures/Linings	Compressed AC Sheet	16.4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R0026 - External Movement - 48.36 m2</b>							
Require Inspection							
<b>B00C - General Learning - 1961 - Brick/Block</b>							
<b>Exterior</b>							
Eaves Linings	Flat AC Sheeting	50m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	20m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00C - R0001 - Home Base - 58.07 m2</b>							
No Asbestos							
<b>B00C - R0002 - Home Base Store - 4.21 m2</b>							
No Asbestos							
<b>B00C - R0003 - Personal Effects Storage - 9.21 m2</b>							
No Asbestos							
<b>B00C - R0004 - Movement - 6.11 m2</b>							
No Asbestos							
<b>B00C - R0005 - Movement - 2.43 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00C - R0006 - Home Base - 57.25 m2</b>							
No Asbestos							
<b>B00C - R0007 - Home Base Store - 4.24 m2</b>							
No Asbestos							
<b>B00C - R0008 - Home Base - 57.09 m2</b>							
No Asbestos							
<b>B00C - R0009 - Home Base Store - 4.16 m2</b>							
No Asbestos							
<b>B00C - R0010 - Personal Effects Storage - 9.27 m2</b>							
No Asbestos							
<b>B00C - R0011 - Movement - 6.21 m2</b>							
No Asbestos							
<b>B00C - R0012 - Movement - 2.43 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00C - R0013 - Home Base - 58.22 m2</b>							
No Asbestos							
<b>B00C - R0014 - Home Base Store - 4.16 m2</b>							
No Asbestos							
<b>B00D - General Learning - 1961 - Brick/Block</b>							

Exterior							
Eaves Linings	Flat AC Sheeting	60m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	20m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	3	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00D - R0001 - Home Base - 57.77 m2							
No Asbestos							
B00D - R0002 - Movement - 4.65 m2							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00D - R0003 - Personal Effects Storage - 17.26 m2							
No Asbestos							
B00D - R0004 - Home Base Store - 5.12 m2							
No Asbestos							
B00D - R0005 - Home Base Store - 5.18 m2							
No Asbestos							
B00D - R0006 - Home Base - 57.7 m2							
No Asbestos							
B00D - R0007 - Home Base - 56.65 m2							
No Asbestos							
B00D - R0008 - Movement - 27.6 m2							
Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00D - R0009 - Personal Effects Storage - 14.62 m2							
No Asbestos							
B00D - R0010 - Home Base Store - 6.26 m2							
No Asbestos							
B00D - R0011 - Home Base Store - 6.22 m2							
No Asbestos							
B00D - R0012 - Home Base - 56.73 m2							
No Asbestos							
B00D - R0013 - Movement - 2.34 m2							
No Asbestos							
B00D - R0014 - Personal Effects Storage - 5.32 m2							
No Asbestos							
B00D - R0015 - Home Base Store - 5.63 m2							
No Asbestos							
B00D - R0016 - Home Base - 56.72 m2							
No Asbestos							
B00D - R9001 - Movement - 10.12 m2							
No Asbestos							
B00D - R9002 - Movement - 11.16 m2							
No Asbestos							
B00D - R9003 - Withdrawal Space - 1hb - 53.44 m2							
Ceiling Structures/Linings	Flat AC Sheeting	54m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00D - R9004 - Personal Effects Storage - 7.57 m2							
No Asbestos							

<b>B00D - R9005 - Home Base Store - 5.68 m2</b>							
No Asbestos							
<b>B00D - R9006 - Special Programs Room - 56.7 m2</b>							
No Asbestos							
<b>B00E - Pupil Facilities/Communal Facilities - 1961 - Brick/Block</b>							
<b>Exterior</b>							
Eaves Linings	Flat AC Sheeting	10m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids - Raked Ceiling	Non Accessible Area Ceiling						
Underfloor Voids - Slab on Ground	No Asbestos Found						
<b>Interior</b>							
<b>B00E - R0001 - Sports Store - 19.51 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00E - R0003 - Disabled Toilet - 12.65 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00E - R0004 - Toilets - Girls - 42.63 m2</b>							
Partition Walls (Cubicles)	Compressed AC Sheet	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	43m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Plant / Equipment - Incinerator	Encapsulated Asbestos material within unit	1	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
<b>B00F - General Learning - 1961 - Brick/Block</b>							
<b>Exterior</b>							
Wall Linings Internal - Infill	Flat AC Sheeting	18	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	20m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Eaves Linings	Flat AC Sheeting	40m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	4	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>Interior</b>							
<b>B00F - R0001 - Home Base - 57.07 m2</b>							
No Asbestos							
<b>B00F - R0002 - Home Base Store - 5.76 m2</b>							
No Asbestos							
<b>B00F - R0003 - Personal Effects Storage - 4.4 m2</b>							
No Asbestos							
<b>B00F - R0004 - Movement - 6.39 m2</b>							
No Asbestos							
<b>B00F - R0005 - Movement - 4.44 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00F - R0006 - General Storeroom - 10.53 m2</b>							
No Asbestos							
<b>B00F - R0007 - Home Base - 56.92 m2</b>							
No Asbestos							
<b>B00F - R0009 - Movement - 3.28 m2</b>							

No Asbestos							
<b>B00F - R0010 - Movement - 9.77 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00F - R0011 - Movement - 3.19 m2</b>							
No Asbestos							
<b>B00F - R0015 - Home Base - 56.62 m2</b>							
No Asbestos							
<b>B00F - R0017 - Movement - 3.03 m2</b>							
No Asbestos							
<b>B00F - R0018 - Movement - 14.2 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00F - R0019 - Personal Effects Storage - 5.18 m2</b>							
No Asbestos							
<b>B00F - R0020 - General Storeroom - 5.25 m2</b>							
No Asbestos							
<b>B00F - R0021 - General Storeroom - 5.37 m2</b>							
No Asbestos							
<b>B00F - R0022 - Personal Effects Storage - 5.4 m2</b>							
No Asbestos							
<b>B00F - R0023 - General Storeroom - 5.22 m2</b>							
No Asbestos							
<b>B00F - R0024 - Personal Effects Storage - 5.4 m2</b>							
No Asbestos							
<b>B00F - R0025 - Home Base - 47.98 m2</b>							
Require Inspection							
<b>B00F - R0026 - Practical Activities - 8.74 m2</b>							
Require Inspection							
<b>B00F - R9001 - Uniform Shop - 40.2 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	41m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G - General Learning - 1961 - Brick/Block</b>							
<b>Exterior</b>							
Eaves Linings	Flat AC Sheeting	40m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	20m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	AC Fragments/Debris		Lower portion	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Assumed Asbestos
<b>Interior</b>							
<b>B00G - R0001 - Home Base - 56.77 m2</b>							
No Asbestos							
<b>B00G - R0003 - Movement - 5.87 m2</b>							
No Asbestos							
<b>B00G - R0004 - External Movement - 10.23 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G - R0006 - Home Base - 57 m2</b>							
No Asbestos							
<b>B00G - R0007 - Staff Room Annexe - 23.54 m2</b>							
No Asbestos							

<b>B00G - R0008 - Movement - 14.65 m2</b>							
No Asbestos							
<b>B00G - R0009 - External Movement - 10.43 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G - R0010 - General Storeroom - 6.28 m2</b>							
No Asbestos							
<b>B00G - R0012 - Home Base - 57.15 m2</b>							
No Asbestos							
<b>B00G - R0013 - Deputy Principal - 15.46 m2</b>							
No Asbestos							
<b>B00G - R0014 - Movement - 3.1 m2</b>							
No Asbestos							
<b>B00G - R0015 - Staff Toilet - 3.06 m2</b>							
No Asbestos							
<b>B00G - R0016 - Movement - 5.84 m2</b>							
No Asbestos							
<b>B00G - R0017 - External Movement - 9.49 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G - R0018 - Personal Effects Storage - 4.64 m2</b>							
No Asbestos							
<b>B00G - R0019 - General Storeroom - 6.13 m2</b>							
No Asbestos							
<b>B00G - R0020 - Personal Effects Storage - 4.58 m2</b>							
No Asbestos							
<b>B00G - R0021 - General Storeroom - 6.09 m2</b>							
No Asbestos							
<b>B00G - R0022 - General Storeroom - 6.09 m2</b>							
No Asbestos							
<b>B00G - R0023 - Personal Effects Storage - 4.58 m2</b>							
No Asbestos							
<b>B00H - General Learning - 1961 - Brick/Block</b>							
<b>Exterior</b>							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Eaves Linings	Flat AC Sheeting	60m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	20m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>Interior</b>							
<b>B00H - R0002 - Movement - 6.34 m2</b>							
No Asbestos							
<b>B00H - R0004 - Toilets - Boys/Girls - 1.43 m2</b>							
No Asbestos							
<b>B00H - R0005 - Practical Activities - 1hb - 16.29 m2</b>							
No Asbestos							
<b>B00H - R0007 - Personal Effects Storage - 10.51 m2</b>							
No Asbestos							
<b>B00H - R0008 - General Storeroom - 22.13 m2</b>							
No Asbestos							
<b>B00H - R0009 - Personal Effects Storage - 10.51 m2</b>							
No Asbestos							



<b>B00H - R0010 - Movement - 11.81 m2</b>							
No Asbestos							
<b>B00H - R0013 - General Storeroom - 4.38 m2</b>							
No Asbestos							
<b>B00H - R0014 - General Storeroom - 5.97 m2</b>							
No Asbestos							
<b>B00H - R0015 - External Movement - 102.26 m2</b>							
No Asbestos							
<b>B00H - R0016 - Home Base - 54.9 m2</b>							
Require Inspection							
<b>B00H - R0017 - Practical Activities - 1hb - 1.92 m2</b>							
Require Inspection							
<b>B00H - R0018 - Practical Activities - 1hb - 1.87 m2</b>							
Require Inspection							
<b>B00H - R0019 - Home Base - 55.21 m2</b>							
Require Inspection							
<b>B00H - R0020 - Home Base - 49.86 m2</b>							
Require Inspection							
<b>B00I - Pupil Facilities - 1961 - Brick/Block</b>							
<b>Exterior</b>							
Eaves Linings	Flat AC Sheeting	6m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids - Raked Ceiling	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
<b>Interior</b>							
<b>B00I - R0001 - Movement - 11.39 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00I - R0002 - Canteen - 17.24 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	18m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	4m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00I - R0003 - Canteen Office/Store - 1.87 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00I - R0004 - Canteen Office/Store - 3.84 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00J - Pupil Facilities - 1961 - Brick/Veneer</b>							
<b>Exterior</b>							
Eaves Linings	Flat AC Sheeting	10m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids - Raked Ceiling	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
<b>Interior</b>							
<b>B00J - R0001 - Toilets - Boys - 43.43 m2</b>							
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	44m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)

<b>B00J - R0002 - Toilets - Girls - 49.83 m2</b>							
Partition Walls (Cubicles)	Compressed AC Sheet	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	50m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00K - Pupil Facilities - 1961 - Brick/Block</b>							
<b>Exterior</b>							
Eaves Linings	Flat AC Sheeting	10m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids - Raked Ceiling	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
<b>Interior</b>							
<b>B00K - R0002 - Toilets - Boys - 28.33 m2</b>							
Ceiling Structures/Linings	Compressed AC Sheet	28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00K - R0003 - Toilets - Girls - 25.76 m2</b>							
Ceiling Structures/Linings	Compressed AC Sheet	25.7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00L - Library - 2011 - Brick/Veneer</b>							
<b>Exterior</b>							
Underfloor Voids	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
No Asbestos							
<b>Interior</b>							
<b>B00L - R0001 - Movement - 2.21 m2</b>							
No Asbestos							
<b>B00L - R0002 - Staff Toilet - 4.65 m2</b>							
No Asbestos							
<b>B00L - R0003 - Distribution Board - .51 m2</b>							
No Asbestos							<b>Note: No inspection of live electrical installation</b>
<b>B00L - R0004 - Cleaning Distributed Store - 3.6 m2</b>							
No Asbestos							
<b>B00L - R0005 - K.L.A. Store - 14.62 m2</b>							
No Asbestos							
<b>B00L - R0006 - Communications Room - 7.79 m2</b>							
No Asbestos							
<b>B00L - R0007 - Library Office/Workroom - 22.64 m2</b>							
No Asbestos							
<b>B00L - R0008 - Reading Area - 166.98 m2</b>							
No Asbestos							
<b>B00L - R0009 - External Movement - 22.05 m2</b>							
No Asbestos							
<b>B00L - R9001 - Other-Not Used - 93.93 m2</b>							
No Asbestos							
<b>B00L - R9002 - Special Programs Room - 47.34 m2</b>							
No Asbestos							

**Demountables**

**OS 606 15040 - Learning Unit - Standard With P.A.A A/C - Placement Date : 23-DEC-2019**

**Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.**

No Asbestos Found