

Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Lisarow High School (8544)
Region:	Hunter/Central Coast AMU
State Electorate:	The Entrance
Local Government Area:	Central Coast

Last Reviewed By:	Greencap 20-MAR-2015
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	No
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>

<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - Performance Learning/Staff - 1979 - Brick/Block							
Exterior							
Wall Cladding	Flat AC Sheeting						
Ceiling Voids - Raked Ceiling	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Interior							
B00A - R0001 - Performance Store - 9.55 m2							
No Asbestos							
B00A - R0002 - Performance Store - 9.52 m2							
No Asbestos							
B00A - R0003 - Performance Workshop - 73.05 m2							
No Asbestos							
B00A - R0004 - Toilets-Girls - 13.18 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	15m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0005 - Toilets-Boys - 13.11 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	12m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0006 - Cleaning Supplies Store - 13.14 m2							
No Asbestos							
B00A - R0007 - Distribution Board Cupboard - .92 m2							
						Note: No inspection of live electrical installation	
No Asbestos							
B00A - R0008 - Cleaning Store - Distributed - .91 m2							
No Asbestos							
B00A - R0012 - Movement - 82.62 m2							
No Asbestos							
B00A - R0013 - Movement - 23.63 m2							
No Asbestos							
B00A - R0014 - External Movement - 21.55 m2							
No Asbestos							
B00A - R0015 - General Storeroom - 17.42 m2							
No Asbestos							
B00A - R0016 - External Movement - 1.75 m2							
No Asbestos							
B00A - R0017 - Stairs - .49 m2							
No Asbestos							
B00A - R0018 - Dark Room - 9.05 m2							
No Asbestos							
B00A - R0019 - General Storeroom - 1.42 m2							
No Asbestos							
B00A - R0020 - Darkroom Space - 2.56 m2							
No Asbestos							
B00A - R0021 - Dark Room - 14.56 m2							
No Asbestos							
B00A - R1002 - Movement - 12.69 m2							
No Asbestos							
B00A - R1003 - Stairs - 4.18 m2							
No Asbestos							
B00A - R1004 - Commonroom - 112.07 m2							

No Asbestos							
B00A - R1005 - Staff Kitchen - 11.09 m2							
Furniture / Fixtures - Sink	Resinous Membrane						
B00B - Administration - 1979 - Brick/Block							
Exterior							
Ceiling Voids - Raked Ceiling	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Interior							
B00B - R0001 - General Assistants - 12.85 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00B - R0002 - Leading Teacher - 13.1 m2							
No Asbestos							
B00B - R0003 - Staff - Toilet - 17.45 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0004 - Toilets-Disabled - 5.18 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	3m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0005 - Staff - Toilet - 17.45 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	15m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0006 - Archive Store - 21.41 m2							
No Asbestos							
B00B - R0007 - Ancillary Staff - 26.12 m2							
No Asbestos							
B00B - R0008 - Clinic - Girls - 13 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
B00B - R0009 - Toilets-Girls - 2.05 m2							
No Asbestos							
B00B - R0010 - Clinic - Boys - 13 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00B - R0011 - Toilets-Boys - 2.05 m2							
No Asbestos							
B00B - R0012 - Principal Office - 23.81 m2							
No Asbestos							
B00B - R0013 - Printing/Photocopying - 24.68 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00B - R0014 - Administration - Clerical - 46.48 m2							
No Asbestos							
B00B - R0015 - Distribution Board Cupboard - .88 m2							
No Asbestos							
B00B - R0016 - Leading Teacher - 15.87 m2							
No Asbestos							
B00B - R0017 - Administration - Clerical - 13.41 m2							
No Asbestos							
B00B - R0018 - Deputy Principal Office - 13.36 m2							
No Asbestos							
B00B - R0019 - Deputy Principal Office - 16.41 m2							
No Asbestos							
B00B - R0020 - Movement - 194.1 m2							

Note: No inspection of live electrical installation

No Asbestos							
B00B - R0021 - Public Reception - 16.45 m2							
No Asbestos							
B00B - R0022 - External Movement - 5.27 m2							
No Asbestos							
B00C - Technological & Applied Studies/Music - 1979 - Brick/Block							
Exterior							
Ceiling Voids - Raked Ceiling	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Interior							
B00C - R0001 - Design L.S. - 68.27 m2							
No Asbestos							
B00C - R0002 - Design L.S. - 68.43 m2							
No Asbestos							
B00C - R0003 - Food Technology L.S. - 103.43 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00C - R0004 - Preparation - Materials - 16.46 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00C - R0005 - Food Technology L.S. - 103.81 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00C - R0008 - Seminar - Type 1 - 20.83 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
Furniture / Fixtures - Sink	Resinous Membrane						
B00C - R0009 - Distribution Board Cupboard - .68 m2						Note: No inspection of live electrical installation	
No Asbestos							
B00C - R0010 - Toilets-Boys - 8.32 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	6m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0011 - Toilets-Girls - 8.19 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	12m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0012 - Cleaning Store - Distributed - .68 m2							
No Asbestos							
B00C - R0014 - External Movement - 7.86 m2							
No Asbestos							
B00C - R0015 - Movement - 83.16 m2							
No Asbestos							
B00C - R0017 - External Movement - 1.77 m2							
No Asbestos							
B00C - R0018 - Staff Study - 11.42 m2							
Wall Linings Internal	Flat AC Sheeting						
B00C - R0019 - Stairs - .5 m2							
No Asbestos							
B00C - R0020 - Movement - 91.22 m2							
Requires Inspection							
B00C - R0021 - Student Kitchen - 11.67 m2							
Requires Inspection							
B00C - R1001 - Music Learning Space - 76.69 m2							
No Asbestos							
B00C - R1002 - Music Learning Space - 60.17 m2							

No Asbestos								
B00C - R1003 - Practice/Seminar - 24.81 m2								
No Asbestos								
B00C - R1004 - Staff Study - 24.75 m2								
No Asbestos								
B00C - R1006 - Music Store - 17.93 m2								
Floor Coverings Res/Textile	Vinyl Tiles							
B00C - R1007 - Movement - 45.02 m2								
No Asbestos								
B00C - R1008 - External Movement - 3.11 m2								
No Asbestos								
B00C - R1009 - Stairs - 4.15 m2								
No Asbestos								
B00C - R1010 - Tea Room - 16.89 m2								
Requires Inspection								
B00D - Art - 1979 - Brick/Block								
Exterior								
Ceiling Voids - Raked Ceiling	No Asbestos Found							
Underfloor Voids - Slab on Ground	No Asbestos Found							
Interior								
B00D - R0001 - Resources Store - 27.83 m2								
Floor Coverings Res/Textile	Vinyl Tiles							
B00D - R0002 - Art Learning Space - 58.71 m2								
Floor Coverings Res/Textile	Vinyl Tiles							
B00D - R0003 - Art Learning Space - 51.51 m2								
Floor Coverings Res/Textile	Vinyl Tiles							
B00D - R0004 - Kiln Space - 8.33 m2								
No Asbestos								
B00D - R0005 - Art Learning Space - 60.68 m2								
Floor Coverings Res/Textile	Vinyl Tiles							
B00D - R0006 - Cleaning Store - Distributed - .81 m2								
Ceiling Structures/Linings	Flat AC Sheeting							
B00D - R0007 - Distribution Board Cupboard - .96 m2								
							Note: No inspection of live electrical installation	
No Asbestos								
B00D - R0008 - Staff - Toilet - 9.21 m2								
Partition Walls (Cubicles)	Compressed AC Sheet	12m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00D - R0009 - Staff - Toilet - 9.23 m2								
Partition Walls (Cubicles)	Compressed AC Sheet	12m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00D - R0010 - Toilets-Boys - 13.14 m2								
Partition Walls (Cubicles)	Compressed AC Sheet	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00D - R0011 - Toilets-Girls - 13 m2								
Partition Walls (Cubicles)	Compressed AC Sheet	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00D - R0012 - General Storeroom - 18.67 m2								
No Asbestos								
B00D - R0014 - External Movement - 8.74 m2								
No Asbestos								
B00D - R0015 - Stairs - .5 m2								

No Asbestos	
B00D - R0016 - Stairs - 7.92 m2	
No Asbestos	
B00D - R0017 - Movement - 69.43 m2	
Requires Inspection	
B00D - R0018 - Stage - 17.27 m2	
Requires Inspection	
B00D - R1001 - Art Learning Space - 60.44 m2	
Floor Coverings Res/Textile	Vinyl Tiles
B00D - R1002 - Computer Learning Space - 60.37 m2	
Floor Coverings Res/Textile	Vinyl Tiles
B00D - R1003 - Office/Store - 21.03 m2	
No Asbestos	
B00D - R1004 - General Storeroom - 4.27 m2	
No Asbestos	
B00D - R1005 - Workshop - 36.25 m2	
Floor Coverings Res/Textile	Vinyl Tiles
B00D - R1006 - Stairs - 4.11 m2	
No Asbestos	
B00D - R1007 - Stairs - 4.31 m2	
No Asbestos	
B00E - Technological & Applied Studies - 1979 - Brick/Block	
Exterior	
Ceiling Voids - Raked Ceiling	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found
Interior	
B00E - R0001 - Metal Technology L.S. - 75.44 m2	
Floor Coverings Res/Textile	Vinyl Sheet
B00E - R0002 - Metal Technology Bay - 35.12 m2	
No Asbestos	
B00E - R0003 - Welding Area - 10.71 m2	
No Asbestos	
B00E - R0004 - Welding Area - 6.68 m2	
No Asbestos	
B00E - R0005 - Metal Technology L.S. - 77.13 m2	
Floor Coverings Res/Textile	Vinyl Sheet
B00E - R0006 - Wood Technology L.S. - 80.5 m2	
No Asbestos	
B00E - R0007 - Project Store - Type 1 - 18.85 m2	
No Asbestos	
B00E - R0008 - Materials Learning Space - Type 1 - 88.83 m2	
No Asbestos	
B00E - R0009 - Design L.S. - 39.29 m2	
No Asbestos	
B00E - R0010 - Cleaning Store - Distributed - 2.18 m2	
No Asbestos	
B00E - R0011 - Distribution Board Cupboard - 1.95 m2	
No Asbestos	Note: No inspection of live electrical installation
No Asbestos	
B00E - R0012 - Materials Store - 34.3 m2	
No Asbestos	

B00E - R0013 - Seminar - Type 1 - 22.66 m2		
No Asbestos		
B00E - R0014 - Movement - 104.79 m2		
No Asbestos		
B00E - R0015 - Main Switchroom - 15.98 m2		
No Asbestos		
B00E - R0016 - External Movement - 6.66 m2		
No Asbestos		
B00E - R0017 - Movement - 47.08 m2		
No Asbestos		
B00E - R0018 - Stairs - .65 m2		
No Asbestos		
B00E - R0019 - Dust Extraction Space - 5.56 m2		
Ceiling Structures/Linings	Flat AC Sheeting	
B00E - R1001 - Staff Study - 60.35 m2		
No Asbestos		
B00E - R1002 - Design/Technology L.S. - 60.44 m2		
No Asbestos		
B00E - R1003 - Computer Resource - 27.1 m2		
No Asbestos		
B00E - R1005 - Resources Store - 20.09 m2		
No Asbestos		
B00E - R1006 - Handwashing Facilities - .91 m2		
No Asbestos		
B00E - R1008 - External Movement - 3.91 m2		
No Asbestos		
B00E - R1009 - Stairs - 4.37 m2		
No Asbestos		
B00E - R1010 - Computer Learning Space - 38.32 m2		
No Asbestos		
B00F - Pupil Facilities - 1979 - Brick/Block		
Exterior		
Ceiling Voids - Raked Ceiling	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00F - R0001 - Covered Area - 120.21 m2		
Floor Coverings Res/Textile	Vinyl Tiles	
B00F - R0002 - Student Canteen - 59.17 m2		
No Asbestos		
B00F - R0003 - Office/Store - 4.17 m2		
No Asbestos		
B00F - R0004 - Staff - Toilet - 2.85 m2		
No Asbestos		
B00F - R0005 - Pantry - 7.61 m2		
No Asbestos		
B00F - R0008 - Covered Area - 60.58 m2		
No Asbestos		
B00F - R0009 - External Movement - 10.27 m2		
No Asbestos		
B00F - R0010 - Toilet - Lobby - 4.63 m2		

No Asbestos							
B00F - R0011 - Toilets-Boys - 20.1 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	8m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00F - R0012 - Toilet - Lobby - 4.59 m2							
No Asbestos							
B00F - R0013 - Toilets-Girls - 19.92 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	20m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G - Multi Purpose Facilities - 1979 - Brick/Block							
Exterior							
Ceiling Voids - Raked Ceiling	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Interior							
B00G - M0002 - Stairs - 3.48 m2							
No Asbestos							
B00G - M0003 - Movement - 1.5 m2							
No Asbestos							
B00G - M0004 - Fitness Laboratory - 68.65 m2							
No Asbestos							
B00G - R0001 - Distribution Board Cupboard - 1.4 m2						Note: No inspection of live electrical installation	
No Asbestos							
B00G - R0002 - Toilets-Boys - 18.86 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	40m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G - R0003 - Change - 64.09 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	60m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G - R0004 - Stage - 96.45 m2							
No Asbestos							
B00G - R0005 - Multi-Purpose Space - 489.51 m2							
No Asbestos							
B00G - R0007 - Sport Equipment Store - 21.9 m2							
No Asbestos							
B00G - R0008 - Sport Equipment Store - 56.36 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00G - R0009 - General Storeroom - 24.83 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00G - R0010 - Movement - 14.98 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00G - R0011 - External Movement - 4.57 m2							
No Asbestos							
B00G - R0012 - Plant - 6.04 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00G - R0013 - Movement - 60.65 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00G - R0014 - Movement - 9.13 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00G - R0015 - External Movement - 70.18 m2							
No Asbestos							
B00G - R0017 - Movement - 47.33 m2							

Floor Coverings Res/Textile	Vinyl Tiles							
B00G - R0019 - Sport Equipment Store - 108.41 m2								
No Asbestos								
B00G - R0020 - Chair Store - 15.71 m2								
No Asbestos								
B00G - R0021 - Chair Store - 22.19 m2								
No Asbestos								
B00G - R0022 - Stairs - .77 m2								
No Asbestos								
B00G - R0023 - Movement - 25.64 m2								
Floor Coverings Res/Textile	Vinyl Tiles							
B00G - R0024 - Movement - 10.33 m2								
Floor Coverings Res/Textile	Vinyl Tiles							
B00G - R0025 - Stairs - .38 m2								
No Asbestos								
B00G - R1001 - Toilets-Girls - 12.59 m2								
Partition Walls (Cubicles)	Compressed AC Sheet	15m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00G - R1002 - Change - 63.92 m2								
Partition Walls (Cubicles)	Compressed AC Sheet	60m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00G - R1003 - Performance Store - 27.1 m2								
Floor Coverings Res/Textile	Vinyl Tiles							
B00G - R1004 - General Storeroom - 11.03 m2								
Floor Coverings Res/Textile	Vinyl Tiles							
B00G - R1005 - Staff Shower - 3.46 m2								
No Asbestos								
B00G - R1006 - Movement - 14.89 m2								
Floor Coverings Res/Textile	Vinyl Tiles							
B00G - R1007 - General Storeroom - 15.63 m2								
No Asbestos								
B00G - R1008 - Stairs - 2.91 m2								
No Asbestos								
B00H - Science Learning - 1979 - Brick/Block								
Exterior								
Ceiling Voids - Raked Ceiling	No Asbestos Found							
Underfloor Voids - Slab on Ground	No Asbestos Found							
Interior								
B00H - R0001 - Laboratory L.S. - 78.96 m2								
Floor Coverings Res/Textile	Vinyl Sheet							
B00H - R0002 - Preparation - Science - 47.7 m2								
Floor Coverings Res/Textile	Vinyl Sheet							
B00H - R0003 - Laboratory L.S. - 78.36 m2								
Floor Coverings Res/Textile	Vinyl Sheet							
B00H - R0004 - Laboratory L.S. - 79.17 m2								
Floor Coverings Res/Textile	Vinyl Sheet							
B00H - R0005 - Staff Study - 48.09 m2								
Floor Coverings Res/Textile	Vinyl Sheet							
B00H - R0006 - Laboratory L.S. - 78.99 m2								
Floor Coverings Res/Textile	Vinyl Sheet							
B00H - R0007 - Laboratory L.S. - 78.18 m2								

Floor Coverings Res/Textile	Vinyl Sheet							
B00H - R0008 - Preparation - Science - 47.33 m2								
Floor Coverings Res/Textile	Vinyl Sheet							
B00H - R0009 - Laboratory L.S. - 78.71 m2								
Floor Coverings Res/Textile	Vinyl Sheet							
B00H - R0010 - Distribution Board Cupboard - 1.75 m2								
Note: No inspection of live electrical installation								
No Asbestos								
B00H - R0011 - Chemical Store - 11.81 m2								
No Asbestos								
B00H - R0012 - Cleaning Store - Distributed - 2.08 m2								
No Asbestos								
B00H - R0013 - Resources Store - 38.65 m2								
No Asbestos								
B00H - R0014 - Preparation - Science - 27.75 m2								
No Asbestos								
B00H - R0015 - Distribution Board Cupboard - 1.74 m2								
Note: No inspection of live electrical installation								
No Asbestos								
B00H - R0016 - General Storeroom - 20.26 m2								
No Asbestos								
B00H - R0017 - Movement - 344.9 m2								
No Asbestos								
B00J - General Learning - 1979 - Brick/Block								
Exterior								
Window	Flat AC Sheeting							
Ceiling Voids - Raked Ceiling	No Asbestos Found							
Underfloor Voids - Slab on Ground	No Asbestos Found							
Interior								
B00J - R0001 - General Learning Space - 47.5 m2								
No Asbestos								
B00J - R0002 - General Learning Space - 46.95 m2								
No Asbestos								
B00J - R0003 - General Learning Space - 46.95 m2								
No Asbestos								
B00J - R0004 - General Learning Space - 46.6 m2								
No Asbestos								
B00J - R0005 - Cleaning Store - Distributed - .88 m2								
No Asbestos								
B00J - R0006 - Distribution Board Cupboard - .91 m2								
Note: No inspection of live electrical installation								
No Asbestos								
B00J - R0007 - Staff - Toilet - 6.97 m2								
Partition Walls (Cubicles)	Compressed AC Sheet	12m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00J - R0008 - Staff - Toilet - 7.01 m2								
Partition Walls (Cubicles)	Compressed AC Sheet	12m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00J - R0009 - Toilets-Boys - 13.42 m2								
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00J - R0010 - Toilets-Girls - 13.46 m2								
Partition Walls (Cubicles)	Compressed AC Sheet	15m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	

B00J - R0014 - General Storeroom - 5.43 m2	
No Asbestos	
B00J - R0016 - External Movement - 7.74 m2	
No Asbestos	
B00J - R0017 - Movement - 81.64 m2	
No Asbestos	
B00J - R0018 - Stairs - .5 m2	
No Asbestos	
B00J - R0019 - Movement - 82.01 m2	
No Asbestos	
B00J - R0020 - Resources Store - 4.73 m2	
Wall Linings Internal	Flat AC Sheeting
Floor Coverings Res/Textile	Vinyl Tiles
B00J - R0021 - External Movement - 1.89 m2	
No Asbestos	
B00J - R0023 - Special Learning Space - 22.26 m2	
Requires Inspection	
B00J - R0024 - Staff Study - 15.4 m2	
Requires Inspection	
B00J - R0025 - Staff Kitchen - 6.13 m2	
Requires Inspection	
B00J - R1001 - General Learning Space - 47.64 m2	
No Asbestos	
B00J - R1002 - General Learning Space - 47.02 m2	
No Asbestos	
B00J - R1003 - General Learning Space - 47.09 m2	
No Asbestos	
B00J - R1004 - General Learning Space - 46.67 m2	
No Asbestos	
B00J - R1008 - Office/Store - 5.45 m2	
No Asbestos	
B00J - R1010 - External Movement - 6.61 m2	
No Asbestos	
B00J - R1011 - General Storeroom - 4.67 m2	
Wall Linings Internal	Flat AC Sheeting
Floor Coverings Res/Textile	Vinyl Tiles
B00J - R1012 - Movement - 62.47 m2	
No Asbestos	
B00J - R1013 - Stairs - 4.17 m2	
No Asbestos	
B00J - R1014 - Staff Study - 41.6 m2	
No Asbestos	
B00K - General Learning - 1979 - Brick/Block	
Exterior	
Ceiling Voids - Raked Ceiling	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found
Interior	
B00K - R0001 - Staff Study - 13.42 m2	
No Asbestos	
B00K - R0002 - Distribution Board Cupboard - .92 m2	
Note: No inspection of live electrical installation	

No Asbestos							
B00K - R0003 - Cleaning Store - Distributed - .79 m2							
No Asbestos							
B00K - R0004 - General Learning Space - 47.63 m2							
No Asbestos							
B00K - R0005 - General Learning Space - 47.5 m2							
No Asbestos							
B00K - R0006 - General Learning Space - 47.43 m2							
No Asbestos							
B00K - R0007 - General Learning Space - 47.5 m2							
No Asbestos							
B00K - R0008 - Interview/Office - Type 1 - 21.49 m2							
No Asbestos							
B00K - R0009 - General Storeroom - 5.13 m2							
No Asbestos							
B00K - R0011 - Resources Store - 22.38 m2							
No Asbestos							
B00K - R0012 - Toilets-Girls - 13.11 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	12m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00K - R0013 - Toilets-Boys - 13.07 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	12m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00K - R0015 - External Movement - 7.51 m2							
No Asbestos							
B00K - R0018 - Stairs - .49 m2							
No Asbestos							
B00K - R0019 - Resources Store - 5.02 m2							
Wall Linings Internal	Flat AC Sheeting						
B00K - R0020 - Movement - 80.38 m2							
No Asbestos							
B00K - R1001 - General Learning Space - 47.7 m2							
No Asbestos							
B00K - R1002 - General Learning Space - 47.7 m2							
No Asbestos							
B00K - R1003 - General Learning Space - 47.57 m2							
No Asbestos							
B00K - R1004 - General Learning Space - 47.84 m2							
No Asbestos							
B00K - R1006 - Resources Store - 5.43 m2							
No Asbestos							
B00K - R1010 - External Movement - 6.64 m2							
No Asbestos							
B00K - R1011 - General Storeroom - 4.95 m2							
Wall Linings Internal	Flat AC Sheeting						
Floor Coverings Res/Textile	Vinyl Tiles						
B00K - R1012 - Movement - 61.89 m2							
No Asbestos							
B00K - R1013 - Stairs - 4.28 m2							
No Asbestos							
B00K - R1014 - Staff Study - 41.72 m2							
No Asbestos							

B00K - R1015 - Tea Room - 2.5 m2		
No Asbestos		
B00L - Library - 1979 - Brick/Block		
Exterior		
Ceiling Voids - Raked Ceiling	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00L - R0006 - Cleaning Store - Distributed - 1.81 m2		
No Asbestos		
B00L - R0007 - Distribution Board Cupboard - 1.16 m2		Note: No inspection of live electrical installation
No Asbestos		
B00L - R0013 - Study Space - 270.22 m2		
No Asbestos		
B00L - R0015 - Main Entry - 35.49 m2		
No Asbestos		
B00L - R0016 - Careers Advisers Office - 12.21 m2		
No Asbestos		
B00L - R0017 - System Administrators Office - 12.41 m2		
No Asbestos		
B00L - R0018 - Computer Room - 9.4 m2		
No Asbestos		
B00L - R0019 - Staff - Toilet - 5.8 m2		
No Asbestos		
B00L - R0020 - Toilets-Disabled - 5.43 m2		
No Asbestos		
B00L - R0021 - Main Area - 224.16 m2		
No Asbestos		
B00L - R0022 - Senior Study - 75.33 m2		
No Asbestos		
B00L - R0023 - Seminar - 14.25 m2		
No Asbestos		
B00L - R0024 - Seminar - 13.86 m2		
No Asbestos		
B00L - R0025 - Seminar - 13.44 m2		
No Asbestos		
B00L - R0026 - Movement - 59.82 m2		
No Asbestos		
B00L - R0027 - Library Administration - 56.61 m2		
No Asbestos		
B00L - R0028 - Tea Room - 5.95 m2		
No Asbestos		
B00M - General Learning - 1979 - Brick/Block		
Exterior		
Ceiling Voids - Raked Ceiling	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00M - R0001 - Interview/Office - Type 1 - 13.15 m2		
No Asbestos		

B00M - R0002 - Distribution Board Cupboard - 1.23 m2					Note: No inspection of live electrical installation			
No Asbestos								
B00M - R0003 - Cleaning Store - Distributed - 1.03 m2								
No Asbestos								
B00M - R0004 - General Learning Space - 47.43 m2								
No Asbestos								
B00M - R0005 - General Learning Space - 47.43 m2								
No Asbestos								
B00M - R0006 - General Learning Space - 47.22 m2								
No Asbestos								
B00M - R0007 - General Learning Space - 47.57 m2								
No Asbestos								
B00M - R0009 - Resources Store - 5.09 m2								
No Asbestos								
B00M - R0012 - Toilets-Girls - 13.36 m2								
Partition Walls (Cubicles)	Compressed AC Sheet	12m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00M - R0013 - Toilets-Boys - 13.28 m2								
Partition Walls (Cubicles)	Compressed AC Sheet	12m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00M - R0015 - External Movement - 7.94 m2								
No Asbestos								
B00M - R0016 - Stairs - .5 m2								
No Asbestos								
B00M - R0017 - General Storeroom - 5.02 m2								
Floor Coverings Res/Textile	Vinyl Tiles							
Wall Linings Internal	Flat AC Sheeting							
B00M - R0018 - Movement - 81.78 m2								
No Asbestos								
B00M - R0019 - Staff Study - 41.22 m2								
No Asbestos								
B00M - R0020 - Tea Room - 1.95 m2								
No Asbestos								
B00M - R1001 - Computer Learning Space - 47.84 m2								
No Asbestos								
B00M - R1002 - General Learning Space - 47.56 m2								
No Asbestos								
B00M - R1003 - General Learning Space - 47.43 m2								
No Asbestos								
B00M - R1004 - General Learning Space - 47.91 m2								
No Asbestos								
B00M - R1006 - Resources Store - 5.36 m2								
No Asbestos								
B00M - R1009 - Movement - 62.63 m2								
No Asbestos								
B00M - R1010 - External Movement - 6.46 m2								
No Asbestos								
B00M - R1011 - General Storeroom - 4.71 m2								
Floor Coverings Res/Textile	Vinyl Tiles							
Wall Linings Internal	Flat AC Sheeting							
B00M - R1012 - Stairs - 4.03 m2								
No Asbestos								

B00M - R1013 - Staff Study - 43.05 m2		
No Asbestos		
B00N - Agricultural Science - 1979 - Brick/Block		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00N - R0003 - Office/Store - 41.72 m2		
No Asbestos		
B00N - R0004 - Growing/Breeding - 7.1 m2		
No Asbestos		
B00N - R0005 - External Movement - 23.69 m2		
No Asbestos		
B00N - R0006 - Movement - 1.94 m2		
No Asbestos		
B00N - R0007 - General Storeroom - 7.06 m2		
No Asbestos		
B00N - R0008 - Staff - Toilet - 7.83 m2		
No Asbestos		
B00N - R0009 - Plant - 1.42 m2		
No Asbestos		
B00O - Storage - 1979 - Brick/Block		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00O - R0001 - Machine Storage - 18.99 m2		
No Asbestos		
B00O - R0002 - Shed Workshop - 36.03 m2		
No Asbestos		
B00P - Storage - 2016 - Metal Shed		
Exterior		
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00P - R0001 - General Storeroom - 53.07 m2		
No Asbestos		
B00Z - Other - 2010 - Metal Shed		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00Z - R0001 - No Access - 11.12 m2		
No Asbestos		

Demountables

OS 522 18179 - Staff Study - Placement Date : 17-NOV-2006

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found