Attachment A – Response to Independent Audit non-compliances

Condition ID	Compliance Requirement	Audit finding	Proponent's Proposed Action/Action Taken/Response	Evidence	Due Date/Status
N/A – No n	on-compliances were identified.				



Attachment B – Response to Independent Audit observations

Condition ID		Audit Observation/Opportunity for Improvement	Proponent's Proposed or Completed Action or reason for not implementing measures/changes		Due Date/Status
	a) must be prominently displayed at the boundaries of the site for the purpose of informing the public of project details including, but not limited to the details of the Builder, Certifier and Structural Engineer. b) is to satisfy the following requirements: i) minimum dimensions of the site notice(s) must measure 841 mm x 594 mm (A1) with any text on the site notice(s) to be a minimum of 30-point type size; ii) the site notice(s) must be durable and weatherproof and must be displayed throughout the works period; iii) the approved hours of work, the name of the builder, Certifier, structural engineer, site/ project manager, the responsible managing company (if any), its address and 24-hour contact phone number for any inquiries, including construction/ noise complaint must be displayed on the site notice(s); and iv) the site notice(s) must be mounted at eye level on the perimeter hoardings/fencing and must state that unauthorised entry to the site is not	During the site inspection, it was noted that the Site Notice did not meet the specifications for items b) i) and ii). Also, the Site Manager name was incorrect.	day of the audit to address requirements i) font size and	A photo of the new site notice (corflute) was provided after the audit.	Closed
C26	construction works and until such time as all ground disturbed by the works have been stabilised and rehabilitated so that it no longer acts as a source of sediment.	August 2017 from Woolacotts Consulting	S S	on day.	Closed