

# Beresfield Public School

## Works notification | 6 February 2025

Dear staff, parents and carers,

Due to a recent storm, we have removed and replaced water-damaged flooring and affected ceiling panels in 4 classrooms in the Administration Building (Building A) and one classroom in Building D at Beresfield Public School.

The material in the ceiling panels and in the vinyl tiles under the carpet in these rooms contain bonded asbestos as listed on the school's asbestos register.

NSW Health explains that 'living or working with asbestos, or just being around it, is a low risk to your health as long as the asbestos is in good condition and not damaged'.

Work to remove and replace the flooring and ceiling panels took place during the recent school holidays on Tuesday 28 January 2025.

All work was done in accordance with work health and safety laws and the NSW Department of Education's Asbestos Management Plan. All work was completed by licensed asbestos contractors and monitored by independent hygienists.

Following the work, the rooms were inspected by the independent hygienist and clearance provided.

The health, safety and wellbeing of the school and the local community is our highest priority.

If you have any questions about this work, please contact the NSW Department of Education on the details below.

Thank you for your cooperation during this important work.



Email: [schoolinfrastructure@det.nsw.edu.au](mailto:schoolinfrastructure@det.nsw.edu.au)  
Phone: 1300 482 651  
[www.schoolinfrastructure.nsw.gov.au](http://www.schoolinfrastructure.nsw.gov.au)