## Bowral Public School Works notification | 28 March 2025

Dear staff, parents and carers,

Urgent roof replacement work was completed on Saturday 15 March 2025 for Building 1 at Bowral Public School was required to repair significant damage caused by possums.

Roofing work also required the planned removal of eave sheets which were known to contain bonded asbestos, as listed in the school's asbestos register.

The eave sheets were undisturbed and in good condition.

NSW Health explains that "living or working with asbestos, or just being around it, is a low risk to your health as long as the asbestos is in good condition and not damaged".

All work was completed by licensed asbestos contractors and inspected by independent hygienists, in accordance with work health and safety laws and the NSW Department of Education's Asbestos Management Plan,


Work involving asbestos-containing materials took place outside of school hours with safety measures in place, including temporary fencing and air monitoring.

The roof replacement work was completed in one day (15 March) and an independent hygienist inspected the area to confirm the eaves had been fully remediated.

The health, safety, and wellbeing of all members of our school and the local community are our highest priorities.

Thank you for your cooperation during this important work.





schoolinfrastructure.nsw.gov.au





NSW Department of Education

Email: schoolinfrastructure@det.nsw.edu.au Phone: 1300 482 651

schoolinfrastructure.nsw.gov.au

