

# Kellys Plains Public School

## Works notification | 14 October 2024

Dear staff, parents and carers,

Following a heavy storm, a water stain was found on one ceiling panel of the admin library building (located next to the football oval) at Kellys Plains Public School on 23 July 2024.

The ceiling is known to contain bonded asbestos, as listed in the school's asbestos register.

NSW Health explains if bonded asbestos is mixed with cement or other hard bonding materials, and in good condition, it is likely to be low risk.

As a precaution, the panel was repaired, as part of planned maintenance work, during the Spring School Holidays.

An independent hygienist was engaged on Wednesday 9 October to install air monitoring and provide advice.

The roof was inspected by the independent hygienist and clearance certificate was issued on Friday 11 October, before the building was reopened today.

All work was done in accordance with work, health and safety laws and the NSW Department of Education's Asbestos Management Plan.

All work was completed by licensed and accredited asbestos contractors and monitored by independent hygienists in strict accordance with all applicable legislation, regulations, policies, and guidelines.

Safety measures and air monitoring were in place during the work.

The health, safety, and wellbeing of the school and the local community remain our highest priority.

Thank you for your cooperation during this important work.



Email: [schoolinfrastructure@det.nsw.edu.au](mailto:schoolinfrastructure@det.nsw.edu.au)  
Phone: 1300 482 651  
[www.schoolinfrastructure.nsw.gov.au](http://www.schoolinfrastructure.nsw.gov.au)

