

# Robertson Public School

## Works notification | 31 July 2024

Dear staff, parents and carers,

During an inspection at Robertson Public School, a hole was identified in the ceiling area located outside of the canteen. The ceiling is suspected to contain asbestos as it is listed in the school's asbestos register.

As a precaution, access to the area was restricted to students and staff from 29 July and the ceiling material has been tested by an independent hygienist.

Testing was done outside of school hours and a report will be provided to indicate what repair or remediation work will be required.

We will update the school community with this information as it becomes available.

The ceiling has been fully encapsulated with core flute and sealant. The surrounding walls are covered with a plastic cover and access remains restricted following the advice of the independent hygienist.

All work will be done outside of school hours, in accordance with work, health and safety laws and the NSW Department of Education's Asbestos Management Plan.

Air monitoring will be in place while the work is carried out.

All work will be completed by licensed and accredited asbestos contractors and monitored by independent hygienists in strict accordance with all applicable legislation, regulations, policies, and guidelines.

The health and wellbeing of students, staff and the local community is our highest priority.

Thank you for your cooperation during this important work.



Email: [schoolinfrastructure@det.nsw.edu.au](mailto:schoolinfrastructure@det.nsw.edu.au)  
Phone: 1300 482 651  
[www.schoolinfrastructure.nsw.gov.au](http://www.schoolinfrastructure.nsw.gov.au)

