

# Kotara South Public School

## Works notification | 27 May 2025

Dear staff, parents and carers,

Suspected mould was found in a general classroom learning space including student toilets and practical activities area in Building C at Kotara South Public School.

This was due to excess moisture after continuous heavy rain. Affected rooms have been temporarily isolated until repairs and cleaning are carried out. Students and staff have access to alternative toilets and classrooms to use during this time.

Remediation work includes an environmental clean of the areas with air scrubbers (a type of filtration device), dehumidifiers and exhaust fans in place.

We expect to have this work completed over the next two weeks and the rooms reopened in the week starting Monday 9 June 2025.

Work involving mould will take place during and after school hours with appropriate safety measures in place.

An independent hygienist will return to inspect all spaces and provide a clearance report before the rooms are reopened for occupation.

Please be aware of the preventative measures as advised by [NSW Health's mould factsheet](#) to help avoid mould growth and follow these steps as best you can.

These measures include maximising natural ventilation where possible by opening windows and doors.

The health, safety and wellbeing of all members of our school and the local community are our highest priorities.

Thank you for your cooperation during this important work.



Email: [schoolinfrastructure@det.nsw.edu.au](mailto:schoolinfrastructure@det.nsw.edu.au)  
Phone: 1300 482 651  
[schoolinfrastructure.nsw.gov.au](http://schoolinfrastructure.nsw.gov.au)