

Killarney Vale Public School

Works notification | 4 May 2026

Dear staff, parents and carers,

The health, safety, and wellbeing of all members of our school and the local community are our highest priorities.

On Monday 27 April 2026, a crack was identified in the external wall of the Building C movement area at Killarney Vale Public School.

The infill panel underneath a window in this area is known to contain bonded asbestos, as listed on the School's Asbestos Management Plan. The area was immediately isolated, an independent hygienist was engaged to undertake testing, and temporary repairs to seal the crack were done.

All air monitoring to date across the site has returned results below the minimum detectable limit, which means it is consistent with acceptable levels in ambient air (i.e. <0.01 fibres/mL) as per SafeWork NSW guidelines.

Work to remove asbestos-containing materials took place on **Saturday 2 May 2026** between 7 am and 1 pm with safety measures in place.

All work was done in accordance with work health and safety laws and the NSW Department of Education's Asbestos Management Plan. All work was completed by licensed asbestos contractors and inspected by independent hygienists.

If you have any questions about this work, please contact the NSW Department of Education using the details below.

Thank you for your understanding and support during this important work.

What makes Killarney Vale Public School special?

The staff at Killarney Vale Public School aspire to create an equitable and outstanding learning community where every child is known, valued and supported.

The educators are dedicated to nurturing each child to reach their unique potential through inclusive, engaging and purposeful education.



Email: schoolinfrastructure@det.nsw.edu.au
Phone: 1300 482 651
www.schoolinfrastructure.nsw.gov.au