

Braddock Public School

Works notification | 18 August 2023

Dear staff and parents/carers,

During routine inspections at Braddock Public School, a crack was identified in the ceiling of the veranda outside the canteen and hall in Building B. The ceiling lining is known to contain asbestos materials as per the school's asbestos register.

We are following all the advice and protocols of an independent asbestos hygienists and other experts.

The crack has been covered and the veranda continues to be used.

Work to remove and replace the ceiling lining will take place as soon as licensed and accredited contractors can be scheduled. The area will be cordoned off and additional safety measures and monitoring will be put in place before works start. All work involving asbestos containing materials will take place outside of school hours.

Work will be done in accordance with SafeWork NSW regulations and the NSW Department of Education's Asbestos Management Plan. All work will be completed by licensed and accredited asbestos contractors and monitored by occupational hygienists in strict accordance with all applicable legislation, regulations, policies, and guidelines.

The health, safety, and wellbeing of the school and the local community is our highest priority, and we will continue to keep the community updated.

Thank you for your cooperation during this important work.

