

# Arranounbai School

Works notification | 16 February 2024

Dear staff, parents and carers,

Damage occurred to the ceiling of the carport at Arranoubai School on 9 February 2024. The area is known to contain asbestos as per the school's asbestos register and was cordoned off.

Work was carried out to remove and replace the damaged ceiling of the carport on 14 February 2024. Safety measures and air monitoring were in place during the work and the area remained out of bounds until the asbestos removal work was finished.

An independent hygienist has inspected the area to confirm that it has been fully remediated, and the school received a clearance certificate.

Work was done in accordance with work, health and safety laws and the NSW Department of Education's Asbestos Management Plan. All work was completed by licensed and accredited asbestos contractors and monitored by occupational hygienists in strict accordance with all applicable legislation, regulations, policies, and guidelines.

The health, safety, and wellbeing of the school and the local community is our highest priority. If you have any questions about the work, please contact us on the details below.

Thank you for your cooperation during this important work.

