

Lakeside School

Works notification | 10 August 2023

Dear staff and parents/carers,

During inspections to investigate the source of a roof leak in Building K at Lakeside School, suspected asbestos containing material was identified in a crack found in the ceiling sheets.

We are following all the advice and protocols of independent asbestos hygienists and other experts.

The crack has been taped up and testing will be conducted by an independent hygienist to confirm the nature of the material and if remediation is needed.

If necessary, this area will be remediated in accordance with SafeWork NSW regulations and the NSW Department of Education's Asbestos Management Plan. All work will be completed by licensed and accredited independent asbestos contractors and monitored by occupational hygienists in strict accordance with all applicable legislation, regulations, policies, and guidelines.

The area will be inspected to ensure it has been fully remediated and the school will receive a clearance certificate.

The health, safety, and wellbeing of the school and local community is our highest priority, and we will continue to keep the community updated.

Thank you for your understanding during this important work.

