

Plattsburg Public School

Works notification | 17 March 2026

Dear staff, parents and carers,

On Wednesday 11 March 2026, 2 small holes were accidentally made to the wall lining in a Building H classroom at Plattsburg Public School.

The wall lining in this location is known to contain bonded asbestos, as listed on the School Asbestos Management Plan.

NSW Health explains that "living or working with asbestos, or just being around it, is a low risk to your health as long as the asbestos is in good condition and not damaged".

An independent hygienist was engaged to provide advice and conduct air monitoring. Air monitoring returned results below the minimum detectable limit, which means it is consistent with acceptable levels in ambient air (i.e. <0.01 fibres/mL) as per SafeWork NSW guidelines.

Access to the classroom was restricted while work to seal the holes was carried out between 6:30 am and 8 am on Thursday 12 March 2026.

The independent hygienist inspected the area and provided clearance for it to be reopened.

All work was done in accordance with work health and safety laws and the NSW Department of Education's Asbestos Management Plan. Safety measures are in place. All work was completed by licensed asbestos contractors.

The health, safety, and wellbeing of all members of our school and the local community are our highest priorities.

If you have any questions about this work, please contact the NSW Department of Education on the details below.

Thank you for your understanding and support during this important work.



Email: schoolinfrastructure@det.nsw.edu.au
Phone: 1300 482 651
schoolinfrastructure.nsw.gov.au

