

Chester Hill High School

Works notification | 22 May 2026

Dear staff, parents and carers,

The health, safety, and wellbeing of all members of our school and the local community are our highest priorities.

On Monday 18 May 2026, staff discovered a crack in an internal wall suspected to contain bonded asbestos in IEC room 7 at Chester Hill High School.

This area is assumed to contain bonded asbestos as listed on the School Asbestos Management Plan (SAMP). An independent hygienist was engaged to undertake testing and provide advice. Testing confirmed that the wall material contained bonded asbestos. The register will be updated to include this confirmed find as required.

As precaution, the room was closed to restrict access to students, staff and school visitors.

Work to repair the wall took place on Tuesday 19 May 2026 with further planned maintenance, including painting, continuing in the coming days.

All work involving asbestos containing material took place outside of school hours with safety measures such as PPE in place.

All work was done in accordance with work health and safety laws and the NSW Department of Education's Asbestos Management Plan. Safety measures were in place while work was being done. All work was completed by licensed asbestos contractors.

If you have any questions about this work, please contact the NSW Department of Education on the details below.

Thank you for your understanding and support during this important work.



For more information about asbestos please visit the [NSW Health website](#) or scan the QR code.



Email: schoolinfrastructure@det.nsw.edu.au
Phone: 1300 482 651
schoolinfrastructure.nsw.gov.au