

Upgrades to Chatswood Public School and Chatswood High School

\$ S S H Q G L [% & \$ 6 W D W H P H Q W

SSD 9483

Prepared by 0 F. H Q] L H * U R X S

For School Infrastructure NSW, Department of Education



A Bureau Veritas Group Company

McKenzie Group Consulting (NSW) Pty Ltd

ACN: 093 211 995

Level 6, 189 Kent Street, Sydney NSW 2000

Tel: 02 8298 6800 Fax: 02 8298 6899

sydney@mckenzie-group.com.au

Department of Education (School Infrastructure) NSW
Level 8, 259 George Street
Sydney NSW 2000

Attention: Mr Frank Princi

Dear Frank,

**Re: Chatswood Education Precinct Buildings G, P1, P2, Q, S & T
Development Application – BCA Compliance**

We have reviewed the design documentation against the provisions of the Building Code of Australia 2019. We confirm that, based on the below documentation, the project is capable of complying with Building Code of Australia 2019.

Drawings reviewed:

Architectural Drawings prepared by Architectus:

Site Plans

SD-AX-A0042[A], SD-AX-A0043[A], SD-AX-A0044[A], SD-AX-A0045[A], SD-AX-A0046[A], SD-AX-A0047[A], SD-BX-A0042[A], SD-BX-A0043[A], SD-BX-A0044[A], SD-BX-A0045[A], SD-BX-A0046[A], SD-BX-A0047[A], SD-BX-A0048[A] and SD-BX-A0049[A].

Building G:

SD-BG-A1000[A], SD-BG-A1001[A], SD-BG-A1002[B], SD-BG-A1100[A], SD-BG-A2000[C], SD-BG-A2001[C], SD-BG-A2010[C] and SD-BG-A3000[A].

Building P1+P2

SD-BP-A1000[E], SD-BP-A1001[E], SD-BP-A1002[E], SD-BP-A1003[E], SD-BP-A1004[E], SD-BP-A1005[E], SD-BP-A1006[E], SD-BP-A1007[E], SD-BP-A1008[E], SD-BP-A1009[E], SD-BP-A1010[E], SD-BP-A1011[E], SD-BP-A1012[D], SD-BP-A2000[B], SD-BP-A2001[B], SD-BP-A2002[B], SD-BP-A2003[B], SD-BP-A2012[B], SD-BP-A2013[B], SD-BP-A2100[D], SD-BP-A2101[D], SD-BP-A2110[D] and SD-BP-A2111[D].

Building Q:

SA-AQ-A1000[B], SA-AQ-A1001[B], SA-AQ-A1002[B], SA-AQ-A1003[B], SA-AQ-A1004[B], SA-AQ-A1005[B], SA-AQ-A1006[B], SA-AQ-A1007[B], SA-AQ-A1008[B], SA-AQ-A1009[B], SA-AQ-A2000[A], SA-AQ-A2001[A], SA-AQ-A2002[A], SA-AQ-A2100[A] and SA-AQ-A2101[A].

Building S

SD-AS-A1000[C], SD-AS-A1001[C], SD-AS-A1002[C], SD-AS-A1003[C], SD-AS-A1004[C], SD-AS-A1005[C], SD-AS-A1006[C], SD-AS-A1007[C], SD-AS-A1008[C], SD-AS-A1009[C], SD-AS-A1010[C], SD-AS-A1100[C], SD-AS-A1101[C], SD-AS-A1102[C], SD-AS-A1103[C], SD-AS-A1104[C], SD-AS-A1105[C], SD-AS-A1106[C], SD-AS-A1107[C], SD-AS-A1108[C], SD-AS-A2000[C], SD-AS-A2001, SD-AS-A2002[C], SD-AS-A2100[C], SD-AS-A2101[C], SD-AS-A3000[C], SD-AS-A3001[C], SD-AS-A3002[C], SD-AS-A3003[C], SD-AS-A3004[C], SD-AS-A3005[C], SD-AS-A3006[C], SD-AS-A3007[C] and SD-AS-A3008[C].

Building T:

SD-AT-A1000[C], SD-AT-A1001[C], SD-AT-A1002[C], SD-AT-A1100[A], SD-AT-A1101[A], SD-AT-A2000[C], SD-AT-A2001[C], SD-AT-A2010[B], SD-AT-A3000[A] and SD-AT-A3001[A].

Yours faithfully

Elie Ishac
Senior Building Surveyor
McKenzie Group Consulting (NSW) Pty Ltd
ACN 093 211 995