

Cammeray Public School

Works notification

13 October 2022

Dear staff and parents/carers,

During the recent wet weather, erosion events caused by the heavy rain have resulted in fragments of suspected asbestos containing material resurfacing on the north east corner of the school site behind the sports court. The area was previously out of bounds to students and staff as it is part of the ongoing maintenance works to rectify stormwater, kerb and guttering at Cammeray Public School.

We are following all the advice and protocols of independent asbestos hygienists and other experts.

Work to inspect and test the area will take place on Friday 14 October 2022. All suspected asbestos containing material will be removed outside of school hours and in accordance with the advice of the independent hygienist.

The area will remain out of bounds to students and staff until the removal and associated maintenance work is completed.

This area will be remediated in accordance with SafeWork NSW regulations and the NSW Department of Education's Asbestos Management Plan. All work will be completed by licensed and accredited asbestos contractors, and monitored by occupational hygienists in strict accordance with all applicable legislation, regulations, policies and guidelines.

The area will be inspected to ensure it has been fully remediated. The school will receive a clearance certificate before the area is open to students and staff.

The health, safety, and wellbeing of the school and the local community is our highest priority.

Thank you for your cooperation during this important work.

For more information contact:

School Infrastructure NSW
Email: schoolinfrastructure@det.nsw.edu.au
Phone: 1300 482 651
www.schoolinfrastructure.nsw.gov.au